Checklist for Phase I Site Assessments Conducted using EPA Brownfields **Assessment Grant Funds Contact Information** Grantee Name: Grand Rapids Brownfield Redevelopment Authority Grant Number: BF 00E01375 181701 ACRES Property ID: Jonathan Klooster Program Manager Name: (Point of Contact) Contact Phone Number: 616-456-3462 Name / Address of Property Assessed: 802 Alpine Avenue NW, Grand Rapids, MI Checklist Please indicate that each of the following All Appropriate Inquiries documentation requirements were met for the Phase I assessment conducted at the above listed property: An opinion as to whether the inquiry has identified conditions indicative of releases or threatened releases of hazardous substances, and as applicable, pollutants and contaminants, petroleum or petroleum products, or controlled substances, on, at, in, or to the subject property. An identification of "significant" data gaps (as defined in §312.10 of AAI final rule and §12.7 of ASTM E1527-05), if any, in the information collected for the inquiry, as well as comments regarding the significance of these data gaps. Significant data gaps including missing and unattainable information that affects the ability of the environmental professional to identify conditions indicative of releases or threatened releases of hazardous substances, and as applicable, pollutants and contaminants, petroleum or petroleum products, or controlled substances, on, at, in, or to the subject property. **Qualifications** and signature of the environmental professional(s). The environmental professional must place the following statements in the document and sign the document: [I] '[I, We] declare that, to the best of [my, our] professional knowledge and belief, [I, we] meet the definition of Environmental Professional as defined in §312.10 of this part." [I] ''[I, We] have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. [I, We] have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.'' Note: Please use either "I" or "We." In compliance with §312.31(b) of the AAI final rule and §12.6.1 of ASTM E1527-05, the environmental professional must include in the final report an opinion regarding additional appropriate investigation, if the environmental professional has such an opinion.

Signature of Grantee Program Manager

Date



Environmental & Engineering Services Nationwide



PHASE I ENVIRONMENTAL SITE ASSESSMENT

802 Alpine Avenue NW | Grand Rapids, Michigan PM Project Number 03-4006-0

Prepared for:

City of Grand Rapids 300 Monroe NW Grand Rapids, Michigan 49503

Prepared by:

PM Environmental, Inc. 560 5th Street NW, Suite 301 Grand Rapids, Michigan 49504

ENVIRONMENTAL SERVICES

BUILDING ARCHITECTURE, ENGINEERING & SCIENCE

INDUSTRIAL HYGIENE SERVICES

BROWNFIELDS & ECONOMIC INCENTIVES CONSULTING

Know Your Risk.
Take Control.
Work with the Experts.

www.pmenv.com



Detroit 4080 W. 11 Mile Road Berkley, MI 48072 f: 877.884.6775

f: 877.884.6775 f: 877.884.6775 t: 248.336.9988 t: 517.321.3331

Lansing 3340 Ranger Road Lansing, MI 48906 f: 877.884.6775 Grand Rapids 560 5th Street NW, Suite 301 Grand Rapids, MI 49504 f: 877.884.6775

t: 616.285.8857

January 19, 2015

Mr. Jonathan Klooster City Of Grand Rapids 300 Monroe NW Grand Rapids, Michigan 49503

Re: Phase I Environmental Site Assessment of the Commercial Property Located at 802 Alpine Avenue NW, Grand Rapids, Michigan PM Environmental, Inc. Project No. 03-4006-0

Dear Mr. Klooster:

PM Environmental, Incorporated (PM) has completed the Phase I Environmental Site Assessment (ESA) of the above referenced property. This Phase I ESA was conducted in accordance with (1) the United States Environmental Protection Agency (USEPA) Standards and Practices for All Appropriate Inquiries {(AAI), 40 CFR Part 312} and (2) guidelines established by the American Society for Testing and Materials (ASTM) in the Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process / Designation E 1527-13 (ASTM Standard Practice E 1527-13).

The Phase I ESA for the above referenced property represents the product of PM's professional expertise and judgment in the environmental consulting industry, and it is reasonable for <u>TKKA PROPERTIES LLC</u> AND <u>GRAND RAPIDS BROWNFIELD REDEVELOPMENT AUTHORITY</u> to rely on PM's Phase I ESA report.

If you have any questions related to this report please do not hesitate to contact our office at 877.313.2991.

Sincerely,

PM ENVIRONMENTAL, INC.

Bryant J. Hengst Staff Consultant

Beth Sexton National Due Diligence Manager

EXECUTIVE SUMMARY

PM Environmental, Inc., (PM) was retained to conduct a Phase I Environmental Site Assessment (ESA) of the Commercial Property located at 802 Alpine Avenue NW, Grand Rapids, Kent County, Michigan (hereafter referred to as the "subject property"). This Phase I ESA was conducted in accordance with (1) the United States Environmental Protection Agency (USEPA) Standards and Practices for All Appropriate Inquiries {(AAI), 40 CFR Part 312} and (2) guidelines established by the American Society for Testing and Materials (ASTM) in the Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process / Designation E 1527-13 (ASTM Standard Practice E 1527-13).

THIS REPORT WAS PREPARED FOR THE EXCLUSIVE USE OF TKKA PROPERTIES LLC AND GRAND RAPIDS BROWNFIELD REDEVELOPMENT AUTHORITY, EACH OF WHOM MAY RELY ON THE REPORT'S CONTENTS.

Item	Comments
Number of Parcels and Acreage	One parcel containing 0.15 acres
Number of Building(s) and Square Footage	A single-story commercial building containing 2,244 square feet
Current Property Use	Automotive transmission repair shop

Reasonably ascertainable records for the subject property extended back to approximately 1888. Data failure occurred prior to that date. In PM's professional opinion, this data failure does not represent a significant data gap.

Standard and other historical sources were able to document that the subject property was originally developed as a mixed-use property prior to 1888. Original development included two residences and a commercial building, all of which were demolished by 1929. Former commercial occupants included a grocery store from at least 1919 until 1924. The occupants associated with the original commercial building from initial construction prior to 1888 until 1919 could not be determined through review of historical sources; however, based on the layout of the building and the known past uses, the tenants were likely commercial in nature and included similar retail operations. The property was redeveloped between 1924 and 1929 with a commercial building in the central portion of the property, which was demolished by 1967. Former occupants included a gasoline service station from at least 1929 until 1959 and an automotive transmission repair shop from 1961 until 1967. The current building was constructed in the central portion of the property in 1967, and has been occupied by an automotive transmission repair shop since that time.

The following table summarizes the conditions identified as part of this assessment. Affirmative answers are further discussed below the table:

Type of Condition	Identified During the Course of this Assessment
De Minimis Condition	No
Significant Data Gap	No
Historical Recognized Environmental Condition (HREC)	Yes
Controlled Recognized Environmental Condition (CREC)	No

Recognized Environmental Condition (REC)	Yes
--	-----

Historical Recognized Environmental Condition

An HREC, as defined in the ASTM Standard, is a past release of hazardous substances or petroleum products that has occurred in connection with the subject property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted residential use criteria established by a regulatory authority, without subjecting the subject property to any required controls. The following HREC was identified:

• The subject property is a closed Leaking Underground Storage Tank (LUST) site with one release reported in 1990, which was granted a Type B LUST Closure in 1992. The release was reported during removal of a 6,000-gallon used oil UST, located south of the subject building. Review of site assessment activities completed in 1991 documents that no subsurface contamination associated with the release remains on-site above the most restrictive Part 213 Risk Based Screening Levels (RBSLs). Based on the closed LUST status and documented site assessment activities which were adequate to assess the former release, PM has identified the closed LUST status as an HREC.

Recognized Environmental Condition

We have performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E 1527-13 of the Commercial Property located at 802 Alpine Avenue NW, Grand Rapids, Kent County, Michigan, the property. Any exceptions to, or deletions from, this practice are described in Section 1.4 of this report. This assessment has revealed no evidence of recognized environmental conditions connected with the property except the following:

- The subject property was formerly occupied by a gasoline service station from at least 1929 until 1959 and has been occupied by an automotive transmission repair shops since 1961. Based upon review of the previous subsurface investigations completed in 1991, soil contamination is present which exceeds the current Part 201 Residential and Nonresidential Generic Cleanup Criteria. Review of previous site investigation activities documents that the exceedances are within the building footprint and therefore are not associated with the former release. The soil contamination is likely associated with the long-term service operations that have been present on the property since the 1920s. Based on these analytical results, the subject property would be classified as a "facility," as defined by Part 201 of P.A. 451 of the Michigan Natural Resources Environmental Protection Act (NREPA), as amended.
- The subject property has been occupied by various automotive service operations since at least 1929. Historical interior waste streams associated with the current and former operations would have consisted of general hazardous substances and/or petroleum products. A significant portion of this time period preceded major environmental regulations and current waste management and disposal procedures. The historical waste management practices associated with the current and former operations are unknown and may be a source of subsurface contamination.
- PM observed four in-ground hoists in the shop area within the current building. According
 to the site representative, two of the hoists were installed in 1967. The installation dates of

the remaining hoists were unknown. In-ground hoists have an underground reservoir for hydraulic fluids, which can contain polychlorinated biphenyls (PCBs). The potential exists that a release occurred from the former hydraulic hoist system and/or underground reservoir.

- PM observed two dry wells in the shop area within the current building. The original installation date of the dry wells is unknown. According to the site representative, the dry wells are pumped by Crystal Clean on an as needed basis. The integrity of the dry wells is unknown. Historical interior waste streams associated with the automotive transmission repair shop would have consisted of general hazardous substances and/or petroleum products. A significant portion of this time period preceded major environmental regulations and current waste management and disposal procedures. Based upon the age of the building, the potential exists for failure of the dry wells (i.e. cracks, leaks) to have occurred over time. The current and historical waste management practices associated with the dry wells are unknown and could be a source of subsurface contamination.
- According to information obtained from the City of Grand Rapids Building Department, the
 former commercial building utilized an oil heater in at least 1951. PM was unable to
 determine the heat source for the building from at least 1929 until 1967. Given the use of
 an oil heater in at least 1951, it is likely that a fuel oil above-ground storage tank (AST) or
 underground storage tank (UST) was used during that time. The potential exists for orphan
 USTs to be present on the property and/or for a release to have occurred.
- According to information obtained from the Michigan Department of Environmental Quality (MDEQ) and City of Grand Rapids Fire Department, the property formerly contained two 1,500-gallon USTs and a 1,000-gallon UST that were reportedly removed in 1986. The contents of the USTs were not documented, and the location of the USTs was not provided. Additionally, PM was unable to confirm whether these USTs were the only USTs associated with the service station operations from 1929 until 1959. The potential exists for orphan USTs to be present and/or for a release to have occurred from the former UST systems and/or fuel dispensers.

No adjoining and/or nearby RECs have been identified.

Recommendations

These RECs have been brought to the attention of the client within the requirements of the ASTM Standard Designation E-1527-13.

Verification of the presence or absence of contaminants potentially associated with these RECs may be determined through a Phase II investigation at the request of the client. Cost/risk analysis decisions associated with further investigation of these conditions are the decision of the client.

The summary presented above is general in nature and should not be considered apart from the entire text of the report, which contains the qualifications, considerations and subject property details mentioned herein. Details of findings and conclusions are elaborated upon in this report.

This report has been reviewed for its completeness and accuracy. Please feel free to contact our office at 877.313.2991 to discuss this report.

Phase I ESA of the Commercial Property Located at 802 Alpine Avenue NW, Grand Rapids, Michigan PM Project No. 03-4006-0; January 19, 2015

REPORT PREPARED BY:

PM Environmental, Inc.

Bryant J. Hengst Staff Consultant **REPORT REVIEWED BY:**

PM Environmental, Inc.

Shawn Shadley

Regional Due Diligence Manager

Beth Sexton

National Due Diligence Manager

TABLE OF CONTENTS

1.0	INTRODUCTION	1
	1.1: Property Overview	1
	1.2: Purpose and Scope of Services	1
	1.3: Significant Assumptions	
	1.4: Limitations, Deviations, and Special Terms and Conditions	
2.0		
	2.1: Recorded Land Title Records	
	2.2: Reason for Performing this Phase I ESA	
3.0		
4.0		
_	4.1: Aerial Photographs and Sanborn Maps	
	4.2: Local Street Directories	
	4.3: Assessing Department	
	4.4: Building Department	
	4.5: Fire Department	
	4.6: Health Department	
	4.7: Utilities	
	4.7.1: Municipal Water/Water Wells	
	4.7.2: Sanitary Sewer/Septic System	
	4.7.3: Heat Source	
	4.8: Underground Storage Tank (UST) Systems	
	4.9: Previous Environmental Reports	
	4.9.1: Summary of Previous Environmental Reports	
	4.10: Environmental Liens, Activity and Use Limitations, and Government Institutional	and
	Engineering Controls	
5.0	INTERVIEWS	
6.0	SUMMARY OF HISTORICAL USE	
7.0	SUBJECT PROPERTY RECONNAISSANCE	13
_	7.1: Subject Property Observations	
	7.1.1: Current Operations	
8.0	·	
9.0	REGULATORY RECORDS REVIEW	
	9.1: Subject Property and Occupant Listings	
	9.2: Adjoining and Nearby Sites	
10.0	·	
10.	10.1: De Minimis Condition	
	10.2: Significant Data Gaps	18
	10.3: Historical Recognized Environmental Conditions (HRECs)	
	10.4: Controlled Recognized Environmental Conditions (CRECs)	19
	10.5: Recognized Environmental Conditions (RECs)	10
	10.6: Recommendations	
11.0		20
12.0		
13.0		
	·	

FIGURES

Figure 1: Site Location Map

Figure 2: Generalized Diagram of the Subject Property and Surrounding Area

APPENDICES

Appendix A: Property Photographs from Site Reconnaissance Appendix B: Correspondence and Supporting Documentation

Appendix C: Previous Site Investigations

Appendix D: Regulatory Database and File Review Correspondence

Appendix E: Professional Resumes

Appendix F: Acronyms and Terminology, Scope of Work, ASTM Reference Document, and

User's Continuing Obligations under CERCLA

1.0 INTRODUCTION

This Phase I ESA was conducted in accordance with (1) the United States Environmental Protection Agency (USEPA) Standards and Practices for All Appropriate Inquiries {(AAI), 40 CFR Part 312} and (2) guidelines established by the American Society for Testing and Materials (ASTM) in the Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process / Designation E 1527-13 (ASTM Standard Practice E 1527-13).

THIS REPORT WAS PREPARED FOR THE EXCLUSIVE USE OF <u>TKKA PROPERTIES LLC</u> AND <u>GRAND RAPIDS BROWNFIELD REDEVELOPMENT AUTHORITY</u>, EACH OF WHOM MAY RELY ON THE REPORT'S CONTENTS.

PM acknowledges that these parties may rely on the contents and conclusions presented in this report. Unless stated otherwise in writing, PM makes no other warranty, representation, or extension of reliance upon the findings of this report to any other entity or third party.

1.1: Property Overview

Subject Property Location/Address	802 Alpine Avenue NW, Grand Rapids, Kent County, Michigan
Number of Parcels and Acreage	One parcel containing 0.15 acres
Number of Building(s) and Square Footage	A single-story commercial building containing 2,244 square feet
Current Property Use	Automotive transmission repair shop
Current Zoning	TBA: Traditional Business Area

The subject property location is depicted on Figure 1, Site Location Map. A diagram of the subject property and adjoining properties is included as Figure 2, Generalized Diagram of the Subject Property and Surrounding Area. Photographs taken during the site reconnaissance are included in Appendix A.

1.2: Purpose and Scope of Services

The purpose of this Phase I ESA was to evaluate the current and historical conditions of the subject property in an effort to identify *recognized environmental conditions* (RECs), *controlled recognized environmental conditions* (CRECs), and *historical recognized environmental conditions* (HRECs) in connection with the subject property. This Phase I ESA is intended to reduce, but not eliminate, uncertainty regarding the potential for RECs, CRECs, and HRECs in connection with the subject property.

Acronyms and terms used in this report are described in Appendix F. Additionally, PM's scope of services is included in Appendix F.

1.3: Significant Assumptions

Pursuant to ASTM Standard Practice E 1527-13, PM assumes that the information provided by all sources and parties, including the User, is accurate and complete, except where obvious inconsistencies or inaccuracies were identified.

1.4: Limitations, Deviations, and Special Terms and Conditions

There are no deviations from the ASTM Standard. Non-ASTM Scope considerations are included in Section 11.0. Any physical limitations identified during the completion of this report are referenced in Section 7.0.

Due to changing environmental regulatory conditions and potential on-site or adjacent activities occurring after this assessment, the client may not presume the continuing applicability to the subject property of the conclusions in this assessment for more than 180 days after the report's issuance date, per ASTM Standard Practice E 1527-13.

To the best of PM's knowledge, no special terms or conditions apply to the preparation of this Phase I ESA that would deviate the scope of work from the ASTM Standard Practice E 1527-13.

PM was not provided with a copy of the recorded land title records for subject property by the client and was not requested to complete a title search. Therefore, PM cannot comment on any potential relevant information that may have been obtained through review of these records.

2.0 USER PROVIDED INFORMATION

The ASTM Standard defines a User as "the party seeking to use Practice E 1527 to complete an environmental site assessment. A User may include, without limitation, a potential purchaser of property, a potential tenant of property, an owner of property, a lender, or a property manager." The User has specific obligations for completing a successful application of this practice as outlined in Section 6 of the ASTM Standard Practice E 1527-13.

In order to qualify for one of the Landowner Liability Protections (LLPs) offered by the Small Business Liability Relief and Brownfield's Revitalization Act of 2001 (the "Brownfield's Amendments") (if desired), the User must provide certain information (if available) identified in the User Questionnaire to the environmental professional. Failure to provide this information could result in a determination that "all appropriate inquiry" is not complete.

The following responses were provided by the User. A copy of the completed User Questionnaire is included in Appendix B.

Question	Response
Name of Preparer and User Entity	Mr. David Lee Parm; TKKA Properties LLC
Are you aware of any environmental cleanup liens against the property that are filed or recorded under federal, tribal, state or local law?	No
Are you aware of any Activity and Use Limitations, such as engineering controls, land use restrictions or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state or local law?	No

Question	Response
As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?	Yes; automotive repair (oil, antifreeze, etc.)
Does the purchase price being paid for this property reasonably reflect the fair market value of the property?	Yes
If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?	Not applicable
Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example, as user:	
Do you know the past uses of the property?	No
Do you know of specific chemicals that are present or once were present at the property?	No
Do you know of spills or other chemical releases that have taken place at the property?	No
Do you know of any environmental cleanups that have taken place at the property?	No
As the user of this ESA, based on your knowledge and experience related to the property are there any obvious indicators that point to the presence or likely presence of contamination at the property?	No

2.1: Recorded Land Title Records

PM was not provided with land title records for the subject property by the User and was not requested to complete a chain of title for the subject property. PM reviewed reasonably ascertainable environmental liens and activity and use limitation documents, which are further discussed in Section 4.10. Based upon the information reviewed as part of this Phase I ESA, PM has not identified the lack of provided land title records as a data failure that represents a significant data gap.

2.2: Reason for Performing this Phase I ESA

According to the User, this Phase I ESA was conducted as part of environmental due diligence related to purchasing the subject property.

3.0 PHYSICAL SETTING

PHYSICAL SETTING INFORMATION FOR THE SUBJECT PROPERTY AND SURROUNDING AREA		SOURCE
Topography: Refer to Figure 1 for an excerpt of the Topographic Map		
Site Elevation	600-610 feet above mean sea level (msl)	United States Geological
Topographic Gradient	East	Survey Division (U.S.G.S.)

	NG INFORMATION FOR THE SUBJECT TY AND SURROUNDING AREA	SOURCE
Closest Surface Water	Grand River, located approximately 3,300 feet east of the subject property at an elevation of 600 feet above msl	7.5-Minute Topographic Map of the Grand Rapids West, Michigan Quadrangle, 1996
General Soil Character descriptions	ristics: Refer to Appendix B for a copy of the so	il survey map and soil type
Soil Type	Urban land-Spinks complex, 0 to 8 percent slopes	
Description	Urban land comprises 60 percent of this soils composition. These areas are covered with airports, shopping centers, parking lots, large buildings, streets, or sidewalks. Spinks and similar soils comprise 35 percent of this soils composition. A typical soil profile consists of sand to a depth of ten inches below ground surface (bgs), underlain by loamy sand to 60 inches bgs. The permeability is high for this soil. The corrosivity for steel is low, but moderate for concrete.	United States Department of Agriculture, Custom Soil Resource Report for Kent County, Michigan (survey area data from September 2014)
Area Specific Geology	/Hydrogeology Characteristics:	
Geology	Geology generally consists of sand to a depth of 10.0 feet bgs, silty clay to 12.0 feet bgs, underlain by limestone	Previous site investigations for the subject property
Hydrogeology	No groundwater was encountered during previous site assessment activities	for the subject property
Oil and Gas Wells:		
Current Oil and Gas Wells on Subject Property	None identified	MDEQ Geologic Survey
Historical Oil and Gas Wells On Subject property	None identified	Division (GSD) web site

4.0 RECORDS REVIEW

PM reviewed reasonably ascertainable records to identify obvious uses of the subject property from the present, back to the property's obvious first developed use, or back to 1940, whichever is earlier. Reasonably ascertainable records reviewed as part of this Phase I ESA documented the use of the property back to 1888. Data failure occurred prior to that date. In PM's professional opinion, this data failure does not represent a significant data gap.

4.1: Aerial Photographs and Sanborn Maps

PM reviewed reasonably ascertainable aerial photographs for the subject property area. The sources and years reviewed are identified in the table below. Relevant aerial photographs are included in Appendix B.

PM reviewed reasonably ascertainable Sanborn Fire Insurance Maps for the subject property area, which were obtained from EDR. The sources and years reviewed are identified in the table below. Relevant Sanborn Maps are included in Appendix B.

The following table summarizes the sources reviewed and the information obtained about the subject property from these sources. Information obtained about the adjoining properties from these sources is summarized in Section 8.0.

Aerial and Sanborn Summary for the Subject Property

Year and Source	Summary of Information
1888 Sanborn Map (EDR)	A residence is present in the northern portion of the property, which includes a dwelling and stable. A residence is present in the southeastern portion of the property, which includes a dwelling. A commercial building is present in the southwestern portion of the property and is occupied by a general storefront.
1895 Sanborn Map (EDR)	An addition has been completed to the western portion of the stable in the northern portion of the property. An addition has been completed to the northern portion of the dwelling in the southeastern portion of the property. An addition has been completed to the eastern portion of commercial building in the southwestern portion of the property, which is occupied by a general storefront. The remaining portions of the property appear to be similar to the previous Sanborn year.
1913 Sanborn Map (EDR)	The stable in the northern portion of the property has been demolished. The remaining portions of the property appear to be similar to the previous Sanborn year.
1938 Aerial (EDR)	The residences in the northern and southeastern portions of the property, and the commercial building in the southwestern portion have been demolished. The property appears to be developed; however, due to the scale and resolution, more definitive details could not be determined.
1950 Sanborn Map (EDR) A commercial building is present in the central portion of the property, which occupied by a gasoline filling station. A canopy extends off of the southwe portion of the building. A gasoline UST is depicted to the south of the building.	
1953 Sanborn Map (EDR) Similar to the previous Sanborn year.	
1960 Aerial (EDR)	The layout is generally consistent with the previous Sanborn year.
1965 Sanborn Map (EDR)	The layout is generally consistent with the previous aerial year; however, automotive repair is depicted in the northern portion of the building.
1967 Aerial (EDR)	The commercial building and canopy in the central portion of the property have been demolished. The property has been redeveloped with the current building in the central portion of the property. This layout is similar to the current layout.
1968 Sanborn Map (EDR)	The layout is generally consistent with the previous aerial year. The building is identified as an automotive repair shop.
1973 Aerial (Kent County)	The layout is generally consistent with the previous Sanborn year.
1978 Aerial (Kent County)	Similar to the previous aerial year.
1981 Aerial (EDR)	Similar to the previous aerial year.
1984 Sanborn Map (EDR)	The layout is generally consistent with the previous aerial year.
1986 Aerial (EDR)	The layout is generally consistent with the previous Sanborn year.

Year and Source	Summary of Information
1989 Aerial (Kent County)	Similar to the previous aerial year.
1993 Aerial (EDR)	Similar to the previous aerial year.
1999 Aerial (EDR)	Similar to the previous aerial year.
2005 Aerial (EDR)	Similar to the previous aerial year.
2006 Aerial (EDR)	Similar to the previous aerial year.
2009 Aerial (EDR)	Similar to the previous aerial year.
2010 Aerial (EDR)	Similar to the previous aerial year.
2012 Aerial (EDR)	Similar to the previous aerial year.

A summary of this information along with other historical sources is included in Section 6.0.

4.2: Local Street Directories

Reasonably ascertainable local street directories for Grand Rapids, Michigan were researched. Directories were available from 1904 to 2015. Directories were researched in at least five-year increments, when available. It should not be construed that the earliest date represented is the initial date of occupancy.

PM also reviewed listings for adjoining commercial properties. Information from the listings reviewed is included in Section 8.0.

Subject Property: 802 Alpine Avenue NW

2015-1982	North End Transmission
1978-1977	North End Transmission
	Automatic Transmission Parts
1973-1972	North End Transmission
1968-1914	Not Listed
1909-1904	Street Listed, Addresses Not Listed

Historical Subject Property Address: 800 Alpine Avenue NW

2015-1914	Not Listed
1909-1904	Street Listed, Addresses Not Listed

Historical Subject Property Address: 808 Alpine Avenue NW

2015-1934	Not Listed
1929	Vacant
1924	Not Listed
1919-1914	Residential
1909-1904	Street Listed, Addresses Not Listed

Historical Subject Property Address: 761 7th Street NW

2015-1934	Not Listed
1929-1914	Residential
1909-1904	Street Listed, Addresses Not Listed

Historical Subject Property Address: 763 7th Street NW

2015-1972	Not Listed
1968-1962	North End Transmission
1959	Bob's Service
1954	Seventh Street Texaco, filling station
1949	Skiver's Service Station, filling station and auto repair
1944-1929	Not Listed
1924-1914	Residential
1909-1904	Street Listed, Addresses Not Listed

Historical Subject Property Address: 765 7th Street NW

2015-1949	Not Listed
1944	Dutkiewicz, filling station
1939	Schultz Service, filling station
1934-1929	National Refrigeration Company, filling station
1924-1919	Jakubowski, grocery
1914	Residential
1909-1904	Street Listed, Addresses Not Listed

A summary of this information along with other historical sources is included in Section 6.0.

4.3: Assessing Department

Reasonably ascertainable assessment information provided by the City of Grand Rapids Assessing Department was obtained and reviewed. Assessing records document that the subject property consists of one parcel containing 0.15 acres and is developed with a 2,244 square foot building that was reportedly rebuilt from an existing building in 1967. A historical field card was included in the records reviewed which documented that during construction activities in 1967, the original north wall of the former commercial building provided central roof support for the current commercial building. Copies of available assessment records for the subject property and the current legal description are included in Appendix B.

4.4: Building Department

PM reviewed City of Grand Rapids Building Department records for the subject property. Copies of relevant information obtained from the department are included in Appendix B. The table below describes the permit issued, the date of issuance, and the reason for issue.

Building Permit Information

Permit Number	Date of Issuance	Reason For Issue
42082	06-12-1945	Construct 28'x44' garage addition

Permit Number	nit Number Date of Issuance Reason For Issue	
44663	12-17-1951	Oil unit heater
86380	07-17-1958	Appeal to sell used cars
8699	12-21-1960	Appeal for 1 st class garage
19067	12-18-1962	Appeal to have 1st class garage
23452	10-15-1963	Gas unit heater
30675	03-17-1965	Appeal for 1st class garage, use with service station
9374	02-06-1967	Appeal for 1st class garage in C-1 zone & side yard
10758	05-25-1967	Building one-story commercial building and steel addition (53'x16')

4.5: Fire Department

Reasonably ascertainable assessment information provided by the City of Grand Rapids Fire Department was obtained and reviewed. Fire records included several inspection reports completed between 1988 and 2008. According to a chemical survey completed in January 1995, chemicals were observed, but were below the specified quantity allowed on-site during that time.

Fire records also included documentation from May 1986, which indicates that two 1,500-gallon USTs and a 1,000-gallon UST were removed from the property. The contents of the UST were not documented, and the location of the USTs was not provided. A 6,000-gallon gasoline UST was reportedly removed in January 1990; however, based on review of MDEQ file information, this UST contained used oil. Refer to Section 4.8 for a summary of the former UST systems.

4.6: Health Department

PM submitted a Freedom of Information Act (FOIA) request to the Kent County Health Department to review records for the subject property. PM received a written response from a representative of the department indicating no files were available for the subject property.

4.7: Utilities

4.7.1: Municipal Water/Water Wells

The subject property is currently connected to municipal water. PM interviewed a representative of the City of Grand Rapids Public Works Department, who indicated the property was connected to municipal water in 1967, which is consistent with the construction of the current building. The representative indicated that municipal water mains were originally installed in the area of the property in 1888. Based upon this information, the former buildings on the property were likely connected to municipal water during initial construction. No records of private water wells have been identified through review of reasonably ascertainable information.

4.7.2: Sanitary Sewer/Septic System

The subject property is currently connected to municipal sewer. PM interviewed a representative of the City of Grand Rapids Public Works Department, who indicated the property was connected to municipal sewer in 1967, which is consistent with the construction of the current building. The representative indicated that municipal sewer mains were originally installed in the area of the property in 1888. Based upon this information, the former buildings on the property were likely

connected to municipal sewer during initial construction. No records of private septic fields have been identified through review of reasonably ascertainable information.

4.7.3: Heat Source

The subject property is connected to natural gas, which is supplied by DTE Energy (DTE). PM attempted to obtain an initial tap date from DTE; however, no records were available. PM obtained a distribution map, which indicates that natural gas has been available in the area of the property since at least 1994, which is not consistent with the construction of the current building. However, based on records obtained from the City of Grand Rapids Building Department, the former commercial building utilized natural gas heaters in at least 1963. Based upon this information, the current building was likely connected to natural gas during construction in 1967.

According to City of Grand Rapids Building Department records, the former commercial building utilized an oil heater in at least 1951. PM was unable to determine the heat source for the building from at least 1929 until 1967. Given the use of an oil heater in at least 1951, it is likely that a fuel oil above-ground storage tank (AST) or underground storage tank (UST) was used during that time. The potential exists for orphan USTs to be present on the property and/or for a release to have occurred, which represents a REC.

PM was unable to determine the heat source for the former residences and original commercial building that were present on the subject property from at least 1888 until 1924. It is PM's professional opinion that fuel oil was not commonly utilized until the early 1920s, and based upon this information, the buildings likely utilized coal or wood as a fuel source.

4.8: Underground Storage Tank (UST) Systems

The subject property contained four former USTs. The following table indicates the size of the UST, contents, location (if known), the dates of installation and removal, and the source of the information.

Historical UST Information

Size	Contents	Location	Date Installed	Date Removed	Source
1,000-gallon	Unknown	Unknown	Unknown	1986	Fire Dept. & MDEQ
1,500-gallon	Unknown	Unknown	Unknown	1986	Fire Dept.
1,500-gallon	Unknown	Unknown	Unknown	1986	Fire Dept.
6,000-gallon**	Used Oil	South of the current building	Unknown	1990	Fire Dept. & MDEQ

^{**}Several documents received from the MDEQ also identify this UST as a 5,000-gallon used oil UST; however, during removal activities it was determined that the tank had a capacity of 6,000-gallons.

According to information obtained from the Michigan Department of Environmental Quality (MDEQ) and City of Grand Rapids Fire Department, the property formerly contained two 1,500-gallon USTs and a 1,000-gallon UST that were reportedly removed in 1986. The contents of the USTs were not documented, and the location of the USTs was not provided. Additionally, PM was unable to confirm whether these USTs were the only USTs associated with the service station

operations from 1929 until 1959. The potential exists for orphan USTs to be present and/or for a release to have occurred from the former UST systems and/or fuel dispensers, which represents a REC.

According to the information received from the MDEQ, a confirmed release (C-0390-90) was reported on January 23, 1990, and was based upon petroleum vapors detected during the removal of the 6,000-gallon used oil UST that was formerly located south of the current building. Refer to Section 4.9 for additional information.

4.9: Previous Environmental Reports

PM reviewed the following previous environmental reports for the subject property. Relevant portions of the reports are included in Appendix C.

Name of Report	Date of Report	Company that Prepared Report
Report of UST Closure and Initial Abatement Measures	February 1990	Superior Environmental Corporation (Superior)
Report of Findings	November 1990	Alderink and Associates, Inc. (Alderink)
Report of Findings	July 1991	Alderink
Results of Subsurface Investigations	December 1991	Alderink

4.9.1: Summary of Previous Environmental Reports

According to the information received from the MDEQ, a confirmed release (C-0390-90) was reported on January 23, 1990, and was based upon petroleum vapors detected during the removal of a former 6,000-gallon used oil UST that was located south of the current building. Approximately 100 cubic yards of soil was removed from the UST basin. A total of two soil borings (T1-A and T1-B) were advanced in the former UST basin. Groundwater was not encountered during the excavation activities. Soil samples were collected and analyzed for benzene, toluene, ethyl benzene, and xylene (BTEX) and total petroleum hydrocarbon (TPH) parameters. The analytical results confirmed contamination within the subsurface soil above the laboratory method detection limits, but below the current most restrictive Part 213 Risk Based Screening Levels (RBSLs). A composite sample was also collected from the excavated soil and analytical results confirmed contamination above the most restrictive Part 213 RBSLs.

The site investigation activities performed by Alderink in November 1990 included the advancement of five soil borings (SB-1 through SB-5) in the area of the former UST basin. Groundwater was not encountered during the site investigation activities. Soil samples were collected and analyzed for BTEX and polynuclear aromatic hydrocarbons (PNAs). The analytical results confirmed contamination within the subsurface soil above the laboratory method detection limits, but were below the current most restrictive Part 213 RBSLs.

The site investigation activities performed by Alderink in July 1991 included the advancement of five soil borings (HA-1 through HA-5) to further delineate the extent of contamination as well as verify diminishing concentrations of contaminated soil. Groundwater was not encountered during the site investigation activities. Soil samples were collected and analyzed for BTEX. The analytical results confirmed contamination consisting of ethylbenzene and xylene within the subsurface soil above the most restrictive Part 213 RBSLs for Groundwater Surface Water Interface Protection (GSIP) criteria.

The site investigation activities performed by Alderink in December 1991 included the advancement of five soil borings (HA-6 through HA-10) to further delineate the extent of contamination as well as verify diminishing concentrations of contaminated soil. Groundwater was not encountered during the site investigation activities. Soil samples were collected and analyzed for BTEX. The analytical results confirmed contamination within the subsurface soil above the laboratory method detection limits, but were below the most restrictive Part 213 RBSLs.

No significant deficiencies were identified for the previous site assessment activities.

The MDEQ granted a Type B LUST Closure in January 1992. Review of site assessment activities completed in 1991 documents that no subsurface contamination associated with the release remains on-site above the most restrictive Part 213 RBSLs. Based on the closed LUST status and documented site assessment activities which were adequate to assess the former release, PM has identified the closed LUST status as an HREC.

Based upon review of the previous subsurface investigations completed in 1991, soil contamination is present which exceeds the current Part 201 Residential and Nonresidential Generic Cleanup Criteria. Review of previous site investigation activities documents that the exceedances are within the building footprint and therefore are not associated with the former release. The soil contamination is likely associated with the long-term service operations that have been present on the property since the 1920s. Based on these analytical results, the subject property would be classified as a "facility," as defined by Part 201 of P.A. 451 of the Michigan Natural Resources Environmental Protection Act (NREPA), as amended. **The known contamination on the subject property represents a REC.**

4.10: Environmental Liens, Activity and Use Limitations, and Government Institutional and Engineering Controls

PM has not identified any record of environmental liens, activity and use limitations, or institutional controls or engineering controls associated with the subject property through review of reasonable ascertainable records.

5.0 INTERVIEWS

The objective of completing interviews with knowledgeable site contacts is to obtain information about the uses and physical characteristics of the property. In general, interviewees supported the information reviewed from other historical sources (i.e. aerial photos, city records, etc.).

Represents	Interviewed	Name and Title	Length of Time Associated with Subject Property	Comments
Current Property Owner	Yes	Mr. David Sherd, the current owner	54 years	Mr. Sherd indicated that his father originally purchased the subject property in 1967. Mr. Sherd later purchased the property from his father in 1988. According to Mr. Sherd, the current transmission repair operation has occupied the subject property since 1961. Other information from this interview is referenced throughout this report.
Former Property Owner	Yes/No	Not applicable	Not applicable	Contact information for the former owner was not reasonably ascertainable or provided by the User.
Key Site Manager	Yes	Mr. David Sherd, the current owner	54 years	Refer to the Current Property Owner section for additional information.
Current Occupant(s)	Yes	Mr. David Sherd, the current owner	54 years	Refer to the Current Property Owner section for additional information.
Former Occupant(s)	No	Not applicable	Not applicable	Contact information for the former occupants was not reasonably ascertainable or provided by the User.
Other(s)	No	Not applicable	Not applicable	No other relevant interviews were conducted as part of this Phase I ESA.

6.0 SUMMARY OF HISTORICAL USE

Standard and other historical sources were able to document that the subject property was originally developed as a mixed-use property prior to 1888. Original development included two residences and a commercial building, all of which were demolished by 1929. Former commercial occupants included a grocery store from at least 1919 until 1924. The occupants associated with the original commercial building from initial construction prior to 1888 until 1919 could not be determined through review of historical sources; however, based on the layout of the building and the known past uses, the tenants were likely commercial in nature and included similar retail operations. The property was redeveloped between 1924 and 1929 with a commercial building in the central portion of the property, which was demolished by 1967. Former occupants included a gasoline service station from at least 1929 until 1959 and an automotive transmission repair shop from 1961 until 1967. The current building was constructed in the central portion of the property in 1967, and has been occupied by an automotive transmission repair shop since that time.

Historical interior waste streams associated with the current and former operations would have consisted of general hazardous substances and/or petroleum products. A significant portion of this time period preceded major environmental regulations and current waste management and

disposal procedures. The historical waste management practices associated with the current and former operations are unknown and may be a source of subsurface contamination, which represents a REC.

7.0 SUBJECT PROPERTY RECONNAISSANCE

Reconnaissance Information		
PM Field Personnel:	Mr. Bryant Hengst	
Site Reconnaissance Date:	January 6, 2015	
Weather Conditions:	12°F and overcast	
Escort:	Mr. David Sherd	
Limitations:	Interior observations were limited by automobiles and other	
	miscellaneous storage	

7.1: Subject Property Observations

The subject building contains a total of 2,244 square feet of floor space, which is divided into an office, a lobby area, a shop area, and bathrooms.

Interior finish materials in the building generally include drywall walls and/or open metal-deck ceilings; concrete block walls; and poured concrete flooring. The entire building is on a poured concrete foundation.

Exterior pavement is present north and south of the building. The remainder of the property contains groomed grass and landscaped areas.

The following table summarizes the site observations. Affirmative responses are discussed in more detail following the table.

Category	Feature	Observed
	Elevators	No
	Air Compressors	Yes
	Incinerators	No
	Waste Treatment Systems	No
Interior Equipment	Presses/Stamping Equipment	No
intenor Equipment	Press Pits	No
	Hydraulic Lifts or In-ground hoists	Yes
	Paint Booth	No
	Plating Tanks	No
	Lathes, Screw Machines, etc.	No
Above ground Chemical or	Aboveground Storage Tanks (ASTs)	No
Aboveground Chemical or Other Waste Storage or Waste Streams	Drums, Barrels and/or Containers > 5 gallons	Yes
	Chip Hoppers	No
	Hazardous or Petroleum Waste Streams	Yes
	Underground Storage Tanks	No
	Fuel Dispensers	No
Underground Chemical or	Sumps or Cisterns	No
Waste Storage, Drainage or	Dry Wells	Yes
Collection Systems	Oil/Water Separators	No
	Floor Drains, Trench Drains, etc.	No
	Pipeline Markers	No

Category	Feature	Observed
	Stressed Vegetation	No
	Stained Soil or Pavement	No
	Monitoring Wells	No
	Pad or Pole Mounted Transformers and/or Capacitors	No
	Soil Piles of Unknown Origin	No
	Exterior Dumpsters with Staining	No
Exterior Observations	Leachate or Other Waste Seeps	No
	Trash, Debris, and/or Other Waste Materials	No
	Uncontrolled Dumping or Disposal Areas	No
	Surface Water Discoloration, Sheen or Free Product	No
	Strong, Pungent or Noxious Odors	No
	Storm water retention or detention ponds	No
	Pits, Ponds, Lagoons	No

Air Compressors: PM observed an air compressor elevated in the shop area within the building (see Figure 2). PM did not observe a discharge hose associated with the compressor. No staining or evidence of poor waste management was observed at the base of the compressor. The concrete in the area of the compressor appeared to be in generally good condition. Based on the observed site conditions, PM has not identified the air compressor as a REC.

Hydraulic Lifts or In-Ground Hoists: PM observed four in-ground hoists in the shop area within the current building (see Figure 2). According to the site representative, two of the hoists were installed in 1967. The installation dates of the remaining two hoists were unknown. In-ground hoists have an underground reservoir for hydraulic fluids, which can contain PCBs. **The potential exists that a release occurred from the former hydraulic hoist system and/or underground reservoir, which represents a REC.**

Drums, Barrels, and/or Containers > 5-gallons: PM observe two 55-gallon drums of cleaning solvent in the shop area within the current building (see Figure 2). The drums were not staged within secondary containment. No staining or evidence of poor waste management was observed at the base of the drums. The concrete in the area of the drums appeared to be in generally good condition. Based on the observed site conditions, PM has not identified the 55-gallon drum storage as a REC. PM recommends that the drums be placed in secondary containment to implement good housekeeping practices.

Hazardous or Petroleum Waste Streams: PM observed a large parts washer in the shop area within the building (see Figure 2). No staining or evidence of poor waste management was observed at the base of the parts washer. According to the site representative, the parts washer is serviced by Crystal Clean on an as needed basis. Based on the observed site conditions, PM has not identified the parts washer as a REC.

Dry Wells: PM observed two dry wells in the shop area within the building (see Figure 2). The original installation date of the dry wells is unknown. According to the site representative, the dry wells are pumped by Crystal Clean on an as needed basis. The integrity of the dry wells in the building is unknown. Historical interior waste streams associated with the transmission repair operations would have consisted of general hazardous substances and/or petroleum products. A portion of this time period preceded major environmental regulations and current waste management and disposal procedures. Based upon the age of the building, the potential exists for failure of the dry wells (i.e. cracks, leaks) to have occurred over time. **The current and**

historical waste management practices associated with the dry wells are unknown and could be a source of subsurface contamination, which represents a REC.

7.1.1: Current Operations

Current business operations consist of repair of automotive transmissions.

8.0 ADJOINING PROPERTIES

The following paragraphs provide information about the adjoining properties obtained during the site reconnaissance and through review of reasonably ascertainable information.

North Adjoining Property

The north adjoining property is currently and has historically been residential dating back to at least 1888.

East Adjoining Property

The east adjoining property is currently and has historically been residential dating back to at least 1888.

South Adjoining Properties, across 7th Street NW

The south adjoining property, identified as 766 7th Street NW, is currently occupied by Matthew's House Ministry. Review of historical sources indicates that this property was originally developed for residential purposes prior to 1888. This property was redeveloped between 1888 and 1895 with the current building. The building has historically been utilized for residential purposes; however, former occupants included an office operation in at least 1914, various grocery stores from at least 1924 until 1949, a sign painter in at least 1949, a restaurant in at least 1959, and various office operations from at least 1977 until 2001. The building was reportedly unoccupied in at least 1919, 1944, and 1954. The occupants associated with this property from at least 1888 until 1914 and from 2001 until 2013 could not be determined through review of historical sources; however, based on the layout of the building and the known past uses, the tenants were likely commercial in nature. This property has been occupied by the current operations since at least 2013. Based on the assumed groundwater flow to the east (cross-gradient to the subject property), distance from the subject property to the building of operation (approximately 65 feet), and PM's extensive experience in assessing similar properties, PM has not identified the former operations as a REC.

The southwest adjoining property, identified as 800-802 7th Street NW, contains commercial building that is currently unoccupied. Review of historical sources indicates that this property was originally developed for residential purposes prior to 1888. This property was redeveloped between 1913 and 1919 with the current building. Former occupants included an office operation in at least 1919, a pharmacy from at least 1924 until 1959, a salon from at least 1967 until 1987, and a screen printing operation from at least 1990 until 2007. The building has been unoccupied since at least 2014. The occupants associated with this property from at least 2007 until 2014 could not be determined through review of historical sources; however, based on the layout of the building and the known past uses, the tenants were likely commercial in nature. Based on the assumed groundwater flow to the east (cross-gradient to the subject property), distance from the

subject property to the building of operation (approximately 100 feet), and PM's extensive experience in assessing similar properties, PM has not identified the former operations as a REC.

The remaining south adjoining properties are currently and have historically been residential dating back to at least 1888.

West Adjoining Properties, across Alpine Avenue NW

The west adjoining property is currently and has historically been residential dating back to at least 1888.

9.0 REGULATORY RECORDS REVIEW

PM retained EDR to provide current regulatory database information compiled by a variety of federal and state regulatory agencies. A copy of the complete database is included in Appendix D. The following information was obtained:

Туре	Regulatory Agency Database	Approximate Minimum Search Distance (AMSD)	Number of Sites within AMSD
Federal	National Priority List (NPL) Sites	1 mile	0
Federal	Delisted National Priority List (DNPL) Sites	½ mile	0
Federal	Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) Sites	½ mile	0
Federal	CERCLIS No Further Remediation Action Planned (NFRAP) Sites	½ mile	1
Federal	Resource Conservation and Recovery Act (RCRA) Corrective Action Report (CORRACTS) Sites	1 mile	0
Federal	RCRA non-CORRACTS Treatment, Storage or Disposal (TSD) Sites	½ mile	0
Federal	RCRA Large Quantity Generators (LQG) Sites	subject property and adjoining properties	0
Federal	RCRA Small Quantity Generators (SQG) Sites	subject property and adjoining properties	0
Federal	RCRA Conditionally Exempt Small Quantity Generators (CESQG) Sites	subject property and adjoining properties	0
Federal	RCRA Non-Generators (NON-GEN) Sites	subject property and adjoining properties	1
Federal	Institutional Control / Engineering Control Registries	subject property	0
Federal	Environmental Response and Notification System (ERNS)	subject property	0
Federal	US Brownfields	½ mile	5
State & Tribal	Hazardous Waste Sites (HWS) (equivalents to NPL and CERCLIS)	1 mile	6
State & Tribal	Solid Waste Facilities/Landfill Sites (SWLF)	½ mile	0
State & Tribal	Leaking Underground Storage Tank (LUST) Sites	½ mile	10
State & Tribal	Registered Underground Storage Tank (UST) Sites	subject property and adjoining properties	1

Туре	Regulatory Agency Database	Approximate Minimum Search Distance (AMSD)	Number of Sites within AMSD
State & Tribal	Institutional Control / Engineering Control Registries	subject property	0
State & Tribal	Brownfield Sites	½ mile	0
State & Tribal	Baseline Environmental Assessment (BEA) Sites	½ mile	19
Either	Unmappable Database Listings (a.k.a. Orphan Sites)	database-dependent	4

9.1: Subject Property and Occupant Listings

The regulatory database report identified the following listings for the subject property or its known occupants on the referenced databases:

North End Transmission Service – This property is identified as a WDS site, RCRA-NONGEN site, closed UST site, and closed LUST site with one reported release. According to the regulatory database, this property was most recently listed as a non-generator in December 2001, but was previously listed as a SQG in 1987 with no reported RCRA violations. Refer to Section 4.8 for a summary of the former UST system and Section 4.9 for a summary of the LUST site investigation activities.

9.2: Adjoining and Nearby Sites

PM's review of the referenced databases also considered the potential or likelihood of contamination from adjoining and nearby sites. To evaluate which of the adjoining and nearby sites identified in the regulatory database report present an environmental risk to the subject property, PM considered the following criteria:

- The type of database on which the site is identified.
- The topographic position of the identified site relative to the subject property.
- The direction and distance of the identified site from the subject property.
- Local soil conditions in the subject property area.
- The known or inferred groundwater flow direction in the subject property area.
- The status of the respective regulatory agency-required investigation(s) of the identified site, if any.
- Surface and subsurface obstructions and diversions (e.g., buildings, roads, sewer systems, utility service lines, rivers, lakes, and ditches) located between the identified site and the subject property.

Only those sites that are judged to present a potential environmental risk to the subject property and/or warrant additional clarification are further evaluated. Using the referenced criteria, and based upon a review of readily available information contained within the regulatory database report, PM did not identify adjoining (i.e., bordering) or nearby sites (e.g., properties within a ¼-mile radius) listed in the regulatory database report that were judged to present a potential environmental risk to the subject property, with the exception of the following:

Mike Wawee & Sons Auto Sales Inc. – This property is identified as 856 7th Street NW, and is located within one-eighth mile west of the subject property. Review of the regulatory database indicates that this property is identified as a RCRA-CESQG site, closed UST site, and closed LUST site with one reported release. Review of MDEQ file information indicates that a release was reported on July 14, 1999. The source of the release was unknown; however, it was later determined that the release likely occurred in the former UST basin. According to the most recent subsurface investigation activities completed in 1999, soil contamination consisting of VOCs, PNAs, and metals were identified above the most restrictive Part 213 Tier 1 RBSLs. No groundwater was encountered during the LUST closure activities. The contamination is limited to the property and is delineated towards the subject property. Based on the source removal, closed LUST status, delineation of contamination towards the subject property, distance from the subject property (approximately 600 feet), and PM's extensive experience in assessing similar properties, PM has not identified this property as a REC.

10.0 FINDINGS, OPINIONS AND CONCLUSIONS

10.1: De Minimis Condition

A de minimis condition, as defined in the ASTM Standard, is a condition that generally does not present a threat to human health or the environment and generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be de minimis are not RECs or CRECs. No de minimis conditions were identified during this assessment.

10.2: Significant Data Gaps

A data gap, as defined in the ASTM Standard, is a lack of or inability to obtain information required by the ASTM Standard despite good faith efforts by the environmental professional to gather such information. The environmental professional must then determine whether these gaps are significant. PM did not identify or encounter any instances of significant data gaps during the course of this ESA.

10.3: Historical Recognized Environmental Conditions (HRECs)

An HREC, as defined in the ASTM Standard, is a past release of hazardous substances or petroleum products that has occurred in connection with the subject property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted residential use criteria established by a regulatory authority, without subjecting the subject property to any required controls. The following HREC was identified:

• The subject property is a closed Leaking Underground Storage Tank (LUST) site with one release reported in 1990, which was granted a Type B LUST Closure in 1992. The release was reported during removal of a 6,000-gallon used oil UST, located south of the subject building. Review of site assessment activities completed in 1991 documents that no subsurface contamination associated with the release remains on-site above the most restrictive Part 213 Risk Based Screening Levels (RBSLs). Based on the closed LUST status and documented site assessment activities which were adequate to assess the former release, PM has identified the closed LUST status as an HREC.

10.4: Controlled Recognized Environmental Conditions (CRECs)

A CREC, as defined in the ASTM Standard, is a recognized environmental condition (REC) resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls. PM has not identified any CRECs in association with the subject property.

10.5: Recognized Environmental Conditions (RECs)

We have performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E 1527-13 of the Commercial Property located at 802 Alpine Avenue NW, Grand Rapids, Kent County, Michigan, the property. Any exceptions to, or deletions from, this practice are described in Section 1.4 of this report. This assessment has revealed no evidence of recognized environmental conditions connected with the property except the following:

- The subject property was formerly occupied by a gasoline service station from at least 1929 until 1959 and has been occupied by an automotive transmission repair shops since 1961. Based upon review of the previous subsurface investigations completed in 1991, soil contamination is present which exceeds the current Part 201 Residential and Nonresidential Generic Cleanup Criteria. Review of previous site investigation activities documents that the exceedances are within the building footprint and therefore are not associated with the former release. The soil contamination is likely associated with the long-term service operations that have been present on the property since the 1920s. Based on these analytical results, the subject property would be classified as a "facility," as defined by Part 201 of P.A. 451 of the Michigan Natural Resources Environmental Protection Act (NREPA), as amended.
- The subject property has been occupied by various automotive service operations since at least 1929. Historical interior waste streams associated with the current and former operations would have consisted of general hazardous substances and/or petroleum products. A significant portion of this time period preceded major environmental regulations and current waste management and disposal procedures. The historical waste management practices associated with the current and former operations are unknown and may be a source of subsurface contamination.
- PM observed four in-ground hoists in the shop area within the current building. According
 to the site representative, two of the hoists were installed in 1967. The installation dates of
 the remaining hoists were unknown. In-ground hoists have an underground reservoir for
 hydraulic fluids, which can contain polychlorinated biphenyls (PCBs). The potential exists
 that a release occurred from the former hydraulic hoist system and/or underground
 reservoir.
- PM observed two dry wells in the shop area within the current building. The original installation date of the dry wells is unknown. According to the site representative, the dry wells are pumped by Crystal Clean on an as needed basis. The integrity of the dry wells is unknown. Historical interior waste streams associated with the automotive transmission repair shop would have consisted of general hazardous substances and/or petroleum products. A significant portion of this time period preceded major environmental regulations

and current waste management and disposal procedures. Based upon the age of the building, the potential exists for failure of the dry wells (i.e. cracks, leaks) to have occurred over time. The current and historical waste management practices associated with the dry wells are unknown and could be a source of subsurface contamination.

- According to information obtained from the City of Grand Rapids Building Department, the
 former commercial building utilized an oil heater in at least 1951. PM was unable to
 determine the heat source for the building from at least 1929 until 1967. Given the use of
 an oil heater in at least 1951, it is likely that a fuel oil above-ground storage tank (AST) or
 underground storage tank (UST) was used during that time. The potential exists for orphan
 USTs to be present on the property and/or for a release to have occurred.
- According to information obtained from the Michigan Department of Environmental Quality (MDEQ) and City of Grand Rapids Fire Department, the property formerly contained two 1,500-gallon USTs and a 1,000-gallon UST that were reportedly removed in 1986. The contents of the USTs were not documented, and the location of the USTs was not provided. Additionally, PM was unable to confirm whether these USTs were the only USTs associated with the service station operations from 1929 until 1959. The potential exists for orphan USTs to be present and/or for a release to have occurred from the former UST systems and/or fuel dispensers.

No adjoining and/or nearby RECs have been identified.

10.6: Recommendations

We have performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E 1527-13 of the Commercial Property located at 802 Alpine Avenue NW, Grand Rapids, Kent County, Michigan, the property. Any exceptions to, or deletions from, this practice are described in Section 1.4 of this report. This assessment has revealed no evidence of recognized environmental conditions connected with the property except as listed in Section 10.5 of this report.

Verification of the presence or absence of contaminants potentially associated with these RECs may be determined through a Phase II investigation at the request of the client. Cost/risk analysis decisions associated with further investigation of these conditions are the decision of the client.

11.0 NON-ASTM SCOPE CONSIDERATIONS/BUSINESS ENVIRONMENTAL RISKS

PM has included a discussion of Non-ASTM Scope Considerations based upon industry standards and lender requirements. A Business Environmental Risk is defined as a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated in this practice.

Non-ASTM Item	Observations or Information		
Potential Asbestos Containing Building Materials (ACBM)	Based upon PM's limited visual observations during the site reconnaissance, suspect ACBMs identified included drywall walls and acoustical ceiling tiles. The materials appeared to be in good condition. Based on the 1967 construction date of the current building, the potential exists for ACMs to be present. However, if any significant demolition or renovation activities are planned, PM recommends that an ACM survey be completed by a qualified inspector.		
Lead Based Paint	PM observed the painted surfaces in the current building to be in good condition with no apparent chipping or peeling. Based on the 1967 construction date of the current building, the potential exists for lead based paint (LBP) to be present.		
Visual Mold or Significant Moisture	PM did not observe any visual mold or moisture damage		
Damage	during the site reconnaissance.		

12.0 SIGNATURE(S) OF ENVIRONMENTAL PROFESSIONAL(S)

We declare that, to the best of our professional knowledge and belief, we meet the definition of *Environmental professional* as defined in §312.10 of 40 CFR 312 and we have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. We have developed and performed the all appropriate inquires in conformance with the standards and practices set forth in 40 CFR Part 312.

Shawn Shadley

Regional Due Diligence Manager

Beth Sexton

National Due Diligence Manager

13.0 REFERENCES

The following published sources were utilized during completion of this Phase I ESA:


- Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, ASTM, ASTM Designation E 1527-13, Published November 2013.
- Bresser's Cross-Index City Directories, Bresser's in Detroit, Michigan. City: Grand Rapids. Years: 1959-2015.
- R.L. Polk's Directories, obtained from the State of Michigan Library in Lansing, Michigan. City: Grand Rapids. Years: 1904-1954.
- United States Geological Survey Division (U.S.G.S.) 7.5 Minute Topographic Map Grand Rapids West, Michigan Quadrangle, 1996.
- United States Department of Agriculture, Custom Soil Resource Report for Kent County, Michigan (survey area data from September 2014).

In addition, PM reviewed the following previous site investigations, some of which are available from public sources.

Name of Report	Date of Report	Company that Prepared Report
Report of UST Closure and Initial Abatement Measures	February 1990	Superior Environmental Corporation (Superior)
Report of Findings	November 1990	Alderink and Associates, Inc. (Alderink)
Report of Findings	July 1991	Alderink
Results of Subsurface December 1991		Alderink

Figures





KENT COUNTY



FIGURE 1

PROPERTY VICINITY MAP
USGS, 7.5 MINUTE SERIES
GRAND RAPIDS WEST, MI QUADRANGLE, 1996.




PROJ: COMMERCIAL PROPERTY 802 ALPINE AVENUE NW GRAND RAPIDS, MI

THIS IS NOT A LEGAL SURVEY		DRN BY:	KS	DATE: 1/19/2015
VERIFY SCALE	2,000'	CHKD BY:	ВН	SCALE: " = 2,000'
IF NOT 1" ON THIS SHEET, ADJUST SCALES ACCORDINGLY.		FILE NAME:	03-	4006-0F01R00



Appendix A







Photographs From Site Reconnaissance PM Project No. 03-4006-0

Location: 802 Alpine Avenue NW, Grand Rapids, Michigan

Photograph 1



The front and south face of the current building

Photograph 2



The north face of the current building



Photographs From Site Reconnaissance PM Project No. 03-4006-0


Location: 802 Alpine Avenue NW, Grand Rapids, Michigan

Photograph 3



The west face of the current building

Photograph 4



General view of the subject building interior



Photographs From Site Reconnaissance PM Project No. 03-4006-0 Location: 802 Alpine Avenue NW, Grand Rapids, Michigan

Photograph 5



General view of the subject building interior

Photograph 6



General view of the subject building interior



Photographs From Site Reconnaissance PM Project No. 03-4006-0

Location: 802 Alpine Avenue NW, Grand Rapids, Michigan

Photograph 7



General view of the subject building interior (in-ground hoist)

Photograph 8



General view of the subject building interior (dry well)



Photographs From Site Reconnaissance PM Project No. 03-4006-0

Location: 802 Alpine Avenue NW, Grand Rapids, Michigan

Photograph 9



General view of the north adjoining residential property

Photograph 10



General view of the east adjoining residential property



Photographs From Site Reconnaissance PM Project No. 03-4006-0

Location: 802 Alpine Avenue NW, Grand Rapids, Michigan

Photograph 11



The south adjoining property, identified as 766 7th Street NW

Photograph 12



The southwest adjoining property, identified as 800-802 7th Street NW



Photographs From Site Reconnaissance PM Project No. 03-4006-0 Location: 802 Alpine Avenue NW, Grand Rapids, Michigan


Photograph 13



General view of the west adjoining residential properties

Appendix B





Phase I ESA - ASTM User Questionnaire

Project Address: 802 Alpine Avenue NW, Grand Rapids, MI

In order to qualify for one of the Landowner Liability Protections (LLPs) offered by the Small business Liability relief and Brownfield's Revitalization Act of 2001 (the "Brownfield's Amendments") the user must provide the following information (if available) to the environmental professional. Failure to provide this information could results in a determination that "all appropriate inquiry" is not complete.

Please answer the following questions to the best of your knowledge and return to PM Environmental, Inc. (PM) via facsimile (877-884-6775) or e-mail (hengst@pmenv.com).

1. Environmental Clean-up liens that are filed or recorded against the site (40 CFR 312.25)
Are you aware of any environmental cleanup liens against the property that are filed or recorded under federal, tribal, state or local law?
If so, please describe that type of liens:
2. Activity and land use limitations that are in place on the site or that have been filed in a registry (40 CFR 312.26) Are you aware of any Activity and Use Limitations (AULs), such as engineering controls, land use restrictions, or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state, or local law?
If yes, what type of AULs are you aware of?
3. Specialized knowledge or experience of the person seeking to qualify for a LLP (40 CFR 312.28)
As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?
If yes, what type of business are you associated with? fire lepton
What types of chemicals are used in your business? ### Loptor Loptor
All necessary Automotive Chemicals

PM Environmental, Inc. Page 1

Phase I ESA - ASTM User Questionnaire

Project Address: 802 Alpine Avenue NW, Grand Rapids, MI

4. Relationship to the purchase p	rice to the fair market value of the property if it were not
contaminated (40 CFR 312.29)	The property if it were not

Does the purchase price being paid for this property reasonably reflect the fair market value of the property?

/er

If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?

5. Commonly known or reasonably ascertainable information about the property (40 CFR 312.30)

Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example as a user:

a. Do you know of the past uses of the property? If yes, please list what past uses are you aware of? Yes No

b. Do you know of specific chemicals that are present or once were present at the property?

es No

If yes, please list what chemicals you are aware of?

c. Do you know of spills or other chemical releases that have taken place on the property?

Yes No

d. Do you know of any environmental cleanups which have taken place on the property?

Yes

If yes, do you have copies of any of the reports documenting the work?

Yes No

If you have any documentation of the previous environmental clean-up please provide copies to PME when you return this questionnaire.

PM Environmental, Inc. Page 2

Phase I ESA - ASTM User Questionnaire

Project Address: 802 Alpine Avenue NW, Grand Rapids, MI


6. The degree of the obviousness of the presence of likely presence of contamination at the property and the ability to detect the contamination by appropriate investigation (40CFR 312.31)

As the user of this ESA, based on your knowledge and experience related to the property are there any obvious indicators that point to the presence or likely presence of contamination on the property?

If yes, please comment on what those indicators are (i.e. lower purchase price, areas of staining, poor housekeeping, etc.:

User Name:	David lee Parm
Company Name	David Re Lakin
property is being purchased under:	TKKA Properties
Street Address:	856- Seventh St. NW
City, State, Zip code:	Grans Rapin 49504
User Phone Number:	614-690-4197
Signature of the User:	Want for
Date Questionnaire was completed on:	01-18-15

PM Environmental, Inc. Page 3





NRCS

Natural Resources Conservation Service A product of the National Cooperative Soil Survey, a joint effort of the United States Department of Agriculture and other Federal agencies, State agencies including the Agricultural Experiment Stations, and local participants

Custom Soil Resource Report for Kent County, Michigan





MAP LEGEND

Spoil Area

Stony Spot

Wet Spot

Other

Rails

US Routes

Major Roads

Local Roads

Ŷ

Δ

Water Features

Transportation

Background

Very Stony Spot

Special Line Features

Streams and Canals

Interstate Highways

Aerial Photography

Area of Interest (AOI)

Area of Interest (AOI)

Soils

Soil Map Unit Polygons



Soil Map Unit Lines



Soil Map Unit Points

Special Point Features

Blowout



Clay Spot

Closed Depression

Gravel Pit

Gravelly Spot

Landfill

Lava Flow

Marsh or swamp

Mine or Quarry

Miscellaneous Water

Perennial Water

+ Saline Spot

Sandy Spot

Severely Eroded Spot

Sinkhole

Slide or Slip

MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:15,800.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service Web Soil Survey URL: http://websoilsurvey.nrcs.usda.gov Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Kent County, Michigan Survey Area Data: Version 13, Sep 16, 2014

Soil map units are labeled (as space allows) for map scales 1:50,000 or larger.

Date(s) aerial images were photographed: Mar 13, 2012—Apr 6, 2012

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

Map Unit Legend

Kent County, Michigan (MI081)						
Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI			
81B	Urban land-Spinks complex, 0 to 8 percent slopes	0.3	100.0%			
Totals for Area of Interest		0.3	100.0%			

Map Unit Descriptions

The map units delineated on the detailed soil maps in a soil survey represent the soils or miscellaneous areas in the survey area. The map unit descriptions, along with the maps, can be used to determine the composition and properties of a unit.

A map unit delineation on a soil map represents an area dominated by one or more major kinds of soil or miscellaneous areas. A map unit is identified and named according to the taxonomic classification of the dominant soils. Within a taxonomic class there are precisely defined limits for the properties of the soils. On the landscape, however, the soils are natural phenomena, and they have the characteristic variability of all natural phenomena. Thus, the range of some observed properties may extend beyond the limits defined for a taxonomic class. Areas of soils of a single taxonomic class rarely, if ever, can be mapped without including areas of other taxonomic classes. Consequently, every map unit is made up of the soils or miscellaneous areas for which it is named and some minor components that belong to taxonomic classes other than those of the major soils.

Most minor soils have properties similar to those of the dominant soil or soils in the map unit, and thus they do not affect use and management. These are called noncontrasting, or similar, components. They may or may not be mentioned in a particular map unit description. Other minor components, however, have properties and behavioral characteristics divergent enough to affect use or to require different management. These are called contrasting, or dissimilar, components. They generally are in small areas and could not be mapped separately because of the scale used. Some small areas of strongly contrasting soils or miscellaneous areas are identified by a special symbol on the maps. If included in the database for a given area, the contrasting minor components are identified in the map unit descriptions along with some characteristics of each. A few areas of minor components may not have been observed, and consequently they are not mentioned in the descriptions, especially where the pattern was so complex that it was impractical to make enough observations to identify all the soils and miscellaneous areas on the landscape.

The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The objective of mapping is not to delineate pure taxonomic classes but rather to separate the landscape into landforms or landform segments that have similar use and management requirements. The delineation of such segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, however, onsite investigation is needed to define and locate the soils and miscellaneous areas.

An identifying symbol precedes the map unit name in the map unit descriptions. Each description includes general facts about the unit and gives important soil properties and qualities.

Soils that have profiles that are almost alike make up a *soil series*. Except for differences in texture of the surface layer, all the soils of a series have major horizons that are similar in composition, thickness, and arrangement.

Soils of one series can differ in texture of the surface layer, slope, stoniness, salinity, degree of erosion, and other characteristics that affect their use. On the basis of such differences, a soil series is divided into *soil phases*. Most of the areas shown on the detailed soil maps are phases of soil series. The name of a soil phase commonly indicates a feature that affects use or management. For example, Alpha silt loam, 0 to 2 percent slopes, is a phase of the Alpha series.

Some map units are made up of two or more major soils or miscellaneous areas. These map units are complexes, associations, or undifferentiated groups.

A *complex* consists of two or more soils or miscellaneous areas in such an intricate pattern or in such small areas that they cannot be shown separately on the maps. The pattern and proportion of the soils or miscellaneous areas are somewhat similar in all areas. Alpha-Beta complex, 0 to 6 percent slopes, is an example.

An association is made up of two or more geographically associated soils or miscellaneous areas that are shown as one unit on the maps. Because of present or anticipated uses of the map units in the survey area, it was not considered practical or necessary to map the soils or miscellaneous areas separately. The pattern and relative proportion of the soils or miscellaneous areas are somewhat similar. Alpha-Beta association, 0 to 2 percent slopes, is an example.

An *undifferentiated group* is made up of two or more soils or miscellaneous areas that could be mapped individually but are mapped as one unit because similar interpretations can be made for use and management. The pattern and proportion of the soils or miscellaneous areas in a mapped area are not uniform. An area can be made up of only one of the major soils or miscellaneous areas, or it can be made up of all of them. Alpha and Beta soils, 0 to 2 percent slopes, is an example.

Some surveys include *miscellaneous areas*. Such areas have little or no soil material and support little or no vegetation. Rock outcrop is an example.

Kent County, Michigan

81B—Urban land-Spinks complex, 0 to 8 percent slopes

Map Unit Setting

National map unit symbol: 68sw Elevation: 600 to 1,200 feet

Mean annual precipitation: 32 to 36 inches
Mean annual air temperature: 46 to 50 degrees F

Frost-free period: 160 to 180 days

Farmland classification: Not prime farmland

Map Unit Composition

Urban land: 60 percent

Spinks and similar soils: 35 percent *Minor components*: 5 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Spinks

Setting

Landform: Beach ridges

Landform position (two-dimensional): Summit, backslope

Landform position (three-dimensional): Riser

Down-slope shape: Linear Across-slope shape: Linear Parent material: Sandy drift

Typical profile

H1 - 0 to 10 inches: sand

H2 - 10 to 16 inches: loamy sand H3 - 16 to 60 inches: loamy sand, sand

H3 - 16 to 60 inches:

Properties and qualities

Slope: 0 to 8 percent

Depth to restrictive feature: More than 80 inches

Natural drainage class: Well drained

Runoff class: Very low

Capacity of the most limiting layer to transmit water (Ksat): High (1.98 to 5.95 in/hr)

Depth to water table: More than 80 inches

Frequency of flooding: None Frequency of ponding: None

Available water storage in profile: Moderate (about 6.4 inches)

Interpretive groups

Land capability classification (irrigated): 3s Land capability classification (nonirrigated): 3s

Hydrologic Soil Group: A

Minor Components

Thetford

Percent of map unit: 3 percent Landform: Flats on outwash plains

Wasepi

Percent of map unit: 2 percent

Landform: Drainageways on outwash plains, drainageways on terraces

Soil Information for All Uses

Soil Reports

The Soil Reports section includes various formatted tabular and narrative reports (tables) containing data for each selected soil map unit and each component of each unit. No aggregation of data has occurred as is done in reports in the Soil Properties and Qualities and Suitabilities and Limitations sections.

The reports contain soil interpretive information as well as basic soil properties and qualities. A description of each report (table) is included.

Soil Qualities and Features

This folder contains tabular reports that present various soil qualities and features. The reports (tables) include all selected map units and components for each map unit. Soil qualities are behavior and performance attributes that are not directly measured, but are inferred from observations of dynamic conditions and from soil properties. Example soil qualities include natural drainage, and frost action. Soil features are attributes that are not directly part of the soil. Example soil features include slope and depth to restrictive layer. These features can greatly impact the use and management of the soil.

Soil Features

This table gives estimates of various soil features. The estimates are used in land use planning that involves engineering considerations.

A *restrictive layer* is a nearly continuous layer that has one or more physical, chemical, or thermal properties that significantly impede the movement of water and air through the soil or that restrict roots or otherwise provide an unfavorable root environment. Examples are bedrock, cemented layers, dense layers, and frozen layers. The table indicates the hardness and thickness of the restrictive layer, both of which significantly affect the ease of excavation. *Depth to top* is the vertical distance from the soil surface to the upper boundary of the restrictive layer.

Subsidence is the settlement of organic soils or of saturated mineral soils of very low density. Subsidence generally results from either desiccation and shrinkage, or oxidation of organic material, or both, following drainage. Subsidence takes place gradually, usually over a period of several years. The table shows the expected initial

subsidence, which usually is a result of drainage, and total subsidence, which results from a combination of factors.

Potential for frost action is the likelihood of upward or lateral expansion of the soil caused by the formation of segregated ice lenses (frost heave) and the subsequent collapse of the soil and loss of strength on thawing. Frost action occurs when moisture moves into the freezing zone of the soil. Temperature, texture, density, saturated hydraulic conductivity (Ksat), content of organic matter, and depth to the water table are the most important factors considered in evaluating the potential for frost action. It is assumed that the soil is not insulated by vegetation or snow and is not artificially drained. Silty and highly structured, clayey soils that have a high water table in winter are the most susceptible to frost action. Well drained, very gravelly, or very sandy soils are the least susceptible. Frost heave and low soil strength during thawing cause damage to pavements and other rigid structures.

Risk of corrosion pertains to potential soil-induced electrochemical or chemical action that corrodes or weakens uncoated steel or concrete. The rate of corrosion of uncoated steel is related to such factors as soil moisture, particle-size distribution, acidity, and electrical conductivity of the soil. The rate of corrosion of concrete is based mainly on the sulfate and sodium content, texture, moisture content, and acidity of the soil. Special site examination and design may be needed if the combination of factors results in a severe hazard of corrosion. The steel or concrete in installations that intersect soil boundaries or soil layers is more susceptible to corrosion than the steel or concrete in installations that are entirely within one kind of soil or within one soil layer.

For uncoated steel, the risk of corrosion, expressed as *low*, *moderate*, or *high*, is based on soil drainage class, total acidity, electrical resistivity near field capacity, and electrical conductivity of the saturation extract.

For concrete, the risk of corrosion also is expressed as *low*, *moderate*, or *high*. It is based on soil texture, acidity, and amount of sulfates in the saturation extract.

Soil Features–Kent County, Michigan									
Map symbol and soil name	Restrictive Layer			Subsidence		Potential for frost	Risk of corrosion		
	Kind	Depth to top	Thickness	Hardness	Initial	Total	action	Uncoated steel	Concrete
		In	In		In	In			
81B—Urban land- Spinks complex, 0 to 8 percent slopes									
Urban land		_	_		_	_			
Spinks		_	_		0	0	Low	Low	Moderate
Thetford		_	_		0	_	Moderate	High	Moderate
Wasepi		_	_		0	_	High	High	Moderate

References

American Association of State Highway and Transportation Officials (AASHTO). 2004. Standard specifications for transportation materials and methods of sampling and testing. 24th edition.

American Society for Testing and Materials (ASTM). 2005. Standard classification of soils for engineering purposes. ASTM Standard D2487-00.

Cowardin, L.M., V. Carter, F.C. Golet, and E.T. LaRoe. 1979. Classification of wetlands and deep-water habitats of the United States. U.S. Fish and Wildlife Service FWS/OBS-79/31.

Federal Register. July 13, 1994. Changes in hydric soils of the United States.

Federal Register. September 18, 2002. Hydric soils of the United States.

Hurt, G.W., and L.M. Vasilas, editors. Version 6.0, 2006. Field indicators of hydric soils in the United States.

National Research Council. 1995. Wetlands: Characteristics and boundaries.

Soil Survey Division Staff. 1993. Soil survey manual. Soil Conservation Service. U.S. Department of Agriculture Handbook 18. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_054262

Soil Survey Staff. 1999. Soil taxonomy: A basic system of soil classification for making and interpreting soil surveys. 2nd edition. Natural Resources Conservation Service, U.S. Department of Agriculture Handbook 436. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2 053577

Soil Survey Staff. 2010. Keys to soil taxonomy. 11th edition. U.S. Department of Agriculture, Natural Resources Conservation Service. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_053580

Tiner, R.W., Jr. 1985. Wetlands of Delaware. U.S. Fish and Wildlife Service and Delaware Department of Natural Resources and Environmental Control, Wetlands Section.

United States Army Corps of Engineers, Environmental Laboratory. 1987. Corps of Engineers wetlands delineation manual. Waterways Experiment Station Technical Report Y-87-1.


United States Department of Agriculture, Natural Resources Conservation Service. National forestry manual. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/home/?cid=nrcs142p2 053374

United States Department of Agriculture, Natural Resources Conservation Service. National range and pasture handbook. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/landuse/rangepasture/?cid=stelprdb1043084

United States Department of Agriculture, Natural Resources Conservation Service. National soil survey handbook, title 430-VI. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/scientists/?cid=nrcs142p2 054242

United States Department of Agriculture, Natural Resources Conservation Service. 2006. Land resource regions and major land resource areas of the United States, the Caribbean, and the Pacific Basin. U.S. Department of Agriculture Handbook 296. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_053624

United States Department of Agriculture, Soil Conservation Service. 1961. Land capability classification. U.S. Department of Agriculture Handbook 210. http://www.nrcs.usda.gov/Internet/FSE_DOCUMENTS/nrcs142p2_052290.pdf



802 Alpine Avenue NW

802 Alpine Avenue NW Grand Rapids, MI 49504

Inquiry Number: 4170139.5

January 05, 2015

The EDR Aerial Photo Decade Package



EDR Aerial Photo Decade Package

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Thank you for your business.
Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2015 by Environmental Data Resources, Inc., All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


Date EDR Searched Historical Sources:

Aerial Photography January 05, 2015


Target Property:

802 Alpine Avenue NW Grand Rapids, MI 49504

<u>Year</u>	<u>Scale</u>	<u>Details</u>	<u>Source</u>
1938	Aerial Photograph. Scale: 1"=500'	Flight Year: 1938	AAA
1950	Aerial Photograph. Scale: 1"=500'	Flight Year: 1950	PMA
1960	Aerial Photograph. Scale: 1"=500'	Flight Year: 1960	CSS
1967	Aerial Photograph. Scale: 1"=500'	Flight Year: 1967	ASCS
1978	Aerial Photograph. Scale: 1"=600'	Flight Year: 1978	ASCS
1981	Aerial Photograph. Scale: 1"=500'	Flight Year: 1981	USGS
1986 1993	Aerial Photograph. Scale: 1"=500'	Flight Year: 1986	USGS NAPP
1993	Aerial Photograph. Scale: 1"=600' Aerial Photograph. Scale: 1"=500'	Flight Year: 1993 /DOQQ - acquisition dates: 1999	USGS/DOQQ
2005	Aerial Photograph. Scale: 1"=500'	Flight Year: 2005	USDA/NAIP
2006	Aerial Photograph. Scale: 1"=500'	Flight Year: 2006	USDA/NAIP
2009	Aerial Photograph. Scale: 1"=500'	Flight Year: 2009	USDA/NAIP
2010	Aerial Photograph. Scale: 1"=500'	Flight Year: 2010	USDA/NAIP
2012	Aerial Photograph. Scale: 1"=500'	Flight Year: 2012	USDA/NAIP





































802 Alpine Avenue NW

802 Alpine Avenue NW Grand Rapids, MI 49504

Inquiry Number: 4170139.3

December 29, 2014

Certified Sanborn® Map Report



Certified Sanborn® Map Report

12/29/14

Site Name: Client Name:

802 Alpine Avenue NW PM Environmental, Inc. 802 Alpine Avenue NW 3340 Ranger Road Grand Rapids, MI 49504 Lansing, MI 48906

EDR Inquiry # 4170139.3 Contact: Lindsey Sorensen



The Sanborn Library has been searched by EDR and maps covering the target property location as provided by PM Environmental, Inc. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Site Name: 802 Alpine Avenue NW Address: 802 Alpine Avenue NW City, State, Zip: Grand Rapids, MI 49504

Cross Street:

P.O. # NA

Project: 03-4006-0

Certification # CB7E-48BF-82A0

Maps Provided:

1984 18951968 1888

196519531950

1913



Sanborn® Library search results Certification # CB7E-48BF-82A0

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

Library of Congress

University Publications of America

▼ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies


PM Environmental, Inc. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2014 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.


EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.






















Land Division Act Information

Date of Last Split/Combine	Not Available	Number of Splits Left Not A	vailable
Date Form Filed	Not Available	Unallocated Div.s of Parent 0	
Date Created	Not Available	Unallocated Div.s Transferred 0	
Acreage of Parent	0.00	Rights Were Transferred No	
Split Number	0	Courtesy Split No	
Parent Parcel	Not Available	· ·	

Sale History

Sale Date	Sale Price	Instrument	Grantor	Grantee	Liber/Page	Comments
03/30/1993	\$0.00	QC	SHERD D/SHERD TRUST		3210/0284	
02/05/1993	\$30,000.00	WD	SHERD TST/SHERD D&C		3187/0116	
02/05/1993	\$30,000.00	WD	SHERD TST/SHERD D&C		3187/0116	

Building Information - 2244.00 sq ft Garage, Service/Repair (Commercial)

Floor Area	2,244 sq ft	Estimated TCV	\$48,349
Occupancy	Garage, Service/Repair	Class	С
Stories Above Ground	1	Average Story Height	14 ft
Basement Wall Height	0 ft		
Year Built	1967	Year Remodeled	Not Available
Percent Complete	100%	Heat	Space Heaters, Gas with Fan
Physical Percent Good	47%	Functional Percent Good	100%
Economic Percent Good	100%	Effective Age	25 yrs

^{**}Disclaimer: BS&A Software provides AccessMyGov.com as a way for municipalities to display information online and is not responsible for the content or accuracy of the data herein. This data is provided for reference only and WITHOUT WARRANTY of any kind, expressed or inferred. Please contact your local municipality if you believe there are errors in the data.

Copyright © 2014 BS&A Software, Inc.





ISO 9001 REGISTERED

Lansing

3340 Ranger Road Lansing, MI 48906

f: 877-884-6775 t: 517-321-3331

Detroit

4080 W. 11 Mile Rd Berkley, MI 48072 f: 877-884-6775

f: 877-884-6775 t: 248-336-9988

560 5th Street NW, Suite 301 Grand Rapids, MI 49504

f: 877.884.6775 t: 616.285.8857

Grand Rapids

VIA FASICIMILE (616) 456-4569

December 29, 2014

City Attorney's Office Elizabeth White, Deputy City Attorney 300 Monroe Avenue NW Grand Rapids, MI 49503-2206

Please accept this as a Freedom of Information Act (FOIA) request for information on the following property;

802 Alpine Avenue NW, Grand Rapids (PID: 41-13-24-155-024)

Information we are interested in obtaining includes;

Development Center Files

- Any building permits that have been issued to this property or any other indication a building has ever been present
- Any site plans or diagrams of the property

Environmental Services Files

- Any files regarding reported spills on the property

Fire Department Files

- Any current or historical records of fires, spills, or chemical storage;
- Any fire violations that indicate an environmental concern
- Historical sketches / layouts of the building and property or any indication of underground or above ground storage tanks;
- Any current or historical inspection records indicating chemical use or storage.

We would appreciate any assistance in receiving information in a timely manner, due to our scheduled deadlines. Please call me at 616-222-1777 if you have any questions or concerns regarding this request. I can also be reached by email at Sorensen@pmenv.com or by fax at 877-884-6775.

Sincerely,

PM Environmental, Inc.

Lindsey Sorensen Staff Consultant

560 5th Street NW, Suite 301 Grand Rapids, MI 49504

NAME OF OWNER	NO. OF PERMIT	DATE		763 PORM 510
Kent County Oil Co.	19067	Isanto	IMPROVEMENT	DESCRIPTION OF IMPROVEMEN OR ALTERATION
Texaco Serv. Station		12-18-62	Appeal t	o have 1sty class gar
Robert Noce.	4466 6380	3 12-17-5 1-17-58 a	1 800.	Oil unit heater. sell used cars in C-1
	8699	12-21-60	Appeal on	lst. class gar.
Northend Transmission J. R. Adrianse	23452 30675	10-15-63 3-17-65	350 0	as unit best
Edward Sherd	9374	2-6-67	g V	arage, use with ser-
			,	peal for 1st class rage in C-1 zone & de yard
	1			

NAME OF OWNER		1pine N.W.		765 FORM BIO 2370
A STATE OF THE STA	NO. OF PERMIT	DATE	VALUE IMPROVE- MENT	DESCRIPTION OF IMPROVEMEN
Nellie Eastman North End Transmissio	3550 8441 42082	3-90-16 10-3-24 3-11-31 11-30-34 6-12-45 5-25-67	25 4000 100 25 1700 5,000	Build 28xth; garage addition. Build 1-sty. CB & steel add'n.53x16;





ISO 9001 REGISTERED

Lansing

3340 Ranger Road Lansing, MI 48906

f: 877-884-6775 t: 517-321-3331

Detroit

4080 W. 11 Mile Rd Berkley, MI 48072 f: 877-884-6775

f: 877-884-6775 t: 248-336-9988

560 5th Street NW, Suite 301 Grand Rapids, MI 49504

f: 877.884.6775 t: 616.285.8857

Grand Rapids

VIA FASICIMILE (616) 456-4569

December 29, 2014

City Attorney's Office Elizabeth White, Deputy City Attorney 300 Monroe Avenue NW Grand Rapids, MI 49503-2206

Please accept this as a Freedom of Information Act (FOIA) request for information on the following property;

802 Alpine Avenue NW, Grand Rapids (PID: 41-13-24-155-024)

Information we are interested in obtaining includes;

Development Center Files

- Any building permits that have been issued to this property or any other indication a building has ever been present
- Any site plans or diagrams of the property

Environmental Services Files

- Any files regarding reported spills on the property

Fire Department Files

- Any current or historical records of fires, spills, or chemical storage;
- Any fire violations that indicate an environmental concern
- Historical sketches / layouts of the building and property or any indication of underground or above ground storage tanks;
- Any current or historical inspection records indicating chemical use or storage.

We would appreciate any assistance in receiving information in a timely manner, due to our scheduled deadlines. Please call me at 616-222-1777 if you have any questions or concerns regarding this request. I can also be reached by email at Sorensen@pmenv.com or by fax at 877-884-6775.

Sincerely,

PM Environmental, Inc.

Lindsey Sorensen Staff Consultant

560 5th Street NW, Suite 301 Grand Rapids, MI 49504 02248

Grand Rapids Fire Department January 5, 1995



Chemical Survey

Chemical Survey GRFD - HAPLI Information: This survey is requested to determine the quantity of specific chemical groups used, produced or stored in your facility. Fire Chiefs are required to collect chemical data under the Michigan Occupational Safety and Health Act (MIOSHA), P. A. 154 of 1974, as amended, and the Fire Prevention Code, PA 207 of 1974, as amended.

Instructions: Indicate below whether your site uses or produces any of the chemical types listed. Check all the categories that apply when a chemical has more than one characteristic, (example: both a Class 3 flammable and a Class 6 poison), see definitions. Each chemical group listed in this survey includes a specified quantity. Indicate the quantity category for each chemical group on your site. To complete this survey, you may need to reference Material Safety Data Sheets, SARA Title III reporting forms, along with the attached definitions.

(Note: You must complete each line. Do not leave blanks. If you do not use a chemical group listed, mark "DO NOT HAVE" box.)

When substantial changes occur in the quantity or type of chemical use, manufacture or related storage, a revised survey must be submitted to the Fire Chief. In addition, a revised survey will be requested periodically as the fire chief determines necessary, but at least once every five years.

This survey may be followed-up with a request for more detailed information. This may include a request for Material Safety Data Sheets, chemical lists maintained under the Employee Right to Know provisions of MIOSHA and other information.

Please return this questionnaire as indicated in the attached cover letter. This site is: Chemical User - (Chemicals consumed in activities on site) Chemical Producer - (Chemicals manufactured at this site, includes packaging) Other - Mark this box if chemicals are stored on site, but not used or produced. Please Specify (Examples: service station, retail store, storage facility) Date Completed: Site Address: Name of Premises: Site Telephone: Emergency Contacts: (Include Private Alarm/Security Companies) Home number Business Telephone Name/Title

Grand Rapids Fire Department January 5, 1995

Respond based on the maximum quantity you would have on-site, including storage, at any one time during the year.

Respond based on the	he maximum quantity you would	Check 1	Box for Each Categ	gory
Chemical Type Class I	Specified Quantity	Have at or above Specified Quantity	Have but Below Specified Quantity	DO NOT HAVE
Explosives & Blasting Agents (Not including Class C Explosives)	Any Quantity			
Class 2 Poison Gas	Any Quantity			
Flammable Gas	100 gal. water capacity			
NonFlammable Gas	100 gal. water capacity			
Class 3 Flammable Liquid	1,000 galions			
Combustible Liquid	10,000 gallons			
Class 4 Flammable Solid (Dangerous when wet)	100 lbs.			
Flammable Solid	500 lbs.			
Spontaneously Combustible Material	100 lbs.			
Class 5 Oxidizer	500 lbs.			
Organic Peroxide	250 lbs.	<u> </u>		7
Class 6 Poison Irritating Material:	500 lbs.			
Liquid.	1,000 gal			
Solid	500 lbs			
Class 7 Radioactive Material (Yellow III Label)	Any quantity		. L	·
Class 8 Corrosives: Liquid	1,000 gal			
Solid	500 lbs.	. —	!	
No DOT Category Known Human Carcinogen	Any Quantity			

GRFD - HMPU SURVEY EVALUATION

Additional Information:
Telephone Data on File Survey Data
If Site Specific plan is not required, provide an explanation. Have Chemicals But below the
specified quantity. Need general plan
,
Additional Notes: HMPUH 02248
Evaluator Signature Hein Sollyer Date 5/9/25

GRFD INSPECTION ROUTING FORM

FIRE PREVENTION SUBTYPE	E				74.74.5		
ASSEMBLY	FIRE DRILL				RESIDENT	IAL	
Business	HAZARDOUS				SMOKE DE	ETECTOR	
CAPACITY	INSTITUTIONA	,L			STORAGE	4884-488	
EDUCATIONAL	☐ KNOX BOX				SPECIAL E	VENT	
FACTORY	MERCANTILE				OTHER		
INSPECTION ACTIONS							
Administatively Close (ADMIN)			Case Not	te(s) (1	NOTE)		
Issue Attorney Warning Letter ((AWL)	101	Issue Not	tice of	Violation L	etter (NOV)	
Compliant (COMP)			No Violat	ion (N	VIO)		X
Denied Entry (DENT)			Refer to 0	Other I	Department	t (RFR)	
Extension Granted (EXTG)	3		Stop Wor	k Orde	er (SW)		
Failure to Keep Appointment (F	TKA)		Verbal Or	rders (Given (VER	B)	
Information Call (INFO)			Violations	Prese	ent (VIO)		
License Approval (LIC)			Issue Wa	Issue Warrant (WAR)			
INSPECTION RESULT							
Inspection Time (Reg. Hours):			,5			Minutes:	
Inspection Time (After Hours):		Hours:	Minutes:				
Administrative Time:	The Manager of the Control of the Co	Hours:	Hours: Minutes:		Minutes:		
COMMENTS E-3 A							
Good inspertur							
Billable Non-Billable Non-Billable 108.00133							



CITY OF GRAND RAPIDS FIRE DEPARTMENT

INSPECTION REPORT

			-		-			
Property Parcel #:	41-13-	24-155-024		Date:		3-7	3-08	
Business Address:	802	ALPINE N.	V .					
Type of Business:	TRANSM	ission Repair		Business Name:	North	+ END	TRANS	mission
Contact Person:	DAVID	SHERD	E	Business Phone:	6	54-	309	7
Contact Phone:	430-	4971	E	Business Fax #:				
Mailing Address:	802	Alpine /	5	gove)				
Emergency Contact:			E	Emerg, Cont. Ph.:				
Emergency Contact:			E	Emerg. Cont. Ph.:				
Emergency Contact:				Emerg. Cont. Ph.:				
Number of Stories				verage # of Occupa	unto:	2_		7,100 4 CO 1 C 11 3
Number of Stories				Werage # 01 Occupa				
Number of Employees:	2							
Construction Type Prot.	steel Steel	Ord. (mason. & steel) 🔀	Ord	. (mason. & wood) [Wood	frame	Heavy timber	
Side(s) of Building Acces	sible to Fire Appar	ratus (1-2/3)4, that is, front-l	left-b	ack-right): 1	2	3⊠ 4□		
	- Coloro to Tito Appar							
EXTERIOR 1. Street Address Pres	antA (inible	YES NO NA	26	COMPRESSED G Proper Storage/Se			YES NO NA	Χ .
Exits Clear to Open			20.	-		A 0.F		JUH PON
Grounds Clear of De	bris/Overgrowth		27.	FLAMMABLE LIQI "No Smoking" Sigr				177
 Gas Meter Protected Fire Lanes/Fire Approximation 			28.	Ignition Sources Is	olated			Tt. Just
6. Knox Box Present	alatus Accessible			Fire Extinguisher F				or total
Knox Box Operates			(00	ntact HazMat Plann	er for riam	mable Liqu	ias in arums c	or totes)
Correct Keys Inside				ELECTRICAL			/	/ ,
AUTOMATIC SPRIM	KLER SYSTEM	N		Smoke Det. Prese Smoke Detectors I		1)	HHK/	
Sprinkler System Pr	esent			Exit Signs Present				_
10. System Inspected 11. System Tagged				Exit Signs Illumina				7,,,
,	Date:			Emerg. Egress Lig Emerg. Egress Lig			HHH	<i>/:</i>
	Date.			Clearance to Pane				
12. Proper Signage				Panel Door Installe		لم		
13. Control Valves Acce 2' sides / 3 fro				All Openings in Pa Disconnect Provide			品岩片	/:
14. Valves Supervised/0	Chained		40.	Cords in Good Cor	ndition			
15. Fire Department Co.	nnection w/Caps	日日日		Free of Extension Cover Plates on sy				
 Spare Sprinklers Sprinkler Wrench 		물물물	42.		junct. boxe	es	000	
18. Storage at least 18'				1 15				
Standpipe System T	ested/Inspected		42	EMERGENCY GE Proper Maint. Of E		- Table 198		
	Date:	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	44.					
20. Fire Pump Tested A	ultering			FIRE EXTINOUS	IEDO			
20. File Fullip residu A			45	FIRE EXTINGUISI Present	HERS		ппп	
	Date:			Accessible				
21. SP Inspection Repo	rts Filed On Site			Visible .	nan 40h in 1	handla		
111/60		VECTO NA		4" to bottom/less to Certified and Tagg		nanule		
HVAC 22. Accessible: 1' sides,	3' front	AE& NO PAY	,		Date	. 2,	13-67	
23. Clearance to Combi					Date		-1 -1	
24. Combustion Air								
Shut-offs Provided		니니니						



INSPECTION REPORT

51.	Institutional? Haz Mat? Atrium Mercantile (>500 pers.) Assisted I Evacuation Routes Posted Written Fire Evacuation Plan INTERIOR		74. 75. 76.	HOOD SUPPRESSION SYSTEM Hood System Present Cooking Equip./Hood Free of Grease System Inspected System Tagged Date: Appliance(s) Protected Proper Deep Fryer Clear./16* to Open Flame
53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65.	Celling Tiles in Place/Continuous Storage at least 24" below ceiling (if no sprinkler system) Exits Remote Door Swing/Midth Proper Door Hardware Proper Door Closing Device(s) Function(s) Exit Stairways Clear Exit Access Clear Exit Doors Unlocked Stairway/Fire Doors Closed Aisle Width/Proper (36" minimum) Aisles Clear Good Housekeeping Exits ADA Compliant Exit Signs over Exit Doors	00000000000000000000000000000000000000	79. 80. 81. 82. 83. 84. 85. 86. 87.	Hand-Puil Located Property HD Inspection Report Filed On Site FIRE ALARM SYSTEM Fire Alarm System Present System Inspected System Tagged Date: FA Registration Posted Puil Stations Present/Proper Loc. Notification Devices (A/V's)/Proper Smoke Detectors Provided Type of System Central Station Remote Local Manual Automatic
69. 70. 71.	HAZARDOUS CHEMICALS Flammable Storage Room/ Areas 3 or More Electric Hi – Los Chemicals in Drums or Totes Chemical User or Producer Aboveground or Underground Storage Tank (Yes answers to any of these, contact H	rds, describe in "COMMEN	90. 91. NOT	PA Inspection Reports Filed On Site Date: OPERATIONAL PERMIT(S) Operational Permit Required Operational Permit Posted Department Posted
	SECTION. Inspected by: COMMENTS		7	eceived by: Danilike Skerel



CITY OF GRAND RAPIDS

Fire Department

Inspection Form

Property Parcel #	Date: 3 3 - 08
Property Parcel #	***
ADDITIONAL COMMENTS	
6000 inspection	
ANY ??	
4 J. Sm. +2	
11/	

	\
nspected By J 5 M Th Received By L	Jewily Skerel

FIRE PREVENTION BUREAU FILE REPORT

DATE / / 2-99			
ADDRESS 85/ 4/	Dine NW		•
TENANT	** ***		
CONTACT PERSON			
OWNER LANDLORD			
COMPANY			
PHONE	PAGER`		
SMOKE DETECTOR COMPLAIN	T	BUSINESS LICENSE	
. Is I	Inspection	Is Inspection	-
REINSPECTION 2 ND	Inspection	TEMPORARY USE & OCCU	PANCY
3 rd]	Inspection	FINAL USE & OCCUPANCY	<u></u>
Fina	al Inspection	TELEPHONE CONVERSAT	10N
SMOKE DETECTOR VIOLATION	τ	COMPLAINT	OTHER
CO	MPLETED		
CASE ReView	NOTE	osecl	
·			
			- St Annual Res (CVIII-Annual Subsection Consumer)
		and the second s	
	•	•	
	,		

FIRE PREVENTION BUREAU



11-8-99 Not complet

11-8-99 Not complet

Owner Spid he eduld not get in

Owner Spid he eduld not get in

That if he was not complet by

Tinformed him That if he was not complet by

Tinformed him That if he was not complet by

Tinformed him That if he was not complet by

Tinformed him That if he was not complet by

That he would knee

Lagrage Action,

FIRE DEPARTMENT

11-12-99 OK

November 1, 1999

Mr. Stickney
B & D Properties
1186 144th Ave., Box 6
Moline, MI 49335

Re: 851 Alpine N. W.

Dear Mr. Stickney,

An inspection was conducted on October 19, 1999 at the above captioned address. The following items were found to be in violation of the City of Grand Rapids Fire Codes and must be corrected.:

- Improperly located smoke detector.
- · Lack of smoke detector in back bedroom.
- Extension cords running through out the apartment.

This is a violation of Section F-105.2, F-411.1, F-105.1.1 BOCA National Fire Prevention Code, 1984 Edition and must be corrected.

A re-inspection will be conducted on November 8, 1999 at 11:00 a.m. to check for compliance. Please make arrangements for you or your representative to be present. If an alternative time would be more convenient, please contact me. Unless I hear from you, I will arrive at 851 Alpine N. W. at 11:00 a. m. on November 8, 1999.

If the violation is not corrected by date of inspection, legal action may be taken against you.

If you have any questions or we may provide additional assistance to you, please contact me at 456-3900.

Sincerely,

Ted Jensen Fire Hazard Inspector

TJ/sk

cc: Richard Roersma, Fire Marshal

enc.

SMOKE DETECTORS SAVE LIVES





CITY OF GRAND RAPIDS FIRE DEPARTMENT

October 20, 1999

Mr. Stickney
B & D Properties
1186 144th Ave., Box 6
Moline, MI 49335

Re:

851 Alpine N. W.

Dear Mr. Stickney,

An inspection was conducted on October 19, 1999 at the above captioned address. The following items were found to be in violation of the City of Grand Rapids Fire Codes and must be corrected.:

- Improperly located smoke detector.
- · Lack of smoke detector in back bedroom.
- Extension cords running through out the apartment.

This is a violation of Section F-105.2, F-411.1, F-105.1.1 BOCA National Fire Prevention Code, 1984 Edition and must be corrected.

A re-inspection will be conducted on October 28, 1999 at 11:00 a.m. to check for compliance. Please make arrangements for you or your representative to be present. If an alternative time would be more convenient, please contact me. Unless I hear from you, I will arrive at 851 Alpine N. W. at 11:00 a. m. on October 28, 1999.

If you have any questions or we may provide additional assistance to you, please contact me at 456-3900.

Sincerely,

Ted Jensen Fire Hazard Inspector

TJ/sk

cc:

Richard Roersma, Fire Marshal

enc.

SMOKE DETECTORS SAVE LIVES

IMPORTANT MESSAGE
IMPORIAIVI
For Card 3-99 Time 1:30 F.M. Day 13-99 Time 1:30 F.M. Of Spectherner Cor Merry Coppe Cop
Space heaters electrices 2 white problems 3 2 Formula Signed LITHO IN U.S.A.

MOTES

B & O Proporties

Dave Stickney

Bruce Unger

877-6736
877-4834

0559-111

to as the master elevator, which provides Fire Department emergency access to every floor normally provided with elevator service by that group. The cabs of the master elevator shall be of such size as to accommodate an ambulance cot, twenty-two (22) inches wide by seventy-five (75) inches long in its horizontal open position.

F-108.4 The master elevator shall be located in hoistways equipped for pressurization to at least 0.15 inch of water column, pressurization will commence automatically upon activation of the detection system or manual fire alarm with air uncontaminated by the fire or products of combustion.

F-108.5 When transfer levels exist which necessitate changing master elevators in order to travel from one (1) floor to another, the connecting elevator lobby at each transfer point shall be enclosed in smoke-proof, one-hour fire-resistive construction with the doors between the corridors or floor area and the elevator lobby swinging in the direction of the lobby only.

F-108.6 Mechanical equipment used for hoistway pressurization shall be on the building electrical service and the emergency power supply.

F-108.7 An existing elevator installation not conforming to the dimensions previously mentioned in this Section may be accepted by the Fire Official.

F-108.8 A locked metal box shall be installed at the main elevator lobby and the alternate floor as designated by the Fire Chief or his or her designated representative. The box will be installed on the wall in the designated areas and will contain the elevator control master key or keys; said box will be painted red.

F-109.0 Duty to Inform the Fire Department.

F-109.1 Action to be Taken in the Event of a Fire: In the event of fire, the Fire Department shall be notified and the evacuation plan implemented immediately.

F-109.2 Fires to be Reported: The person having charge of any building, room or space within a building shall make certain that the Fire Department has been notified as soon as

he or she becomes aware of a fire within said building, room or space.

ARTICLE 3. GENERAL PRECAUTIONS AGAINST FIRE

F-312.3 Circuit Protection Devices: Electrical box covers, switch panels, and other protective devices shall be maintained unless the circuit is actually being worked on.

F-315.0 Fire Retardant Coatings.

F-315.1 General: All fire retardant coatings shall be maintained so as to retain the effectiveness of the treatment under the service conditions encountered in actual use.

ARTICLE 4. SMOKE DETECTOR ORDINANCE

F-400.7 Tampering: A person shall not obstruct, remove, tamper with, or otherwise disturb any fire protection device or system required to be installed or maintained under the provisions of this Code, except as may be necessary for maintenance of the device or system or necessary for the use of the device or system during an actual emergency.

F-411.1 General: All existing residential uses, as defined by the Building Code listed in Appendix A, shall be provided with a minimum of one (1) approved photoelectric smoke detector in the sleeping area, guest room or suite of a hotel, motel, lodging house, boarding house or residential multi-family dwelling unit. Each detector shall be installed in accordance with Nfipa 72E or Nfipa 74 listed in Appendix A. When actuated, the smoke detector shall provide an alarm suitable to warn the occupants within the individual room or unit.

F-411.2 Exceptions: Owner-occupied detached single-family dwellings in existence as of the date of adoption of this Code shall be exempt from these requirements.

F-411.3 Tampering: Anyone who tampers with or interferes with the manufactured operation of a smoke detector shall be in violation of this Code.

F-411.4 Owner-Occupied Detached Single-Family Dwellings: All existing owner-occupied detached single-family dwellings shall be equipped with a minimum of one (1) approved smoke detector. This detector shall be installed near the sleeping area in accordance with NFIPA 72 or NFIPA 74. The detector can be directly wired or battery powered. This provision shall only be applicable when possession is transferred, in whole or in part, by deed or land contract to another individual or entity. The person(s) or entity transferring possession in whole or in part shall be the party responsible under this Section to see that compliance is made.

F-412.1 Access: A roadway shall be provided for Fire Department vehicles from the nearest available right-of-way to a construction site prior to any structural framing being done involving combustible materials. The roadway shall be reasonably level and suitable for traverse by fire equipment. Access roads must be maintained year around to accommodate use by fire equipment.

F-412.2 Fire Hydrant Locations: For new plats being developed, hydrants shall be spaced in the following manner;

- Residential, four hundred (400) feet between hydrants.
- 2. Commercial/industrial, three hundred (300) feet between hydrants.
- 3. As near as possible to intersections.

In addition, an activated hydrant shall be located within three hundred (300) feet of buildings under construction. The three hundred (300) feet shall be measured from the hydrant along the Fire Department vehicle access road to the building.

F-412.3 Fire Hydrant Installation: All newly installed or relocated hydrants shall be installed so that distance from the curb facing to the center of the hydrant shall be no less than four (4) feet and no more than six (6) feet. The four-inch opening must face the street and a minimum of an eighteen-inch clearance from grade

to the bottom of the lowest hose connection must be maintained.

412.3.1 Exceptions: Exceptions to the above rules may be granted by the Fire Official or his or her designated representative.

412.4 Water Main Requirements: All new water mains installed shall be looped or cross connected so that they may be fed from two (2) different locations.

412.4.1 Exceptions: Deadend streets, cul de sac streets, or streets which terminate at a cross street which is not serviced with water may be exempt from this Section if approved by the Fire Official.

ARTICLE 7. APPLICATION OF FLAMMABLE FINISHES

F-700.1.1 Spray Application: "Spray application" means the application of flammable or combustible materials when applied as a spray by compressed air, airless or hydraulic atomization, steam, electrostatic methods, or by any other means in continuous or intermittent processes.

ARTICLE 14. OVENS AND FURNACES

F-1401.2 Fuel Oil: The grade of fuel oil used in a burner shall be that for which the burner has been tested and approved and as specified by the manufacturer.

ARTICLE 16. SERVICE STATIONS AND GARAGES

F-1601.1 through F-1605.1 modified herein under Section F-2800.1 through F-2804.9.11.3.

ARTICLE 26. EXPLOSIVES, AMMUNITION AND BLASTING AGENTS

F-2600.1 Scope: The equipment, processes and operations involving the manufacture, possession, storage, sale, transportation and use of explosives and blasting agents shall comply with Act. No. 202 of the Public Acts of 1970, State of Michigan, being Section 29.41 et seq. of the Michigan Compiled Laws (MSA 4.559(41) et seq.) and the applicable requirements of this Code

FIRE PREVENTION BUREAU FILE REPORT

Water the second of the second

DATE 16~19-99	INSPECTOR T. Jensen
ADDRESS 8,51 Alpine	
TENANT	
CONSTRUCTION SPRINKT PRE-PLAN REVIEW INSPECTION PLAN REVIEW INSPECTION TEMPOPARY USE & OCCUPANCY TEMPOPARY USE & OCCUPANCY TEMPOPARY USE & OCCUPANCY NOTES	COMPLAINT AGST'S COMPLAINT OTEER AGST'S COMPLAINT OTER AGST'S COMPLAI
- Extention Cords Through o	at.
- Smoke Detector improper	ly hocated
· No Smake Detector in BAC	k Bedrum
Peeling PAINT	
- Missing Plaster	
NoTI- working out Lets	
I TAlked with duAnitA	Williams OF Houseing And told
	house And She indecated That There
Are orders on The house Already.	
BED Propertys	1186 144 THAVE BOXG
DAVE Stickney *	Moline M: 49335
Bruce Jager	
792-6736	
877-4834	

GRAND PAPIDS FIRE PREVENTION INSPECTION REPORT

•		DATE 7-12-90
Buch NESS N	AME NORTH ENO	TRANS PHONE
Dustrocc	802 ALPING, NI	w
+ acress	DAVID CHE	RO
OM NEW IN OIS	DAVID SHE	
	· · · · · · · · · · · · · · · · · · ·	CITY LICENCE YELL DUPLAYED
GARAGE	Booy Shop_	Chiq Licence The Description
	8	
SPRIAY BOOT	-HH	SPRINKLER SYSTEM
FIDE EXTING	WISHERS 3-90	MOUNTED VES
Mane of	EGRESS BH	EXIT SIGNS OH
Francis or	quids	PROPER STORAGE
PLAM/COMB LI	quico	
	11/1	
. PROPER RAG	STORAGE VES	C: 252 1/6 C.
COMPLESSED	TANKS 1/2.5	Secures 1/25
		and the second of the second o
Electrical_	APPEARI OK	
HEATING.	APPIEARS OK	
112/1/70		
	a ga	
COMMENTS_		
,		
	· .	. Carrie Decompositions
<u>-</u>		Spraying Regulations
		PROUIDED
	A	
		LETTER SENT
INSPECTOR.		

MICHIGAN STATE POLICE FIRE MARSHAL DIVISION

UST PROGRAM SUSPECTED CONFIRMED RELEASE Sec. 280.50/280.61 EPA Rules

Person Reporting Release Td Sheped
Company/Contractor Name
Location of Release
Facility Name North End transmission
Address 802 Alpine
Address 802 Alpine City/State/Zip Grand Rapids, 49504
County Kent Township
Company Mailing Address
Address Same
City/State/Zip
Contact Person Phone # 616/454-3097
Have you notified
DNR: Yes No Local Fire Department: Yes No
Release Information
Type of tank Capacity
Substance Released
Site Condition (Circle reason for believing a leak may have/has occurred)
Presence of product/vapors in soil/basements/failed tank tightness test
Unusual operating conditions (sudden loss of product/inventory records)
other Site ass. showed contamination
Copy of this form sent to: DNR FD (info only) DMB
Financial Responsibility Letter Mailed Date Received (confirmed release only)
Person Receiving Information Date/Time Received 10/90 1k
(10/89) ****INTERNAL USE ONLY**** WINDERNAL USE ONLY****
Person Receiving Information Date/Time Received
₩

MICHIGAN STATE POLICE FIRE HARSHAL DIVISION UST PROGRAY NOTIFICATION OF USTRE-OVALYOLOGIRE Sec. 280.71(a) EPA HUTES

Date Received 12689 Person Receiving Information Mohr
Hethod of Notification: Phone_Letter X (attach to file copy of form) Name of Person Giving Information: Darriett Visser
Location of Tarks
company Name North End Transmission
Address 802 alpine aue NW
city/state/zip Grand Rapido 49504
county_dentTownship
Contect Person Edward Sherd Phone 6/6/454-309
Company Mailing Address
Tenk Information
Date Tanks are to be Removed 12390
Number Removed Capacity : 2 3
5 5
Company Doing Removal
Neme
Address
City/State/Zip
Copy of this Form Sent To: DMR (field) FD (information only)
Date Sent
Follow-Up Letter Sent (owner/operator): Date

INTERNAL USE ONLY

pd 275.00

APPLICATION FOR INSTALLATION, ESTABLISHMENT, RELOCATION REMODELING AND/OR REMOVAL OF A FILLING STATION

, RELOCATION, recipt +1 0983

The undersigned hereby makes application for permission to Install-Remove (delete one)

Public Capalina Filling State			
Private Gasoline Filling Stati		N. H. ODLIND D	IDTDG AIT (ARA)
NORTH END TRANSMISS	ION 802 ALPINE AVE	. N.W. GRAND R	APIDS, MI. 49504
Gasoline Tanks Capac	ity	New	_ Used
Gasoline Pumps	*	New	Used
Fuel Oil Tanks Capac	ity	New_	Used
Fuel Oil Pumps	į	New	Used
Additional InformationREMOVAL OF (1) 6000 GALLON U/G TANK			
Date DEC. 26, L989	•	ISSER V 260-	
	Phone No. 6L6-45		
RECOMMENDED:			
ZONING OFFICIAL COMMON (M. 5)	WWW :		
INSPECTION SERVICES John John	Man 1-4-90		
CITY ENGINEER OR Trail			
FIRE CHIEF BC Stycki FHI	1-22	2-90	
TRANSPORTATION Julius	1-22	-90	
APPROVED: SAMDE	A L. WEIGHT 354	c -26 -90	
CITY CLERK GRAID RA	TIME OF THE		

This application must be filed with the City Clerk, accompanied by the Inspection and License Fee for the installation, or removal and a sketch or plan showing the proposed location and shall indicate distances between proposed construction and property lines and right-of-way.

71d 275.00

APPLICATION FOR INSTALLATION, ESTABLISHMENT, RELOCATI REMODELING AND/OR REMOVAL OF A FILLING STATION

1 ...

The undersigned hereby makes application for permission to Install-Remove (delete one)

Public	soline Filling	Station at	<u>.</u>		
Private		RANSMISSION		T N U CDAN	ND RAPIDS, MI. 49504
* .	NOMIN DAD IF	CANOLIDOTOR	OOZ ADITNE AVI	J. H.W. GRAP	TD RAI 103, N1. 49304
Gasoline Tanks	·	Capacity_		New	Useď
Gasoline Pumps	-			New	Used
Fuel Oil Tanks	-	Capacity_		New	Used
Fuel Oil Pumps			,	New	Used
Additional Inf	ormation) 6000 GALLON U/G	TANK			
Date <u>DEC. 20</u>	5, L989	By Addr	HARRIET L.	VISSER V 2	& SERVICE INC. 260-298-537-290 N.W. G.R. MI. 4950
RECOMMENDED:		. ,			1
ZONING OFFICIA	L Countal	1. Dunios	\mathcal{L}		*
INSPECTION SER	VICES John	Jalenson	1-4-90		
CITY ENGINEER	DR. Joel	/			
FIRE CHIEF	D. Sbychi	FHI	1-22	2-90	
TRANSPORTATION				-	
APPROVED:					
CITY CLERK					

This application must be filed with the City Clerk, accompanied by the Inspection and License Fee for the installation, or removal and a sketch or plan showing the proposed location and shall indicate distances between proposed construction and property lines and right-of-way.

North END Transmission 802 AlPine N.W. Over head doors (3) CHAIN LINK 28' APProx. Fence ON property Line 6000 GAllon ESTIMATED LOC.

SeveNTA

GRAND RAPIDS FIRE PREVENTION INSPECTION REPORT

DATE 7/19/88
BUSINESS NAME North End Transmission PHONE 454-3097
Aldress 802 Alpine Avenue N.W.
OWNER/MGR David Sherd
GARAGE_X BODY Shop CITY LICENCE YES DUPLAYEDINES
SPRAY BOOTH SPRINKLER SYSTEM_NO
FIRE EXTINGUISHERS YOS MOUNTED YES
MEANS OF EGRESS VOS EXIT SIGNS NO
FLAM/COMB LIQUIDS PROPER STORAGE
PLAM/COMB CIQUICS
PROPER RAG STORAGE YES
COMPRESSED TANKS YES SECURED YES
Electrical Appears to be in Compliance HEATING Appears to be in Compliance
HEATING Appear to be in Complexed
COMMENTS
Spraying Regulations
PROUIDED MA
1.41
INSPECTOR_ B. Tuto LETTER SENT_ N.A.
de compliace 7/19/88

PJ. \$ 27500 B

APPLICATION FOR INSTALLATION, ESTABLISHMENT, RELOCATION, 5-2-86 REMODELING AND/OR REMOVAL OF A FILLING STATION FILLING STATION

RELOCATION, 2228 RECEIVE DI JUN 20 1986

The undersigned hereby makes application for permission to Install Remove

			DONE	·
Public Private		ng Station at 1/0	1	
	802 A	pine Nu	1.	
Gasoline Ta	anks	Capacity	New	Used
Gasoline Pu	ımps		New	Used
Fuel Oil Ta	anks	Capacity	New	Used
Fuel Oil Pu	ımps		New	Used
Additional	Informationse	7-100 1-100	10 U/G TAN	
3TAXKS WER	e FOUND AND Re	moves 1-1000 2	-1500	
Date <u>5-2</u>	-86	Applicanț	North End	LANS MISSISM
	-			iNTENANCE (
*				my-fockroed a
*,			874-8833	
RECOMMENDED		. 1		
ZONING OFFI	CIAL COMUNIC	Letumos		и
INSPECTION :	services Ciff	and Bremer		ECEIVEM
CITY ENGINE	ER REJUBB	6-6-86	<i>U\</i>	IU)
FIRE CHIEF_	Konuld f	Men 5/211	186	MAY 21 1986
TRANSPORTAT	ION Lolent	The Charaki	6/17/86 BUR	EAU OF FIRE INSP.
APPROVED:	SANOR.	L. IVRIGHT		
CITY CLERK_	GRAND RAP	Och W. Cork Co. N. W. Co. MICH. 49503	\$6 	
This applica	stion must be fil	od with the 19503	011	

This application must be filed with the City Clerk, accompanied by the Inspection and License Fee for the installation, or removal and a sketch or plan showing the proposed location and shall indicate distances between proposed construction and property lines and right-of-way.





ISO 9001

Detroit 4080 West Eleven Mile 560 5th Street NW, Road

f: 877-884-6775 t: 248-336-9988

Berkley, MI 48072

Grand Rapids Suite 301 Grand Rapids, MI 49504

f: 877.884.6775 t: 616.285.8857

Lansing 3340 Ranger Road Lansing, MI 48906

f: 877-884-6775 t: 517-321-3331

VIA FACSIMILE 616-632-6892

December 29, 2014

FOIA Coordinator Kent County Health Department **Environmental Health Division** 700 Fuller Avenue NE. Grand Rapids, MI 49503 (616) 632-6900

Dear FOIA Coordinator:

Please accept this request for copies of information in your files relative to the following site:

802 Alpine Avenue NW, Grand Rapids (PID: 41-13-24-155-024)

Information we are interested in obtaining includes from the current or historic address:

- Results of any water quality testing conducted on the property
- Individual files that are available for the site which may include records of health department inspections, violations, environmental concerns or issues, etc. If you have historical information which appears to correspond with the general property area, we would appreciate that information as well.
- Any files regarding USTs or other storage tanks on the property.
- Water well and/or septic system permits/registrations for the property
- Results of any soil borings conducted on the property.

We would appreciate any assistance in receiving information as soon as possible, due to our scheduled deadlines. Information can be sent to my attention via fax at 877-884-6775, emailed to sorensen@pmenv.com, or mailed to the address below. Please call me at 616-222-1777 if you have any questions or concerns regarding this request.


Sincerely,

PM Environmental, Inc.

Lindsey Sorensen Staff Researcher

820 Monroe Avenue NW, Suite 433

Grand Rapids, MI 49503





ISO 9001 REGISTERED

Lansing

3340 Ranger Road Lansing, MI 48906

f: 877-884-6775 t: 517-321-3331

Detroit

4080 W. 11 Mile Rd Berkley, MI 48072

f: 877-884-6775 t: 248-336-9988 560 5th Street NW, Suite 301 Grand Rapids, MI 49504

f: 877.884.6775 t: 616.285.8857

Grand Rapids

VIA FASICIMILE (616) 456-4569

December 29, 2014

City Attorney's Office Elizabeth White, Deputy City Attorney 300 Monroe Avenue NW Grand Rapids, MI 49503-2206

Please accept this as a Freedom of Information Act (FOIA) request for information on the following property;

802 Alpine Avenue NW, Grand Rapids

Information we are interested in obtaining includes;

Water & Sewer Services Files

- Date in which property originally tapped into water & sewer utilities
- Year in which the original water & sewer utility mains were available in the vicinity of the property
- If sanitary & storm sewer systems are combines or separate.

We would appreciate any assistance in receiving information in a timely manner, due to our scheduled deadlines. Please call me at 616-222-1777 if you have any questions or concerns regarding this request. I can also be reached by email at Sorensen@pmenv.com or by fax at 877-884-6775.

Sincerely,

PM Environmental, Inc.

dundsey Derensen

Lindsey Sorensen Staff Consultant

560 5th Street NW, Suite 301

Grand Rapids, MI 49504

EM/-4093Permission is hereby granted by the 3 6

DEPARTMENT OF PUBLIC SERVICE GRAND RAPIDS, MICHIGAN


OFFICE COPY

FORM 564			F 16697		
CONTRACTORS		Contract to the			
Henry Prin	nce Plbg	5 •			
owner Ed Scherd					
ADDRESS 763 Seven	th, N.	+. 80	200	bine	2 N.W
PLUMBING:	Sewer	Water X	Inspection /	Repair in Yard	PRICE \$ 3.00
TAPPING:	Size				
METER:	3/4 X	5/8	Installation	Sale	5.00
Walks, Drives and Areawo	ys		and an arrangement of the second		
METER BAR ISSUED	Yes	No			
UNMETERED WATER FOR 120 DAYS	Yes .	No	WHEN NOT SET METER I		20.00
Date 6/15/	/67		тот	A L ->	S-2-000
					800
Plumber			Roll No. or Code	No.	
STATE BRIEFLY WORK 1	TO BE DONE:			773	6697
Repair wat	er serv	ice -	Extend		
				Robert DIRECTOR OF INS	Boelens SPECTION SERVICES
				Robert DIRECTOR OF INS	Boelens SPECTION SERVICES
Owner			_	DIRECTOR OF IN	SPECTION SERVICES
Owner Address				DIRECTOR OF IN	Boelens SPECTION SERVICES

Permission is hereby granted by the

DEPARTMENT OF PUBLIC SERVICE GRAND RAPIDS, MICHIGAN

ONTRACTORS	man Diha				
Henry Pri DWNER Ed Scherd					
763 Seven	ith, N. W	. 80	200	bene	nn.
PLUMBING:	Sewer	Water	Inspection	Repair in Yard	PRICE \$
TAPPING:	Size				
METER:	Size		Installation	Sale	
Walks, Drives and Area	ways				
METER BAR ISSUED	Yes	No			
UNMETERED WATER FOR 120 DAYS	Yes X	No		T CHARGED, IMMEDIATELY	10.00
6/16/6"	7		тот	AL ->	\$ 10.00
Plumber			Roll No. or Code	No.	
STATE BRIEFLY WOR	K TO BE DONE:			F]	6713
Repair wa	ater serv	rice =	Extend w	ater se	rvice.
				DIRECTOR OF IN	Boelens SPECTION SERVICES
				mh	





Lansing

3340 Ranger Road Lansing, MI 48906

f: 877-884-6775 t: 517-321-3331 Detroit 4080 W. 11 Mile

t: 248-336-9988

4080 W. 11 Mile Rd Berkley, MI 48072 f: 877-884-6775 560 5th Street NW, Suite 301 Grand Rapids, MI 49504

Grand Rapids

f: 877.884.6775 t: 616.285.8857

ISO 9001 REGISTERED

VIA EMAIL: <u>LUCASJ@michigan.gov</u>

Cc: Sorensen@pmenv.com

December 29, 2014

Jim Lucas, FOIA Coordinator
Fire Services, Aboveground/Underground Storage Tanks
Department of Licensing and Regulatory Affairs

Jim Lucas:

Please accept this Freedom of Information Act request for file information for the following site(s) located in **Kent County**:

North End Transmissions Service; 802 Alpine Avenue NW, Grand Rapids (FID: 00013761)

Please email available file information to Sorensen@pmenv.com.

Please contact me at 616-222-1777 if you have any questions or concerns. Thank you.

Sincerely,


PM Environmental, Inc.,

Lindsey Sorensen Staff Researcher 560 5th Street NW, Suite 301 Grand Rapids, MI 49504

PME Project Number: 03-4006-0 BH (1/9/15)

Appendix C







14641 16th Ave. P.O. Box 118 Marne, MI 49435-0118

REPORT OF UST CLOSURE
AND
INITIAL ABATEMENT MEASURES
NORTH END TRANSMISSION
802 ALPINE AVE.
GRAND RAPIDS, MICHIGAN

PREPARED FOR:

NORTH GARFIELD EXCAVATING 2240 BYRON CENTER RD. WYOMING, MICHIGAN 49509

PREPARED BY:

SUPERIOR ENVIRONMENTAL CORP.
BOX 118
MARNE, MICHIGAN 49435

JAMES R. QUINCE, CPG PROJECT MANAGER/HYDROGEOLOGIST

> PROJECT NO. 19065 FEBRUARY 12, 1990

REPORT OF UST CLOSURE AND INITIAL ABATEMENT MEASURES NORTH END TRANSMISSION GRAND RAPIDS, MICHIGAN PROJECT # 19065 FEBRUARY 12, 1990

Introduction

Superior Environmental Corp. (Superior) was requested by North Garfield Excavating (NGE) to perform a site assessment at North End Transmission in Grand Rapids, Michigan. The assessment was performed as part of an underground storage tank system (UST) closure as required under Federal Regulations (40CFR, 280.72). The initial abatement activities were performed pursuant to Michigan Law (Act No. 478, P.A. of 1988 as amended).

The closure was achieved by excavation, removal and appropriate disposal of one underground storage tank along with the associated piping, venting, and a limited amount of contaminated soil. The tank, constructed of steel, was formerly utilized as storage for waste transmission oil. The tank was originally installed for gasoline storage.

Scope of Work

The scope of work requested of and provided by Superior included the following:

- -observation and documentation of excavation and removal of the tanks and soils.
- -visual inspection of the tanks upon removal
- -soil screening with an organic vapor monitor
- -soil sample collection and analysis
- -preparation of a report of on-site activities and analytical results

Site Description

The site is located at 802 Alpine Ave. in Grand Rapids, Michigan. The surrounding area consists of private housing as well as some commercial properties. The predominant feature at the site is a cement block building at the corner of Alpine and 7th street. The building is surrounded by a concrete parking area. A 6,000-gallon tank was located beneath the concrete on the south side of the building.



Page 2, N.E. Transmission, Project No. 19065, February 12, 1990

Closure Activities

The first tank (T1) was excavated by NGE utilizing a Komatsu hydraulic excavator. The tank was buried beneath the gravel parking lot with its axis oriented east to west. The north side of the tank was buried 19 feet from the building (see attached UST closure form).

During excavation activities, the soils encountered consisted of sand to 10 feet followed by clay and rocks. Screening of soil around T1 for volatile organic compounds, yielded up to 278 parts per million (PPM) using a Thermoenvironmental 580A Photoionization Detector (PID). Soil was screened with the PID using head-space screening (see protocol for head-space screening method, attached). No detections were observed on the PID in the soil that was removed from depths less than 8 feet (depth to base of the tank). Contaminated soils, identified by PID, were staged next to the excavation pending disposal at an approved type II landfill.

The tanks were removed and visually inspected for corrosion, holes or signs of a release. The tank was observed to leak some waste oil as it was being removed. During inspection severe corrosion was noted as well as a 1-inch diameter hole in the bottom of the tank (west end) and a 1/4-inch hole in the bottom (east end). Heavily stained soil was observed below the tank as well high readings on the PID (up to 278 PPM).

Contaminated soils, identified by PID, were removed until non-detect levels were observed. Two samples (T1-A & T1-B) were obtained from the base of the excavation. The samples were taken from the base of the excavation, approximately 10-12 feet below ground level (4 feet below the former tank base). The samples were labeled, recorded on a chain of custody form, and immediately preserved in an insulated container at 40°F. The samples were submitted to an independant analytical laboratory for EPA Method 601/602 and total petroleum hydrocarbons (TPH) analysis.

Initial Abatement Measures

Detectable levels of volatile organic vapors were identified in soil at the site. North End Transmission took specific measures beyond reporting the release to the Michigan State Police Fire Marshal Division (MSPFMD) as required by the Leaking Underground Storage Tank Act. These measures were as follows:

1) Free Product Removal

Waste oil was pumped from the tank prior to removal activities. During visual inspection of the tank exterior following removal, two holes were observed.



Page 3, N.E. Transmission, Project No. 19065, February 12, 1990

2) Prevention of Further Migration of Contamination

Contaminated soils were removed from the tank excavation and staged on-site awaiting appropriate disposal. Contaminated soil was removed until all visually stained soil was removed and non-detect levels were obtained on the PID.

3) Monitoring and/or Mitigating Fire and Safety Hazards

The site activities were monitored by Superior Health and Safety Coordinator, Mr. Mike Kendall. No Hazards, beyond those normally anticipated, were identified during site activities and none required abatement.

4) Contaminated Soil Remediation

Approximately 100 cubic yards of soil were excavated and staged on-site. This soil had concentrations of volatile organic vapors of up to 278 ppm as indicated by PID screening. A composite soil sample (listed as T-1 on analytical) of the spoils was obtained and sent to an independent analytical lab and analyzed as required to permit entry to a type II landfill (see results, attached).

5) Free Product

Free product outside the tank was identified during the closure. The free product was immediately removed by excavation. Being that it was waste oil the product was easily recovered. All stained soil observed was subsequently removed, as well as soil that exhibited volatile organic vapor readings on the PID.

6) Soil and Ground Water Sampling

Soil samples (results attached) were collected and analyzed for EPA 601/602 and TPH parameters. Ground water was not encountered during the excavation activities.

Analytical Results

The analyses (attached) indicate that detectable levels of benzene, toluene, ethylbenzene and xylenes remain in the soils adjacent to the former tank location. These levels exist above the allowable concentrations of 10 parts per billion as defined by MDNR guidelines. Furthermore, additional remediation/investigation will need to be undertaken to comply with Act 478. This includes an initial site characterization and work plan due to the Michigan Department of Natural Resources within 45 days of the reported release date.



PROTOCOL FOR HEAD-SPACE SCREENING FOR VOLATILE ORGANIC COMPOUNDS

On-site screening of soils for volatile organic compounds (V.O.C.) is a powerful tool for the environmental investigator attempting to optimize the acquisition of data and requisite expenditure of clients funds. Because many variables are involved in the process, Superior Environmental Corp. has developed an analytical protocol to minimize the influence of these variables.

The detection component of the technique is accomplished using a Thermo-Environmental Model 580-A (or comparable brand) organic vapor monitor (OVM). The OVM has a small diaphragm pump which pulls air through a 1/4" I.D. inlet tube. The air passes through a detection chamber where it is subjected to bombardment by photons which are emitted from an 11.2 electron volt (eV) ultraviolet lamp. The organic molecules which have sufficiently low photoionization potentials are ionized by this energy source. The liberated ions are collected, forming a small current which is amplified and eventually measured by a potentiometric recorder. The signal is then converted by an internal microprocessor to a digital reading in parts per million.

Through this collection of gas with the pump and ionization it becomes possible to quantify the volatile organic compounds present in a particular volume of gas.

The operation of the OVM is largely independent of sampling techniques. To insure optimal VOC screening, the quantity of sample, temperature, flow rate and head space volume are kept as constant as possible. The OVM is calibrated daily by sending pure isobutylene in known concentrations through the detector in order to assure quality control and minimize error through instrument drift.

A step by step description of the field method follows:

PORTABLE PHOTO-IONIZATION DETECTOR FIELD HEAD-SPACE SCREENING FOR VOLATILE ORGANIC COMPOUNDS

- Place the soil sample in a 16 oz mason jar with a "ringtype" two part lid until approximately half filled.
- 2) Place a piece of aluminum foil over the top of the jar and seal the lid with:
 - a) both parts of the lid if the samples are going to be held for later analysis or,
 - b) with just the ring portion if analysis is to be performed immediately.
- The sample can be equilibrated with either the ambient air temperature or a water bath as long as the temperature of the medium (air or water) is constant for all of the samples that are going to be compared with one another. (A waterbath should be used whenever possible.)
- Place the sample in the water bath (or somewhere out of direct sunlight if ambient air is used) for approximately 20 minutes. If sample still has two-part lid remove the lid without disturbing the foil and replace the ring prior to placing in water bath.
- 5) Record the base line reading on the P.I.D.
- Remove sample and pierce the foil with the PID probe, making as small a hole as possible. Hold the probe as close to the center of the head space as possible and watch the PID meter/readout and hold the probe until the reading peaks.
- 7) Remove the probe and record the highest meter reading.
- 8) Return the sample to the spoils pile or reseal and place into storage as appropriate.

TABLE 1

Ionization Potentials for Selected Molecules

Compound	<pre>I.P. (eV)</pre>
Diethylesulfide	8.43
M-Xylene	8.56
Dimethyl Sulfide	8.68
Toluene	8.82
Cyclohexane	8.94
1, 3 - Butadiene	9.07
Benzene	9.25
Pyridine	9.32
TetrachloroEthylene	9.32
Trichloroethylene	9.45
Allyl Alcohol	9.67
Acetone	9.69
Methyl Ethyl Ketone	9.53
Tetrahydrofuran	9.54
Cyclohexene	9.88
Vinyl Chloride	9.95
Carbon Disulfide	10.08
Acrolein	10.10
Hexane	10.17
Ethyl Alcohol	10.48
Ethylene	10.51
Choloroethane	10.98
1, 1 - Dichloroethane	11.06
	11.12
T=1, 2 - Dichloroethene	11.28
Methylene Chloride	11.20



14641 16th Ave. P.O. Box 118 Marne, MI 49435-0118

HIST CLOSHRE/INSPECTION

ool chooding	THOIDCITON
Job#	:e: <u>1-23-90</u>
Job Name: North end Transmission Cl.	Lent:
UST Owner: Ed Shered Own	ner Phone:
site Add.: 802 Alpine Ave.	GRAND Rapids, Michigan
Owner Add:	7
Regulatory Agency/Rep.: NONE	PRESENT
Superior Representative: Mr. Mic	hael Kennall
Site Sketch: include North Arrow	& Approx. Distances Measurements

North End Transmission

AND AR€	UEWAY PARKIN FA	u 6		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	-24' 28'			} →	10'>
7 TH Street									
INFO	RMATION			•	SITE	COND	ITIOI	NS	
SIZE	FORMER CONTNT	COATING	CONST.	CORR.	ODOR	WATER PRES.	PID RD.	PROD PRES	RELEA
6,000	H	\mathbb{B}	2	Н Х	Y	7	4278	N	Υ
					·				
	-					asono es te			
									•
	INFO	7 TH INFORMATION SIZE FORMER GAL CONTNT	7 TH Street INFORMATION SIZE FORMER COATING GAL CONTNT 6,000 H B	7 TH Street INFORMATION SIZE FORMER COATING CONST. GAL. CONTNT GOOD H B S	7 TH Street INFORMATION SIZE FORMER COATING CONST. CORR. GAL CONTNT 6,000 H B S H*	TH Street INFORMATION SITE SIZE FORMER COATING CONST. CORR. ODOR GAL CONTNT LOOO H B S H* Y	TH Street INFORMATION SITE COND. SIZE FORMER COATING CONST. CORR. ODOR WATER PRES. 6AL. CONTNT B S H* Y N	7 TH Street INFORMATION SITE CONDITION SIZE FORMER COATING CONST. CORR. ODOR WATER PID PRES. RD. 6AL. CONTNT B S H* Y N 6278	TH Street INFORMATION SIZE FORMER COATING CONST. CORR. ODOR WATER PID PROD PRES. RD. PRES 6000 H B S H Y Y N 6278 N

See reverse for comments/key



Brighton Analytical Inc.

1576 Alloy Parkway

Phone (313) 887-6364

Highland, Michigan 48031

VOLATILE ORGANIC ANALYSIS

DATE: February 12, 1990

PROJECT: Superior - #19065 N End Transmission

SAMPLE: T1-B 1/24/90

COMPOUND	UNITS	CONC.	DETECTION LIMIT
_	(ppb)		5
Bromomethane	ug/kg	u	5
Bromodichloromethane	ug/kg	u	
Bromoform	ug/kg	u	5 5
Carbon Tetrachloride	ug/kg	u , ,	5 5
Chlorobenzene	ug/kg	t i	5
Chlorocthane	ug/kg	u	5
2-Chloroethyl Vinyl Ether	ug/kg	u	5
Chloroform	ug/kg	น	5
Chloromethane	ug/kg	u	5
Dibromochloromethane	ug/kg	u	5 5
1,1-Dichloroethane	ug/kg	\mathbf{u}	5
1,2-Dichloroethane	ug/kg	u	5
1,1-Dichloroethene	ug/kg	u	5 5
Trans-1,2-Dichloroethene	ug/kg	u	
1,2-Dichloropropane .	ug/kg	u	5
Cis-1,3-Dichlorpropene	ug/kg	u	5
Trans-1,3-Dichloropropens	ug/kg	u	5
Methylene Chloride	ug/kg	u	5
1,1,2,2-Tetrachloroethane	ug/kg	\mathbf{u}	5
Tetrachloroethene	ug/kg	u	5
1,1,1-Trichloroethane	ug/kg	u	5
1,1,2-Trichlorgethane	ug/kg	u	5
Trichloroethene	ug/kg	u	5
Trichlorofluoromethane	ug/kg	. u	5
Vinyl Chloride	ug/kg	u	5
Benzene	ug/kg	u	5
Toluene	ug/kg	ŭ	5 5
Ethyl Benzene	ug/kg	u	5
Xylenes	ug/kg	42	5
y V V	45/ NB	74	ΰ

NOTE: u = NOT detected at this detection limit

K = Present at a level BELOW detection limit



Brighton Analytical Inc.

1576 Alloy Parkway

Phone (313) 887-6364

Highland, Michigan 48031

VOLATILE ORGANIC ANALYSIS

DATE: February 12, 1990

PROJECT: Superior - #19065 N End Transmission

SAMPLE: TI-A 1/24/90

COMPOUND	UNITS	CONC.	DETECTION LIMIT
	(ppb)		
Bromomethane	ug/kg	u	5
Bromodichloromethane	ug/kg	u	5
Bromoform	ug/kg	u	5
Carbon Tetrachloride	ug/kg	u	5
Chlorobenzene	ug/kg	u	5
Chloroethane	ug/kg	u	5
2-Chloroethyl Vinyl Ether	ug/kg	u .	5
Chloroform	ug/kg	u	5
Chloromethane	ug/kg	u	5
Dibromochloromethane	ug/kg	tī.	5 5
1,1-Dichloroethane	ug/kg	u	5
1,2-Dichloroethane	ug/kg	u	5 5
1,1-Dichloroethene	ug/kg	12	5
Trans-1,2-Dichloroethene	ug/kg	u	5
1,2-Dichloropropane	ug/kg	u	5
Cis-1,3-Dichlorpropene	ug/kg	\mathbf{u}	5
Trans-1,3-Dichloropropene	ug/kg	u	5
Methylene Chloride	ug/kg	u	5
1,1,2,2-Tetrachloroethane	ug/kg	u	5
Tetrachloroethene	ug/kg	u	5
1,1,1-Trichloroethane	ug/kg	u	5
1,1,2-Trichloroethane	ug/kg	u	5
Trichloroethene	ug/kg	\cdot u	5
Trichlorofluoromethane	ug/kg	u	5 5
Vinyl Chloride	ug/kg	u	
Benzene	ug/kg	10	5
Toluene	ug/kg	41	5
Ethyl Benzene	ug/kg	15	5 5
Xylenes	ug/kg	540	5

NOTE: u = NOT detected at this detection limit

K = Present at a level BELOW detection limit



Brighton Analytical Inc.

1576 Alloy Parkway

Phone (313) 887-6364 DATA SUMMARY SHEET Highland, Michigan 48031

DATE: January 27, 1990

PROJECT: Superior Environmental - #19065 N. E. Transmission

		T-1
PARAMETER	UNITS	1/23
Benzene	ug/kg	<2000
Toluene	ug/kg	19000
Ethyl Benzene	ug/kg	<2000
Xylenes	ug/kg	100000
Total Petroleum Hydrocarbons	mg/kg	4000
Flashpoint	٠F	130°

CONTINUE ON REVERSE SIDE

EDWARD

D. SHERD

OWNER

NORTH GARFIELD EXCAVATING 2240 BYRON CENTER RD WYOMING, MI 49509

₩...?



RON FORTIN PRESIDENT (616) 532-6550

JOB NO.		MID or MIG NO.			
#013 NAME OF OWNE	200000 ; ER: North End Tr	N/A PRODUCT DESTINATION			
Ed Shered			None		
ADDRESS:	Grand Rapids (616) 454-30	TANK DESTINATION Grand Rapids Lot			
1130 Arianna St NW			LAB ANALYSIS NO. OF SAMPLES ***		
ADDRESS: PHONE:	Grand Rapids, (616) 459-8254	SOLID/LIQUID '			
LOCATION OF TANK: 802 Alpine			TANK SIZE: 6,000 /		
Grand Rapids, MI			NO. OF TANKS: 1		
HAZARDOUS NON-HAZARDOU ++ +xxx+					
ADDITIONAL COMMENTS: Tank was removed by North Garfield Excavating, Inc.					
	OF DISMANTLEMENT D SIGNATURE-	RECYCLED YES NO +XXX ++	PICK UP DATE: 01-23-90		
RONALD A.	FORTIN	· · · · · · · · · · · · · · · · · · ·	- P		
PRESIDENT	ten	PRODUCT WASTE TO ENERGY YES NO ++ None	DISMANTLEMENT DATE: 02-09-90		

Occupational Health and Safety, Energy Management and Environmental Consultants



REPORT OF FINDINGS

SITE INVESTIGATION

NORTH END TRANSMISSION 802 ALPINE AVENUE N.W. GRAND RAPIDS, MICHIGAN 49504

> DECEMBER, 1990 PROJECT NO. 2139

PREPARED FOR:

MR. DAVID SHERD 802 ALPINE AVENUE N.W. GRAND RAPIDS, MI 49504

PREPARED BY:

JEWE L.) HUMB.

ALDERINK AND ASSOCIATES INC.

3221 3-MILE ROAD N.W.

GRAND RAPIDS, MI 49504

Associates, Inc.

Occupational Health and Safety,
Energy Management and Environmental Consultants

REPORT OF FINDINGS

JAN 8 1991

NORTH END TRANSMISSION



INTRODUCTION

Alderink and Associates, Inc., of Grand Rapids, Michigan conducted a site investigation at North End Transmission on November 21 and 28, 1990. The investigation was performed in response to soil contamination identified during the closure of an underground storage tank located at the site. The scope of the investigation was based upon information provided in the "Report of UST Closure and Initial Abatement Measures" dated February 12, 1990 and prepared by Superior Environmental Corp.

DISCUSSION

Site Description

The site is located at 802 Alpine Avenue in Grand Rapids, on the northeast corner of Alpine Avenue and Seventh Street. The surrounding area consists predominantly of residential houses, with some commercial businesses along Alpine Ave. According to Superior's report, a 6000 gallon waste oil Underground Storage Tank (UST) was removed from the south side of the existing building within a parking lot covered with asphalt and concrete. The site is serviced by the City of Grand Rapids municipalities (i.e. water, sanitary).

Field Investigation

As indicated on Figure 1, a series of five (5) soil borings were drilled at locations necessary to encompass the area from which the underground storage tank was removed. The study area was bound on the north by the existing building structure, on the east by a chain link fence, on the south by Seventh Street and on the west by Alpine Avenue. A number of buried utilities were suspected to exist along the south and west sides of the site. In addition, overhead electrical power lines were present along the south and west sides of the site, limiting the lateral extent of the drilling activities.

In general, the natural soils on the site consisted of a brown fine to medium sand grading to a gray silty clay at a depth between 10 and 12 feet. Limestone bedrock was encountered at a depth of 12 feet. No groundwater was encountered in the borings on the site. The soil boring logs have been included in Appendix B.

3221 - 3 Mile Rd., N.W. • Grand Rapids, Michigan 49504 • (616) 791-0730

NORTH END TRANSMISSION SITE INVESTIGATION Page 2

H-NU Field Readings

An H-NU PhotoIonization Detector (PID), Model PI-101, was used to field screen all soils immediately upon removing the samples from the ground. The H-NU device is a direct reading instrument capable of detecting total Volatile Organic Compounds (VOC) in concentrations ranging from 0.1 to 2000 parts per million (ppm). The results of H-NU field screening activities can be found along the right hand column of the boring log in Appendix B.

The H-NU device did not indicate the presence of volatile organic compounds within any of the soil borings with the exception of Soil Boring #2. An H-NU reading of 40 ppm was detected in the soils at a depth between 10 and 12 feet in Soil Boring #2.

Decontamination Procedures

In order to eliminate the possibility of cross-contaminating samples and soil, all down-hole equipment was decontaminated using a high temperature, high pressure steam cleaner before and after each boring. A water temperature in excess of 230 degrees Fahrenheit was maintained during decontamination procedures. In addition, the split-spoon sampling devices were decontaminated with a solution of tri-sodium phosphate and rinsed with distilled water between each use.

Laboratory Results

A total of five (5) soil samples were collected and submitted to Prein and Newhof for laboratory analysis. The soil samples were analyzed for PolyNuclear Aromatic Hydrocarbons (PNA's) and purgeable aromatic hydrocarbons (Benzene, Toluene, Ethylbenzene, Xylene - BTEX).

As indicated on the laboratory results found in Appendix A, no detectable concentrations of PNA's or BTEX were identified in soil samples SB1, SB4 and SB5. Soil sample SB3 was found to contained 25 parts per billion of Xylenes. Soil sample SB2 was found to contain 100 ppb Ethylbenzene, 29 ppb Toluene, and 205 ppb Xylenes. No PNA constituents were detected in either SB2 or SB3.

Discussion of Results

The indicated concentrations of hydrocarbon contamination exceed the State's recommended clean-up guidelines established for a Type A site closure, P.A. Act 478 as amended (See Table I). However, the detected levels fall within the limits of a Type B site closure.

In review of the inital abatement measures conducted at the site as well as the results of this site investigation, it is evident that the most significantly impacted soils have been removed from the site. Only a trace (25 ppb) of Xylenes remain on the west

NORTH END TRANSMISSION SITE INVESTIGATION Page 3

end of the site when compared to the original Xylene concentrations of 100,000 ppb existing prior to abatement (See sample T-1, Initial Abatement Report - Feb. 12, 1990).


The northern extent of the original excavation lies approximately 15 feet south of the facility wall. Soil boring SB2 was drilled approximately 7 feet south of the facility wall or 8 feet north of the north wall of the excavation. Laboratory analysis of SB2 indicates that contamination remains within the soils along the north side of the excavation. It is possible that the contamination extends to some point beneath the existing building structure, however this has not been confirmed.


Recommendations

Based on the field observations and laboratory results, the following are considered to be the most feasible options available.

- 1. Additional Soil Excavation: The soil along the north and west sides of the original excavation should be removed to a depth of approximately 12 feet. As shown on Figure 2, an estimated 395 cubic yards of soil may require removal. Concerns with undermining both the building structure and city utilities will need to be addressed prior to implementing any additional excavation at the site. Additional soil samples should be collected from the walls and, if neccessary, the floor of the resulting excavation.
- 2. Request for Type B Site Closure: The elimination of the source of contamination and the removal of the significantly impacted soils have minimized the extent of soil contamination at the site. Pathways such as groundwater, which act as a mechanism for the spread of contamination, do not exist at the site. The absence of contamination within the soil samples collected from the east, south and center of the former tank location as well as the evident decrease in the BTEX concentrations along the west and north sides of the site, and the presence of subsurface obstacles and hazards are all conditions characteristic of a Type B Site Closure.

It is recommended that the Michigan Department of Natural Resources, Environmental Response Division be contacted for review of the avalable information and approval of any such actions being considered. If Alderink and Associates, Inc. can be of any further assisitance to you in this matter, please do not hesitate to contact our office.





APPENDIX A

Results of Laboratory Analysis



H EDWARD PREIN PEIR LS

MICHAEL S BERGSTROM PE MICHAEL S FULLER PE PHILIP C GLUPKER PE

BASIL J ANDRESS JR RLS RICHARD J REIMBOLD PE LARPY D STEHOUWER PE

THOMAS NEWHOF PE WILSON D MIQUEEN PE

JAMES A COOK PE ROBERT J VANDER MALE PE ROBERT J REIMINK PE ARTHJR W BRINTNALL R LS REX A MILLIRON R LS SIDNEY P WAGNER JR PE

PREIN ENEWHOF, P.C.



ENGINEERS - SURVEYORS - ENVIRONMENTAL & SOILS LABORATORIES

3355 EVERGREEN DR., N.E. GRAND RAPIDS, MICHIGAN 49505 TELEPHONE (616) 364-84\$1 TELECOPIER (616) 364-6955 BRANCH OFFICE: 400 136th AVE., SUITE 517 HOLLAND, MICHIGAN 49424 TELEPHONE (616) 394-0200 TELECOPIER (616) 394-5914

RECEIVED DEC 1 2 1990

December 11,1990 90033L

Mr. Gene Gutting Alderink & Associates 3221 3 Mile Road NW Grand Rapids, Mi 49504

Re: Project: North End Trans Project = 2139 Chain of Custody = 002672 Samples received 11/28/90

LABORATORY RESULTS

Soil Sample =	SB 1 (10-12)	SB 2 (12)	SB 3 (10-12)	SB 4 (10-11)	SB 5 (10-12)
Lab Log =	5737	5708	5789	5740	5741
Method 610: Polynuclear	Aromatic	Hydroca	rbons, reporte	d as ug/K	<u>द</u>
Acenaphthene	ND**	ND	ND	ND	ND
Acenaphthylene	ND	ND	ND	ND	ND
Anthracene	ND	ND	ND	ND	ND
Benzo(a)anthracene	ND	ND	ND	ND	ND
Benzo(a)pyrene	ND	ND	ND	ND	ND
Benzo(b)fluoranthene &					
Benzo(k)fluoranthene (1)	ХD	ND	ND	ND	ND
Benzo(ghi)perylene	ND	ND	ND	ND	ND
Chrysene	ND	ND	ND	ND	ND
Dibenzo(a,h)anthracene &					
Indeno(1,2,3-cd)pyrene	ND	ND	ND	ND	ND
Fluoranthene	ND	ND	ND	ND	ND
Fluorene	ND	ND	ND	ND	ND
Naphthalene	ND	ND	ND	ND	ИD
Phenanthrene	ND	ND	ND	ND	ND
Pyrene	ND	ND	ND	ND	ND

(1) Compounds Coelute

ND** indicates none detected at or above the method detection limit of 300 ug/Kg

Alderink-2139 12/11/90 Page 2

Soil Sample =	SB 1 (10-12)	SB 2 (12)	SB 3 (10-12)	SB 4 (10-11)	SB 5 (10-12)
Lab Log =	5737	5738	5739	5740	5741
ETEX.reported as ug/Kg					
Benzene	ND≉	ND	ND	ND	ND
Ethylbenzene	ND	100	ND	CZ	ND
Toluene	ND	29	ND	ND	ND
<pre>Xylene isomers (o-,m-&p+)</pre>	ND	205	25	ND	ND

^{*}ND indicates none detected at or above the method detection limit of 10 ug/Kg

PREIN & NEWHOF
Environmental Laboratory

Jane Hoch

Laboratory Director

APPENDIX B

Soil Boring Logs

3221 - 3 Mile Rd. N.W. Grand Rapids, Michigan 49504 Ph (616) 791-0730 Fax (616) 791-4114

Vanture .	
PROJECT#_	2139
BORING #	SB 1
SHEET#	1 of 1

Project	North	End Transi	mission	Cont	ractor_	Ste	arns Dr	illing		
									ate End	
Location_		Rapids, M			J		Туре	Dia. No.		ndwater
Crew Chie	ef D. Da	verman	Rig Type	CME-	55		, , , ,			
	E. Gu		Plugging Rec			Casing	HSA	3 1/4"	During	none
	B <u>y</u>		Cuttings and		nix	Sample		2"	End	none
Flevation						Core			Seepa	
Datum			Depth Drilled	12.0'		Tube			Date	Depth
	Rain									
										
DEPTH FT	SAMPLE NO	REC. FT	PENETRATION (Blows per 6") ASTM D-1586	UNIF. SOIL CLASS		DESCRI	PTION		P	EMARKS
						6" cor	ocrete		H-I	NU Deflections (ppm)
2 -			N/A	SP	Brown F-M SAND. Trace fine gravel, damp.			ace fine		
·		8/24"								
6 -	_								none	
8 -				SP	Gra wet		y grave	elly SAND,	- 8.0 +/-ft	
10 -	SB 1	12/24"					- _		10.5 +/-ft. none	
10		:		CL	Gra	y silty CL	AY, dar	np		
12					adva	stone at 1: ncement r 3. at 12.0'				

3221 - 3 Mile Rd. N.W. Grand Rapids, Michigan 49504 Ph (616) 791-0730 Fax (616) 791-4114

PROJECT # 2139
BORING # SB 2
SHEET#1of1

-										_		
	Project	nission	Cont	ractor	Sto	arne D	rilling					
-	Client	Mr. Dav	vid Sherd							ate End	ate End November 21, 1990	
		Grand I							Dia. No.		ndwater	
ı	Crew Chie			Rig Type (CME-55			. ,,,,	_ 101. 110.			
J	Inspector			Plugging Rec			Casing	HSA	3 1/4"	During	none	
	Reviewed			Cuttings and		Vlix	Sample	SBS	2"	End	none	
٦	Elevation						Core				ge none	
1	Datum			Depth Drilled	12.0'		Tube			Date	Depth	
	Notes	Rain										
٦												
┵	DEPTH	SAMPLE	חרכ	DENIETDATION	LINUE		1					
İ	FT	NO	REC. FT	PENETRATION (Blows per 6")	UNIF. SOIL	[DESCRI	ртілм			EMARKS	
٦		l NO	' '	ASTM D-1586	CLASS		DESCHI	FIION		"	EWANKS	
ᅪ				7,01112 1000	+	 			·			
		 		N/A						}	H-NU Deflections (ppm)	
٦	χF	}										
	2 +	1				ъ.	own F-M S	CANID	Trace		none	
-	_	1			SP		e gravel, d		Trace			
	4 上	1					o gravor, c	aurip.				
	4 7	i i										
			18/24"									
	6 -											
ł	ĭ E											
_	F				}							
-	8 🖵					<u> </u>				 8.5 +/- ft.		
1										0.0 1, 1.		
-										4	0 ppm	
***	10 -		12/24"		CL	Gre	y sandy Cl	LAY				
	12 -	SB 2				Limes	tone at 12	.0'			none	
***	12 🕇					HSA /	Advancem		possible			
	F						at 12.0'				ı	
-												
7												
	\Box											
7												
_	廿											
	_		ľ									
7	H								į			
Ţ	#		ļ									
	H											
	Н		[
	H								•			
7	H										:	
	H											
1	Н		ļ									
					<u> </u>						 	

3221 - 3 Mile Rd. N.W. Grand Rapids, Michigan 49504 Ph (616) 791-0730 Fax (616) 791-4114

~			
PROJECT#_	2139		
BORING #	SB 3		
SHEET#	1	of	1

	Project Client	Mr. Day	rid Sherd	ssion		ractor_ te Begir		arns Di 28	D	ate End	11/28	
۲	Location _	Grand F	Rapids, MI				}	Туре	Dia. No.	Grou	ndwater	
ı	Crew Chie	ef D. Dav	erman	Rig Type	CME-5	5						
4	Inspector_			Plugging Rec			Casing	HSA	3 1/4"	During	none	
	Reviewed			Cuttings and		nix	Sample		2"	End	none	
٦	Elevation						Core				ge none	
1	Datum		• • • •	Depth Drilled	12.0'		Tube			Date	Depth	
	Notes			Bopar Brillion			1000			Date	Ворат	
	110103								·			
L												
	DEPTH FT	SAMPLE NO	REC. FT	PENETRATION (Blows per 6") ASTM D-1586	UNIF. SOIL CLASS		DESCR	IPTION		F	REMARKS	
1											H-NU Deflections (ppm)	
	2 +			N/A	SM							
	4 -					Brox	wn sandy '	SII T da	ımn			
-	6 -		12/24"			Brown sandy SILT damp (Gravel in sampler shoe)					none	
1	8 -						<u>des to grav</u> y SILT and			8.5 +/- ft	. none	
					IVIL-OL		ne gravel,		uace			
	10 -		20/24"			Spoon a	attempted	at 12'- i	no advancer	nent		
	12						ne at 12'	l. at 12'		†		
							E.O.B	. at 12				
										:		
-	-											
	-											
			}									

3221 - 3 Mile Rd. N.W. Grand Rapids, Michigan 49504 Ph (616) 791-0730 Fax (616) 791-4114

PROJECT#_	2139			
BORING #	SB 3		·	
SHEET#	1	of	1	

	Project Client		nd Transmi rid Sherd	ssion		ractor_ te Begir		arns Di 28		ate End	11/28
	Location _		Rapids, MI			3		Type Dia. No.			ndwater
٦				Dia Typo	CNAE 5	E	1	. ,,,	Dia. 110.	G .00.	
1	Crew Chie	Rig Type	CME-5	<u> </u>			0.4/48	Di.a.a.	2000		
-	Inspector_			Plugging Rec			Casing	HŞA		During	none
	Reviewed			Cuttings and	Bentonite n	<u> </u>	Sample	r SBS	2"	End	none
1	Elevation _						Core			Seepa	ge none
1	Datum			Depth Drilled	12.0'		Tube			Date	Depth
	Notes				LEIV						
	140103			-							
I											
J		0.4451.5	550	DENIETO ATION							
ļ	DEPTH	SAMPLE	REC.	PENETRATION	UNIF.			==:0.		_	S-144-DI/O
	FT	NO	FT	(Blows per 6")	SOIL		DESCRI	PHON		[-	REMARKS
ı				ASTM D-1586	CLASS						
4											H-NU Deflections (ppm)
١	H									! '	1-140 Delicetions (ppm)
٦						1					
I	2 +			N/A	1	1				İ	
1											
	 -	:				j					
٦	4 -				1						
					ML		wn sandy				
٦			12/24"		1	(Gravel in sampler shoe)				1	200
1			12/24		1						none
1	6 -				1						
J	<u>-</u>										
1						Gra	des to gra	y sand	y SILT		none
4	8 🕂					l		·		8.5 +/- ft.	
ı										0.5 -7- 11.	
4	'				l		y SILT and		', trace		
I	10 -		20/24"		ML-CL	of fi	ne gravel,	damp			
1		0.00	-0,-			.	ann attempted at 101, as advancement				
ı		SB3			Spoon attempted at 12'- no advancement						
1	12				L	limestone at 12'					
J	'- 'F						FOR	at 12'			
1							L.O.D	. at 12		;	
J	H					1					
I											
1	H										
۱	日										
1	+					}					
	\Box										
1	H										
J	+										
1	Ц										
	H		ļ			i					
l			ŀ								
Į	H										
I											
۱	H										
I	廿		ľ								
ł											
l	日										
۱	\Box										
		ļ								1	
•					4						

3221 - 3 Mile Rd. N.W. Grand Rapids, Michigan 49504 Ph (616) 791-0730 Fax (616) 791-4114

PROJECT#_	2139	
BORING #	SB 4	
SHEET#	of	1

Inspector E. Gutting Reviewed By Elevation		Rig Type Plugging Rec Cuttings and	Rig Type CME-55 Plugging Record C			arns Di /28/90 Type HSA r SBS		During End	11/28/90 ndwater none none qe none Depth	
DEPTH FT	SAMPLE NO	REC. FT	PENETRATION (Blows per 6") ASTM D-1586	UNIF. SOIL CLASS		DESCR	IPTION		R	EMARKS
2 4 -		24/24"	N/A	SP				nedium vel, damp		I-NU Deflections (ppm)
10	SB 4	12/12"		ML-CL	Lim	y SILT and estone at advancem	11.0' ent of F		9.0 +/- ft.	
						E.O.B.	at 11.V			

3221 - 3 Mile Rd. N.W. Grand Rapids, Michigan 49504 Ph (616) 791-0730 Fax (616) 791-4114

PROJECT #_	2139			~
BORING #	<u>\$B 5</u>			
SHEET#	1	of	1	

Projec	et	North	End Trans	mission	Con	tractor_	St	earns [Drillings		
Client			avid Sherd			e Begir		11/28		ate End	11/28/90
Locati			l Rapids, M	1			Dia. No.	Grour	ndwater		
Crew		f D. Da	verman	Rig Type	CME-	55					
Inspec		•	ıtting	Plugging Re			Casing	HSA	3 1/4"	During	none
		By	· ·		Bentonite m	nix	Sample			End	none
							Core			Seepa	ge none
Datun				Depth Drille	d 12.0'		Tube			Date	Depth
Notes											
DEPTH		SAMPLE	REC.	<u>I</u> PENETRATIO	N UNIF.	<u> </u>	<u> </u>				
FT		NO	FT	(Blows per 6")	SOIL		DES	CRIPTI	ON		REMARKS
				ASTM D-158	6 CLAS)				<u> </u>	
	H				}					1	H-NU Deflections (ppm)
	H									ł	
;	2 ╁┤				}						
	Я										
										İ	
	4 😾					İ					
			24/24"		6146	Date	6:	C	ANID		
			24/24		SW		wn fine-co		ลเงเบ, e silt, damp] r	none
(ê 🕇					,,,,,,	illie glavi	si, trace	s siit, dairip	0.5 (()	
	Н					1		_		6.5 +/- ft	•
	۸Н						des to yell				
	▫丗				SP		edium SA	ND, tra	ice silt		
	日		ļ			dam	ip				
1	∘⋣				⊢ − −			-		9.5 +/-ft	i.
'		SB 5	24/24"		ML	Gray	y sandy Sl	ILT, da	mp	n	one
			_ ,_ ,			1			·		
1:	2 -		-				estone at				
	ΪН						dvancem		₹ig		
	Н		1		1	E.O	.B, at 12.0)'			
	\mathbb{H}										
			1			į					
	日		ļ								
	\forall		1								
	H	1									
	日										
	廿	l	l								
	日		1								
	H]									
	H									-	
	口		1								
	Н	ŀ	ŀ								
; !	Н	1	:								
ı	日		ļ								
	口]	İ								
	H									ĺ	

3221 - 3 Mile Rd. N.W. Grand Rapids, Michigan 49504 Ph (616) 791-0730 Fax (616) 791-4114

PROJECT #_	2139
BORING #	SB 5A
SHEET#	1of1

	Project		End Transi avid Sherd			ractor_		arns Dr	_			
]	Client		Dat	e Begir]	11/28/		ate End	11/28/90			
4	Location _		l Rapids, M					Type	Dia. No.	Grour	ndwater	
1	Crew Chie	•	averman	Rig Type	CME-	55						
7	Inspector_			Plugging Rec	<u>ord</u>		Casing	HSA	3 1/4"	During	none	
	Reviewed			Cuttings and	Bentonite n	nix	Sample	SBS	2"	End	none	
	Elevation .						Core			Seepag		
닉	Datum			Depth Drilled	4.0'		Tube			Date	Depth	
	Notes											
٦												
1	DEPTH FT	SAMPLE NO	REC. FT	PENETRATION (Blows per 6") ASTM D-1586	UNIF. SOIL CLASS		DESCRI	PTION		R	EMARKS	
┪											•	
4					SP	اام۷	ow Brown	fine to	Medium	_		
I	2 —				31		ND, trace fi			יח	one	
7							,	9'4	,p			
-	, F											
1	4 🕇					Λ#.	empted spo	oon at	1 0'			
٦	-				ļ	end	countered i	unknow	n obstacle			
-	6 📙	<u> </u>			ļ				ELOCATE			
۱	ა -	•					RING			ŀ		
٦												
	8 🗜	1										
1		1								İ		
-		{										
	10	1										
7												
		1										
1	12 🛨	1								-		
~	 	-								Ì		
_		1								ŀ		
	士	1										
•		<u> </u>										
	-											
7	F											
-												
I										1		
٦	<u> </u>											
,												
	<u></u>											
-												
ار	-											
7	F											
												j
ı												Ì
4	\blacksquare											
1	<u> </u>	1 1	1		1					1		

APPENDIX C

Terminology

BORING LOG TERMINOLOGY

Sample Type:

"SBS" and "L" are the split barrel and liner samplers used to recover soil samples in the ASTM D 1586 Standard Penetration Test.

"S.T." refers to the thin-walled sampler used to recover relatively undisturbed soil samples in the ASTM D 1587 method of sampling.

"A" refers to a disturbed auger sample.

"C" refers to a rock core sample obtained by Diamond Core Drilling in accordance with ASTM D 2113.

"P.M." refers to Pressurmeter Test Location.

"C.S." refers to CME Continuous Sampler.

Boring Method:

"H.S.A." refers to Hollow Stem Auger.

"S.S.A." refers to the Solid Stem Auger.

"W" refers to the Wash Boring Method.

"R" refers to the Rotary Method.

"C" refers to the Casing Method by Driving.

"C.A." refers to Casing Advancer.

Water Observations:

Depth of water is measured from the top of ground to top of water level. Initial depth indicates water encountered during boring, completion depth indicates water level immediately after boring, and depth of "X" number of hours indicates water level after a time period.

Water observations in pervious soils are considered reliable groundwater levels for the date. Water observations in impervious soils may not be accurate groundwater measurements unless records are made over several days' time. The groundwater level will fluctuate for both pervious and impervious soils.

Soil Descriptors

Color: When the color of the soil is uniform throughout, a single color such as brown, gray or black will be used. If the soil is shaded by a secondary color, the secondary color precedes the primary color, such as: gray-brown, yellow-brown. If two distinct colors are swirled throughout the soil, the colors will be described as mottled, such as mottled brown and gray.

Soil Type:	Coarse-Grained Soil Component	Size or Sieve No.
	Boulders	Larger than 12"
	Cobbles	12" to 3"
	GravelCoarse	3" to 3/4"
	Fine	3/4" to No. 4
	SandCoarse	No. 4 to No. 10
	Meduim	No. 10 to No. 40
	fine	No. 40 to No. 200

Fine-Grained Soil Component (Burmister)	Plasticity Index
Silt	<1
Clayey Silt	1 to 5
Silt and Clay	5 to 10
Clay and Silt	10 to 20
Silty Clay	20 to 40
Clay	>4Ø

- Clay Soil passing a No. 200 (0.075mm) sieve that can be made to exhibit plasticity (putty-like properties) and exhibits considerable strength when air dry (ASTM D 2487).
- Silt Soil passing a No. 200 (0.075mm) sieve that is nonplastic or very slightly plastic and exhibits little or no strength when air dry (ASTM D 2487).

Organic Soil Components (ASTM D 2487)

Organic Clay - a clay with sufficient organic content to influence the soil properties (liquid limit after oven drying less than 75% of its value before oven drying).

Organic Silt - a silt with sufficient organic content to influence the soil properties (liquid limit after oven drying less than 75% of its value before oven drying).

Peat - a soil composed of decomposed vegetable tissue with organic odor, dark-brown to black color, spongy consistency, and a fibrous to amorphous texture.

Moisture Condition:

Description	Criteria
Dry	Absence of moisture, dusty, dry to the touch
Damp	Enough moisture present to darken the appearance, but no moisture on material adheres to the hand
Moist	Will moisten the hand
Wet	Visible free water, usually soil is below water table

Layer or Stratum:

Soil mass which can be characterized, for engineering purposes, by a single set of strength and classifications parameters.

Lenses:

Lenses of soil occur within soil layer and range in thickness from a fraction of an inch to approximately one (1) foot thick.

Seams:

Planer opening in a soil layer filled with soils of different characteristics. Soil seams are usually a fraction of an inch thick and may occur in various directions.

Density:

Granular Soils (Cohesionless)

Number of Blows	Relative Density	Compactness
Ø - 4	Ø – 2Ø%	Very Loose
5–1Ø	20-40%	Loose
11-30	40-70%	Medium Dense
31-50	70-90%	Dense
above 50	90-100%	Very Dense

Consistency: Cohesive Soils

Number of Blows	Approximate Shear Strength in K.S.F.	Cohesion
Ø - 2	Ø . 25	Very Soft
3-4	Ø.25-Ø.5	Soft
5–8	Ø.5-1	Medium Stiff
9–16	1-2	Stiff
17-32	2-4	Very Stiff
above 32	above 4	Hard

Minor Component Quantifying Terms

Trace	1 - 10%
Little	10 - 20%
Some	20 - 35%
And	35 - 50%

Percentages are visual estimates of component percentage by weight, unless particle size analyses are performed.

Grading:	When Soil characteristics vary gradually with depth within the same soil stratum, the variation is described by using the term "grading".
N.P.M.:	Natural Percent Moisture of recovered soil sample.
N.D.:	Natural Density of recovered soil sample in p.c.f.
S.S.:	Underdrained Shear Strength of cohesive soil samples in k.s.f.
01:C:	

Classification

Data:


Laboratory data to assist in classification of soils and classification of soil characteristics. i.e.: Plastic

classification of soil characterisitics. i.e.: Plastic Limit, Liquid Limit.

UNIFIED SOIL CLASSIFICATION SYSTEM

MAJOR DIVISIONS		LETTER Symbol	TYPICAL DESCRIPTIONS	
	GRAVEL	CLEAN GRAVELS (LITTLE OR NO FINES)	GW	WELL-GRADED GRAVELS, GRAVEL-SAND Fixtures, Little or No Fines
	AND GRAVELLY SOILS MORE THAN 50% OF COARSE FRACTION RETAINED ON NO. 4 SIEVE		GP	POORLY-GRADED GRAVELS, GRAVEL-SAMD Mixtures, Little or No Fines
COARSE		GRAVELS WITH FINES (APPRE- CIABLE AMT. OF FINES)	GM	SILTY GRAVELS, GRAVEL-SANDY-CLAY MIXTURES
GRAINED SOILS			GC	CLAYEY GRAVELS, GRAVEL-SAND-CLAY Mixtures
MORE THAN 50% OF MATERIAL	SAND AND SANDY SOILS MORE THAN 30% OF COARSE FRACTION	CLEAN SAND (LITTLE OR NO FINES)	sw	WELL-GRADED SANDS, GRAVELLY SANDS. LITTLE OR NO FINES
IS <u>LARGER</u> THAN NO. 200 SIEVE SIZE			SP	POORLY-GRADED SANDS, GRAVELLY SANDS, Little or No Fines
		SANDS WITH FINES	SM	SILTY SANDS, SAND-SILT MIXTURES
	PASSING NO. 4 SIEVE	(APPRECIABLE AMT. OF FINES)	sc	CLAYEY SANDS, SAND-CLAY MIXTURES
			ML	INORGANIC SILTS & VERY FINE SANDS. ROCK FLOUR, SILTY OR CLAYEY FINE SANDS OR CLAYEY SILTS WITH SLIGHT PLASTICITY
FINE	SILTS AND CLAYS	LIQUID LIMIT LESS THAN 50	CL	INORGANIC CLAYS OF LOW TO MEDIUM PLASTICITY, Gravelly Clays, Sandy Clays, Silty Glays, Lean Clays
GRAINED SOILS			OL	ORGANIC SILTS AND ORGANIC SILTY CLAYS OF LOW PLASTICITY
MORE THAN 50% OF MATERIAL IS SMALLER THAN NO. 200 SIEVE SIZE			мн	INORGANIC SILTS, MICACEOUS OR DIATOMACEOUS FINE SAND OR SILTY SOILS
	AND	LIQUID LIMIT GREATER THAN 50	СН	INORGANIC CLAYS OF HIGH PLASTICITY, FAT CLAYS
			он	ORGANIC CLAYS OF MEDIUM TO HISH PLASTICITY, ORGANIC SILTS
	HIGHLY ORGANIC SOILS		PT	PEAT, HUMUS, SWAMP SOILS WITH HIGH ORGANIC CONTENTS

FOR LABORATORY CLASSIFICATION OF FINE GRAINED SOILS



Iderink and Cases, Inc.

Occupational Health and Safety, Energy Management and Environmental Consultants ENV. RESPONSE DIV.

GRAND RAPIDS

AUG 14 1991

RECEIVED

REPORT OF FINDINGS

SUBSURFACE INVESTIGATIONS

NORTH END TRANSMISSION GRAND RAPIDS, MICHIGAN

JULY, 1991 PROJECT NO. 1-2139

Prepared for:

Mr. David Sherd North End Transmission 802 Alpine Avenue N.W. Grand Rapids, Michigan 49504

Prepared by:

Alderink and Associates, Inc. 3221 3-Mile Road N.W. Grand Rapids, Michigan 49504

TABLE OF CONTENTS

1.0	INTROD	UCTION					
1.1	Purp	ose		• • • • • •	• • • • •		1
2.0	REVIEW	OF BAC	CKGROUND	INFORM	ATION		`
2.2.	.~ Init	ial Aba	atement l	Measure	s		1
3.0	TYPE B	INVEST	rigation				
3.1 3.2	Soil Resu	Boring lts of	js Sample i	Analyse	s	• • • •	2
4.0	CONCLU	sion					3
4.1	Reco	mmendat	ions/Si	te Plan	• • • • • •	· • • •	4
Figure	≥ 2 E	xtent o	ring Loca of Remain I Boring	ning Co	ntamina ons	ation	1
A DDFMC)TY 7	Pocult	e of Tal	horator	w Anals	7505	

1.0 INTRODUCTION

As authorized by Mr. David Sherd, Alderink and Associates, Inc. (AAI) has completed a subsurface investigation at North End Transmission located at 802 Alpine Avenue in Grand Rapids, Michigan. The investigation was performed in accord with a work plan prepared by AAI and approved by the Michigan Department of Natural Resources, Environmental Response Division.

1.1 Purpose

The purpose of this study was to identify levels of remaining contamination and determine the site's suitability for a Type B Site Closure in accordance with 1982 P.A. 307, as amended. The closure of the site has been withheld due to the presence of contamination attributed to a leaking underground storage tank formerly located at the site. Previous results of laboratory analyses indicated remaining contaminant levels to fall within the Type B criteria.

2.0 REVIEW OF BACKGROUND INFORMATION

This section contains a review of background information presented in previous reports.

2.1 Location

North End Transmission is located at the intersection of Seventh Street and Alpine Avenue in Grand Rapids, Michigan. A vicinity map is provided in the attached Figure No. 1.

2.2 Initial Abatement Measures

On January 23, 1990, one (1) 6,000 gallon waste transmission oil underground storage tank was removed from the south side of the premises. The tank was originally used for the storage of gasoline. The tank was excavated by North Garfield and assessed by Superior Environmental.

Upon removal, the soil within the excavation was determined to be contaminated based upon olfactory observations and readings from field instrumentation (PID meter). Approximately 100 cubic yards of soil were excavated and transported off-site to a licensed Type II landfill. Soil removal was continued to a depth of

NORTHEND TRANSMISSION
SITE INVESTIGATION, TYPE B PAGE 2

approximately 10 feet below grade at which point PID readings were not observed. Laboratory analyses of soil samples collected from the east and west ends of the resulting excavation indicated the presence of BTEX constituents between 10 to 540 parts per billion.

2.3 Subsurface Investigation

On November 21 and 28, 1990, AAI completed five soil borings in the vicinity of the former UST in order to determine the extent and levels of remaining contamination. The borings were continued to a depth of approximately 12 feet below grade. At this depth weathered shale and/or limestone was encountered, preventing further advancement of the drilling rig's hollow stem augers. Soil sample results of laboratory testing for PNA and BTEX constituents indicated low BTEX levels (25-205 ppb) remaining within the soils along the west and north perimeter of the excavation. Groundwater was not encountered during the investigation.

Based upon the low levels of BTEX remaining near the building foundation and subsurface utilities, it was agreed with the MDNR that the application of a Type B site closure warranted additional soil sampling at various locations along the perimeter of the site.

3.0 TYPE B INVESTIGATION

3.1 Soil Borings

In July, 1991, AAI completed the collection of soil samples from five borings located along the perimeter of the site. The work was completed in accord with a work plan prepared by AAI and approved by the MDNR-Environmental Response Division. The investigation included the collection and analysis of two soil samples per boring; one sample at approximately 6 feet below grade and one sample at approximately 11 feet below grade, above the underlying shale or limestone base.

As indicated in the work plan, the borings were advanced using a hand-held gasoline powered auger to 6 feet below grade followed by a manually operated hand auger to the bottom boring depth at approximately 11 feet. Three borings were conducted in this manner, however, due to the presence of cobbles at boring locations HA#3 and HA#5, the hand auger could not be advanced

NORTHEND TRANSMISSION
SITE INVESTIGATION, TYPE B PAGE 3

beyond 6 feet. On July 18, a trailer mounted drilling rig, CME-45, was utilized to complete the collection of soil samples at HA#3 and HA#5. No groundwater was encountered during the site investigation.

While completing HA#2, located under the concrete floor of the garage, evident soil contamination was encountered approximately 11.0 feet below grade. On-site field screening of the soils utilizing an Organic Vapor Monitor (OVM), Model 580B, yielded readings of 40 parts per million (ppm).

3.2 Results of Soil Sample Analyses

A total of ten (10) soil samples were analyzed for BTEX constituents. As indicated in Table I below, BTEX was detected within HA#2B and HA#4A collected from depths of 11.0 feet and 6.5 feet respectively. For comparison, the maximum allowable BTEX contaminant levels required to meet Type B criteria are shown in the right hand column of the table. The remaining samples did not contain BTEX constituents at or above 10 parts per billion (ppb), the method detection limit (see Appendix A). The Type B criteria are based upon recently amended levels as of August 2, 1991.

TABLE	Ι	•
	_	_

		Type B		
Constituent	Sample HA#2B	Sample HA#4A	Criteria	
Benzene Ethylbenzene Toluene Xylenes (o,m,p)	ND* 510 1,392 3,800	ND ND 99 134	20 1000 20,000 6,000	

^{*} None Detected at or above 10 ppb

4.0 CONCLUSION

Based upon the results of field observations and laboratory analyses, BTEX contamination remains along the west and north ends of the former excavation located to the south of the existing building (see Figure 2). The vertical extent of contamination to the west extends from the ground surface to approximately 6.5 feet below grade. Although the lateral extent of this contamination could not be defined, it is reasonable to assume that the contamination terminates at some point beneath Alpine Avenue.

NORTHEND TRANSMISSION
SITE INVESTIGATION, TYPE B PAGE 4

In comparison to the low levels remaining to the west, significantly higher levels of BTEX were found under the building to the north. The contaminants were not detected in soil sample HA#2A, collected at 6.5 feet below grade, therefore, the plume of contamination extends northward at a depth of approximately 8 feet below grade to the top underlying shale/limestone located at 12.0 feet below grade.

The BTEX levels found in sample HA#2B fall within the State's maximum allowable levels for Type B criteria. In accordance with 1982 P.A. 307, the Michigan Department of Natural Resources, Environmental Response Division (MDNR-ERD) District staff may approve a Type B Site Closure plan with specific approval from the MDNR-ERD Committee.

In our opinion, the site conditions encountered as a result of this investigation warrant broadening the area of study to include the north and west perimeter of the site. Extending the area of investigation will facilitate the identification and characterization of the contaminant plume within the soil at North End Transmission. Two criteria which must be met for Type B consideration are 1) the contaminant levels at the site must fall below the State's maximum allowable risk-based levels, and 2) the site must exhibit decreasing contaminant levels as the outer extent of the contaminant plume is approached.

4.1 Recommendation/Site Plan

We recommend that additional investigative efforts include the completion of three soil borings and laboratory analyses of soil samples. As shown on Figure 3, the addition of two soil borings to the north and one boring to the west may completely define the lateral extent of remaining contamination. The procedures for soil boring advancement, sample collection and decontamination will be conducted in a manner consistent with those previously implemented. This will include boring to approximately 12 feet below grade and collecting soil samples at depths of approximately 6 and 11 feet. The samples will be submitted to Prein and Newhof for laboratory analyses of BTEX constituents.

Based upon the difficulties previously encountered during the advancement of the hand auger, it is recommended that a trailer mounted drilling rig, equipped with hollow stem auger and splitbarrel sampler, be utilized to advance the two exterior borings. The boring located inside the facility will be completed by hand augering through a cored opening in the concrete floor slab.

NORTHEND TRANSMISSION SITE INVESTIGATION, TYPE B PAGE 5

Subsequent to MDNR approval and authorization from North End Transmission, the work plan outlined above will be completed within 45 days. The results of field and analytical data will be presented in a final report. In the event site conditions warrant consideration for a Type B Site Closure, an application as such will be incorporated into the final report.


If there are any questions or comments regarding the information provided, please do not hesitate to contact me at (616) 791-0730.


Respectfully submitted,


ALDERINK AND ASSOCIATES, INC.

Eugene J. Gytting III Geological/Engineer

cc: Project File 1-2139 cc: Michelle Hohn, MDNR-Environmental Response Division







APPENDIX A
RESULTS OF LABORATORY ANALYSIS



PREIN NEWHOF, P.C.

ENGINEERS - SURVEYORS - ENVIRONMENTAL & SOILS LABORATORIES

3355 EVERGREEN DR., N.E. GRAND RAPIDS, MICHIGAN 49505 TELEPHONE (616) 364-8491 TELECOPIER (616) 364-6955 BRANCH OFFICE: 400 136th AVE., SUITE 517 HOLLAND, MICHIGAN 49424 TELEPHONE (616) 394-0200 TELECOPIER (616) 394-5914

& RECENTED

July 25,1991 90033L

HEDWARD PREIN PE FUS THOMAS NEWHOR PE AUSWIND MODUSEN PE WICHAELS PERBSTROM PE WICHAELS FULLER PE FHUR DISLUPKER PE LAMES AI TOOK PE ROSEPT LIANDER MALE PE ROSEPT LIANDER MALE PE ROSEPT LIANDER MALE PE ROSEPT LIANDER MALE PE ROSEPT LIANDER MALE PE ROSEPT LIANDER NEW PE BASIL ANDRESS OF RE SIGNEY PLAGRESS OF RE BASIL ANDRESS OF RE DIAFPUL REMISOLO PE LARPY DISTERDOUGER PE

j.

Mr. Gene Gutting Alderink & Associates 3221 3 Mile Road NW Grand Rapids, MI 49504

Re: Project: Northend Transmission

Project # 2139

Chain of Custody # 001798 Samples received 7/11/91

LABORATORY RESULTS

Hand Auger Sample: Lab Log #	# 1A 3641	# 1B 3642	# 2A 3643	# 2B <u>3644</u>	# 4A <u>3645</u>	# 4B 3646
Total Solid,%	85	90	92	82	89	. 89
Benzene,ug/Kg Ethylbenzene,ug/Kg Toluene,ug/Kg m/p-Xylene,ug/Kg o-Xylene,ug/Kg	ND* ND ND ND ND	ND ND ND ND ND	ND ND ND ND	ND 510 1,392 2,400 1,400	ND ND 99 92 42	ND ND ND ND ND

ND* indicates none detected at or above the method detection limit of 10 ug/Kg

PREIN & NEWHOF
Environmental Laboratory

Robert Erickson Laboratory Director



PREIN ONEWHOF, P.C.

ENGINEERS - SURVEYORS - ENVIRONMENTAL & BOILS LABORATORIES

3355 EVERGREEN DR., N.E. GRAND RAPIDS, MICHIGAN 49505 TELEPHONE (616) 364-8491 TELECOPIER (616) 364-6955 BRANCH OFFICE: 400 136th AVE., SUITE 517 HOLLAND, MICHIGAN 49424 TELEPHONE (616) 394-0200 TELECOPIER (616) 394-5914

August 1,1991 90033L

H EDMARD PREIN PE BLS
THOWAS NEWHOF PE
ALSON DIMODEEN BE
MOHARL'S BERGSTROM RE
MOHARL'S FULLER PE
PHURE CAUDKER PE
LIMES A COOK PE
ROBERT L'ANDER MALE PE
ROBERT L'ANDER MALE PE
ROBERT L'ANDER MALE PE
ROBERT A REMINEN PE
BOSEST A ROBERT BLS
SOTIES PILABOR BLS
SOTIES PILABOR BLS
BOSES PILABOR BLS
BOSES PILABOR BLS
BOSES PILABOR BLS
BOSES PILABOR BLS
BOSES PILABOR BLS
LIBERT D'STEHOUMER PE

Mr. Gene Gutting Alderink & Associates 3221 3 Mile Road NW Grand Rapids, MI 49504

Re: Project: Northend Transmission

Project # 2139

Chain of Custody # 002034 Samples received 7/18/91

LABORATORY RESULTS

Soil Boring Sample: Lab Log #	# 3 A 3839	# 3 B 3840	# 5 A <u>3841</u>	# 5 B <u>3842</u>
Total Solids,%	91	92	93	91
Benzene, ug/Kg	ND*	ND	ND	ND
Ethylbenzene,ug/Kg	ND	ND	ND	ND
Toluene, ug/Kg	ND	ND	ND	ND
m/p-Xylene,ug/Kg	ND	ND	ND	ND
o-Xylene,ug/Kg	ND	ND	ND	ND

ND* indicates none detected at or above the method detection limit of 10 ug/Kg

PREIN & NEWHOF
Environmental Laboratory

Robert Erickson Laboratory Director

PREIN & NEWHOF, P.C.

ENGINEERS - SURVEYORS - ENVIRONMENTAL & SOILS LABORATOF

3260 Evergreen Drive, N.E. Grand Rapids, Michigan 49505 616-364-7600 Telecopier 616-364-6955

CLIENT: A	Icler it	K & Assex INEL: R Rocker 1 6	PROJECT N	AME:	<u>///</u>	1h.,	Tremen	ingesalle R	PROJE	CT NO: 21	139	
DATE	TIME	SAMPLE ID/DESCRIPTION		PE SAI	SEAB	NO. OF		RAMETERS		REMA		
7/10/91		Hill A det #1A	6 5	i	6	1	SITE	<		a frankrik	Ti	:
, ,		H. 1 Ayer 41 A	10.0		1	- 1						(
		* " " ZA	l l		1						, n <u></u>	
		" "#2B	11.0'		レ	. 1		,				
		min			1	1				- 		-
						,						
		· * * * * * * * * * * * * * * * * * * *	6.51		_/	· /						reservit.
		" " " " " " 10	2.51		./	1	,				***	
		MAN	1		1	\\\	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		,	****		. 1
	· · · · · · · · · · · · · · · · · · ·							•				
	T 11-11-2					`.			•	8 - 8 3 8 3 - 11	448 442	
						- · · · · · · · · · · · · · · · · · · ·			_	11 -	448	·
Relinquished by:	10	Date: Time: Received by: (5		Time:		quished by: (Sigi		: Time:	Received by:	(Signature)	Date:	Time:
Relinquished by:	(Signature)	Date: Time: Received by: (5	Signature) Date:	Tima:	Math	od of Shipment	:		Bill of Ladi	ng:		
NI 00:	1798	Received for Laboratory by: (Signature)	Date: Time:	Data Pa	ckage	Relinquished by	Lab: Date	: Time:	Data Receive	ed by: (Signature)	Date:	Time:

PREIN & NEWHOF, P.C.

ENGINEERS - SURVEYORS - ENVIRONMENTAL & SOILS LABORATORIES

3000 EAST BELTLINE, N.E. GRAND RAPIDS, MICHIGAN 49505 TELEPHONE (616) 364-8491 TELECOPIER (616) 364-6955

CLIENT: 1	lele, ist	4 Asser	PROJE	ECT NA	ME:_	N .,	Mecil T.	- ! <u>carotiri</u> -	.50.00.1		· _ <i>PROJE</i>	CT NO: I	1139	<u>7 </u>
SAMPLING	PERSON	NEL: G. G	offing to R. Roc	ter	<i>S</i>	AMPI	LING SITE	: <u> ></u>	. 1: 1	<u> 307 0</u>	10.5			
DATE	TIME	SAMPLE	ID / DESCRIPTION	TYP	E		NO. OF CONTAINERS		PARAM	METERS		REM	ARKS	
7/13/91	· · · · · · · · · · · · · · · · · · ·	50.1 Bor.	ng #3 A @60	Soi	1			\mathcal{B}	TEX			Standa	0 T.	A.
157		v.	" #3 A @6.0" #3 B. e12.0	} ;		L		,,						(
		.,	" 5 A. e6.0'			L		Ų.	,			1		
			" 5 A. e6.0' " 15 B e12.0'	1		i		`.	• • • • • • • • • • • • • • • • • • • •	 -				
		,												
-												<u> </u>		
												-		
											•			
										,/				-(
									· · · · · · · · · · · · · · · · · · ·			, <u> </u>		
						\dashv								
Relinquished by:		Date: Time:	Received by: (Signature)	Date:	Time:	Rell	nquished by: (Sig	inature)	Date:	Time:	Received by:	(Signature)	Date:	Time:
Relinquished by:		Date: Time:	Received by: (Signature)	Date:	Time:	Mell	hod of Shipment	;			Bill of Ladia	ng:]	<u></u>
M2 00	2034	Received for Labor		Time:	Data F	Packago	Relinquished by	Lab:	Date:	Time:	Data Receive	d by: (Signature)	Date:	Time:

(FR)

PREIN & NEWHOF, P.C.

ENGINEERS - SURVEYORS - ENVIRONMENTAL & SOILS LABORATORIES

3000 EAST BELTLINE, N.E. GRAND RAPIDS, MICHIGAN 49505 TELEPHONE (616) 364-8491 TELECOPIER (616) 364-6955

IENT:_A IMPLING	l <u>cleriak</u> PERSON	L & Assex WEL: R. Recta	r \$ 6	PROJ 	ECT N	AME:_ SA	∆le ampi	rthend LING SIT	Trun E: <u>501</u>	smis 1 Be	sion scinas	_ PROJ	IECT NO: 2	2139	
DATE	TIME		/ DESCRIPT		TY	PE	GRAB	NO. OF CONTAINER	<i>'S</i>		 AMETERS		RE	MARKS	
10/91		Hand Auger	#1 A	· · · · · · · · · · · · · · · · · · ·	Soi	1	V	1	B7	EX			Standan	1 T.	4.
			1B				L	- 1	"	(1					
		v 11 ±	ZA			··	L	i	,,	"					
		" "#	2B				レ	1	"	,,					
	•							/			1				
									"	"					
		" "#	4A		+		- V	1	"	′′		1			
			4B	·			- 	/ /		11			<u> </u>		
		1											·····		
				1 Tel 18 1										<u>-</u>	
							- 								
equished by:	(Signature)		eceived by: (Signature)	Date:	Time:	Relin	quished by: (:	Signature)	Dote:	Time:	Received b	y: (Signature)	Date:	Time:
nquished by:	'Signature)		eceived by: (Date:	Time:	Moth	od of Shipme	nt :		-1	Bill of Lo	ading:	1	1
12 001	.798 、	Received for Laborator,	pr: (Signature	1 2910: 111191	Time:		Sokog.	Relinquished L	y Lab:	0010/	Time: SCA	Data Rece	ived by: (Signature	Dote:	Time

PREIN & NEWHOF, P.C.

ENGINEERS - SURVEYORS - ENVIRONMENTAL & SOILS LABORATORIES

3000 EAST BELTLINE, N.E. GRAND RAPIDS, MICHIGAN 49505 TELEPHONE (616) 364-8491 TELECOPIER (616) 364-6955

CLIENT: A	lelevint	y 1 550	<u> </u>					131001 11.0.1 To		les las				139	ĵ
SAMPLING	PERSON	NEL: G.	Gutting #	- PRW R. Rec	ter-	ние: : _ S4	IMP	LING SITE	ипът : 5:	137191	Bosiv	_ <i>PKO</i> U 2015	IECT NO: 🚅	-10/	
DATE	TIME	SAM	PLE ID/DESCRIPT	TION	TY		••	NO. OF CONTAINERS			METERS	7	REMA	ARKS	
1/18/91		Soil B	"#3 E	A	501	1	سا		\mathcal{B}^{\cdot}	TEX			Standar	PT.	\overline{A}
)		"	"#3E	3			L		1,		//		1		
			" #5A				u		N		/ /				
		"	"#5B				L		71	′ ′				, <u> </u>	
											-	-		. ,	
				11.00						*					
															
															
												-=			
												·		· · · · · · · · · · · · · · · · · · ·	
	-				,			,		<u>.</u>	×				
	· · · · · ·			, - ·· <u>, - ·· , </u>						·········					
elinquished by:	•	Date: Time	1	(Signature)	Date:	Time:	Rell	nquished by: (Sign	nature)	Date:	Time:	Received b	y: (Signature)	Date:	Tin
elinquished by:		7/19/9/ 10 Doje: Tim		(Signature)	Date:	Time:	Meti	hod of Shipment				Bill of Lo	ading :		<u> </u> _
Nº 002	2034	Received for	aboratory by: (Signatur	10) Pgro:	Time:	Data F		Relinquished by		Date:	Time:		ived by:(Signature)	Date:	<i>Ti</i>

Alderink and Associates, Inc.



Occupational Health and Safety, Energy Management and Environmental Consultants

ENV. RESPONSE CI..

DEC 23 1991

RECEIVED

RESULTS OF SUBSURFACE INVESTIGATIONS

NORTH END TRANSMISSION GRAND RAPIDS, MICHIGAN

December 20, 1991 Project No. 1-2139

Prepared for:

Mr. David Sherd North End Transmission 802 Alpine Avenue N.W. Grand Rapids, Michigan 49504

DEC 23 1991

TABLE OF CONTENTS

1

2.00	PURP	OSE	1	
3.00	SUBS	JRFACE INVESTIGATION METHODOLOGY	1	
4.00	RESU	LTS OF LABORATORY ANALYSIS	2	
5.00	TYPE	B CRITERIA	2	
		CT HUMAN CONTACT ECTION OF AQUIFERS	3 3	
6.00	CONC	LUSION	3	
Figures				
Figure Figure Figure	2	Soil Boring Locations, November 1 Summary of Sample Results Remaining BTEX Contaminant Levels		
Tables				
Table I Table I		Type B Criteria Summary of Sample Results		
Appendi	ces			
Appendi:	хА	Results of Laboratory Analysis, N	November	1991

1.00

INTRODUCTION

ENV. RESPONSE DIV. GRAND RAPIDS

JAN 0 2 1992

1.0 INTRODUCTION

RECEIVED

As authorized by Mr. David Sherd, Alderink and Associates, Inc. (AAI) has completed additional subsurface investigation activities at North End Transmission located at 802 Alpine Avenue in Grand Rapids, Michigan. The work was conducted in accordance with a work plan prepared by AAI and approved by the Michigan Department of Natural Resources, Environmental Response Division on October 24, 1991.

2.0 PURPOSE

The study was conducted in order to satisfy the criteria setforth in Act 307 (1982 as amended) for Type B closure of the subject site. The Act 307 Type B criteria for soils can only be satisfied when concentrations of the hazardous substances in the soil do not exceed certain criteria established for exposure routes/ migration pathways pertinent to the site. The Type B criteria have been developed using standard exposure assumptions and currently available toxicologic data. The contaminant levels identified on the site have been compared to Type B criteria presented in the MDNR's interoffice communication entitled New Type B Criteria for Toluene, Ethylbenzene and Xylene, August 2, 1991.

3.0 SUBSURFACE INVESTIGATION METHODOLOGY

On November 8 and 12, 1991, a total of five (5) additional soil borings were completed and soil samples collected. Two (2) hand augered soil borings were placed inside of the building and one (1) hand augered soil boring was conducted along the eastern side of Alpine Avenue. The remaining two (2) borings were completed utilizing a drilling rig and hollow stem augering techniques. The sample locations have been identified Figure 1.

The borings were advanced to a depth of approximately 12 feet below grade or until an underlying weathered shale layer was encountered. No groundwater was encountered in the borings. Two (2) soil samples were collected from each boring at depths of approximately 5 to 6 and 11 to 12 feet below grade. The soil samples were preserved in an insulated cooler, maintained at 40 degrees Fahrenheit, for transport to Prein and Newhof Laboratories of Grand Rapids, Michigan. The samples were analyzed for the presence or absence of purgeable aromatic hydrocarbons (Benzene, Toluene, Ethylbenzene, and Xylenes-BTEX).



NORTH END TRANSMISSION
Results of Subsurface Investigations Page 2

The auger flite cuttings, and each of the collected soil samples, were field screened for the presence of Volatile Organic Compounds (VOC's) using an Organic Vapor Monitor (OVM), Model 580B. Field screening did not yield any observable OVM readings within the sensitivity range of the OVM Meter (0.1 ppm to 2,000 ppm).

4.00 RESULTS OF LABORATORY ANALYSIS

The results of the laboratory analyses indicated the presence of 22 parts per billion (ppb) and 19 ppb of Total BTEX in the soil samples collected at a depth of approximately 6 feet below grade in borings HA#6 and HA#7, respectively (see Figure 2).

Total BTEX levels of 10 ppb, 10 ppb and 25 ppb were identified in the soil samples collected at depths ranging between 11 and 12 feet below grade in borings HA#7, HA#8 and HA#9, respectively (see Table II for laboratory results).

As shown on Figure 3, the BTEX contaminant levels identified over the study area, in it's entirety, indicate significant decreases in BTEX levels farther away from the source area. The outer perimeter of the study area have verified either traces of residual BTEX levels or non-detectable BTEX levels. The majority of residual BTEX levels is comprised of toluene and xylenes. Benzene has not been detected in any of the soil samples collected by AAI to date.

5.0 TYPE B CRITERIA

Based upon the results of the site investigation and subsequent analytical data, the residual BTEX levels present at the site remain below the maximum acceptable levels for Type B closure. The soils that contain residual ethylbenzene, toluene and xylenes are limited to a depth of 12 feet below grade due to the presence of weathered shale bed underlying the study area. Groundwater has not been encountered at the site is therefore not a prevalent exposure/migration pathway.

As shown on Figure 2, the residual BTEX levels along the west perimeter of the site (SB#4, HA#6) diminish to non-detectable levels at some point between 6 and 12 feet below grade. The BTEX levels remaining under the existing building (SB#2, HA#8, HA#9) have not impacted the soil from the ground surface to a depth of at least 6 feet. A northward movement of the contaminants has evidently occurred along the soil/shale interface at approximately 12 feet below grade.

NORTH END TRANSMISSION
Results of Subsurface Investigations Page 3

5.10 DIRECT HUMAN CONTACT

Approximately 441 cubic yard of soil remain contaminated with residual BTEX levels. This quantity of soil has been based on calculations assuming that the vertical depth of contamination along the western extent of the plume extends from ground surface to 9 feet below grade and from 9 to 12 feet below grade along the remainder of the plume. Of the 441 cubic yards of contaminated soil, approximately 341 cubic yards of soil remain under the foundation of the building. The remaining soil is located under the asphalt and concrete parking lot around the perimeter of the site. Therefore, the potential for direct human contact with these soils will be minimal.

Nonetheless, the remaining BTEX levels within the soils have been compared to the levels of ethylbenzene, toluene, and xylenes for Type B criteria for the direct human contact route of exposure. As shown in Table I, the levels for ethylbenzene, toluene, and xylenes are well below their respective Type B criteria. No further remediation is necessary to achieve compliance with the Type B criteria for direct human contact (dermal contact and incidental ingestion).

5.20 PROTECTION OF AQUIFERS

Although groundwater has not been encountered at the site, the remaining BTEX levels have been compared to twenty times the Type B criteria for groundwater. As indicated on Table I, the levels of ethylbenzene, toluene, and xylenes are well below their respective Type B criteria. No further remediation is necessary to ensure the protection of groundwater in the event leaching of the soils occur in the future.

6.0 CONCLUSIONS

Based upon the current MDNR guidelines regarding the use of Type B criteria for acceptable cleanup levels at UST closure sites, the levels of ethylbenzene, toluene, and xylenes at North End Transmission are well below all relevant Type B criteria. Comparisons have indicated that these residual levels remaining within the soil at the site are several orders of magnitude below the Type B criteria for direct human contact and protection of aquifers. Considering the existing site conditions and the ability to oxidize/volatilize the BTEX constituents, biodegradation of the residual contaminants will very probably occur within the next few years.

NORTH END TRANSMISSION
Results of Subsurface Investigations Page 4

Based on this premise, Alderink and Associates, Inc. concludes that no further remediation or site investigations are necessary for closure of the site under Act 307 (1982 as amended).


If there are any questions regarding the contents of this report, please feel free to contact our office at (616) 791-0730.


Respectfully submitted,

ALDERINK AND ASSOCIATES, INC.

Eugene J. Gutting Geological Engineer

EJG:lg








TABLE I: TYPE B CRITERIA

Current MDNR Type B Closure criteria for soils contaminated by leaking underground storage tanks (UST's)

	<u>20 x GW</u> *	<u>DC</u> **
Ethylbenzene	20,000 ppb	2E+7
Toluene	1,000 ppb	8E+7
Xylenes	6,000 ppb	2E+7

- * Twenty times the Type B criteria for groundwater
 ** Direct human Contact (dermal contact, incidental ingestion)

TABLE II: SUMMARY OF SAMPLE RESULTS

NOVEMBER 1990 - (Soil samples collected November, 1990)

Sample No.	Depth	Benzene	Ethylbenzene	Toluene	Xylene	Total
SB-1	12.0'	*ND	ND	ND	ND	
SB-2	11.5′	ND	100	29	205	334
SB-3	11.0'	ND	ND	ND	25	25
SB-4	12.0'	ND	ND	ИD	ИD	
SB-5	12.0′	ND	ND	ND	ND	

^{*(}ND=None Detected at or above 10 ppb)

JULY 1991 - (Soil samples collected July, 1991)

Sample No.	Depth	Benzene	Ethylbenzene	Toluene	Xylene	<u>Total</u>
#1A	6.0′	ND	ND	ND	ND	
#18	11.5′	ND	ND	ND	ND	
#2A	6.0′	ND	ND	ND	ND	
#2B	11.0′	ND	510	1392	3800	5702
#3A	6.0′	ND	ND	ND	ND	
#3B	11.5′	ND	ND	ND	ND	
#4A	6.0′	ND	ND	99	134	233
#4B	11.5'	ND	ND	ND	ND	
#5A	6.0′	ND	ND	ND	ND	
#5B	11.5′	ND	ND	ND	ND	

Table II Continued....

NOVEMBER 1991 - (Soil samples collected November, 1991)

Sample	No. Depth	Benzene	Ethylbenzene	Toluene	<u>Xylene</u>	<u>Total</u>
на ба	6.0	ND	10	12	ND	22
HA 6B	11.0'	ND	ND	ND	ND	
HA 7A	6.0'	ND	ND	ND	19	19
HA 7B	11.5'	ND	ND	ND	10	10
HA 8A	6.0'	ND	ND	ND	ND	
HA 8B	11.5'	ND	ND	ND	10	10
HA 9A	6.0'	ND	ND	ND	ND	
HA 9B	11.0'	ND	ND	ND	25	25
HA 10		ND	ND	ND	ND	
HA 10	B 11.0′	ND	ND	ND	ND	

APPENDIX A

Results of Laboratory Analysis November 1991

PREIN & NEWHOF, P.C.

ENGINEERS — SURVEYORS — ENVIRONMENTAL & SOILS LABORATORIES

3355 EVERGREEN DR., N.E. GRAND RAPIDS, MICHIGAN 49505 TELEPHONE (616) 364-8491 TELECOPIER (616) 364-6955 BRANCH OFFICE: 400 136th AVE., SUITE 517 HOLLAND, MICHIGAN 49424 TELEPHONE (616) 394-0200 TELECOPIER (616) 394-5914

November 29,1991 90033L

H EDWARD PREIN, PE., R L S THOMAS NEWHOF, PE. WILSON D MCQUEEN, PE MICHAEL S BERGSTROM, PE. MICHAEL S FULLER, PE. PHILIP C GLUPKER, PE. JAMES A COOK, PE. ROBERT J VANDER MALE, PE. ROBERT J REIMINK, PE. ARTHUR W BRINTNALL, R L S REX A MILLIRON, R L S. SIDNEY P. WAGNER JR., PE BASIL J ANDRESS JR., R L S. RICHARD J REIMBOLD, PE. LARRY D STEHOUWER, PE.

Mr. Gene Gutting Alderink & Associates 3221 3 Mile Road NW Grand Rapids, MI 49504

Re: Project: North End Project # 2139

> Chain of Custody # 001802 Samples received 11/13/91


LABORATORY RESULTS

Sample: Lab Log #:	HA-6A <u>6726</u>	HA-6B <u>6727</u>	HA-7A 6728	HA-7B 6729	HA-8A <u>6730</u>
Total Solids, %	88	92	83	89	96
BTEX, reported as ug/Kg Benzene Ethylbenzene Toluene m/p-Xylene o-Xylene	ND ND 12 10 ND	ND ND ND ND ND	ND ND ND ND 19	ND ND ND 10 ND	ND ND ND ND
Sample: Lab Log #:	HA-8B 6731	HA-9A 6732	HA-9B <u>6733</u>	HA-10A <u>6734</u>	HA-10B 6735
Total Solids, %	85	86	87	93	91
BTEX, reported as ug/Kg Benzene Ethylbenzene Toluene m/p-Xylene o-Xylene	ND ND ND ND 10	ND ND ND ND	ND ND ND 25 ND	ND ND ND ND ND	ND ND ND ND ND

ND* indicates none detected at or above the method detection limit of 10 ug/Kg.


PREIN & NEWHOF

Robert Erickson Laboratory Director



Appendix D





802 Alpine Avenue NW 802 Alpine Avenue NW Grand Rapids, MI 49504

Inquiry Number: 04170139.2r

December 30, 2014

The EDR Radius Map™ Report with GeoCheck®




TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map.	2
Detail Map.	3
Map Findings Summary.	
Map Findings.	7
Orphan Summary	
Government Records Searched/Data Currency Tracking	GR-1
GEOCHECK ADDENDUM	,
Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-8
Physical Setting Source Map Findings.	A-9
Physical Setting Source Records Searched	PSGR-1

Thank you for your business. Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2014 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

802 ALPINE AVENUE NW KENT County, MI 49504

COORDINATES

Latitude (North): 42.9782000 - 42° 58' 41.52" Longitude (West): 85.6877000 - 85° 41' 15.72"

Universal Tranverse Mercator: Zone 16 UTM X (Meters): 607004.9 UTM Y (Meters): 4759014.5

Elevation: 615 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 42085-H6 GRAND RAPIDS WEST, MI

Most Recent Revision: 1996

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from: 20120625, 20120705

Source: USDA

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 7 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
NORTH END TRANSMISSION SERVICE 802 ALPINE NE GRAND RAPIDS, MI 49504	LUST Facility Status: Closed UST WDS	N/A
NORTH END TRANSMISSION SERVICE 802 ALPINE NE GRAND RAPIDS, MI	RGA LUST	N/A
NORTH END TRANSMISSION 802 ALPINE GRAND RAPIDS, MI	RGA LUST	N/A
802 ALPINE AVE NW 802 ALPINE AVE NW GRAND RAPIDS, MI 49504	EDR US Hist Auto Stat	N/A

NORTH END TRANSMISSION INC 802 ALPINE AVE NW GRAND RAPIDS, MI 49504 RCRA NonGen / NLR FINDS

MID017095530

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal ERNS list

ERNS_____ Emergency Response Notification System

Federal NPL site list NPL Proposed NPL NPL LIENS	. Proposed National Priority List Sites
Federal Delisted NPL site li	st
Delisted NPL	National Priority List Deletions
Federal CERCLIS list	
	Comprehensive Environmental Response, Compensation, and Liability Information System Federal Facility Site Information listing
Federal RCRA CORRACTS	facilities list
CORRACTS	Corrective Action Report
Federal RCRA non-CORRA	CTS TSD facilities list
RCRA-TSDF	RCRA - Treatment, Storage and Disposal
Federal RCRA generators li	ist
	RCRA - Large Quantity Generators RCRA - Small Quantity Generators
Federal institutional control	ls / engineering controls registries
US INST CONTROL	Engineering Controls Sites List Sites with Institutional Controls Land Use Control Information System

State- and tribal - equivalent CERCLIS

NPL list.

State and tribal landfill and/or solid waste disposal site lists

SWF/LF..... Solid Waste Facilities Database

State and tribal leaking storage tank lists

INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

FEMA UST..... Underground Storage Tank Listing

State and tribal voluntary cleanup sites

INDIAN VCP..... Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

BROWNFIELDS______ Brownfields and UST Site Database

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

..... Open Dump Inventory

DEBRIS REGION 9..... Torres Martinez Reservation Illegal Dump Site Locations

SWRCY..... Recycling Facilities

HIST LF..... Inactive Solid Waste Facilities

INDIAN ODI...... Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL..... Clandestine Drug Labs CDL..... Clandestine Drug Lab Listing

US HIST CDL..... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information

LIENS.....Lien List

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System

SPILLS...... Pollution Emergency Alerting System

Other Ascertainable Records

DOT OPS..... Incident and Accident Data

DOD...... Department of Defense Sites FUDS..... Formerly Used Defense Sites

CONSENT...... Superfund (CERCLA) Consent Decrees

ROD...... Records Of Decision UMTRA..... Uranium Mill Tailings Sites US MINES..... Mines Master Index File

TRIS...... Toxic Chemical Release Inventory System

TSCA...... Toxic Substances Control Act

Act)/TSCA (Toxic Substances Control Act)

HIST FTTS..... FIFRA/TSCA Tracking System Administrative Case Listing

SSTS..... Section 7 Tracking Systems

ICIS...... Integrated Compliance Information System PADS...... PCB Activity Database System MLTS..... Material Licensing Tracking System RADINFO...... Radiation Information Database

RAATS...... RCRA Administrative Action Tracking System

RMP..... Risk Management Plans

UIC...... Underground Injection Wells Database

DRYCLEANERS..... Drycleaning Establishments NPDES..... List of Active NPDES Permits AIRS..... Permit and Emissions Inventory Data

INDIAN RESERV...... Indian Reservations
SCRD DRYCLEANERS..... State Coalition for Remediation of Drycleaners Listing

Financial Assurance Information Listing PCB TRANSFORMER...... PCB Transformer Registration Database

COAL ASH..... Coal Ash Disposal Sites

US FIN ASSUR..... Financial Assurance Information

EPA WATCH LIST..... EPA WATCH LIST

COAL ASH DOE..... Steam-Electric Plant Operation Data 2020 COR ACTION............ 2020 Corrective Action Program List PRP...... Potentially Responsible Parties

LEAD SMELTERS..... Lead Smelter Sites

US AIRS..... Aerometric Information Retrieval System Facility Subsystem COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP..... EDR Proprietary Manufactured Gas Plants EDR US Hist Cleaners..... EDR Exclusive Historic Dry Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF...... Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in **bold italics** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS NFRAP site List

CERC-NFRAP: Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

A review of the CERC-NFRAP list, as provided by EDR, and dated 10/25/2013 has revealed that there is 1 CERC-NFRAP site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SPUR GAS STATION	420 STOCKING ST	SSE 1/4 - 1/2 (0.486 mi.)	N63	110

Federal RCRA generators list

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 06/10/2014 has revealed that there is 1 RCRA-CESQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MIKE WAWEE & SONS AUTO SALES I	856 7TH ST NW	W 0 - 1/8 (0.076 mi.)	B7	12

State and tribal leaking storage tank lists

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Environmental Quality's Leaking Underground Storage Tank (LUST) Database.

A review of the LUST list, as provided by EDR, and dated 08/01/2014 has revealed that there are 9

LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WALDMILLER ALL-SERVICE Facility Status: Closed	856 7TH ST NW	W 0 - 1/8 (0.076 mi.)	B8	13
EL MATADOR TORTILLA CHIPS (FOR Facility Status: Closed	669 STOCKING AVE NW	S 1/8 - 1/4 (0.168 mi.)	C12	25
CITY OF GRAND RAPIDS ROW Facility Status: Closed	800 LEONARD ST NW	N 1/4 - 1/2 (0.473 mi.)	O58	103
JACK'S SERVICE CENTER Facility Status: Open Facility Status: Closed	850 LEONARD ST NW	NNW 1/4 - 1/2 (0.484 mi.)	P59	106
Lower Elevation	Address	Direction / Distance	Map ID	Page
JOHN WIDDICOMB CO Facility Status: Closed	601 5TH ST NW	ESE 1/8 - 1/4 (0.240 mi.)	E21	29
J & L ROOFING CO Facility Status: Closed	567 11TH ST NW	NE 1/4 - 1/2 (0.346 mi.)	37	41
FOUR STAR SERVICE STATION #8 Facility Status: Closed	513 STOCKING NW	SSE 1/4 - 1/2 (0.417 mi.)	J45	45
AMERICAN SEATING CO Facility Status: Closed	901 BROADWAY AVE NW	ENE 1/4 - 1/2 (0.424 mi.)	L46	47
GSG LLC Facility Status: Closed	438 STOCKING AVE NW	SSE 1/4 - 1/2 (0.500 mi.)	N66	130

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Quality's Michigan UST database.

A review of the UST list, as provided by EDR, and dated 08/01/2014 has revealed that there are 4 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WALDMILLER ALL-SERVICE	856 7TH ST NW	W 0 - 1/8 (0.076 mi.)	B8	13
EL MATADOR TORTILLA CHIPS (FOR	669 STOCKING AVE NW	S 1/8 - 1/4 (0.168 mi.)	C12	25
Lower Elevation	Address	Direction / Distance	Map ID	Page
Lower Elevation GET IT GO	Address 5664 ALPINE NW	Direction / Distance S 1/8 - 1/4 (0.139 mi.)	Map ID	<u>Page</u> 23

State and tribal institutional control / engineering control registries

AUL: A listing of sites with institutional and/or engineering controls in place.

A review of the AUL list, as provided by EDR, and dated 09/03/2014 has revealed that there is 1 AUL site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
AMOCO STATION	1152 ELIZABETH AVENUE N	NNE 1/4 - 1/2 (0.469 mi.)	54	101

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 09/22/2014 has revealed that there are 5 US BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
STOCKING ELEMENTARY SCHOOL	863 SEVENTH ST. NW	W 0 - 1/8 (0.084 mi.)	В9	16
FORMER MILLER PRODUCTS PROPERT	601 AND 614 FIRST ST.,	SE 1/4 - 1/2 (0.443 mi.)	M48	54
MERCANTILE BANK PROPERTIES	420 AND 430 STOCKING AV	SSE 1/4 - 1/2 (0.468 mi.)	N53	88
Lower Elevation	Address	Direction / Distance	Map ID	Page
AMERICAN SEATING COMPANY HQ	901 BROADWAY AVENUE NV	` ,	L47	52
RALPH'S MARKET	655-667 LEONARD STREET	NNE 1/4 - 1/2 (0.489 mi.)	Q64	110

Local Lists of Hazardous waste / Contaminated Sites

INVENTORY: The Inventory of Facilities has three data sources: Facilities under Part 201, Environmental Remediation, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (NREPA) identified through state funded or private party response activities (Projects); Facilities under Part 213, Leaking Underground Storage Tanks of the NREPA; and Facilities identified through submittals of Baseline Environmental Assessments (BEA) submitted pursuant to Part 201 or Part 213 of the NREPA. The Part 201 Projects Inventory does not include all of the facilities that are subject to regulation under Part 201 because owners are not required to inform the Department of Environmental Quality (DEQ) about the facilities and can pursue cleanup independently. Facilities that are not known to DEQ are not on the Inventory, nor are locations with releases that resulted in low environmental impact. Part 213 facilities listed here may have more than one release; a list of releases for which corrective actions have been completed and list of releases for which corrective action has not been completed is located on the Leaking Underground Storage Tanks Site Search webpage. The DEQ may or may not have reviewed and concurred with the conclusion that the corrective actions described in a closure report meets criteria. A BEA is a document that new or prospective property owners/operations disclose to the DEQ identifying the property as a facility pursuant to Part 201 and Part 213. The Inventory of BEA Facilities overlaps in part with the Part 201 Projects facilities and Part 213 facilities. There may be more than one BEA for each facility.

A review of the INVENTORY list, as provided by EDR, and dated 10/27/2014 has revealed that there are

23 INVENTORY sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
555 7TH STREET NW	555 7TH STREET NW AKA 8	SW 0 - 1/8 (0.005 mi.)	A6	12
618 DEWEY AVENUE NW	618 DEWEY AVENUE NW	SE 1/4 - 1/2 (0.387 mi.)	138	42
607 DEWEY AVENUE NW	607 DEWEY AVENUE NW	SE 1/4 - 1/2 (0.391 mi.)	140	43
1147 ALPINE AVENUE NW	1147 ALPINE AVENUE NW	N 1/4 - 1/2 (0.405 mi.)	K44	45
601, 614 1ST ST/520 2ND ST/501	601 & 614 1ST ST, 520 2	SSE 1/4 - 1/2 (0.472 mi.)	M56	103
500 & 502 2ND STREET NW	500 & 502 2ND STREET NW	SE 1/4 - 1/2 (0.472 mi.)	M57	103
JACK'S SERVICE CENTER	850 LEONARD ST NW	NNW 1/4 - 1/2 (0.484 mi.)	P59	106
1ST STREET N.W., 601	601 1ST STREET NW	SSE 1/4 - 1/2 (0.485 mi.)	60	109
900 LEONARD STREET NW	900 LEONARD STREET NW	NNW 1/4 - 1/2 (0.497 mi.)	P65	130
Lower Elevation	Address	Direction / Distance	Map ID	Page
600 7TH STREET NW	600 7TH STREET NW	E 1/8 - 1/4 (0.174 mi.)	D13	26
600 SEVENTH STREET NW	600 SEVENTH STREET NW	E 1/8 - 1/4 (0.174 mi.)	D14	27
601 & 611 5TH ST/609 6TH ST/71	601 & 611 5TH STREET NW	ESE 1/8 - 1/4 (0.226 mi.)	E16	28
601&611 FIFTH, 609 SIXTH, 710	601 & 611 FIFTH ST NW,	ESE 1/8 - 1/4 (0.226 mi.)	E17	28
JOHN WIDDICOMB PROPERTY	600 BLOCK OF FIFTH STRE	ESE 1/8 - 1/4 (0.226 mi.)	E18	29
601 5TH STREET NW	601 5TH STREET NW	ESE 1/8 - 1/4 (0.226 mi.)	E19	29
JOHN WIDDICOMB CO	601 5TH ST NW	ESE 1/8 - 1/4 (0.240 mi.)	E21	29
600 FIFTH STREET N. W.	600 FIFTH STREET N. W.	SE 1/4 - 1/2 (0.276 mi.)	G28	37
516 SEVENTH STREET NW	516 SEVENTH STREET NW	E 1/4 - 1/2 (0.295 mi.)	F32	39
560 FIFTH STREET NW	560 FIFTH STREET NW	ESE 1/4 - 1/2 (0.296 mi.)	G33	39
522 STOCKING AVENUE NW	522 STOCKING AVENUE NW	SSE 1/4 - 1/2 (0.398 mi.)	J41	43
AMERICAN SEATING CO	901 BROADWAY AVE NW	ENE 1/4 - 1/2 (0.424 mi.)	L46	47
EQUILON ENTERPRISES LLC	747 LEONARD ST NW	N 1/4 - 1/2 (0.472 mi.)	O55	102
667 LEONARD STREET NW	667 LEONARD STREET NW	NNE 1/4 - 1/2 (0.485 mi.)	Q61	109

PART 201: A Part 201 Listed site is a location that has been evaluated and scored by the DEQ using the Part 201 scoring model. The location is or includes a "facility" as defined by Part 201, where there has been a release of a hazardous substance(s) in excess of the Part 201 residential criteria, and/or where corrective actions have not been completed under Part 201 to meet the applicable cleanup criteria for unrestricted residential use. The Part 201 List does not include all of the sites of contamination that are subject to regulation under Part 201 because owners are not required to inform the DEQ about the sites and can pursue cleanup independently. Sites of environmental contamination that are not known to DEQ are not on the list, nor are sites with releases that resulted in low environmental impact.

A review of the PART 201 list, as provided by EDR, and dated 10/01/2013 has revealed that there are 6 PART 201 sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
AUTOBOND (FORMER)	706 BOND AVE. NW	ESE 1/2 - 1 (0.841 mi.)	71	135
RELIABLE EQUIPMENT	633 RICHMOND ST NW	NNE 1/2 - 1 (0.982 mi.)	72	137
Lower Elevation	Address	Direction / Distance	Map ID	Page
JOHN WIDDICOMB CO	601 5TH ST NW	ESE 1/8 - 1/4 (0.240 mi.)	E21	29
AMERICAN SEATING CO	901 BROADWAY AVE NW	ENE 1/4 - 1/2 (0.424 mi.)	L46	47
NO AM CORP	329 SUMMER AVE NW	SSE 1/2 - 1 (0.701 mi.)	67	132
WOLVERINE BRASS WORKS	648 MONROE AVE NW	ESE 1/2 - 1 (0.814 mi.)	69	134

DEL PART 201: A deleted site has been removed from the Part 201 List because information known to the DEQ at the time of the evaluation does not support inclusion on the Part 201 List. This designation is often applied to sites where changes in cleanup criteria resulted in a determination that the site no longer exceeds any applicable cleanup criterion. A delisted site has been removed from the Part 201 List because response actions have reduced the levels of contaminants to concentrations which meet or are below the criteria for unrestricted residential use.

A review of the DEL PART 201 list, as provided by EDR, and dated 08/01/2013 has revealed that there are 6 DEL PART 201 sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
JOHN WIDDICOMB CO	601 5TH ST NW	ESE 1/8 - 1/4 (0.240 mi.)	E21	29
5TH STREET NW, 600	600 5TH STREET NW	ESE 1/4 - 1/2 (0.266 mi.)	G27	37
4TH STREET NW, 615	615 4TH STREET NW	SE 1/4 - 1/2 (0.292 mi.)	H29	38
JEUP INC	560 5TH ST NW	ESE 1/4 - 1/2 (0.296 mi.)	G34	40
900-1010 MONROE AVENUE NW	900-1010 MONROE AVENUE	E 1/2 - 1 (0.762 mi.)	68	133
WHITTAKER ELECTRIC	1320 FRONT	NE 1/2 - 1 (0.831 mi.)	70	135

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 06/10/2014 has revealed that there are 2 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MI DEPT/STATE POLICE	648 6TH ST NW	ESE 1/8 - 1/4 (0.165 mi.)	11	24
WIDDICOMB JOHN CO	601 5TH ST NW	ESE 1/8 - 1/4 (0.240 mi.)	E22	32

BEA: A BEA is a document that new or prospective property owners/operations disclose to the DEQ identifying the property as a facility pursuant to Part 201 and Part 213. The Inventory of BEA Facilities overlaps in part with the Part 201 Projects facilities and Part 213 facilities. There may be more than one BEA for each facility.

A review of the BEA list, as provided by EDR, and dated 08/21/2013 has revealed that there are 19 BEA sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
607 DEWEY AVENUE NW	607 DEWEY AVENUE NW	SE 1/4 - 1/2 (0.391 mi.)	139	43
1147 ALPINE AVENUE NW	1147 ALPINE AVENUE NW	N 1/4 - 1/2 (0.405 mi.)	K43	44
614 FIRST STREET PARTNERS LLC	601 1ST ST NW	SE 1/4 - 1/2 (0.443 mi.)	M49	<i>7</i> 8
601, 614 1ST ST/520 2ND ST/501	601 & 614 1ST ST, 520 2	SE 1/4 - 1/2 (0.443 mi.)	M50	86
601 & 614 1ST ST/501 ALABAMA/5	601 & 614 1ST STREET &	SE 1/4 - 1/2 (0.443 mi.)	M51	87
601 FIRST STREET NW	601 FIRST STREET NW	SE 1/4 - 1/2 (0.443 mi.)	M52	87
500 & 502 2ND STREET NW	500 & 502 2ND STREET NW	SE 1/4 - 1/2 (0.472 mi.)	M57	103
Lower Elevation	Address	Direction / Distance	Map ID	Page
600 SEVENTH STREET NW	600 SEVENTH STREET NW	ESE 1/8 - 1/4 (0.207 mi.)	D15	27

Lower Elevation	Address	Direction / Distance	Map ID	Page
JOHN WIDDICOMB CO	601 5TH ST NW	ESE 1/8 - 1/4 (0.240 mi.)	E21	29
601 & 611 5TH ST/609 6TH ST/71	601 & 611 5TH STREET NW	ESE 1/8 - 1/4 (0.240 mi.)	E23	35
555 7TH STREET NW	555 7TH STREET NW	E 1/4 - 1/2 (0.251 mi.)	F24	36
JOHN WIDDICOMB PROPERTY	600 BLOCK OF FIFTH STRE	ESE 1/4 - 1/2 (0.265 mi.)	E25	36
600 FIFTH STREET N. W.	600 FIFTH STREET N. W.	ESE 1/4 - 1/2 (0.266 mi.)	G26	37
615 FOURTH STREET NW	615 FOURTH STREET NW	SE 1/4 - 1/2 (0.292 mi.)	H30	38
516 SEVENTH STREET NW	516 SEVENTH STREET NW	E 1/4 - 1/2 (0.295 mi.)	F31	38
560 FIFTH STREET NW	560 FIFTH STREET NW	ESE 1/4 - 1/2 (0.296 mi.)	G35	40
AMERICAN SEATING	801-889 BROADWAY AVENUE	E ENE 1/4 - 1/2 (0.303 mi.)	36	41
OXY METAL INDUSTRIES CORP GRAN	522 STOCKING AVE NW	SSE 1/4 - 1/2 (0.398 mi.)	J42	44
667 LEONARD STREET NW	667 LEONARD STREET NW	NNE 1/4 - 1/2 (0.485 mi.)	Q62	109

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR US Hist Auto Stat: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Auto Stat list, as provided by EDR, has revealed that there is 1 EDR US Hist Auto Stat site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	1002 ALPINE AVE NW	N 1/8 - 1/4 (0.227 mi.)	20	29


Due to poor or inadequate address information, the following sites were not mapped. Count: 4 records.

Site Name

68TH. ST. & DIVISION AREA 1271-1727 ALPINE AVENUE 3718 ALPINE AVENUE NW 1750 ALPINE AVENUE N. W. (A TO Z M Database(s)

PART 201, DEL PART 201 INVENTORY INVENTORY INVENTORY

OVERVIEW MAP - 04170139.2R



802 Alpine Avenue NW 802 Alpine Avenue NW

Grand Rapids MI 49504

42.9782 / 85.6877

SITE NAME: ADDRESS:


LAT/LONG:

CLIENT: PM Environmental, Inc. CONTACT: Lindsey Sorensen INQUIRY #: 04170139.2r

DATE: December 30, 2014 8:42 am

Copyright © 2014 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

DETAIL MAP - 04170139.2R



display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 802 Alpine Avenue NW ADDRESS: 802 Alpine Avenue NW Grand Rapids MI 49504

LAT/LONG: 42.9782 / 85.6877

CLIENT: PM Environmental, Inc. CONTACT: Lindsey Sorensen INQUIRY #: 04170139.2r

DATE: December 30, 2014 8:42 am

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	Total Plotted
STANDARD ENVIRONMENT	AL RECORDS							
Federal NPL site list								
NPL Proposed NPL NPL LIENS	1.000 1.000 TP		0 0 NR	0 0 NR	0 0 NR	0 0 NR	NR NR NR	0 0 0
Federal Delisted NPL site	e list							
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
CERCLIS FEDERAL FACILITY	0.500 0.500		0 0	0 0	0 0	NR NR	NR NR	0 0
Federal CERCLIS NFRAF	site List							
CERC-NFRAP	0.500		0	0	1	NR	NR	1
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators	s list							
RCRA-LQG RCRA-SQG RCRA-CESQG	0.250 0.250 0.250		0 0 1	0 0 0	NR NR NR	NR NR NR	NR NR NR	0 0 1
Federal institutional controls / engineering controls registries								
US ENG CONTROLS US INST CONTROL LUCIS	0.500 0.500 0.500		0 0 0	0 0 0	0 0 0	NR NR NR	NR NR NR	0 0 0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
SHWS	1.000		0	0	0	0	NR	0
State and tribal landfill and/or solid waste disposal site lists								
SWF/LF	0.500		0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
LUST INDIAN LUST	0.500 0.500	1	1 0	2 0	6 0	NR NR	NR NR	10 0
State and tribal registered storage tank lists								
UST	0.250	1	1	3	NR	NR	NR	5

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
AST INDIAN UST FEMA UST	0.250 0.250 0.250		0 0 0	0 0 0	NR NR NR	NR NR NR	NR NR NR	0 0 0
State and tribal institution control / engineering control /		s						
AUL	0.500		0	0	1	NR	NR	1
State and tribal voluntary	y cleanup site	es						
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfie	elds sites							
BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMEN	TAL RECORDS	:						
ALDERIO IL LIVINGO IL		_						
Local Brownfield lists								
US BROWNFIELDS	0.500		1	0	4	NR	NR	5
Local Lists of Landfill / Solid Waste Disposal Sites								
ODI DEBRIS REGION 9 SWRCY HIST LF INDIAN ODI	0.500 0.500 0.500 0.500 0.500		0 0 0 0	0 0 0 0	0 0 0 0	NR NR NR NR NR	NR NR NR NR NR	0 0 0 0
Local Lists of Hazardous waste / Contaminated Sites								
US CDL INVENTORY PART 201 DEL PART 201 CDL US HIST CDL	TP 0.500 1.000 1.000 TP TP		NR 1 0 0 NR NR	NR 7 1 1 NR NR	NR 15 1 3 NR NR	NR NR 4 2 NR NR	NR NR NR NR NR	0 23 6 6 0
Local Land Records								
LIENS 2 LIENS	TP TP		NR NR	NR NR	NR NR	NR NR	NR NR	0 0
Records of Emergency Release Reports								
HMIRS SPILLS	TP TP		NR NR	NR NR	NR NR	NR NR	NR NR	0 0
Other Ascertainable Records								
RCRA NonGen / NLR DOT OPS DOD FUDS CONSENT	0.250 TP 1.000 1.000 1.000	1	0 NR 0 0	2 NR 0 0	NR NR 0 0	NR NR 0 0	NR NR NR NR NR	3 0 0 0 0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	<u>1/2 - 1</u>	<u>> 1</u>	Total Plotted
ROD UMTRA US MINES TRIS TSCA FTTS HIST FTTS SSTS ICIS PADS MLTS RADINFO FINDS RAATS RMP UIC DRYCLEANERS NPDES AIRS BEA INDIAN RESERV SCRD DRYCLEANERS Financial Assurance PCB TRANSFORMER COAL ASH US FIN ASSUR EPA WATCH LIST COAL ASH DOE 2020 COR ACTION PRP LEAD SMELTERS US AIRS COAL ASH EPA	1.000 0.500 0.250 TP TP TP TP TP TP TP TP TP TP TP TP TP	1	0 0 0 R R R R R R R R R R R R R O O O R R O R R R O R	000 R R R R R R R R R R R R R R R R R R	0 0 R R R R R R R R R R R R R R R R R R	ORRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRR		0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
WDS	TP	1	NR	NR	NR	NR	NR	1
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records EDR MGP	1.000		0	0	0	0	NR	0
EDR US Hist Auto Stat EDR US Hist Cleaners	0.250 0.250	1	0	1 0	NR NR	0 NR NR	NR NR	0 2 0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Go	vt. Archives							
RGA LUST RGA PART 201 RGA LF	TP TP TP	2	NR NR NR	NR NR NR	NR NR NR	NR NR NR	NR NR NR	2 0 0

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

A1 NORTH END TRANSMISSION SERVICE LUST U003328538
Target 802 ALPINE NE UST N/A

Target 802 ALPINE NE UST N/
Property GRAND RAPIDS, MI 49504 WDS

Site 1 of 6 in cluster A

Actual: LUST: **615 ft.** Facility ID: 00013761

Source: STATE OF MICHIGAN
Owner Name: North End Transmission
Owner Address: 802 Alpine Ave NW

Owner City, St, Zip: Grand Rapids, MI 49504-4410

Owner Contact: Not reported
Owner Phone: (616) 454-3097

Country: USA

District: Grand Rapids District Office
Site Name: North End Transmission

Latitude: 42.97805 Longitude: -85.68763 Date of Collection: 01/11/2001

Method of Collection: Address Matching-House Number

Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Data: NAD83
Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Leak Number:C-0390-90Release Date:01/23/1990Substance Released:Not reportedRelease Status:ClosedRelease Closed Date:01/09/1992

UST:

Facility ID: 00013761
Facility Type: CLOSED

Owner Name: NORTH END TRANSMISSION

Owner Address: 802 ALPINE AVE NW

Owner City, St, Zip: GRAND RAPIDS, MI 49504-4410

Owner Country: USA
Owner Contact: Not reported
Owner Phone: (616) 454-3097

Contact: Edward D & Betsy K Sherd

Contact Phone: (616) 874-6816
Date of Collection: 01/11/2001
Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Latitude: 42.97805 Longitude: -85.68763

Tank ID: 1

Tank Status: Removed from Ground

Capacity: 5000
Product: Used Oil
Install Date: Not reported

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

NORTH END TRANSMISSION SERVICE (Continued)

U003328538

Remove Date: 01/23/1990 Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Galvanized Steel Piping Type: Not reported Construction Material: Unknown Impressed Device: No

Tank ID:

Removed from Ground **Tank Status:**

1000 Capacity: Product: Not reported Not reported Install Date: 01/23/1990 Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Galvanized Steel Piping Type: Not reported Construction Material: Unknown Impressed Device: No

WDS:

Site Id: MID017095530

WMD Id: 394764

Site Specific Name: NORTH END TRANSMISSION INC

Mailing Address: 802 ALPINE AVE NW

Mailing City/State/Zip: 49504 Mailing County: **KENT**

NORTH END TRANSMISSION SERVICE **A2**

Target 802 ALPINE NE GRAND RAPIDS, MI Property

RGA LUST S115688328 N/A

Site 2 of 6 in cluster A

RGA LUST: Actual:

615 ft.

2012	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
2011	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
2010	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
2009	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
2008	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
2007	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
2006	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
2005	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
2004	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
2003	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
2001	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
2000	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
1999	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
1998	NORTH END TRANSMISSION SERVICE	802 ALPINE NE
1997	NORTH END TRANSMISSION SERVICE	802 ALPINE NE

Direction Distance

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

A3 NORTH END TRANSMISSION RGA LUST S115688329

Target 802 ALPINE Property GRAND RAPIDS, MI

Site 3 of 6 in cluster A

Actual: RGA LUST:

615 ft. 1991 NORTH END TRANSMISSION 802 ALPINE

A4 EDR US Hist Auto Stat 1015639496 Target 802 ALPINE AVE NW EDR US Hist Auto Stat N/A

Target 802 ALPINE AVE NW Property GRAND RAPIDS, MI 49504

, ,

Site 4 of 6 in cluster A

Actual: EDR Historical Auto Stations:

615 ft. Name: NORTH END FAMILY RESTAURANT NORTH END TRANSMISSION

Year: 1999

Address: 802 ALPINE AVE NW

Name: NORTH END FAMILY RESTAURANT NORTH END TRANSMISSION

Year: 2000

Address: 802 ALPINE AVE NW

Name: NORTH END TRANSMISSION

Year: 2001

Address: 802 ALPINE AVE NW

Name: NORTH END TRANSMISSION SERVICE INC

Year: 2003

Address: 802 ALPINE AVE NW

Name: NORTH END TRANSMISSION SERVICE INC

Year: 2005

Address: 802 ALPINE AVE NW

Name: NORTH END TRANSMISSION SERVICE INC

Year: 2006

Address: 802 ALPINE AVE NW

Name: NORTH END TRANSMISSION SERVICE INC

Year: 2007

Address: 802 ALPINE AVE NW

Name: NORTH END TRANSMISSION SERVICE INC

Year: 2008

Address: 802 ALPINE AVE NW

Name: NORTH END TRANSMISSION SERVICE

Year: 2009

Address: 802 ALPINE AVE NW

Name: NORTH END TRANSMISSION SERVICES

Year: 2011

Address: 802 ALPINE AVE NW

Name: NORTH END TRANSMISSION SERVICES

Year: 2012

N/A

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

(Continued) 1015639496

Address: 802 ALPINE AVE NW

Α5 NORTH END TRANSMISSION INC RCRA NonGen / NLR 1000405792 **FINDS** MID017095530

Target 802 ALPINE AVE NW Property GRAND RAPIDS, MI 49504

Site 5 of 6 in cluster A

RCRA NonGen / NLR: Actual:

Date form received by agency: 12/31/2001 615 ft.

NORTH END TRANSMISSION INC Facility name:

Facility address: 802 ALPINE AVE NW

GRAND RAPIDS, MI 49504

EPA ID: MID017095530 DAVID SHERD Contact: Contact address: 802 ALPINE AVE NW

GRAND RAPIDS, MI 49504

Contact country: US

Contact telephone: (616) 454-3097 Contact email: Not reported

EPA Region: 05 Land type: Private Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

SHERD DAVID Owner/operator name:

Owner/operator address: Not reported Not reported

Not reported

Owner/operator country: Owner/operator telephone: Not reported Legal status: Private Operator Owner/Operator Type: Owner/Op start date: 12/01/1986 Owner/Op end date: Not reported

SHERD DAVID Owner/operator name: Owner/operator address: Not reported

Not reported

Not reported Owner/operator country: Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Owner 12/01/1986 Owner/Op start date: Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No

Direction Distance

Elevation Site Database(s) EPA ID Number

NORTH END TRANSMISSION INC (Continued)

1000405792

EDR ID Number

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 10/09/1987

Site name: NORTH END TRANSMISSION INC

Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 01/03/1995

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003588243

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

TC04170139.2r Page 11

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

A6 **555 7TH STREET NW INVENTORY** S114027867 555 7TH STREET NW AKA 801 BROADWAY AVENUE NW SW N/A

KENT (County), MI 49504 < 1/8

0.005 mi.

24 ft. Site 6 of 6 in cluster A

Relative:

INVENTORY:

Higher

201303480GR Bea Number: Township: **Grand Rapids** District: **Grand Rapids**

Actual: 615 ft.

Data Source: BEA Latitude: Not reported Longitude: Not reported

201203330GR Bea Number: Township: **Grand Rapids** District: **Grand Rapids** Data Source: **BEA** Latitude: Not reported Longitude: Not reported

B7 MIKE WAWEE & SONS AUTO SALES INC

West **856 7TH ST NW**

< 1/8 **GRAND RAPIDS, MI 49504**

0.076 mi. 400 ft.

Site 1 of 3 in cluster B

RCRA-CESQG: Relative:

Date form received by agency: 01/24/2006 Higher Facility name: MIKE WAWEE & SONS AUTO SALES INC

Actual: Facility address: 856 7TH ST NW

619 ft.

GRAND RAPIDS, MI 49504

EPA ID: MIK226916773

Contact: CHRIS WAWEE Contact address: 856 7TH ST NW

GRAND RAPIDS, MI 49504

Contact country: US

Contact telephone: (616) 791-1043 Contact email: Not reported

EPA Region: 05

Conditionally Exempt Small Quantity Generator Classification:

Handler: generates 100 kg or less of hazardous waste per calendar Description: month, and accumulates 1000 kg or less of hazardous waste at any time;

or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

the cleanup of a spill, into or on any land or water, of acutely

hazardous waste

Owner/Operator Summary:

Owner/operator name: **CHRIS WAWEE** Owner/operator address: Not reported

RCRA-CESQG

1009312026

MIK226916773

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MIKE WAWEE & SONS AUTO SALES INC (Continued)

1009312026

Not reported Owner/operator country: Not reported Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: 09/01/2002 Owner/Op end date: Not reported

CHRIS WAWEE Owner/operator name: Owner/operator address: Not reported Not reported Not reported Owner/operator country:

Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Operator 09/01/2002 Owner/Op start date: Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: Nο Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: Nο Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Hazardous Waste Summary:

Waste code: D001

IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF Waste name:

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET. WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

B8 WALDMILLER ALL-SERVICE LUST U003328372

West **856 7TH ST NW** UST N/A < 1/8 **GRAND RAPIDS, MI 49504 WDS**

0.076 mi.

400 ft. Site 2 of 3 in cluster B

LUST: Relative:

Facility ID: 00011368 Higher

Source: STATE OF MICHIGAN Actual: Owner Name: Richard Waldmiller 619 ft. Owner Address: 359 Scott Ave NW

Direction Distance

Elevation Site Database(s) EPA ID Number

WALDMILLER ALL-SERVICE (Continued)

Owner City, St, Zip: Grand Rapids, MI 49504-4980

Owner Contact: Not reported Owner Phone: (616) 453-3082

Country: USA

District: Grand Rapids District Office
Site Name: Waldmiller All-service

Latitude: 42.97778
Longitude: -85.68973
Date of Collection: 01/11/2001

Method of Collection: Address Matching-House Number

Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Data: NAD83
Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Leak Number: C-0685-99
Release Date: 07/14/1999
Substance Released: Unknown
Release Status: Closed
Release Closed Date: 01/03/2000

UST:

Facility ID: 00011368 Facility Type: CLOSED

Owner Name: RICHARD WALDMILLER
Owner Address: 359 SCOTT AVE NW

Owner City, St, Zip: GRAND RAPIDS, MI 49504-4980

Owner Country: USA
Owner Contact: Not reported
Owner Phone: (616) 453-3082

Contact: RICHARD WALDMILLER

Contact Phone: (616) 453-3082
Date of Collection: 01/11/2001
Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Latitude: 42.97778 Longitude: -85.68973

Tank ID:

Tank Status: Removed from Ground

Capacity: 3000
Product: Gasoline
Install Date: Not reported
Remove Date: 07/16/1987
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

EDR ID Number

U003328372

Direction Distance

Elevation Site Database(s) EPA ID Number

WALDMILLER ALL-SERVICE (Continued)

U003328372

EDR ID Number

Tank ID: 2

Tank Status: Removed from Ground

Capacity: 3000
Product: Gasoline
Install Date: Not reported
Remove Date: 07/16/1987
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID:

Tank Status: Removed from Ground

Capacity: 3000
Product: Kerosene
Install Date: Not reported
Remove Date: 07/16/1987
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 4

Tank Status: Removed from Ground

Capacity: 500

Product: Not reported
Install Date: Not reported
Remove Date: 07/16/1987
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 5

Tank Status: Removed from Ground

Capacity: 500
Product: Used Oil
Install Date: Not reported
Remove Date: 07/31/1995
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

WDS:

Site Id: MIK226916773

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

WALDMILLER ALL-SERVICE (Continued)

U003328372

WMD Id: 480522

MIKE WAWEE & SONS AUTO SALES INC Site Specific Name:

Mailing Address: 856 7TH ST NW

Mailing City/State/Zip: 49504 Mailing County: **KENT**

В9 STOCKING ELEMENTARY SCHOOL **US BROWNFIELDS** 1016457135 **FINDS** N/A

Grand Rapids, City of

West 863 SEVENTH ST. NW **GRAND RAPIDS, MI 49504** < 1/8

0.084 mi.

446 ft.

Site 3 of 3 in cluster B

Relative:

US BROWNFIELDS:

Recipient name: Higher

Grant type: Assessment

Actual: Property name: STOCKING ELEMENTARY SCHOOL 619 ft.

Property #: 41-13-23-284-011

> Parcel size: 3.7

Property Description: Records reviewed indicated the property was developed as residential

prior to construction of the Stocking school on the property; the property was owned by Grand Rapids Public Schools beginning about

1920. The school building was completed around 1923.

Latitude: Not reported Not reported Longitude: HCM label: Not reported Map scale: Not reported Point of reference: Not reported

Datum: North American Datum of 1927

ACRES property ID: 170856 Start date: Not reported Not reported Completed date: Acres cleaned up: Not reported Cleanup funding: Not reported Cleanup funding source: Not reported Assessment funding: 3013

Private/Other Funding Assessment funding source:

Redevelopment funding: Not reported Not reported Redev. funding source: Not reported Redev. funding entity name: Not reported Redevelopment start date:

Assessment funding entity: GR School Lofts, LLC

Cleanup funding entity: Not reported

Grant type:

Accomplishment type: Phase II Environmental Assessment

Accomplishment count:

Cooperative agreement #: 00E00416 Ownership entity: Government

Grand Rapids Public School District Current owner:

Did owner change: Cleanup required: Unknown Video available: No Photo available: Yes

Institutional controls required: Not reported IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported IC in place date: Not reported

Distance
Elevation Site

EDR ID Number
Database(s) EPA ID Number

STOCKING ELEMENTARY SCHOOL (Continued)

1016457135

IC in place: Not reported State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Air cleaned: Not reported Asbestos found: Not reported Not reported Asbestos cleaned: Controled substance found: Not reported Controled substance cleaned: Not reported Not reported Drinking water affected: Not reported Drinking water cleaned: Groundwater affected: Not reported Groundwater cleaned: Not reported Lead contaminant found: Not reported Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported Other metals found: Not reported Not reported Other metals cleaned: Other contaminants found: Not reported Other contams found description: Not reported PAHs found: Not reported PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported Petro products found: Not reported Petro products cleaned: Not reported Sediments found: Not reported Not reported Sediments cleaned: Soil affected: Not reported Not reported Soil cleaned up: Surface water cleaned: Not reported VOCs found: Not reported VOCs cleaned: Not reported Cleanup other description: Not reported Num. of cleanup and re-dev. jobs: Not reported Past use greenspace acreage: Not reported Past use residential acreage: Not reported Not reported Past use commercial acreage: Past use industrial acreage: Not reported Future use greenspace acreage: Not reported Not reported Future use residential acreage: Not reported Future use commercial acreage: Future use industrial acreage: Not reported Greenspace acreage and type: Not reported Superfund Fed. landowner flag: Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported

Pesticides cleaned up:

Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

STOCKING ELEMENTARY SCHOOL (Continued)

1016457135

EDR ID Number

Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Not reported Unknown clean up: Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Not reported Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Not reported Mercury contaminant found: Nickel contaminant found: Not reported Not reported No contaminant found: Not reported Pesticides contaminant found: Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

Property name: STOCKING ELEMENTARY SCHOOL

Property #: 41-13-23-284-011

Parcel size: 3.7

Property Description: Records reviewed indicated the property was developed as residential

prior to construction of the Stocking school on the property; the property was owned by Grand Rapids Public Schools beginning about

1920. The school building was completed around 1923.

Latitude: Not reported
Longitude: Not reported
HCM label: Not reported
Map scale: Not reported
Point of reference: Not reported

Datum: North American Datum of 1927

ACRES property ID: 170856
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported

Assessment funding: 3537

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding:
Redev. funding source:
Redev. funding entity name:
Redevelopment start date:
Assessment funding entity:
Cleanup funding entity:

Not reported
EPA
Not reported
Not reported

Grant type:

Accomplishment type: Phase II Environmental Assessment

Accomplishment count: 0

Cooperative agreement #: 00E00416
Ownership entity: Government

Distance EDR ID Number
Elevation Site EDR ID Number
Database(s) EPA ID Number

STOCKING ELEMENTARY SCHOOL (Continued)

1016457135

Current owner: Grand Rapids Public School District

Did owner change: Y

Cleanup required: Unknown Video available: No Photo available: Yes

Photo available: Institutional controls required: Not reported Not reported IC Category proprietary controls: Not reported IC cat. info. devices: IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported IC in place date: Not reported Not reported IC in place: State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Not reported Air cleaned: Asbestos found: Not reported Asbestos cleaned: Not reported Controled substance found: Not reported Not reported Controled substance cleaned: Drinking water affected: Not reported Drinking water cleaned: Not reported Groundwater affected: Not reported Groundwater cleaned: Not reported Not reported Lead contaminant found: Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Not reported Other cleaned up: Other metals found: Not reported Other metals cleaned: Not reported Not reported Other contaminants found: Other contams found description: Not reported Not reported PAHs found: PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported Petro products found: Not reported Petro products cleaned: Not reported Sediments found: Not reported Not reported Sediments cleaned: Soil affected: Not reported Soil cleaned up: Not reported Surface water cleaned: Not reported VOCs found: Not reported VOCs cleaned: Not reported Cleanup other description: Not reported Num. of cleanup and re-dev. jobs: Not reported Not reported Past use greenspace acreage: Past use residential acreage: Not reported Past use commercial acreage: Not reported Not reported Past use industrial acreage: Not reported Future use greenspace acreage: Future use residential acreage: Not reported Future use commercial acreage: Not reported Future use industrial acreage: Not reported

Distance

Elevation Site Database(s) EPA ID Number

STOCKING ELEMENTARY SCHOOL (Continued)

1016457135

EDR ID Number

Greenspace acreage and type: Not reported Superfund Fed. landowner flag: Arsenic cleaned up: Not reported Not reported Cadmium cleaned up: Chromium cleaned up: Not reported Copper cleaned up: Not reported Not reported Iron cleaned up: Not reported mercury cleaned up: nickel cleaned up: Not reported No clean up: Not reported Not reported Pesticides cleaned up: Not reported Selenium cleaned up: SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Not reported Chromium contaminant found: Not reported Copper contaminant found: Iron contaminant found: Not reported Mercury contaminant found: Not reported Not reported Nickel contaminant found: No contaminant found: Not reported Pesticides contaminant found: Not reported Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Not reported Unknown contaminant found: Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

Property name: STOCKING ELEMENTARY SCHOOL

Not reported

Not reported

Property #: 41-13-23-284-011

Parcel size: 3.7

Unknown media cleaned up:

Past Use: Multistory

Property Description: Records reviewed indicated the property was developed as residential

prior to construction of the Stocking school on the property; the

property was owned by Grand Rapids Public Schools beginning about

1920. The school building was completed around 1923.

Latitude: Not reported
Longitude: Not reported
HCM label: Not reported
Map scale: Not reported
Point of reference: Not reported

Datum: North American Datum of 1927

ACRES property ID: 170856
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported
Assessment funding: 2500

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Distance Elevation

on Site Database(s) EPA ID Number

STOCKING ELEMENTARY SCHOOL (Continued)

1016457135

EDR ID Number

Redevelopment funding:
Redev. funding source:
Redev. funding entity name:
Redevelopment start date:
Assessment funding entity:

Not reported
Not reported
Not reported
EPA

Cleanup funding entity: Not reported

Grant type:

Accomplishment type: Phase I Environmental Assessment

Accomplishment count: 1

Cooperative agreement #: 00E00416
Ownership entity: Government

Current owner: Grand Rapids Public School District

Did owner change:

Cleanup required:

Video available:

Photo available:

Ves

Institutional controls required: Not reported IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported IC in place date: Not reported IC in place: Not reported State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Air cleaned: Not reported Asbestos found: Not reported Not reported Asbestos cleaned: Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported Not reported Groundwater affected: Groundwater cleaned: Not reported Lead contaminant found: Not reported Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Not reported Other cleaned up: Not reported Other metals found: Other metals cleaned: Not reported Not reported Other contaminants found: Not reported Other contams found description: PAHs found: Not reported PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported Petro products found: Not reported Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported Soil affected: Not reported Soil cleaned up: Not reported Surface water cleaned: Not reported

Not reported

VOCs found:

Distance Elevation Site

Site Database(s) EPA ID Number

STOCKING ELEMENTARY SCHOOL (Continued)

1016457135

EDR ID Number

VOCs cleaned: Not reported Cleanup other description: Not reported Not reported Num. of cleanup and re-dev. jobs: Not reported Past use greenspace acreage: Past use residential acreage: Not reported Past use commercial acreage: Not reported Past use industrial acreage: Not reported Not reported Future use greenspace acreage: Future use residential acreage: Not reported Future use commercial acreage: Not reported Future use industrial acreage: Not reported Greenspace acreage and type: Not reported Superfund Fed. landowner flag: Not reported Not reported

Arsenic cleaned up: Cadmium cleaned up: Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported mercury cleaned up: Not reported nickel cleaned up: Not reported Not reported No clean up: Pesticides cleaned up: Not reported Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Unknown clean up: Not reported Not reported Arsenic contaminant found: Cadmium contaminant found: Not reported Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Not reported Not reported Mercury contaminant found: Nickel contaminant found: Not reported Not reported No contaminant found: Pesticides contaminant found: Not reported Not reported Selenium contaminant found: Not reported SVOCs contaminant found: Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Not reported Past Use: Multistory

FINDS:

Registry ID: 110057202600

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Direction Distance

Elevation Site Database(s) EPA ID Number

C10 GET IT GO UST U003327697
South 5664 ALPINE NW N/A

1/8-1/4 GRAND RAPIDS, MI 49544

0.139 mi.

734 ft. Site 1 of 2 in cluster C

Relative: Lower UST:

Facility ID: 00002673
Facility Type: CLOSED

Actual: 614 ft.

Owner Name: VAN MANEN OIL INC

Owner Address: O-305 LAKE MICHIGAN DR NW Owner City,St,Zip: GRAND RAPIDS, MI 49544-3355

Owner Country: USA Owner Contact: Not reported (616) 453-6344 Owner Phone: Contact: G. VAN MANEN (616) 453-6344 Contact Phone: 01/11/2001 Date of Collection: Accuracy: 100 Accuracy Value Unit: FEET Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Latitude: 43.06734 Longitude: -85.68953

Tank ID:

Tank Status: Removed from Ground

Capacity: 2000
Product: Gasoline
Install Date: 05/02/1973
Remove Date: 11/01/1987
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 2

Tank Status: Removed from Ground

Capacity: 3000
Product: Gasoline
Install Date: 05/02/1973
Remove Date: 11/01/1987
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 3

Tank Status: Removed from Ground

Capacity: 1000

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

GET IT GO (Continued) U003327697

Product: Gasoline 05/02/1976 Install Date: Remove Date: 11/01/1987 Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Galvanized Steel Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

MI DEPT/STATE POLICE **RCRA NonGen / NLR** 1007100455 11

ESE 648 6TH ST NW

1/8-1/4 **GRAND RAPIDS, MI 49504**

0.165 mi. 870 ft.

RCRA NonGen / NLR: Relative:

Date form received by agency: 09/03/2002 Lower

> Facility name: MI DEPT/STATE POLICE

Actual: Facility address: 648 6TH ST NW 610 ft.

GRAND RAPIDS, MI 49504

EPA ID: MIK836522946 Mailing address:

588 3 MILE RD NW GRAND RAPIDS, MI 49544

Contact: STEVE RAU

Contact address: 648 6TH ST NW

GRAND RAPIDS, MI 49504

Contact country: US

(616) 647-0821 Contact telephone: Contact email: Not reported

EPA Region: 05

Classification:

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: MI DEPT/STATE POLICE

Owner/operator address: Not reported

Not reported

Not reported

Owner/operator country: Not reported Owner/operator telephone: Not reported Legal status: State Owner/Operator Type: Owner Owner/Op start date: 09/03/2002 Owner/Op end date:

MI DEPT/STATE POLICE Owner/operator name:

Owner/operator address: Not reported Not reported Owner/operator country: Not reported

Owner/operator telephone: Not reported Legal status: State Owner/Operator Type: Operator Owner/Op start date: 09/03/2002 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No MIK836522946

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MI DEPT/STATE POLICE (Continued)

1007100455

U003329581

N/A

LUST

UST

Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: Nο Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

> LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

C12 **EL MATADOR TORTILLA CHIPS (FORME**

> 669 STOCKING AVE NW **GRAND RAPIDS, MI 49504**

1/8-1/4 0.168 mi.

South

885 ft. Site 2 of 2 in cluster C

Relative:

LUST:

Facility ID: Higher

00038602 Source: STATE OF MICHIGAN

Actual: Owner Name: El Matador Tortilla Chips Co 615 ft. Owner Address: 45 Franklin St SW

> Owner City, St, Zip: Grand Rapids, MI 49507-1025

Owner Contact: Not reported Owner Phone: (616) 241-1121

Country: USA

District: **Grand Rapids District Office** Former El Matador Tortilla Chip Site Name:

Latitude: 42.97534 Longitude: -85.68807 Date of Collection: 01/11/2001

Method of Collection: Address Matching-House Number

Accuracy: 100 Accuracy Value Unit: **FEET** Horizontal Data: NAD83 Point Line Area: **POINT**

Plant Entrance (Freight) Desc Category:

Leak Number: C-0580-95 Release Date: 05/22/1995 Substance Released: Gasoline Release Status: Closed

Direction Distance

Elevation Site Database(s) EPA ID Number

EL MATADOR TORTILLA CHIPS (FORME (Continued)

U003329581

EDR ID Number

Release Closed Date: 08/01/1995

UST:

Facility ID: 00038602 Facility Type: CLOSED

Owner Name: EL MATADOR TORTILLA CHIPS CO

Not reported

Owner Address: 45 FRANKLIN ST SW

Owner City, St, Zip: GRAND RAPIDS, MI 49507-1025

Owner Country: USA

Owner Contact:

Owner Phone: (616) 241-1121
Contact: MIQUEL NAVARRO
Contact Phone: (616) 241-1121
Date of Collection: 01/11/2001
Accuracy: 100
Accuracy Value Unit: FEET

Accuracy Value Unit: FEET Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Latitude: 42.97534 Longitude: -85.68807

Tank ID:

Tank Status:

Capacity:

Product:

Install Date:

Remove Date:

Tank Release Detection:

Pipe Realease Detection:

Not reported

Not reported

Not reported

Not reported

Not reported

Unknown

Piping Type: Suction: No Valve At Tank

Construction Material: Excavation Liner

Impressed Device: No

600 7TH STREET NW INVENTORY \$116385977 600 7TH STREET NW N/A

East 600 7TH STREET NW 1/8-1/4 KENT (County), MI 49504

0.174 mi.

D13

921 ft. Site 1 of 3 in cluster D

Relative: INVENTORY:

Lower Bea Number: 201403687GR Township: Grand Rapids

Actual: District: Grand Rapids

610 ft. Data Source: BEA

Latitude: Not reported Longitude: Not reported

Direction Distance

Elevation Site Database(s) **EPA ID Number**

D14 **600 SEVENTH STREET NW INVENTORY** S114028104 **East 600 SEVENTH STREET NW** N/A

1/8-1/4 KENT (County), MI 49504 0.174 mi.

921 ft. Site 2 of 3 in cluster D

Relative: Lower

Actual:

INVENTORY:

200401478GR Bea Number: Township: **Grand Rapids** District: **Grand Rapids**

610 ft. Data Source: BEA

Latitude: Not reported Longitude: Not reported

201102951GR Bea Number: Township: **Grand Rapids** District: **Grand Rapids** Data Source: BEA

Not reported Latitude: Longitude: Not reported

201103023GR Bea Number: Township: **Grand Rapids** District: **Grand Rapids**

Data Source: BEA

Latitude: Not reported Longitude: Not reported

BEA S106521652 D15 **600 SEVENTH STREET NW ESE 600 SEVENTH STREET NW** N/A

1/8-1/4 0.207 mi.

1093 ft. Site 3 of 3 in cluster D

BEA: Relative:

Secondary Address: Not reported Lower

GRAND RAPIDS, MI 49504

BEA Number: 1478

Actual: **Grand Rapids** District: 610 ft. Date Received: 08/04/2004

> Submitter Name: Aslan - 600 Seventh L.L.C.

No Request Petition Determination:

Petition Disclosure:

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer:

Environmental Response Division Division Assigned:

Secondary Address: Not reported BEA Number: 3023

District: **Grand Rapids** Date Received: 10/21/2011

Submitter Name: Coastal-Aslan Building, LLC

Petition Determination: No Request

Petition Disclosure: 0

Category: Not reported Determination 20107A: No Request Reviewer: pawlosj2

Division Assigned: **Environmental Response Division**

Secondary Address: Not reported **EDR ID Number**

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

600 SEVENTH STREET NW (Continued)

S106521652

INVENTORY \$114026242

INVENTORY

N/A

S114026245

N/A

BEA Number: 2951

District: Grand Rapids
Date Received: 06/06/2011
Submitter Name: Fifth Third Bank
Petition Determination: No Request

Petition Disclosure: 0

Category: Not reported Determination 20107A: No Request Reviewer: pawlosi2

Division Assigned: Environmental Response Division

E16 601 & 611 5TH ST/609 6TH ST/710 MUSKEGON

ESE 601 & 611 5TH STREET NW & 609 6TH ST NW & 710 MUSKEGON AVENU

1/8-1/4 KENT (County), MI 49504

0.226 mi.

1193 ft. Site 1 of 8 in cluster E

Relative: INVENTORY:

Lower Bea Number: 201102952GR

Township: Grand Rapids

District: Grand Rapids

Actual: District: Grand Rapi 611 ft. Data Source: BEA

Latitude: 42.97669 Longitude: -85.68342

E17 601&611 FIFTH, 609 SIXTH, 710 MUSKEGON

ESE 601 & 611 FIFTH ST NW, 609 SIXTH ST NW & 710 MUSKEGON AVENUE

1/8-1/4 KENT (County), MI 49423

0.226 mi.

Actual:

1193 ft. Site 2 of 8 in cluster E

Relative: INVENTORY:

Relative: Lower

Bea Number: 201103024GR
Township: Grand Rapids
District: Grand Rapids

Data Source: BEA Latitude: 42.97669

Latitude: 42.97669 Longitude: -85.68342

Bea Number: 201103025GR
Township: Grand Rapids
District: Grand Rapids
Data Source: BEA

Longitude: BEA 42.97669
Longitude: -85.68342

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

E18 JOHN WIDDICOMB PROPERTY **INVENTORY** S114026246 **ESE** 600 BLOCK OF FIFTH STREET NW N/A

1/8-1/4 KENT (County), MI

0.226 mi.

1193 ft. Site 3 of 8 in cluster E

Relative:

Lower Bea Number:

199600066GR Township: **Grand Rapids** Actual: District: **Grand Rapids**

INVENTORY:

611 ft. Data Source: BEA Latitude: 42.97669 -85.68342 Longitude:

INVENTORY E19 **601 5TH STREET NW** S114026243 N/A

ESE 601 5TH STREET NW 1/8-1/4 KENT (County), MI

0.226 mi.

1193 ft. Site 4 of 8 in cluster E

INVENTORY: Relative:

Bea Number:

200100987GR Lower Township: **Grand Rapids**

Actual: District: **Grand Rapids** 611 ft. Data Source: BEA

42.97669 Latitude: Longitude: -85.68342

20 **EDR US Hist Auto Stat** 1015121447 N/A

North 1002 ALPINE AVE NW 1/8-1/4 **GRAND RAPIDS, MI 49504**

0.227 mi. 1196 ft.

EDR Historical Auto Stations: Relative:

Name: A ONE SMALL ENGINE REPAIR LLC Higher

Year: 2010

Actual: Address: 1002 ALPINE AVE NW 617 ft.

E21 **JOHN WIDDICOMB CO** INVENTORY U002301747

ESE 601 5TH ST NW PART 201 N/A

GRAND RAPIDS, MI 49504 1/8-1/4 **DEL PART 201** 0.240 mi. LUST

1268 ft. Site 5 of 8 in cluster E UST **BEA** Relative: **WDS** Lower

INVENTORY:

Actual: Bea Number: Not reported 611 ft. Township: **Grand Rapids**

> District: **Grand Rapids** Data Source: Part 201 Latitude: 42.97669 Longitude: -85.68342

PART 201:

Direction Distance

Elevation Site Database(s) EPA ID Number

JOHN WIDDICOMB CO (Continued)

U002301747

EDR ID Number

Facility ID: 41000773

Facility Status: Interim Response conducted

Source: Not reported

 SAM Score:
 28

 SAM Score Date:
 06/07/2005

 Township:
 07N

 Range:
 12W

 Section:
 24

 Quarter:
 SW

 Quarter/Quarter:
 NW

Pollutants: Fluoranthene; Phenanthrene; Se; Ag

DEL_PART201:

Facility ID: 41000998

Status: Deleted - available documentation does not support listing

LUST:

Facility ID: 00038547

Source: STATE OF MICHIGAN
Owner Name: John Widdicomb Co
Owner Address: 601 5th St NW

Owner City, St, Zip: Grand Rapids, MI 49504-5106

Owner Contact: Not reported
Owner Phone: (616) 459-7173

Country: USA

District: Grand Rapids District Office
Site Name: John Widdicomb Company

 Latitude:
 42.97610

 Longitude:
 -85.68306

 Date of Collection:
 01/11/2001

Method of Collection: Address Matching-House Number

Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Data: NAD83
Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Leak Number: C-0434-95
Release Date: 04/20/1995
Substance Released: Unknown
Release Status: Closed
Release Closed Date: 04/09/1996

UST:

Facility ID: 00038547 Facility Type: CLOSED

Owner Name: JOHN WIDDICOMB CO

Owner Address: 601 5TH ST NW

Owner City, St, Zip: GRAND RAPIDS, MI 49504-5106

Owner Country:
Owner Contact:
Owner Phone:
Contact:
Contact:
Contact Phone:
Date of Collection:

USA
Not reported
(616) 459-7173
MR CLAIR FRENCH
(616) 459-7173
01/11/2001

Accuracy: 100
Accuracy Value Unit: FEET

Direction Distance

Elevation Site Database(s) EPA ID Number

JOHN WIDDICOMB CO (Continued)

Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Latitude: 42.97610 Longitude: -85.68306

Tank ID:

Tank Status: Removed from Ground

Capacity: 550
Product: Gasoline
Install Date: Not reported
Remove Date: 04/13/1995
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Unknown
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 2

Tank Status: Removed from Ground

Capacity: 120

Product: Hazardous Substance

Install Date: Not reported Remove Date: 04/13/1995
Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Unknown Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

BEA:

Secondary Address: Not reported

BEA Number: 987

District: Grand Rapids
Date Received: 12/17/2001
Submitter Name: 601 Properties, LLC

Petition Determination: No Request

Petition Disclosure: 0

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: wierzbid

Division Assigned: Environmental Response Division

WDS:

Site Id: MID985648120

WMD Id: 407500

Site Specific Name: WIDDICOMB JOHN CO

Mailing Address: 601 5TH ST NW

Mailing City/State/Zip: 49504 Mailing County: KENT **EDR ID Number**

U002301747

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

E22 WIDDICOMB JOHN CO RCRA NonGen / NLR 1000827879
ESE 601 5TH ST NW MID985648120

1/8-1/4 GRAND RAPIDS, MI 49504

0.240 mi.

1268 ft. Site 6 of 8 in cluster E

Relative: RCRA NonGen / NLR:

Lower Date form received by agency: 12/31/2001

Facility name: WIDDICOMB JOHN CO
Actual: Facility address: 601 5TH ST NW

611 ft. GRAND RAPIDS, MI 49504

EPA ID: MID985648120
Contact: CLAIR FRENCH
Contact address: 601 5TH ST NW

GRAND RAPIDS, MI 49504

Contact country: US

Contact telephone: (616) 459-7173 Contact email: Not reported

EPA Region: 05

Land type: Other land type Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NO ACTIVE O/OP AS NOT GENERATING WASTE

Owner/operator address: Not reported

Not reported

Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2002
Owner/Op end date: Not reported

Owner/operator name: NO ACTIVE O/OP AS NOT GENERATING WASTE

Owner/operator address:

Owner/operator country:

Owner/operator telephone:
Legal status:

Owner/Operator Type:

Not reported
Not reported
Private
Operator
Operator

Owner/Op start date: 01/01/2002
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No

Direction Distance

EDR ID Number Elevation **EPA ID Number** Site Database(s)

WIDDICOMB JOHN CO (Continued)

1000827879

Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 09/21/1992

Site name: WIDDICOMB JOHN CO Classification: **Small Quantity Generator**

Date form received by agency: 01/01/1981

WIDDICOMB JOHN CO Site name: Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code:

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code:

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET. WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Facility Has Received Notices of Violations:

Regulation violated: Not reported

Area of violation: Generators - Pre-transport

Date violation determined: 07/31/1996 Date achieved compliance: 11/13/1996 Violation lead agency: State

WRITTEN INFORMAL Enforcement action:

Enforcement action date: 07/31/1996 Enf. disposition status: Not reported Not reported Enf. disp. status date: Enforcement lead agency: State Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: Not reported

Direction Distance Elevation

vation Site Database(s) EPA ID Number

WIDDICOMB JOHN CO (Continued)

1000827879

EDR ID Number

Area of violation: Generators - Records/Reporting

Date violation determined: 07/31/1996
Date achieved compliance: 11/13/1996
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 07/31/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Paid penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: Generators - General Date violation determined: 07/31/1996

Date violation determined: 07/31/1996
Date achieved compliance: 11/13/1996
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 07/31/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 07/31/1996
Date achieved compliance: Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 07/31/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 11/12/1996

Evaluation: FOLLOW-UP INSPECTION Area of violation: Generators - Pre-transport

Date achieved compliance: 11/13/1996 Evaluation lead agency: State

Evaluation date: 11/12/1996

Evaluation: FOLLOW-UP INSPECTION

Area of violation: LDR - General Date achieved compliance: 11/13/1996 Evaluation lead agency: State

Evaluation date: 11/12/1996

Evaluation: FOLLOW-UP INSPECTION Area of violation: Generators - General

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

WIDDICOMB JOHN CO (Continued)

1000827879

Date achieved compliance: 11/13/1996 Evaluation lead agency: State

Evaluation date: 11/12/1996

Evaluation: FOLLOW-UP INSPECTION Area of violation: Generators - Records/Reporting

Date achieved compliance: 11/13/1996 Evaluation lead agency: State

Evaluation date: 07/25/1996

COMPLIANCE EVALUATION INSPECTION ON-SITE Evaluation:

Area of violation: LDR - General Date achieved compliance: 11/13/1996 Evaluation lead agency: State

Evaluation date: 07/25/1996

COMPLIANCE EVALUATION INSPECTION ON-SITE Evaluation:

Area of violation: Generators - Pre-transport

Date achieved compliance: 11/13/1996 Evaluation lead agency: State

Evaluation date: 07/25/1996

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Records/Reporting

Date achieved compliance: 11/13/1996 Evaluation lead agency: State

Evaluation date: 07/25/1996

COMPLIANCE EVALUATION INSPECTION ON-SITE Evaluation:

Area of violation: Generators - General

Date achieved compliance: 11/13/1996 Evaluation lead agency: State

E23 601 & 611 5TH ST/609 6TH ST/710 MUSKEGON ESE 601 & 611 5TH STREET NW & 609 6TH ST NW

1/8-1/4 **GRAND RAPIDS, MI 49504**

0.240 mi.

1268 ft. Site 7 of 8 in cluster E

BEA: Relative:

& 710 Muskegon Avenue NW Secondary Address: Lower

BEA Number:

Actual: District: **Grand Rapids** 611 ft. Date Received: 06/06/2011

Fifth Third Bank Submitter Name: Petition Determination: No Request

Petition Disclosure:

Category: Not reported Determination 20107A: No Request Reviewer: monetd

Division Assigned: **Environmental Response Division** BEA

S111120923

N/A

Direction Distance

Elevation Site Database(s) **EPA ID Number**

F24 **555 7TH STREET NW** S113193033 **East 555 7TH STREET NW** N/A

1/4-1/2 **GRAND RAPIDS, MI 49504**

0.251 mi.

1323 ft. Site 1 of 3 in cluster F

Relative:

BEA:

Secondary Address: Lower aka 801 Broadway Avenue NW

BEA Number: 3330

Actual: District: **Grand Rapids** 610 ft. Date Received: 12/14/2012

> Submitter Name: Off Broadway Apartments Acquisition LLC

Petition Determination: No Request

Petition Disclosure:

Category: Not reported Determination 20107A: No Request Reviewer: monetd

Division Assigned: **Environmental Response Division**

Secondary Address: aka 801 Broadway Avenue NW

BEA Number: 3480

Grand Rapids District: Date Received: 07/08/2013

Submitter Name: Clark Place Residential Condominiums LLC

Petition Determination: No Request Petition Disclosure: Category: Not reported Determination 20107A: No Request

Reviewer: monetd

Division Assigned: **Environmental Response Division**

E25 JOHN WIDDICOMB PROPERTY BEA S104909812 **ESE** 600 BLOCK OF FIFTH STREET NW N/A

1/4-1/2 **GRAND RAPIDS, MI**

0.265 mi.

Site 8 of 8 in cluster E 1399 ft.

Relative:

Lower Secondary Address: Not reported

BEA Number: 66

Actual: District: **Grand Rapids** 612 ft. Date Received: 03/13/1996

Submitter Name: JDV Real Estate II, LLC

Petition Determination: Affirmed Petition Disclosure:

No Hazardous Substance(s) Category:

Determination 20107A: No Request Reviewer: monetd

Environmental Response Division Division Assigned:

EDR ID Number

Direction Distance

Elevation Site Database(s) EPA ID Number

G26 600 FIFTH STREET N. W. BEA S104911690
ESE 600 FIFTH STREET N. W. N/A

1/4-1/2 GRAND RAPIDS, MI

0.266 mi.

1403 ft. Site 1 of 6 in cluster G

Relative:

BEA:

Lower Secondary Address: Not reported

BEA Number: 575

Actual: District: Grand Rapids 612 ft. Date Received: 08/18/1999

Submitter Name: Kent Record Management, Inc.

Petition Determination: Affirmed Petition Disclosure: 1

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: whitebl

Division Assigned: Environmental Response Division

Secondary Address: Not reported BEA Number: 576

District: Grand Rapids
Date Received: 08/18/1999

Submitter Name: Offsite Properties, L.L.C.

Petition Determination: No Request

Petition Disclosure:

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: monetd

Division Assigned: Environmental Response Division

G27 5TH STREET NW, 600 DEL PART 201 S106880364
ESE 600 5TH STREET NW N/A

ESE 600 5TH STREET NW 1/4-1/2 GRAND RAPIDS, MI 49504

0.266 mi.

1403 ft. Site 2 of 6 in cluster G

Relative: DEL_PART201:

Lower Facility ID: 41000997

Status: Deleted - available documentation does not support listing

Actual: 612 ft.

012 11.

1/4-1/2 KENT (County), MI

0.276 mi.

1458 ft. Site 3 of 6 in cluster G

Relative: INVENTORY:

Lower Bea Number: 199900576GR
Township: Grand Rapids
Actual: District: Grand Rapids
612 ft. Data Source: BEA

Data Source: BEA
Latitude: Not reported
Longitude: Not reported

Bea Number: 199900575GR Township: Grand Rapids District: Grand Rapids **EDR ID Number**

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

600 FIFTH STREET N. W. (Continued)

S114026285

Data Source: **BEA** Latitude: 42.97571 Longitude: -85.68304

DEL PART 201 H29 S106880362 4TH STREET NW, 615 SE

615 4TH STREET NW N/A

1/4-1/2 **GRAND RAPIDS, MI 49504**

0.292 mi.

1543 ft. Site 1 of 2 in cluster H

DEL_PART201: Relative:

Facility ID: 41000995 Lower

Status: Deleted - available documentation does not support listing Actual:

612 ft.

H30 **615 FOURTH STREET NW** BEA S106174328

SE **615 FOURTH STREET NW** N/A

1/4-1/2 **GRAND RAPIDS, MI**

0.292 mi.

1543 ft. Site 2 of 2 in cluster H

Relative:

Secondary Address: Not reported Lower

BEA Number: 1352 Actual: District: **Grand Rapids** 612 ft.

Date Received: 01/30/2004 Submitter Name: 2320 Properties LLC

Petition Determination: No Request

Petition Disclosure:

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: johnsonn

Environmental Response Division Division Assigned:

F31 BEA S109171386 **516 SEVENTH STREET NW** N/A

East **516 SEVENTH STREET NW** 1/4-1/2 **GRAND RAPIDS, MI 49504**

0.295 mi.

1559 ft. Site 2 of 3 in cluster F

BEA: Relative:

Secondary Address: Not reported Lower

BEA Number: 2349

Actual: District: **Grand Rapids** 612 ft. Date Received: 08/18/2008 Oliver Products Co.

Submitter Name: Petition Determination: No Request

Petition Disclosure:

Category: Different Hazardous Substance(s)

Determination 20107A: No Request Reviewer: pawlosj2

Environmental Response Division Division Assigned:

MAP FINDINGS Map ID

Direction Distance

Elevation Site Database(s) **EPA ID Number**

F32 **516 SEVENTH STREET NW INVENTORY** S114027597 **East 516 SEVENTH STREET NW** N/A

1/4-1/2 KENT (County), MI 49504

0.295 mi.

1559 ft. Site 3 of 3 in cluster F

Relative:

INVENTORY:

Lower

200802349GR Bea Number: **Grand Rapids** Township:

Actual: District: 612 ft.

Grand Rapids Data Source: BEA

Latitude: Not reported Longitude: Not reported

G33 **560 FIFTH STREET NW ESE 560 FIFTH STREET NW** 1/4-1/2 KENT (County), MI 49504

0.296 mi.

Site 4 of 6 in cluster G 1562 ft.

Relative: Lower

Actual:

612 ft.

INVENTORY:

199900633GR Bea Number: Township: **Grand Rapids** District: **Grand Rapids**

BEA Data Source: Latitude: 42.9756 Longitude: -85.68213

Bea Number: 200401351GR Township: **Grand Rapids** District: **Grand Rapids**

Data Source: BEA Latitude: 42.9756 -85.68213 Longitude:

Bea Number: 201102953GR Township: **Grand Rapids** District: **Grand Rapids**

Data Source: BEA Latitude: 42.9756 Longitude: -85.68213

Bea Number: 201403699GR Township: **Grand Rapids** District: **Grand Rapids**

Data Source: BEA 42.9756 Latitude: Longitude: -85.68213

TC04170139.2r Page 39

EDR ID Number

S114026284

N/A

INVENTORY

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

1/4-1/2 GRAND RAPIDS, MI 49504

0.296 mi.

1562 ft. Site 5 of 6 in cluster G

Relative: DEL_PART201:

Lower Facility ID: 41000996

Status: Deleted - available documentation does not support listing

Actual: 612 ft.

WDS:

 Site Id:
 MIR000004069

 WMD Id:
 409679

 Site Specific Name:
 JEUP INC

 Mailing Address:
 560 5TH ST NW

Mailing City/State/Zip: 49504 Mailing County: KENT

1/4-1/2 GRAND RAPIDS, MI 49504

0.296 mi.

1562 ft. Site 6 of 6 in cluster G

Relative: BEA:

Lower Secondary Address: Not reported BEA Number: 1351

Actual: District: Grand Rapids
612 ft. Date Received: 01/30/2004

Submitter Name: 2320 Properties LLC

Petition Determination: No Request

Petition Disclosure: 0

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: johnsonn

Division Assigned: Environmental Response Division

Secondary Address: Not reported

BEA Number: 633

District: Grand Rapids
Date Received: 12/07/1999

Submitter Name: Dillon Acquisition LLC

Petition Determination: No Request

Petition Disclosure: 0

Category: Different Hazardous Substance(s)

Determination 20107A: No Request Reviewer: moyerr

Division Assigned: Environmental Response Division

Secondary Address: Not reported
BEA Number: 2953
District: Grand Rapids
Date Received: 06/06/2011
Submitter Name: Fifth Third Bank
Petition Determination: No Request

Petition Disclosure: 0

Category: Not reported Determination 20107A: No Request Reviewer: odonneld

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

560 FIFTH STREET NW (Continued)

Division Assigned: **Environmental Response Division**

S105768487 36 **AMERICAN SEATING** BEA

ENE 801-889 BROADWAY AVENUE NW N/A

1/4-1/2 **GRAND RAPIDS, MI**

0.303 mi. 1601 ft.

BEA: Relative:

Secondary Address: 850 Seward Avenue NW Lower

BEA Number: 1103

Actual: Grand Rapids District: 610 ft. Date Received: 10/30/2002

American Seating Park, LLC Submitter Name:

Petition Determination: No Request

Petition Disclosure:

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: pawlosj2

Division Assigned: **Environmental Response Division**

37 J & L ROOFING CO

NE **567 11TH ST NW**

GRAND RAPIDS, MI 49504 1/4-1/2

0.346 mi. 1827 ft.

LUST: Relative: Lower

Facility ID: 00002126

Source: STATE OF MICHIGAN Actual: Owner Name: J & L Roofing Co 610 ft. Owner Address: 567 11th St NW

Owner City,St,Zip: Grand Rapids, MI 49504-4450

Owner Contact: Not reported Owner Phone: (616) 459-0840

Country: USA

District: **Grand Rapids District Office**

J & L Roofing Site Name: 42.98147 Latitude: Longitude: -85.68202 Date of Collection: 01/11/2001

Method of Collection: Address Matching-House Number

Accuracy: 100 Accuracy Value Unit: **FEET**

Horizontal Data: NAD83 Point Line Area: **POINT**

Desc Category: Plant Entrance (Freight)

Leak Number: C-1814-90 Release Date: 09/19/1990 Substance Released: Not reported Release Status: Closed Release Closed Date: 04/26/1994

UST:

Facility ID: 00002126 Facility Type: CLOSED

S104911795

LUST

UST

WDS

U000257644

N/A

MAP FINDINGS Map ID

Direction Distance

Elevation Site Database(s) **EPA ID Number**

J & L ROOFING CO (Continued)

U000257644

EDR ID Number

Owner Name: J & L ROOFING CO 567 11TH ST NW Owner Address:

Owner City,St,Zip: GRAND RAPIDS, MI 49504-4450

Owner Country: USA Owner Contact: Not reported (616) 459-0840 Owner Phone: **ROBERT BOOM** Contact: Contact Phone: (616) 459-0840 Date of Collection: 01/11/2001

Accuracy: 100 Accuracy Value Unit: **FEET** Horizontal Datum: NAD83

STATE OF MICHIGAN Source:

Point Line Area: **POINT**

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Latitude: 42.98147 -85.68202 Longitude:

Tank ID:

Tank Status: **Removed from Ground**

Capacity: 1500 Product: Gasoline Install Date: Not reported 05/28/1991 Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Unknown Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

WDS:

MIG000026147 Site Id: WMD Id: 449903 Site Specific Name: J & L ROOFING 567 11TH ST NW Mailing Address:

Mailing City/State/Zip: 49504 Mailing County: **KENT**

138 **618 DEWEY AVENUE NW** SE **618 DEWEY AVENUE NW** 1/4-1/2 KENT (County), MI 49504

0.387 mi.

2044 ft. Site 1 of 3 in cluster I

INVENTORY: Relative:

Bea Number: 201403806GR Higher Township: **Grand Rapids** Actual: District: **Grand Rapids** 617 ft.

Data Source: BEA

Not reported Latitude: Longitude: Not reported S117324855

N/A

INVENTORY

Direction Distance

Elevation Site Database(s) EPA ID Number

 I39
 607 DEWEY AVENUE NW
 BEA
 \$110142397

 SE
 607 DEWEY AVENUE NW
 N/A

SE 607 DEWEY AVENUE NW 1/4-1/2 GRAND RAPIDS, MI 49504

0.391 mi.

2067 ft. Site 2 of 3 in cluster I

Relative:

BEA:

Higher Secondary Address: Not reported

BEA Number: 2668

Actual: District: Grand Rapids 617 ft. Date Received: 02/19/2010

Submitter Name: 607 Dewey LLC Petition Determination: No Request

Petition Disclosure: 0

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: heytg

Division Assigned: Environmental Response Division

I40 607 DEWEY AVENUE NW SE 607 DEWEY AVENUE NW 1/4-1/2 KENT (County), MI 49504

0.391 mi.

Actual:

2067 ft. Site 3 of 3 in cluster I

Relative: INVENTORY:

Higher Bea Number: 201002668GR

Township: Grand Rapids
District: Grand Rapids

617 ft. Data Source: BEA

Latitude: Not reported Longitude: Not reported

J41 522 STOCKING AVENUE NW INVENTORY S114027684
SSE 522 STOCKING AVENUE NW N/A

1/4-1/2 KENT (County), MI 49504 0.398 mi.

2101 ft. Site 1 of 3 in cluster J

Relative: INVENTORY:

Lower Bea Number: 201203109GR
Township: Grand Rapids
Actual: District: Grand Rapids

Actual: District: Grand Rapids 612 ft. Data Source: BEA

Latitude: Not reported Longitude: Not reported

Bea Number: 201203110GR Township: Grand Rapids District: Grand Rapids

Data Source: BEA
Latitude: Not reported
Longitude: Not reported

EDR ID Number

INVENTORY

S114028175

N/A

MAP FINDINGS Map ID

Direction Distance

Elevation Site Database(s) **EPA ID Number**

J42 **OXY METAL INDUSTRIES CORP GRAND RAPID WH BEA** S111455215 WDS N/A

SSE **522 STOCKING AVE NW** 1/4-1/2 **GRAND RAPIDS, MI 49504**

0.398 mi.

2101 ft. Site 2 of 3 in cluster J BEA:

Relative:

Lower

Secondary Address: Not reported

BEA Number: 3109

Actual: District: **Grand Rapids** 612 ft.

Date Received: 01/31/2012 Submitter Name: 522 Stocking LLC Petition Determination: No Request

Petition Disclosure:

Category: Not reported Determination 20107A: No Request Reviewer: pawlosj2

Division Assigned: **Environmental Response Division**

Secondary Address: Not reported BEA Number: 3110

Grand Rapids District: Date Received: 01/31/2012

Submitter Name: Icon Sign Company LLC

Petition Determination: No Request Petition Disclosure: Category: Not reported Determination 20107A: No Request

Reviewer: pawlosi2

Division Assigned: **Environmental Response Division**

WDS:

Site Id: MID057042202

WMD Id: 396386

OXY METAL INDUSTRIES CORP GRAND RAPID WH Site Specific Name:

Mailing Address: 522 STOCKING AVE NW

Mailing City/State/Zip: 49504 Mailing County: KENT

K43 **1147 ALPINE AVENUE NW** BEA S113192988 North **1147 ALPINE AVENUE NW** N/A

1/4-1/2 **GRAND RAPIDS, MI 49504**

0.405 mi.

2140 ft. Site 1 of 2 in cluster K

Relative:

Secondary Address: Not reported Higher BEA Number: 3324

Actual: District: **Grand Rapids** 615 ft. Date Received: 11/21/2012

> Submitter Name: Geenan DeKock Properties Group LLC

Petition Determination: No Request

Petition Disclosure:

Not reported Category: Determination 20107A: No Request Reviewer: iohnsonn

Division Assigned: **Environmental Response Division**

TC04170139.2r Page 44

EDR ID Number

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

K44 1147 ALPINE AVENUE NW **INVENTORY** S114022302 N/A

North 1147 ALPINE AVENUE NW 1/4-1/2 KENT (County), MI 49504

0.405 mi.

2140 ft. Site 2 of 2 in cluster K

Relative:

INVENTORY:

201203324GR Higher Bea Number: Township: **Grand Rapids** Actual: District: **Grand Rapids**

615 ft. Data Source: BEA

Latitude: Not reported Longitude: Not reported

FOUR STAR SERVICE STATION #8 LUST J45

SSE **513 STOCKING NW** 1/4-1/2 **GRAND RAPIDS, MI 49548**

0.417 mi.

2201 ft. Site 3 of 3 in cluster J

LUST: Relative:

Lower

Facility ID: 00001985

STATE OF MICHIGAN Source: Actual: Owner Name: Four Star Service 613 ft. 6025 Division Ave S Owner Address:

> Owner City,St,Zip: Grand Rapids, MI 49548-6737

Owner Contact: Not reported Owner Phone: (616) 534-4913

Country: USA

District: Grand Rapids District Office Four Star Service Station #8 Site Name:

42.97205 Latitude: Longitude: -85.68536 Date of Collection: 01/11/2001

Method of Collection: Address Matching-House Number 100

Accuracy:

FEET Accuracy Value Unit: NAD83 Horizontal Data: Point Line Area: **POINT**

Desc Category: Plant Entrance (Freight)

Leak Number: C-4013-85 Release Date: 10/01/1987 Substance Released: Not reported Release Status: Closed Release Closed Date: 08/12/1997

UST:

Facility ID: 00001985 Facility Type: CLOSED

Owner Name: FOUR STAR SERVICE 6025 DIVISION AVE S Owner Address:

Owner City, St, Zip: GRAND RAPIDS, MI 49548-6737

Owner Country: USA Owner Contact: Not reported Owner Phone: (616) 534-4913 Contact: JEFREY M.TROST Contact Phone: (616) 534-4913 Date of Collection: 01/11/2001

100 Accuracy:

U003330473

N/A

UST

Direction Distance

Elevation Site Database(s) EPA ID Number

FOUR STAR SERVICE STATION #8 (Continued)

Accuracy Value Unit: FEET Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Latitude: 42.97205 Longitude: -85.68536

Tank ID:

Tank Status: Removed from Ground

Capacity: 1000
Product: Gasoline
Install Date: 04/17/1962
Remove Date: 05/01/1989
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 2

Tank Status: Removed from Ground

Capacity: 6000
Product: Gasoline
Install Date: 04/17/1962
Remove Date: 05/01/1989
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 3

Tank Status: Removed from Ground

Capacity: 4000
Product: Gasoline
Install Date: 04/17/1980
Remove Date: 05/01/1989
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

EDR ID Number

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

L46 AMERICAN SEATING CO INVENTORY U002171813
ENE 901 BROADWAY AVE NW PART 201 N/A

1/4-1/2 GRAND RAPIDS, MI 49504 0.424 mi.

2240 ft. Site 1 of 2 in cluster L

Relative: INVENTORY:

Lower

Bea Number: 201403723GR Township: Grand Rapids

Actual: District: Grand Rapids 611 ft. Data Source: BEA

Latitude: 42.98023 Longitude: -85.68066

Bea Number: Not reported
Township: Grand Rapids
District: Grand Rapids
Data Source: Part 201
Latitude: 42.98023
Longitude: -85.68066

PART 201:

Facility ID: 41000148

Facility Status: Inactive - no actions taken to address contamination

Source: Misc Manufacturing Industries

 SAM Score:
 27

 SAM Score Date:
 10/12/2005

 Township:
 7N

 Range:
 12W

 Section:
 24

 Quarter:
 NW

 Quarter/Quarter:
 SE

Pollutants: Methylene chloride; VC

LUST:

Facility ID: 00007898

Source: STATE OF MICHIGAN
Owner Name: American Seating Co
Owner Address: 901 Broadway Ave NW
Owner City,St,Zip: Grand Rapids, MI 49504-4414

Owner Contact: Not reported
Owner Phone: (616) 456-0600

Country: USA

District: Grand Rapids District Office
Site Name: American Seating Company

Latitude: 42.97939 Longitude: -85.67942 Date of Collection: 01/11/2001

Method of Collection: Address Matching-House Number

Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Data: NAD83
Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Leak Number: C-0525-92
Release Date: 04/15/1992
Substance Released: Unknown,Unknown

LUST

UST

Direction Distance

Elevation Site Database(s) EPA ID Number

AMERICAN SEATING CO (Continued)

Release Status: Closed Release Closed Date: 08/08/1996

Leak Number:C-1242-90Release Date:07/12/1990Substance Released:Not reportedRelease Status:ClosedRelease Closed Date:08/08/1996

UST:

Facility ID: 00007898 Facility Type: CLOSED

Owner Name: AMERICAN SEATING CO
Owner Address: 901 BROADWAY AVE NW
Owner City,St,Zip: GRAND RAPIDS, MI 49504-4414

Owner Country: USA
Owner Contact: Not reported
Owner Phone: (616) 456-0600
Contact: GARY ENGERSON
Contact Phone: (616) 732-6650
Date of Collection: 01/11/2001

Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Latitude: 42.97939 Longitude: -85.67942

Tank ID:

Tank Status: Closed in Ground

Capacity: 10000

Product: NAPHA, Hazardous Substance

Install Date: 03/25/1949
Remove Date: 02/01/1984
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Bare Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 2

Tank Status: Closed in Ground

Capacity: 10000

Product: Hazardous Substance

Install Date: 03/25/1949
Remove Date: 02/01/1984
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Bare Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

EDR ID Number

Direction Distance

Elevation Site Database(s) EPA ID Number

AMERICAN SEATING CO (Continued)

Tank ID:

Tank Status: Closed in Ground

Capacity: 10000

Product: Hazardous Substance

Install Date: 03/25/1949
Remove Date: 02/01/1984
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Bare Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID:

Tank Status: Closed in Ground

Capacity: 10000

Product: Hazardous Substance

Install Date: 03/25/1949
Remove Date: 02/01/1984
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Bare Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID:

Tank Status: Closed in Ground

Capacity: 500
Product: Gasoline
Install Date: 03/25/1946
Remove Date: 04/01/1988
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Unknown
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 6

Tank Status: Removed from Ground

Capacity: 1000
Product: Gasoline
Install Date: Not reported
Remove Date: 10/01/1987
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Unknown
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 7

EDR ID Number

Direction Distance

Elevation Site Database(s) EPA ID Number

AMERICAN SEATING CO (Continued)

Tank Status: Removed from Ground

Capacity: 5000
Product: PAINT
Install Date: 03/26/1959
Remove Date: 10/01/1987
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Bare Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 8

Tank Status: Removed from Ground

Capacity: 4000
Product: PAINT
Install Date: 03/26/1959
Remove Date: 04/01/1988
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Bare Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 9

Tank Status: Removed from Ground

Capacity: 2000
Product: Not reported Install Date: 03/25/1957
Remove Date: 03/01/1988
Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Bare Steel Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 10

Tank Status: Removed from Ground

Capacity: 2000
Product: Not reported Install Date: 03/25/1957
Remove Date: 04/01/1988
Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Bare Steel Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 11

Tank Status: Removed from Ground

EDR ID Number

Direction Distance

Elevation Site Database(s) EPA ID Number

AMERICAN SEATING CO (Continued)

U002171813

EDR ID Number

Capacity: 3000
Product: Not reported Install Date: 03/25/1957
Remove Date: 04/01/1988
Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Bare Steel

Construction Material: Asphalt Coated or Bare Steel

Not reported

Impressed Device: No

Piping Type:

Tank ID: 12

Tank Status: Removed from Ground

Capacity: 3000
Product: Not reported
Install Date: 03/25/1957
Remove Date: 04/01/1988
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Bare Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 13

Tank Status: Removed from Ground

Capacity: 1070

Product: FLOW THROUGH/WATER

Install Date: 03/25/1952
Remove Date: 05/04/1992
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Bare Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 14

Tank Status: Removed from Ground

Capacity: 500

Product: Hazardous Substance

Install Date: Not reported Remove Date: 07/25/1990
Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Bare Steel Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 15

Tank Status: Removed from Ground

Capacity: 500

MAP FINDINGS Map ID

Direction Distance

Elevation Site Database(s) **EPA ID Number**

AMERICAN SEATING CO (Continued)

U002171813

EDR ID Number

Product: Gasoline Not reported Install Date: 04/29/1992 Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Bare Steel

Piping Type: Suction: Valve at Tank Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

AMERICAN SEATING COMPANY HQ US BROWNFIELDS 1014476600 L47 N/A

ENE 901 BROADWAY AVENUE NW 1/4-1/2 **GRAND RAPIDS, MI 49504**

0.424 mi.

2240 ft. Site 2 of 2 in cluster L

US BROWNFIELDS: Relative: Lower

Recipient name: Grand Rapids, City of

Grant type: Assessment

Actual: AMERICAN SEATING COMPANY HQ Property name: 611 ft.

Property #: Not reported

Parcel size: Property Description: American Seating is planning to undertake a large-scale property

rehabilitation activities that will include demolition of aging,

obsolete structures along with the construction of a new headquarters building and new manufacturing space. The project will result in significant investment within the community, as well as additional permanent jobs and short term construction jobs. American Seating has

been operating in the City since 1886.

42.9803629 Latitude:

Longitude: -85.68099900000004

Address Matching-House Number HCM label:

Map scale: Not reported

Point of reference: Entrance Point of a Facility or Station North American Datum of 1983 Datum:

ACRES property ID: 113322 Start date: Not reported Not reported Completed date: Acres cleaned up: Not reported Not reported Cleanup funding: Cleanup funding source: Not reported Assessment funding: 16919

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: Not reported Redev. funding source: Not reported Redev. funding entity name: Not reported Not reported Redevelopment start date: Assessment funding entity: Not reported Cleanup funding entity: Not reported

Grant type: Η

Accomplishment type: Supplemental Assessment

Accomplishment count:

Cooperative agreement #: 00E60701 Ownership entity: Private Current owner: Not reported

Did owner change: Ν Cleanup required: Yes Video available: Nο

Distance Elevation Site Database(s)

AMERICAN SEATING COMPANY HQ (Continued)

1014476600

EDR ID Number

EPA ID Number

Photo available: Yes Institutional controls required: Ν

Not reported IC Category proprietary controls: Not reported IC cat. info. devices: IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported IC in place date: Not reported

IC in place: No

State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Air cleaned: Not reported

Asbestos found: Asbestos cleaned: Not reported Controled substance found: Not reported Not reported Controled substance cleaned: Drinking water affected: Not reported Drinking water cleaned: Not reported Groundwater affected: Not reported Not reported Groundwater cleaned: Lead contaminant found: Not reported Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Not reported Other cleaned up: Other metals found: Not reported Other metals cleaned: Not reported Other contaminants found: Not reported Other contams found description: Not reported PAHs found: Not reported PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported Not reported Petro products found: Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported Soil affected: Not reported Soil cleaned up: Not reported

Surface water cleaned: Not reported VOCs found: Not reported VOCs cleaned: Not reported

Cleanup other description: Not reported Not reported Num. of cleanup and re-dev. jobs: Past use greenspace acreage: Not reported Past use residential acreage: Not reported

Not reported

11

Past use commercial acreage: Past use industrial acreage:

Future use greenspace acreage: Not reported Future use residential acreage: Not reported

Future use commercial acreage: 10 Future use industrial acreage:

Not reported Greenspace acreage and type:

Superfund Fed. landowner flag:

Not reported Arsenic cleaned up: Cadmium cleaned up: Not reported

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

AMERICAN SEATING COMPANY HQ (Continued)

1014476600

Chromium cleaned up: Not reported Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported mercury cleaned up: nickel cleaned up: Not reported Not reported No clean up: Not reported Pesticides cleaned up: Not reported Selenium cleaned up: SVOCs cleaned up: Not reported Unknown clean up: Not reported Not reported Arsenic contaminant found: Not reported Cadmium contaminant found: Chromium contaminant found: Not reported Not reported Copper contaminant found: Iron contaminant found: Not reported Mercury contaminant found: Not reported Nickel contaminant found: Not reported No contaminant found: Not reported Pesticides contaminant found: Not reported Selenium contaminant found: Not reported Not reported SVOCs contaminant found: Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Past Use: Multistory Not reported

M48 FORMER MILLER PRODUCTS PROPERTY **US BROWNFIELDS** 1012296585 601 AND 614 FIRST ST., 520 SECOND ST. AND 501 ALABAMA AVE. SE N/A

1/4-1/2 **GRAND RAPIDS, MI 49504**

0.443 mi.

2338 ft. Site 1 of 7 in cluster M

Relative:

621 ft.

US BROWNFIELDS:

Recipient name: Higher

> Grant type: Assessment

Actual: FORMER MILLER PRODUCTS PROPERTY Property name:

Property #: 41-13-24-357-005, 41-13-24-361-027, 41-13-24-378-003, 41-13-24-337-004

Grand Rapids, City of

Parcel size:

Property Description: Not reported Latitude: 42.97213960000001 -85.68820900000003 Longitude:

HCM label: Address Matching-House Number

Map scale: Not reported

Center of a Facility or Station Point of reference: North American Datum of 1983 Datum:

102902 ACRES property ID: Start date: Not reported Not reported Completed date: Not reported Acres cleaned up: Cleanup funding: Not reported Cleanup funding source: Not reported Assessment funding: 2800

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: Not reported

Direction Distance Elevation

nce EDR ID Number tition Site Database(s) EPA ID Number

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

Redev. funding source: Not reported Redev. funding entity name: Not reported Redevelopment start date: Not reported Assessment funding entity: EPA

Cleanup funding entity: Not reported

Grant type:

Accomplishment type: Phase I Environmental Assessment

Accomplishment count: 0

Cooperative agreement #: 00E00416
Ownership entity: Private
Current owner: Not reported

Did owner change: Y
Cleanup required: Yes
Video available: No
Photo available: Yes
Institutional controls required: N

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported IC in place date: Not reported IC in place: Not reported Not reported State/tribal program date: State/tribal program ID: Not reported State/tribal NFA date: Not reported Not reported Air contaminated: Air cleaned: Not reported Asbestos found: Not reported Asbestos cleaned: Not reported Not reported Controled substance found: Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported

Groundwater affected:

Groundwater cleaned: Not reported

Lead contaminant found: Y

Lead cleaned up: Not reported
No media affected: Not reported
Unknown media affected: Not reported
Other cleaned up: Not reported

Other metals found: Y

Other metals cleaned: Not reported Other contaminants found: Not reported Other contams found description: Not reported

PAHs found: Y

PAHs cleaned up:
PCBs found:
Not reported
PCBs cleaned up:
Petro products found:
Not reported
Not reported
Not reported
Not reported
Not reported
Sediments found:
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported

Distance Elevation

vation Site Database(s) EPA ID Number

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Cleanup other description: Not reported Num. of cleanup and re-dev. jobs: Not reported Not reported Past use greenspace acreage: Not reported Past use residential acreage: Past use commercial acreage: Not reported Past use industrial acreage: Not reported Future use greenspace acreage: Not reported Future use residential acreage: Not reported

Future use commercial acreage: .5
Future use industrial acreage: 3.1

Greenspace acreage and type: Not reported

Superfund Fed. landowner flag: Y

Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Copper cleaned up: Not reported Not reported Iron cleaned up: mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported Not reported Selenium cleaned up: SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported Not reported Cadmium contaminant found: Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Not reported Mercury contaminant found: Not reported Nickel contaminant found: Not reported No contaminant found: Not reported Pesticides contaminant found: Not reported Selenium contaminant found: Not reported Not reported SVOCs contaminant found: Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

Property name: FORMER MILLER PRODUCTS PROPERTY

Property #: 41-13-24-357-005, 41-13-24-361-027, 41-13-24-378-003, 41-13-24-337-004

Parcel size: 3.6

Property Description: Not reported
Latitude: 42.97213960000001
Longitude: -85.68820900000003

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 102902

Direction

Elevation Site Database(s) EPA ID Number

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported
Assessment funding: 2800

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding:
Redev. funding source:
Redev. funding entity name:
Redevelopment start date:
Assessment funding entity:
Cleanup funding entity:

Not reported
EPA
Not reported
Not reported

Grant type: H

Accomplishment type: Phase II Environmental Assessment

Accomplishment count: 0

Cooperative agreement #: 00E00416
Ownership entity: Private
Current owner: Not reported

Did owner change:

Cleanup required:

Video available:

Photo available:

Institutional controls required:

Yes

N

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported IC in place date: Not reported IC in place: Not reported Not reported State/tribal program date: State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Air cleaned: Not reported Asbestos found: Not reported Asbestos cleaned: Not reported Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Not reported Drinking water cleaned:

Groundwater affected: Y

Groundwater cleaned: Not reported

Lead contaminant found: Y

Lead cleaned up:
No media affected:
Unknown media affected:
Other cleaned up:
Other metals found:

Not reported
Not reported
Y

Other metals cleaned: Not reported Other contaminants found: Not reported Other contams found description: Not reported

PAHs found:

PAHs cleaned up:
PCBs found:
PCBs cleaned up:
PCBs cleaned up:
Petro products found:
Not reported
Not reported
Not reported

Direction Distance Elevation

Site Database(s) EPA ID Number

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported Num. of cleanup and re-dev. jobs: Not reported Not reported Past use greenspace acreage: Not reported Past use residential acreage: Past use commercial acreage: Not reported Not reported Past use industrial acreage: Future use greenspace acreage: Not reported Future use residential acreage: Not reported

Future use commercial acreage: .5
Future use industrial acreage: 3.1

Greenspace acreage and type: Not reported

Superfund Fed. landowner flag:

Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported Not reported mercury cleaned up: nickel cleaned up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Not reported Chromium contaminant found: Not reported Copper contaminant found: Iron contaminant found: Not reported Mercury contaminant found: Not reported Nickel contaminant found: Not reported No contaminant found: Not reported Not reported Pesticides contaminant found: Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Not reported Unknown contaminant found: Not reported Future Use: Multistory Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

Property name: FORMER MILLER PRODUCTS PROPERTY

Not reported

Not reported

Not reported

Property #: 41-13-24-357-005, 41-13-24-361-027, 41-13-24-378-003, 41-13-24-337-004

Parcel size: 3.6

Indoor air media cleaned up:

Unknown media cleaned up:

Past Use: Multistory

Direction Distance Elevation

tion Site Database(s) EPA ID Number

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Property Description: Not reported
Latitude: 42.97213960000001

Longitude: 42.9721390000001 -85.68820900000003

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 102902
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported
Assessment funding: 13487

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding:
Redev. funding source:
Redev. funding entity name:
Redevelopment start date:

Accompant funding entity:

Accompant funding entity:

EDA

Assessment funding entity: EPA

Cleanup funding entity: Not reported

Grant type: H

Accomplishment type: Supplemental Assessment

Accomplishment count: (

Cooperative agreement #: 00E00416
Ownership entity: Private
Current owner: Not reported

Did owner change:

Cleanup required:

Video available:

Photo available:

Institutional controls required:

Yes

N

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported Not reported IC cat. enforcement permit tools: IC in place date: Not reported IC in place: Not reported State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Not reported Air contaminated: Air cleaned: Not reported Not reported Asbestos found: Not reported Asbestos cleaned: Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported

Groundwater affected:

Groundwater cleaned: Not reported

Lead contaminant found:

Lead cleaned up:

No media affected:

Unknown media affected:

Other cleaned up:

Not reported

Not reported

Not reported

Not reported

Other metals found:

Distance Elevation Site

ite Database(s) EPA ID Number

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Other metals cleaned: Not reported
Other contaminants found: Not reported
Other contams found description: Not reported
PAHs found: Y

PAHs cleaned up:

PCBs found:

PCBs cleaned up:

Petro products found:

Petro products cleaned:

Petro products cleaned:

Sediments found:

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Soil affected: Y

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Not reported Cleanup other description: Num. of cleanup and re-dev. jobs: Not reported Past use greenspace acreage: Not reported Past use residential acreage: Not reported Past use commercial acreage: Not reported Past use industrial acreage: Not reported Future use greenspace acreage: Not reported Future use residential acreage: Not reported

Future use commercial acreage: .5
Future use industrial acreage: 3.1

Greenspace acreage and type: Not reported

Superfund Fed. landowner flag:

Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Not reported Chromium cleaned up: Copper cleaned up: Not reported Not reported Iron cleaned up: mercury cleaned up: Not reported Not reported nickel cleaned up: Not reported No clean up: Pesticides cleaned up: Not reported Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Chromium contaminant found: Not reported Not reported Copper contaminant found: Not reported Iron contaminant found: Mercury contaminant found: Not reported Not reported Nickel contaminant found: No contaminant found: Not reported Pesticides contaminant found: Not reported Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported

Direction Distance

Elevation Site Database(s) **EPA ID Number**

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Unknown media cleaned up: Not reported Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

FORMER MILLER PRODUCTS PROPERTY Property name:

Property #: 41-13-24-357-005, 41-13-24-361-027, 41-13-24-378-003, 41-13-24-337-004

Parcel size:

Property Description: Not reported Latitude: 42.97213960000001 Longitude: -85.68820900000003

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station Datum: North American Datum of 1983

ACRES property ID: 102902 Not reported Start date: Completed date: Not reported Acres cleaned up: Not reported Cleanup funding: Not reported Cleanup funding source: Not reported Assessment funding: 16992

US EPA - Brownfields Assessment Cooperative Agreement Assessment funding source:

Redevelopment funding: 500000 Redev. funding source: Local Funding

Tax Increment Financing Redev. funding entity name:

Redevelopment start date: Not reported

Assessment funding entity: **EPA** Cleanup funding entity: Not reported

Grant type: Phase II Environmental Assessment

Accomplishment type: Accomplishment count:

Cooperative agreement #: 00E60701 Ownership entity: Private Current owner: Not reported

Did owner change: Yes Cleanup required: Video available: No Photo available: Yes Institutional controls required: Ν

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported Not reported IC cat. enforcement permit tools: Not reported IC in place date: IC in place: Not reported State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Air cleaned: Not reported Asbestos found: Not reported Not reported Asbestos cleaned: Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported

Distance Elevation Site

Database(s) **EPA ID Number**

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Groundwater affected:

Not reported Groundwater cleaned:

Lead contaminant found:

Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found:

Other metals cleaned: Not reported Other contaminants found: Not reported Not reported Other contams found description:

PAHs found:

PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported Petro products found: Not reported Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs: 65

Past use greenspace acreage: Not reported Past use residential acreage: Not reported Past use commercial acreage: Not reported Past use industrial acreage: Not reported Future use greenspace acreage: Not reported Future use residential acreage: Not reported

Future use commercial acreage: Future use industrial acreage: 3.1

Not reported Greenspace acreage and type:

Pesticides contaminant found:

Superfund Fed. landowner flag: Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Copper cleaned up: Not reported Not reported Iron cleaned up: mercury cleaned up: Not reported nickel cleaned up: Not reported Not reported No clean up: Not reported Pesticides cleaned up: Selenium cleaned up: Not reported Not reported SVOCs cleaned up: Unknown clean up: Not reported Arsenic contaminant found: Not reported Not reported Cadmium contaminant found: Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Not reported Not reported Mercury contaminant found: Nickel contaminant found: Not reported No contaminant found: Not reported

Not reported

MAP FINDINGS Map ID

Direction Distance Elevation

EDR ID Number Site Database(s) **EPA ID Number**

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Not reported Unknown contaminant found: Not reported Future Use: Multistory Media affected Bluiding Material: Not reported Not reported Media affected indoor air: Building material media cleaned up: Not reported Not reported Indoor air media cleaned up: Unknown media cleaned up: Not reported Past Use: Multistory Not reported

Grand Rapids, City of Recipient name:

Grant type: Assessment

Property name: FORMER MILLER PRODUCTS PROPERTY

Property #: 41-13-24-357-005, 41-13-24-361-027, 41-13-24-378-003, 41-13-24-337-004

Parcel size:

Property Description: Not reported

42.97213960000001 Latitude: Longitude: -85.68820900000003

Address Matching-House Number HCM label:

Map scale: Not reported

Point of reference: Center of a Facility or Station North American Datum of 1983 Datum:

ACRES property ID: 102902 Start date: Not reported Completed date: Not reported Acres cleaned up: Not reported Cleanup funding: Not reported Cleanup funding source: Not reported

Assessment funding: Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

16992

Redevelopment funding: 1000000

Redev. funding source: Private/Other Funding

Redev. funding entity name: Developer Redevelopment start date: Not reported Assessment funding entity: **EPA** Cleanup funding entity: Not reported

Grant type:

Phase II Environmental Assessment Accomplishment type:

Accomplishment count:

00E60701 Cooperative agreement #: Ownership entity: Private Current owner: Not reported

Did owner change: Cleanup required: Yes Video available: No Photo available: Yes Institutional controls required:

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported Not reported IC in place date: IC in place: Not reported State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported

Distance Elevation

Site Database(s) **EPA ID Number**

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Air contaminated: Not reported Not reported Air cleaned: Not reported Asbestos found: Not reported Asbestos cleaned: Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported

Groundwater affected:

Groundwater cleaned: Not reported

Lead contaminant found:

Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found:

Other metals cleaned: Not reported Other contaminants found: Not reported Other contams found description: Not reported

PAHs found:

PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported Petro products found: Not reported Petro products cleaned: Not reported Not reported Sediments found: Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs:

Past use greenspace acreage: Not reported Not reported Past use residential acreage: Past use commercial acreage: Not reported Past use industrial acreage: Not reported Future use greenspace acreage: Not reported Future use residential acreage: Not reported

Future use commercial acreage: .5 Future use industrial acreage: 3.1

Greenspace acreage and type: Not reported

Superfund Fed. landowner flag:

Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported Not reported Selenium cleaned up: SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported

Direction Distance Elevation

tance EDR ID Number vation Site Database(s) EPA ID Number

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

Cadmium contaminant found: Not reported Not reported Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Mercury contaminant found: Not reported Not reported Nickel contaminant found: Not reported No contaminant found: Not reported Pesticides contaminant found: Not reported Selenium contaminant found: SVOCs contaminant found: Not reported Not reported Unknown contaminant found: Not reported Future Use: Multistory Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Not reported Unknown media cleaned up: Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

Property name: FORMER MILLER PRODUCTS PROPERTY

Property #: 41-13-24-357-005, 41-13-24-361-027, 41-13-24-378-003, 41-13-24-337-004

Parcel size: 3.6

Property Description: Not reported
Latitude: 42 97213960000

Latitude: 42.97213960000001 Longitude: -85.68820900000003

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 102902
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported
Assessment funding: 11431

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 500000
Redev. funding source: Local Funding

Redev. funding entity name: Tax Increment Financing

Redevelopment start date:
Assessment funding entity:
Cleanup funding entity:
Not reported
Not reported

Grant type: H

Accomplishment type: Supplemental Assessment

Accomplishment count:

Cooperative agreement #: 00E60701
Ownership entity: Private
Current owner: Not reported

Did owner change:

Cleanup required:

Video available:

Photo available:

Institutional controls required:

Yes

N

IC Category proprietary controls: Not reported

Distance Elevation

Site Database(s) **EPA ID Number**

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

IC cat. info. devices: Not reported IC cat. gov. controls: Not reported Not reported IC cat. enforcement permit tools: Not reported IC in place date: IC in place: Not reported State/tribal program date: Not reported State/tribal program ID: Not reported Not reported State/tribal NFA date: Air contaminated: Not reported Air cleaned: Not reported Not reported Asbestos found: Asbestos cleaned: Not reported Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported

Groundwater affected:

Groundwater cleaned: Not reported

Lead contaminant found:

Lead cleaned up: Not reported Not reported No media affected: Unknown media affected: Not reported Not reported Other cleaned up:

Other metals found:

Other metals cleaned: Not reported Not reported Other contaminants found: Other contams found description: Not reported PAHs found:

PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported Petro products found: Not reported Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs: 65

Past use greenspace acreage: Not reported Not reported Past use residential acreage: Not reported Past use commercial acreage: Past use industrial acreage: Not reported Not reported Future use greenspace acreage: Future use residential acreage: Not reported

Future use commercial acreage: .5 Future use industrial acreage: 3.1

Greenspace acreage and type: Not reported

Superfund Fed. landowner flag:

Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported Not reported Pesticides cleaned up: Selenium cleaned up: Not reported Not reported SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Cadmium contaminant found: Not reported Chromium contaminant found: Not reported Not reported Copper contaminant found: Not reported Iron contaminant found: Mercury contaminant found: Not reported Nickel contaminant found: Not reported No contaminant found: Not reported Pesticides contaminant found: Not reported Not reported Selenium contaminant found: SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

FORMER MILLER PRODUCTS PROPERTY Property name:

41-13-24-357-005, 41-13-24-361-027, 41-13-24-378-003, 41-13-24-337-004 Property #:

Parcel size: 3.6

Property Description: Not reported Latitude: 42.97213960000001 Longitude: -85.68820900000003

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station Datum: North American Datum of 1983

ACRES property ID: 102902 Not reported Start date: Not reported Completed date: Acres cleaned up: Not reported Cleanup funding: Not reported Cleanup funding source: Not reported Assessment funding: 11431

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 1000000

Redev. funding source: Private/Other Funding

Redev. funding entity name: Developer Redevelopment start date: Not reported Assessment funding entity: **EPA** Cleanup funding entity: Not reported

Grant type:

Accomplishment type: Supplemental Assessment

Accomplishment count:

Cooperative agreement #: 00E60701

Distance Elevation

Site Database(s) **EPA ID Number**

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Ownership entity: Private Current owner: Not reported

Did owner change: Cleanup required: Yes Video available: No Photo available: Yes Institutional controls required: Ν

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported Not reported IC cat. enforcement permit tools: IC in place date: Not reported IC in place: Not reported State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Not reported Air contaminated: Air cleaned: Not reported Asbestos found: Not reported Asbestos cleaned: Not reported Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported Groundwater affected:

Groundwater cleaned: Not reported

Lead contaminant found:

Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found:

Other metals cleaned: Not reported Other contaminants found: Not reported Not reported Other contams found description:

PAHs found:

PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported Petro products found: Not reported Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs: 65

Past use greenspace acreage: Not reported Past use residential acreage: Not reported Not reported Past use commercial acreage: Not reported Past use industrial acreage: Future use greenspace acreage: Not reported Future use residential acreage: Not reported

Future use commercial acreage: .5

Direction Distance

Elevation Site Database(s) **EPA ID Number**

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Future use industrial acreage: 3.1

Greenspace acreage and type: Not reported

Superfund Fed. landowner flag:

Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Not reported Chromium cleaned up: Copper cleaned up: Not reported Not reported Iron cleaned up: mercury cleaned up: Not reported nickel cleaned up: Not reported Not reported No clean up: Not reported Pesticides cleaned up: Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported Not reported Cadmium contaminant found: Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Not reported Not reported Mercury contaminant found: Nickel contaminant found: Not reported No contaminant found: Not reported Pesticides contaminant found: Not reported Selenium contaminant found: Not reported Not reported SVOCs contaminant found: Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Not reported Media affected indoor air: Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Not reported Unknown media cleaned up:

Recipient name: Grand Rapids, City of

Grant type: Assessment

Property name: FORMER MILLER PRODUCTS PROPERTY

Not reported

Property #: 41-13-24-357-005, 41-13-24-361-027, 41-13-24-378-003, 41-13-24-337-004

Parcel size: 3.6

Past Use: Multistory

Property Description: Not reported 42.97213960000001 Latitude: Longitude: -85.68820900000003

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station North American Datum of 1983 Datum:

ACRES property ID: 102902 Start date: Not reported Not reported Completed date: Acres cleaned up: Not reported Cleanup funding: Not reported Cleanup funding source: Not reported Assessment funding: 3000

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: Not reported Redev. funding source: Not reported

Distance Elevation

n Site Database(s) EPA ID Number

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Redev. funding entity name:

Redevelopment start date:

Not reported

Not reported

Assessment funding entity: EPA
Cleanup funding entity: Not reported

Grant type:

Accomplishment type: Phase I Environmental Assessment

Accomplishment count: 0

Cooperative agreement #: 00E60801
Ownership entity: Private
Current owner: Not reported

Did owner change:

Cleanup required:

Video available:

Photo available:

Institutional controls required:

N

Yes

No

Yes

N

N

IC Category proprietary controls: Not reported Not reported IC cat. info. devices: IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported IC in place date: Not reported IC in place: Not reported State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Not reported Air cleaned: Asbestos found: Not reported Asbestos cleaned: Not reported Controled substance found: Not reported Not reported Controled substance cleaned: Drinking water affected: Not reported Drinking water cleaned: Not reported

Groundwater affected:

Groundwater cleaned: Not reported

Lead contaminant found: Y

Lead cleaned up:
No media affected:
Unknown media affected:
Other cleaned up:
Not reported
Not reported
Not reported

Other metals found: Y

Other metals cleaned: Not reported Other contaminants found: Not reported Other contams found description: Not reported

PAHs found: Y

PAHs cleaned up:
PCBs found:
PCBs cleaned up:
Petro products found:
Petro products cleaned:
Not reported
Not reported
Not reported
Not reported
Not reported
Sediments found:
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found: Y

VOCs cleaned: Not reported Cleanup other description: Not reported

Direction Distance Elevation

evation Site Database(s) EPA ID Number

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Num. of cleanup and re-dev. jobs:
Past use greenspace acreage:
Past use residential acreage:
Past use commercial acreage:
Past use industrial acreage:
Past use greenspace acreage:
Past use industrial acreage:
Puture use greenspace acreage:
Future use residential acreage:
Not reported
Not reported
Not reported
Not reported

Future use commercial acreage: .5
Future use industrial acreage: 3.1

Greenspace acreage and type: Not reported

Superfund Fed. landowner flag: Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported Not reported mercury cleaned up: nickel cleaned up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Not reported Chromium contaminant found: Copper contaminant found: Not reported Iron contaminant found: Not reported Mercury contaminant found: Not reported Not reported Nickel contaminant found: No contaminant found: Not reported Pesticides contaminant found: Not reported Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Not reported Unknown contaminant found: Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

Building material media cleaned up: Not reported

Property name: FORMER MILLER PRODUCTS PROPERTY

Not reported Not reported

Not reported

Property #: 41-13-24-357-005, 41-13-24-361-027, 41-13-24-378-003, 41-13-24-337-004

Parcel size: 3.6

Indoor air media cleaned up:

Unknown media cleaned up: Past Use: Multistory

Property Description: Not reported

Latitude: 42.97213960000001 Longitude: -85.68820900000003

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 102902 Start date: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

Completed date: Not reported Acres cleaned up: Not reported Cleanup funding: Not reported Not reported Cleanup funding source: Assessment funding: 26033

US EPA - Brownfields Assessment Cooperative Agreement Assessment funding source:

Redevelopment funding: Not reported Not reported Redev. funding source: Redev. funding entity name: Not reported Redevelopment start date: Not reported Assessment funding entity: **EPA**

Cleanup funding entity: Not reported

Grant type:

Accomplishment type: Phase II Environmental Assessment

Accomplishment count: Cooperative agreement #: 00E60801 Private Ownership entity: Current owner: Not reported

Did owner change: Cleanup required: Yes Video available: No Photo available: Yes Institutional controls required: Ν IC Category proprietary controls: Not reported

IC cat. info. devices: Not reported Not reported IC cat. gov. controls: IC cat. enforcement permit tools: Not reported IC in place date: Not reported IC in place: Not reported State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Air cleaned: Not reported Not reported Asbestos found: Asbestos cleaned: Not reported Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported

Groundwater affected:

Groundwater cleaned: Not reported

Lead contaminant found:

Not reported Lead cleaned up: No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found:

Other metals cleaned: Not reported Other contaminants found: Not reported Other contams found description: Not reported

PAHs found:

PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported Petro products found: Not reported Petro products cleaned: Not reported

Distance Elevation

tance EDR ID Number vation Site Database(s) EPA ID Number

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

Sediments found: Not reported Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported Num. of cleanup and re-dev. jobs: Not reported Past use greenspace acreage: Not reported Past use residential acreage: Not reported Not reported Past use commercial acreage: Past use industrial acreage: Not reported Not reported Future use greenspace acreage: Future use residential acreage: Not reported

Future use commercial acreage: .5
Future use industrial acreage: 3.1

Greenspace acreage and type: Not reported

Superfund Fed. landowner flag: Y

Arsenic cleaned up: Not reported Not reported Cadmium cleaned up: Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported mercury cleaned up: Not reported Not reported nickel cleaned up: No clean up: Not reported Pesticides cleaned up: Not reported Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Chromium contaminant found: Not reported Not reported Copper contaminant found: Not reported Iron contaminant found: Mercury contaminant found: Not reported Nickel contaminant found: Not reported No contaminant found: Not reported Pesticides contaminant found: Not reported Not reported Selenium contaminant found: SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Not reported Future Use: Multistory Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

Property name: FORMER MILLER PRODUCTS PROPERTY

Not reported

Not reported

Property #: 41-13-24-357-005, 41-13-24-361-027, 41-13-24-378-003, 41-13-24-337-004

Parcel size: 3.6

Unknown media cleaned up:

Past Use: Multistory

Property Description: Not reported

Direction Distance

Elevation Site Database(s) **EPA ID Number**

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Latitude: 42.97213960000001 Longitude: -85.68820900000003

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station North American Datum of 1983 Datum:

ACRES property ID: 102902 Start date: Not reported Completed date: Not reported Acres cleaned up: Not reported Cleanup funding: Not reported Cleanup funding source: Not reported 3000 Assessment funding:

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 500000 Redev. funding source: Local Funding

Tax Increment Financing Redev. funding entity name:

Redevelopment start date: Not reported Assessment funding entity: **EPA**

Not reported Cleanup funding entity:

Grant type: Н

Accomplishment type: Phase I Environmental Assessment

Accomplishment count: Cooperative agreement #: 00E60701 Ownership entity: Private Current owner: Not reported

Did owner change: Cleanup required: Yes Video available: No Photo available: Yes Institutional controls required: Ν

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported Not reported IC cat. enforcement permit tools: Not reported IC in place date: Not reported IC in place: State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Not reported Air contaminated: Not reported Air cleaned: Asbestos found: Not reported Not reported Asbestos cleaned: Not reported Controled substance found: Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported Groundwater affected: Groundwater cleaned: Not reported

Lead contaminant found:

Lead cleaned up: Not reported Not reported No media affected: Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found:

Other metals cleaned: Not reported Map ID MAP FINDINGS Direction

Distance Elevation Site

Database(s)

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

EPA ID Number

Other contaminants found: Not reported Other contams found description: Not reported PAHs found:

PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported Not reported Petro products found: Not reported Petro products cleaned: Sediments found: Not reported Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs: 65

Past use greenspace acreage: Not reported Past use residential acreage: Not reported Past use commercial acreage: Not reported Not reported Past use industrial acreage: Future use greenspace acreage: Not reported Not reported Future use residential acreage:

Future use commercial acreage: .5 Future use industrial acreage: 3.1

Not reported Greenspace acreage and type:

Superfund Fed. landowner flag:

Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Not reported Chromium cleaned up: Copper cleaned up: Not reported Iron cleaned up: Not reported mercury cleaned up: Not reported nickel cleaned up: Not reported Not reported No clean up: Pesticides cleaned up: Not reported Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported Not reported Cadmium contaminant found: Chromium contaminant found: Not reported Copper contaminant found: Not reported Not reported Iron contaminant found: Not reported Mercury contaminant found: Nickel contaminant found: Not reported No contaminant found: Not reported Pesticides contaminant found: Not reported Selenium contaminant found: Not reported Not reported SVOCs contaminant found: Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported

Building material media cleaned up: Not reported

Not reported

Not reported

Indoor air media cleaned up:

Unknown media cleaned up:

Direction Distance

Elevation Site Database(s) EPA ID Number

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

Property name: FORMER MILLER PRODUCTS PROPERTY

Property #: 41-13-24-357-005, 41-13-24-361-027, 41-13-24-378-003, 41-13-24-337-004

Parcel size: 3.6

Property Description: Not reported
Latitude: 42.97213960000001
Longitude: -85.68820900000003

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 102902
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported

Assessment funding: 3000

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 1000000

Redev. funding source: Private/Other Funding

Redev. funding entity name:

Redevelopment start date:

Assessment funding entity:

Cleanup funding entity:

Developer

Not reported

EPA

Not reported

Grant type:

Accomplishment type: Phase I Environmental Assessment

Accomplishment count: 1

Cooperative agreement #: 00E60701
Ownership entity: Private
Current owner: Not reported

Did owner change:

Cleanup required:

Video available:

Photo available:

Institutional controls required:

Yes

N

IC Category proprietary controls: Not reported Not reported IC cat. info. devices: IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported Not reported IC in place date: Not reported IC in place: State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Not reported Air cleaned: Asbestos found: Not reported Asbestos cleaned: Not reported Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported

Groundwater affected:

Map ID MAP FINDINGS
Direction

Direction Distance Elevation

n Site Database(s) EPA ID Number

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

EDR ID Number

Groundwater cleaned: Not reported

Lead contaminant found:

Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found: Y

Other metals cleaned: Not reported
Other contaminants found: Not reported
Other contams found description: Not reported

PAHs found: Y

PAHs cleaned up:
PCBs found:
Not reported
PCBs cleaned up:
Petro products found:
Petro products cleaned:
Petro products cleaned:
Not reported
Not reported
Not reported
Sediments found:
Not reported
Not reported
Not reported
Not reported

Soil affected: Y

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

65

Num. of cleanup and re-dev. jobs:

Past use greenspace acreage:
Past use residential acreage:
Past use commercial acreage:
Past use industrial acreage:
Past use industrial acreage:
Past use greenspace acreage:
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported

Future use commercial acreage: .5
Future use industrial acreage: 3.1

Greenspace acreage and type: Not reported

Superfund Fed. landowner flag: Y

Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported Not reported Pesticides cleaned up: Not reported Selenium cleaned up: SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Not reported Chromium contaminant found: Copper contaminant found: Not reported Iron contaminant found: Not reported Mercury contaminant found: Not reported Not reported Nickel contaminant found: No contaminant found: Not reported Pesticides contaminant found: Not reported Selenium contaminant found: Not reported

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

FORMER MILLER PRODUCTS PROPERTY (Continued)

1012296585

SVOCs contaminant found: Not reported Not reported Unknown contaminant found: Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Past Use: Multistory Not reported

614 FIRST STREET PARTNERS LLC RCRA-CESQG 1000280605 M49 MID000724864 BEA

SE **601 1ST ST NW**

1/4-1/2 **GRAND RAPIDS, MI 49504**

0.443 mi.

2338 ft. Site 2 of 7 in cluster M

RCRA-CESQG: Relative:

Date form received by agency: 10/26/2012 Higher

Facility name: 614 FIRST STREET PARTNERS LLC

Actual: Facility address: 601 1ST ST NW

621 ft.

GRAND RAPIDS, MI 49504

EPA ID: MID000724864 Contact: GEORGE COLVIN

Contact address: Not reported

Not reported Not reported

Contact country: Contact telephone: (616) 285-6933

GCOLVIN@ROCKFORDCONSTRUCTION.COM Contact email:

05 EPA Region: Land type: Private

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

the cleanup of a spill, into or on any land or water, of acutely

hazardous waste

Owner/Operator Summary:

614 FIRST STREET PARTNERS LLC Owner/operator name:

Owner/operator address: Not reported Not reported Owner/operator country: Not reported

Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: 09/12/2011 Owner/Op end date: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

614 FIRST STREET PARTNERS LLC (Continued)

1000280605

EDR ID Number

Owner/operator name: ROCKFORD CONSTRUCTION COMPANY

Owner/operator address: Not reported Not reported Owner/operator country: Not reported

Owner/operator country.

Owner/operator telephone:

Legal status:

Owner/Operator Type:

Owner/Op start date:

Owner/Op end date:

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: Nο User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 12/16/2011

Site name: MILLER PRODUCTS LLC
Classification: Not a generator, verified

Date form received by agency: 03/01/2008

Site name: MILLER PRODUCTS LLC Classification: Large Quantity Generator

Date form received by agency: 03/01/2008

Site name: MILLER PRODUCTS LLC Classification: Large Quantity Generator

Date form received by agency: 03/01/2006

Site name: MILLER PRODUCTS INC Classification: Large Quantity Generator

Date form received by agency: 02/23/2006

Site name: MILLER PRODUCTS LLC Classification: Large Quantity Generator

Date form received by agency: 03/01/2004

Site name: MILLER PRODUCTS INC Classification: Large Quantity Generator

Date form received by agency: 02/25/2004

Site name: MILLER PRODUCTS LLC
Classification: Large Quantity Generator

Direction Distance

Elevation Site Database(s) EPA ID Number

614 FIRST STREET PARTNERS LLC (Continued)

1000280605

EDR ID Number

Date form received by agency: 03/01/2002

Site name: MILLER PRODUCTS INC Classification: Large Quantity Generator

Date form received by agency: 02/16/2000

Site name: MILLER PRODUCTS INC Classification: Large Quantity Generator

Date form received by agency: 01/23/1998

Site name: MILLER PRODUCTS, INC. Classification: Large Quantity Generator

Date form received by agency: 02/27/1996

Site name: MILLER METAL PRODUCTS
Classification: Large Quantity Generator

Date form received by agency: 11/22/1995

Site name: MILLER PRODUCTS LLC Classification: Large Quantity Generator

Date form received by agency: 02/17/1994

Site name: MILLER METAL PRODUCTS
Classification: Large Quantity Generator

Date form received by agency: 02/19/1992

Site name: MILLER METAL PRODUCTS CORPORATION

Classification: Large Quantity Generator

Date form received by agency: 05/31/1990

Site name: MILLER METAL PRODUCTS CORPORATION

Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE

Direction Distance

Elevation Site Database(s) EPA ID Number

614 FIRST STREET PARTNERS LLC (Continued)

1000280605

EDR ID Number

MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Facility Has Received Notices of Violations:

Regulation violated: Not reported

Area of violation: Generators - Pre-transport

Date violation determined: 06/15/2007
Date achieved compliance: 07/02/2007
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 06/15/2007
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: Generators - Records/Reporting

Date violation determined: 06/15/2007
Date achieved compliance: 07/02/2007
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 06/15/2007
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported

Direction Distance Elevation

ration Site Database(s) EPA ID Number

614 FIRST STREET PARTNERS LLC (Continued)

1000280605

EDR ID Number

Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: Generators - Pre-transport

Date violation determined: 03/07/2001
Date achieved compliance: 04/02/2001
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 03/07/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: Generators - Pre-transport

Date violation determined: 09/25/1997
Date achieved compliance: 01/21/1998
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 09/25/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated:
Area of violation:

Date violation determined:
Date achieved compliance:
Violation lead agency:

Not reported
LDR - General
09/25/1997
01/21/1998
State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 09/25/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General

Date violation determined: 09/25/1997
Date achieved compliance: 01/21/1998
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 09/25/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Direction Distance Elevation

Site Database(s) EPA ID Number

614 FIRST STREET PARTNERS LLC (Continued)

1000280605

EDR ID Number

Regulation violated: Not reported
Area of violation: Generators - General

Date violation determined: 04/27/1994
Date achieved compliance: 07/19/1994
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 05/04/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 04/27/1994
Date achieved compliance: 07/19/1994
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 05/04/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: Generators - Manifest

Date violation determined: 04/27/1994
Date achieved compliance: 07/19/1994
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date:

Enf. disposition status:

Enf. disp. status date:

Enforcement lead agency:

Proposed penalty amount:

Final penalty amount:

Paid penalty amount:

O5/04/1994

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Regulation violated: Not reported

Area of violation: Generators - General

Date violation determined: 05/08/1990
Date achieved compliance: 07/19/1994
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Not reported

Enforcement action date: 06/15/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported

Regulation violated: Not reported

Paid penalty amount:

Direction Distance

Elevation Site Database(s) EPA ID Number

614 FIRST STREET PARTNERS LLC (Continued)

1000280605

EDR ID Number

Area of violation: Generators - General

Date violation determined: 08/25/1987
Date achieved compliance: 12/18/1987
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 08/28/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 10/29/2010

Evaluation: FOCUSED COMPLIANCE INSPECTION

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 06/13/2007

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Records/Reporting

Date achieved compliance: 07/02/2007 Evaluation lead agency: State

Evaluation date: 06/13/2007

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Pre-transport

Date achieved compliance: 07/02/2007 Evaluation lead agency: State

Evaluation date: 09/24/2003

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 03/30/2001

Evaluation: FOLLOW-UP INSPECTION

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 02/27/2001

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Pre-transport

Date achieved compliance: 04/02/2001 Evaluation lead agency: State

Evaluation date: 01/21/1998

Evaluation: FOLLOW-UP INSPECTION Area of violation: Generators - Pre-transport

Date achieved compliance: 01/21/1998 Evaluation lead agency: State

Evaluation date: 01/21/1998

Direction Distance

Elevation Site Database(s) EPA ID Number

614 FIRST STREET PARTNERS LLC (Continued)

1000280605

EDR ID Number

Evaluation: FOLLOW-UP INSPECTION

Area of violation: LDR - General Date achieved compliance: 01/21/1998 Evaluation lead agency: State

Evaluation date: 01/21/1998

Evaluation: FOLLOW-UP INSPECTION
Area of violation: Generators - General

Date achieved compliance: 01/21/1998 Evaluation lead agency: State

Evaluation date: 09/15/1997

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Pre-transport

Date achieved compliance: 01/21/1998 Evaluation lead agency: State

Evaluation date: 09/15/1997

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 01/21/1998 Evaluation lead agency: State

Evaluation date: 09/15/1997

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: LDR - General Date achieved compliance: 01/21/1998 Evaluation lead agency: State

Evaluation date: 07/14/1994

Evaluation: FOLLOW-UP INSPECTION

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 04/27/1994

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 07/19/1994 Evaluation lead agency: State

Evaluation date: 04/27/1994

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Manifest

Date achieved compliance: 07/19/1994 Evaluation lead agency: State

Evaluation date: 04/27/1994

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: LDR - General Date achieved compliance: 07/19/1994 Evaluation lead agency: State

Evaluation date: 05/08/1990

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 07/19/1994

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

614 FIRST STREET PARTNERS LLC (Continued)

1000280605

Evaluation lead agency: State

12/07/1987 Evaluation date:

COMPLIANCE SCHEDULE EVALUATION Evaluation:

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 08/25/1987

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 12/18/1987 Evaluation lead agency: State

Evaluation date: 03/20/1986

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Not reported Area of violation: Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 01/17/1985

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

BEA:

Secondary Address: Not reported

BEA Number: 296

District: **Grand Rapids** Date Received: 11/13/1997

Submitter Name: Pioneer Investment, L.L.C.

Petition Determination: No Request

Petition Disclosure:

Same Hazardous Substance(s) Category:

Determination 20107A: No Request Reviewer: moyerr

Division Assigned: **Environmental Response Division**

M50 601, 614 1ST ST/520 2ND ST/501 ALABAMA SE 601 & 614 1ST ST, 520 2ND ST NW &

1/4-1/2 **GRAND RAPIDS, MI**

0.443 mi.

2338 ft. Site 3 of 7 in cluster M

Relative:

Secondary Address: 501 Alabama Avenue NW Higher

BEA Number: 2680

Actual: District: **Grand Rapids** 621 ft. 03/11/2010 Date Received:

Submitter Name: Comerica Bank Petition Determination: No Request

Petition Disclosure:

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: henderas

Division Assigned: **Environmental Response Division** S110300782

N/A

BEA

Direction Distance

Elevation Site Database(s) EPA ID Number

M51 601 & 614 1ST ST/501 ALABAMA/520 2ND ST BEA S111455217
SE 601 & 614 1ST STREET & 501 ALABAMA AVE & N/A

1/4-1/2 GRAND RAPIDS, MI 49504

0.443 mi.

2338 ft. Site 4 of 7 in cluster M

Relative:

Higher Secondary Address: 520 2nd Street NW

BEA Number: 3060

Actual: District: Grand Rapids 621 ft. Date Received: 12/06/2011

Submitter Name: 614 First Street Partners LLC

Petition Determination: No Request

Petition Disclosure: 0

Category: Not reported
Determination 20107A: No Request
Reviewer: henderas
Division Assigned: RD

 M52
 601 FIRST STREET NW
 BEA
 \$111134664

 SE
 601 FIRST STREET NW
 N/A

 1/4-1/2
 GRAND RAPIDS, MI
 N/A

0.443 mi.

2338 ft. Site 5 of 7 in cluster M

Relative: BEA:

Higher Secondary Address: Not reported

BEA Number: 1869

Actual: District: Grand Rapids 621 ft. Date Received: 06/14/2006

Submitter Name: TMB Industries
Petition Determination: No Request

Petition Disclosure: 0

Category: Same Hazardous Substance(s)

Determination 20107A: No Request Reviewer: pearsons

Division Assigned: Environmental Response Division

Secondary Address: Not reported

BEA Number: 60

District: Grand Rapids
Date Received: 02/15/1996
Submitter Name: Miller Products, Inc.

Petition Determination: No Request

Petition Disclosure: 0

Category: Same Hazardous Substance(s)

Determination 20107A: No Request Reviewer: moyerr

Division Assigned: Environmental Response Division

EDR ID Number

Direction Distance

Elevation Site **EPA ID Number** Database(s)

N53 **MERCANTILE BANK PROPERTIES US BROWNFIELDS** 1012297135 N/A

SSE 420 AND 430 STOCKING AVENUE, 424, 428, 431, 436, AND 437 LEX 1/4-1/2 **GRAND RAPIDS, MI 49504**

0.468 mi.

2472 ft. Site 1 of 3 in cluster N

Relative: Higher

US BROWNFIELDS:

Recipient name: Grand Rapids, City of

Grant type: Assessment

Actual: Property name: MERCANTILE BANK PROPERTIES 615 ft.

Property #: Not reported Parcel size: .75

Property Description: The Property was developed for residential and commercial purposes as

> of 1888. A gasoline filling station and three gasoline tanks were situated on the southern portion of the Property from at least 1936 to 1953. Residential structures remained on the Property until at least 1986, when the residence at 431 Lexington Avenue was razed. Various restaurants occupied the Property from 1951 until 2008, when the Property was transferred to Mercantile Bank through foreclosure.

42.971596 Latitude:

Longitude: -85.68450999999999

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station North American Datum of 1983 Datum:

ACRES property ID: 105847

Start date: Not reported Not reported Completed date: Acres cleaned up: Not reported Cleanup funding: Not reported Cleanup funding source: Not reported

Assessment funding: 4000

US EPA - Brownfields Assessment Cooperative Agreement Assessment funding source:

Not reported Redevelopment funding: Redev. funding source: Not reported Redev. funding entity name: Not reported Not reported Redevelopment start date: Assessment funding entity: **EPA** Cleanup funding entity: Not reported

Grant type: В

Phase I Environmental Assessment Accomplishment type:

Accomplishment count:

Cooperative agreement #: 00E60701 Ownership entity: Not reported Current owner: Not reported

Did owner change: Ν Cleanup required: Yes Video available: No Photo available: Yes Institutional controls required:

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported Not reported IC in place date: IC in place: Not reported State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported **EDR ID Number**

Map ID MAP FINDINGS
Direction

Distance Elevation Site

Database(s)

MERCANTILE BANK PROPERTIES (Continued)

1012297135

EDR ID Number

EPA ID Number

Air contaminated: Not reported Not reported Air cleaned: Not reported Asbestos found: Not reported Asbestos cleaned: Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported

Groundwater affected:

Groundwater cleaned: Not reported

Lead contaminant found: Y

Lead cleaned up:

No media affected:

Unknown media affected:

Other cleaned up:

Not reported

Not reported

Not reported

Other metals found:

Other metals cleaned:
Other contaminants found:
Other contams found description:
PAHs found:
PAHs cleaned up:
PCBs found:
PCBs cleaned up:
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported

Petro products found:

Petro products cleaned:
Sediments found:
Sediments cleaned:
Sediments cleaned:
Soil affected:
Not reported
Y

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported Num. of cleanup and re-dev. jobs: Not reported Past use greenspace acreage: Not reported Not reported Past use residential acreage: Past use commercial acreage: Not reported Past use industrial acreage: Not reported Future use greenspace acreage: Not reported Future use residential acreage: Not reported

Future use commercial acreage: .75

Future use industrial acreage: Not reported Greenspace acreage and type: Not reported Not reported Superfund Fed. landowner flag: Not reported Arsenic cleaned up: Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported Not reported Selenium cleaned up: SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

MERCANTILE BANK PROPERTIES (Continued)

1012297135

EDR ID Number

Cadmium contaminant found: Not reported Not reported Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Mercury contaminant found: Not reported Nickel contaminant found: Not reported Not reported No contaminant found: Not reported Pesticides contaminant found: Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Not reported Unknown contaminant found: Not reported Future Use: Multistory Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Not reported Indoor air media cleaned up: Unknown media cleaned up: Not reported Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

Property name: MERCANTILE BANK PROPERTIES

Property #: Not reported

Parcel size: .75

Latitude:

Property Description: The Property was developed for residential and commercial purposes as

of 1888. A gasoline filling station and three gasoline tanks were situated on the southern portion of the Property from at least 1936 to 1953. Residential structures remained on the Property until at least 1986, when the residence at 431 Lexington Avenue was razed. Various restaurants occupied the Property from 1951 until 2008, when the Property was transferred to Mercantile Bank through foreclosure.

42.971596

Longitude: -85.68450999999999

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 105847
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported

Assessment funding: 3960

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding:
Redev. funding source:
Redev. funding entity name:
Redevelopment start date:
Assessment funding entity:
Cleanup funding entity:

Not reported
Not reported
Not reported
Pea

Grant type:

Accomplishment type: Supplemental Assessment

Accomplishment count: 0

Cooperative agreement #: 00E60701
Ownership entity: Not reported
Current owner: Not reported

Map ID MAP FINDINGS Direction

Distance Elevation Site

Database(s) **EPA ID Number**

MERCANTILE BANK PROPERTIES (Continued)

1012297135

EDR ID Number

Did owner change: Ν Cleanup required: Yes Video available: No Photo available: Yes Institutional controls required: Ν

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported Not reported IC cat. gov. controls: IC cat. enforcement permit tools: Not reported IC in place date: Not reported Not reported IC in place: State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Air cleaned: Not reported Not reported Asbestos found: Asbestos cleaned: Not reported Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported

Groundwater affected:

Groundwater cleaned: Not reported

Lead contaminant found:

Not reported Lead cleaned up: No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found:

Other metals cleaned: Not reported Other contaminants found: Not reported Not reported Other contams found description: PAHs found: Not reported PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported

Petro products found:

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported Num. of cleanup and re-dev. jobs: Not reported Past use greenspace acreage: Not reported Not reported Past use residential acreage: Past use commercial acreage: Not reported Past use industrial acreage: Not reported Future use greenspace acreage: Not reported Not reported Future use residential acreage:

Future use commercial acreage: .75

Not reported Future use industrial acreage: Greenspace acreage and type: Not reported Map ID MAP FINDINGS
Direction

Distance

Elevation Site Database(s) EPA ID Number

MERCANTILE BANK PROPERTIES (Continued)

1012297135

EDR ID Number

Superfund Fed. landowner flag: Not reported Arsenic cleaned up: Not reported Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Copper cleaned up: Not reported Iron cleaned up: Not reported mercury cleaned up: Not reported Not reported nickel cleaned up: No clean up: Not reported Pesticides cleaned up: Not reported Not reported Selenium cleaned up: Not reported SVOCs cleaned up: Unknown clean up: Not reported Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Chromium contaminant found: Not reported Not reported Copper contaminant found: Not reported Iron contaminant found: Mercury contaminant found: Not reported Nickel contaminant found: Not reported Not reported No contaminant found: Pesticides contaminant found: Not reported Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Not reported Future Use: Multistory Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

Property name: MERCANTILE BANK PROPERTIES

Property #: Not reported

Parcel size: .75

Property Description: The Property was developed for residential and commercial purposes as

of 1888. A gasoline filling station and three gasoline tanks were situated on the southern portion of the Property from at least 1936 to 1953. Residential structures remained on the Property until at least 1986, when the residence at 431 Lexington Avenue was razed. Various restaurants occupied the Property from 1951 until 2008, when the Property was transferred to Mercantile Bank through foreclosure.

Latitude: 42.971596

Longitude: -85.68450999999999

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 105847
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported

Map ID MAP FINDINGS Direction

Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MERCANTILE BANK PROPERTIES (Continued)

1012297135

Assessment funding: 2675

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 200000 Local Funding Redev. funding source: Redev. funding entity name: Tax Incentives Redevelopment start date: Not reported Assessment funding entity: **EPA** Cleanup funding entity: Not reported

Grant type:

Accomplishment type: Phase I Environmental Assessment

Accomplishment count:

00E60801 Cooperative agreement #: Ownership entity: Not reported Current owner: Not reported

Did owner change: Cleanup required: Yes Video available: Nο Photo available: Yes Institutional controls required: Not reported IC Category proprietary controls:

IC cat. info. devices: Not reported IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported IC in place date: Not reported IC in place: Not reported Not reported State/tribal program date: State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Not reported Air cleaned: Asbestos found: Not reported Asbestos cleaned: Not reported Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported

Groundwater affected:

Groundwater cleaned: Not reported

Lead contaminant found:

Not reported Lead cleaned up: Not reported No media affected: Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found:

Other metals cleaned: Not reported Other contaminants found: Not reported Other contams found description: Not reported PAHs found: Not reported PAHs cleaned up: Not reported Not reported PCBs found: PCBs cleaned up: Not reported

Petro products found:

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported Map ID MAP FINDINGS Direction

Elevation Site

Distance

EPA ID Number Database(s)

MERCANTILE BANK PROPERTIES (Continued)

1012297135

EDR ID Number

Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Not reported Cleanup other description:

Num. of cleanup and re-dev. jobs:

Past use greenspace acreage: Not reported Past use residential acreage: Not reported Past use commercial acreage: Not reported Past use industrial acreage: Not reported Future use greenspace acreage: Not reported Not reported Future use residential acreage:

Future use commercial acreage: .75

Future use industrial acreage: Not reported Not reported Greenspace acreage and type: Superfund Fed. landowner flag: Not reported Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported Not reported mercury cleaned up: Not reported nickel cleaned up: No clean up: Not reported Pesticides cleaned up: Not reported Selenium cleaned up: Not reported Not reported SVOCs cleaned up: Unknown clean up: Not reported Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Not reported Not reported Mercury contaminant found: Nickel contaminant found: Not reported Not reported No contaminant found: Pesticides contaminant found: Not reported Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Future Use: Multistory Not reported Not reported Media affected Bluiding Material: Media affected indoor air: Not reported Building material media cleaned up: Not reported Not reported Indoor air media cleaned up: Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

MERCANTILE BANK PROPERTIES Property name:

Not reported

Property #: Not reported

Parcel size:

Unknown media cleaned up: Past Use: Multistory

Property Description: The Property was developed for residential and commercial purposes as

> of 1888. A gasoline filling station and three gasoline tanks were situated on the southern portion of the Property from at least 1936 to 1953. Residential structures remained on the Property until at least 1986, when the residence at 431 Lexington Avenue was razed.

Direction Distance

Elevation Site Database(s) EPA ID Number

MERCANTILE BANK PROPERTIES (Continued)

1012297135

EDR ID Number

Various restaurants occupied the Property from 1951 until 2008, when the Property was transferred to Mercantile Bank through foreclosure.

Latitude: 42.971596

Longitude: -85.68450999999999

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 105847
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported
Assessment funding: 2675

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 500000

Redev. funding source: Private/Other Funding

Redev. funding entity name: Developer Redevelopment start date: Not reported

Assessment funding entity: EPA

Cleanup funding entity: Not reported

Grant type:

Accomplishment type: Phase I Environmental Assessment

Accomplishment count:

Cooperative agreement #: 00E60801
Ownership entity: Not reported
Current owner: Not reported

Did owner change:

Cleanup required:

Video available:

Photo available:

Institutional controls required:

N

N

N

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported IC in place date: Not reported IC in place: Not reported State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Not reported Air cleaned: Not reported Asbestos found: Asbestos cleaned: Not reported Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported Groundwater affected: Groundwater cleaned: Not reported

Lead contaminant found:

Lead cleaned up:

No media affected:

Unknown media affected:

Other cleaned up:

Not reported

Not reported

Not reported

Not reported

Map ID MAP FINDINGS Direction

Distance Elevation Site

EDR ID Number Database(s) **EPA ID Number**

MERCANTILE BANK PROPERTIES (Continued)

1012297135

Other metals found: Not reported Other metals cleaned: Not reported Other contaminants found: Not reported Other contams found description: PAHs found: Not reported PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported

Petro products found:

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs:

Past use greenspace acreage: Not reported Past use residential acreage: Not reported Past use commercial acreage: Not reported Past use industrial acreage: Not reported Future use greenspace acreage: Not reported Future use residential acreage: Not reported

Future use commercial acreage:

Cadmium contaminant found:

Chromium contaminant found:

Copper contaminant found: Iron contaminant found:

Mercury contaminant found: Nickel contaminant found:

No contaminant found:

.75 Future use industrial acreage: Not reported Greenspace acreage and type: Not reported Superfund Fed. landowner flag: Not reported Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Not reported Copper cleaned up: Iron cleaned up: Not reported mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported

> Not reported Not reported

Not reported

Not reported Not reported

Not reported

Not reported

Not reported Pesticides contaminant found: Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Not reported Future Use: Multistory Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

MERCANTILE BANK PROPERTIES (Continued)

1012297135

EDR ID Number

Indoor air media cleaned up:
Unknown media cleaned up:
Past Use: Multistory

Not reported
Not reported
Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

Property name: MERCANTILE BANK PROPERTIES

Property #: Not reported

Parcel size: .75

Property Description: The Property was developed for residential and commercial purposes as

of 1888. A gasoline filling station and three gasoline tanks were situated on the southern portion of the Property from at least 1936 to 1953. Residential structures remained on the Property until at least 1986, when the residence at 431 Lexington Avenue was razed. Various restaurants occupied the Property from 1951 until 2008, when the Property was transferred to Mercantile Bank through foreclosure.

Latitude: 42.971596

Longitude: -85.68450999999999

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 105847
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported
Assessment funding: 36627

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding:

Redev. funding source:

Redev. funding entity name:

Redevelopment start date:

Assessment funding entity:

Cleanup funding entity:

200000

Local Funding

Tax Incentives

Not reported

EPA

Not reported

Grant type:

Accomplishment type: Phase II Environmental Assessment

Accomplishment count: 0
Cooperative agreement #: 00E60801
Ownership entity: Not reported

Current owner:

Did owner change:

Cleanup required:

Not reported

Not reported

Yes

Video available: No Photo available: Yes Institutional controls required: N

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported Not reported IC cat. gov. controls: IC cat. enforcement permit tools: Not reported IC in place date: Not reported Not reported IC in place: State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Map ID MAP FINDINGS Direction

Distance Elevation

Site Database(s) **EPA ID Number**

MERCANTILE BANK PROPERTIES (Continued)

1012297135

EDR ID Number

Air cleaned: Not reported Asbestos found: Not reported Not reported Asbestos cleaned: Not reported Controled substance found: Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported Groundwater affected:

Groundwater cleaned: Not reported

Lead contaminant found:

Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found:

Other metals cleaned: Not reported Not reported Other contaminants found: Other contams found description: Not reported PAHs found: Not reported PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported

Petro products found:

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs:

Past use greenspace acreage: Not reported Past use residential acreage: Not reported Past use commercial acreage: Not reported Past use industrial acreage: Not reported Future use greenspace acreage: Not reported Future use residential acreage: Not reported

Future use commercial acreage: .75

Not reported Future use industrial acreage: Not reported Greenspace acreage and type: Superfund Fed. landowner flag: Not reported Not reported Arsenic cleaned up: Not reported Cadmium cleaned up: Chromium cleaned up: Not reported Not reported Copper cleaned up: Iron cleaned up: Not reported mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported Selenium cleaned up: Not reported Not reported SVOCs cleaned up: Unknown clean up: Not reported Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Map ID MAP FINDINGS
Direction

Distance

Elevation Site Database(s) EPA ID Number

MERCANTILE BANK PROPERTIES (Continued)

1012297135

EDR ID Number

Chromium contaminant found: Not reported Not reported Copper contaminant found: Not reported Iron contaminant found: Not reported Mercury contaminant found: Nickel contaminant found: Not reported Not reported No contaminant found: Not reported Pesticides contaminant found: Not reported Selenium contaminant found: SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Not reported Future Use: Multistory Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Not reported Unknown media cleaned up: Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment

Property name: MERCANTILE BANK PROPERTIES

Property #: Not reported

Parcel size: .75

Latitude:

Property Description: The Property was developed for residential and commercial purposes as

of 1888. A gasoline filling station and three gasoline tanks were situated on the southern portion of the Property from at least 1936 to 1953. Residential structures remained on the Property until at least 1986, when the residence at 431 Lexington Avenue was razed. Various restaurants occupied the Property from 1951 until 2008, when the Property was transferred to Mercantile Bank through foreclosure.

42.971596

Longitude: -85.68450999999999

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Center of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 105847
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported
Assessment funding: 36627

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 500000

Redev. funding source: Private/Other Funding

Redev. funding entity name:
Redevelopment start date:
Assessment funding entity:
Cleanup funding entity:

Developer
Not reported
Not reported

Grant type:

Accomplishment type: Phase II Environmental Assessment

Accomplishment count:

Cooperative agreement #: 00E60801
Ownership entity: Not reported
Current owner: Not reported

Did owner change:

Map ID MAP FINDINGS
Direction

Distance Elevation Site

ite Database(s) EPA ID Number

MERCANTILE BANK PROPERTIES (Continued)

1012297135

EDR ID Number

Cleanup required: Yes
Video available: No
Photo available: Yes
Institutional controls required: N

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported Not reported IC cat. enforcement permit tools: IC in place date: Not reported IC in place: Not reported Not reported State/tribal program date: State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Air cleaned: Not reported Asbestos found: Not reported Not reported Asbestos cleaned: Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Not reported Drinking water cleaned: Groundwater affected:

Groundwater cleaned: Not reported

Lead contaminant found:

Lead cleaned up: Not reported
No media affected: Not reported
Unknown media affected: Not reported
Other cleaned up: Not reported

Other metals found: Y

Other metals cleaned:
Other contaminants found:
Other contams found description:
PAHs found:
PAHs cleaned up:
PCBs found:
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported

Petro products found: Y

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected: Y

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs: 30

Past use greenspace acreage:
Past use residential acreage:
Past use commercial acreage:
Past use industrial acreage:
Past use industrial acreage:
Patture use greenspace acreage:
Future use residential acreage:
Not reported
Not reported
Not reported

Future use commercial acreage: .75

Future use industrial acreage:

Greenspace acreage and type:

Superfund Fed. landowner flag:

Not reported

Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MERCANTILE BANK PROPERTIES (Continued)

1012297135

Arsenic cleaned up: Not reported Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Copper cleaned up: Iron cleaned up: Not reported mercury cleaned up: Not reported nickel cleaned up: Not reported Not reported No clean up: Pesticides cleaned up: Not reported Selenium cleaned up: Not reported Not reported SVOCs cleaned up: Not reported Unknown clean up: Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Chromium contaminant found: Not reported Copper contaminant found: Not reported Not reported Iron contaminant found: Mercury contaminant found: Not reported Nickel contaminant found: Not reported No contaminant found: Not reported Not reported Pesticides contaminant found: Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Past Use: Multistory Not reported

54 S117057694 **AMOCO STATION** AUL NNE 1152 ELIZABETH AVENUE NW N/A

1/4-1/2 0.469 mi. 2477 ft.

AUL: Relative:

Status: Pending Lower Site Name: Not reported

GRAND RAPIDS, MI 49504

Actual: Property: off-site 610 ft. Land Use Restriction Type: RC Part 213 Program Type:

Program Support Assigned User: Not reported Program Support Assigned Date: Not reported Legal Description Of Property: Not reported Based On The Deq Ref #: 11121314172 MDEQ Reference Number: RC-RRD-213-14-172

Property Or Description Restricted Area: Not reported

Lead Division:

File Name Of Hyperlinked Legal Doc: Not reported Mapped Polygons Area In Acres: Not reported Mapped Polygons Area In Square Miles: Not reported Date Data Entry Started: Not reported Date Data Entry Finished: Not reported

Individual Or Staff Assoc With The Mapping: Not reported Program Used To Map Restricted Features: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

AMOCO STATION (Continued)

S117057694

INVENTORY

WDS

S111952876

N/A

Date Legal Paperwork Stamped/Filed/Register Of Deeds: Not reported Commercial I Land Use Restriction: 0

Commercial li Land Use Restriction: 0 Commercial lii Land Use Restriction: 0 Commercial Iv Land Use Restriction: 0 Industrial Land Use Restriction: 0 Residential Land Use Restriction: 0 Recreational Land Use Restriction: 0 Multiple Land-Use Restrictions: 0 Site Specific Restrictions: 0 Groundwater Consumption Restrictions: 0 **Groundwater Contact Restrictions:** Special Well Construction Requirements: 0 Special Building Restrictions: **Excavation And Soil Movement Restrictions:**

0 Soil Movement Requirements: 0 There Is A Restriction On All Construction: 0 Monitoring Well Protected, No Tampering Or Removal: 0 There Is An Exposure Barrier In Place: 0 0 There Is A Health And Safety Plan: There Is A Permanent Marker On The Site: 0

Map Comments: Not reported

Comment: August 19, 2014 consultant requested DEQ reference #.

O55 EQUILON ENTERPRISES LLC North 747 LEONARD ST NW 1/4-1/2 **GRAND RAPIDS, MI 49504**

0.472 mi.

2490 ft. Site 1 of 2 in cluster O

INVENTORY: Relative:

Bea Number: Lower

Not reported Township: Actual: District: Grand Rapids 614 ft. Data Source: Part 213 42.98578 Latitude: Longitude: -85.68776

WDS:

Site Id: MIG000041673

Not reported

WMD Id: 426856

Site Specific Name: **EQUILON ENTERPRISES** Mailing Address: 747 LEONARD ST NW

Mailing City/State/Zip: 49504 Mailing County: **KENT**

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

INVENTORY

INVENTORY

BEA

LUST

UST

WDS

U002301774

N/A

S114026283

S109569498

N/A

N/A

M56 601, 614 1ST ST/520 2ND ST/501 ALABAMA

SSE 601 & 614 1ST ST, 520 2ND ST NW & 501 ALABAMA AVENUE NW

1/4-1/2 KENT (County), MI

0.472 mi.

Site 6 of 7 in cluster M 2491 ft.

Relative:

617 ft.

INVENTORY:

201002680GR Higher Bea Number: Township: **Grand Rapids** Actual: District: **Grand Rapids**

> Data Source: BEA Latitude: 42.97214 Longitude: -85.68274

M57 **500 & 502 2ND STREET NW 500 & 502 2ND STREET NW** SE

1/4-1/2 **GRAND RAPIDS, MI**

0.472 mi.

2491 ft. Site 7 of 7 in cluster M

Relative:

INVENTORY: Bea Number: Higher

Not reported Township: **Grand Rapids** Actual: District: **Grand Rapids** 619 ft. Data Source: Part 201

42.97251 Latitude: Longitude: -85.68198

BEA:

Secondary Address: Not reported BEA Number: 2490

District: **Grand Rapids** Date Received: 05/14/2009 Submitter Name: 1 to 3.org LLC Petition Determination: No Request

Petition Disclosure:

No Hazardous Substance(s) Category:

Determination 20107A: No Request Reviewer: pawlosj2

Division Assigned: **Environmental Response Division**

O58 CITY OF GRAND RAPIDS ROW North **800 LEONARD ST NW** 1/4-1/2 **GRAND RAPIDS, MI 49504**

0.473 mi.

2498 ft. Site 2 of 2 in cluster O

LUST: Relative:

Facility ID: 00036405 Higher

Source: STATE OF MICHIGAN Actual: Owner Name: Mr Steve Kishkorn 615 ft. Owner Address: PO Box 141426

Owner City,St,Zip: Grand Rapids, MI 49514-1426

Owner Contact: Not reported Owner Phone: (616) 453-5034

Country: USA

Grand Rapids District Office District:

Site Name: Walgreens

TC04170139.2r Page 103

Direction Distance

Elevation Site Database(s) EPA ID Number

CITY OF GRAND RAPIDS ROW (Continued)

U002301774

EDR ID Number

Latitude: 42.98511 Longitude: -85.68813 Date of Collection: 01/11/2001

Method of Collection: Address Matching-House Number

Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Data: NAD83
Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Leak Number: C-0674-92
Release Date: 04/27/1992
Substance Released: Gasoline
Release Status: Closed
Release Closed Date: 11/09/1992

Leak Number: C-0821-94
Release Date: 08/02/1994
Substance Released: Gasoline
Release Status: Closed
Release Closed Date: 03/31/1995

UST:

Facility ID: 00038187 Facility Type: CLOSED

Owner Name: CITY OF GRAND RAPIDS DDA
Owner Address: 300 MONROE NW 9TH FLOOR
Owner City, St, Zip: GRAND RAPIDS, MI 49503

Owner Country: USA Owner Contact: Not reported Owner Phone: (616) 456-3034 **BILL COLE** Contact: Contact Phone: (616) 456-3060 Date of Collection: 01/11/2001 Accuracy: 100 Accuracy Value Unit: FEET

Horizontal Datum: NAD83

Source: STATE OF MICHIGAN Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Latitude: 42.98511 Longitude: -85.68813

Tank ID:

Tank Status: Removed from Ground

Capacity: 560
Product: Gasoline
Install Date: Not reported
Remove Date: 08/02/1994
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Unknown
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Direction Distance

Elevation Site Database(s) EPA ID Number

CITY OF GRAND RAPIDS ROW (Continued)

U002301774

EDR ID Number

Tank ID:

Tank Status: Removed from Ground

Capacity: 1000 Product: Gasoline Install Date: Not reported 04/30/1992 Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Not reported Piping Type: Not reported Construction Material: Not reported

Impressed Device: No

Tank ID: 2

Tank Status: Removed from Ground

Capacity: 1000 Product: Gasoline Install Date: Not reported 04/30/1992 Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Not reported Piping Type: Not reported Construction Material: Not reported

Impressed Device: No

Tank ID:

Tank Status: Removed from Ground

1000 Capacity: Product: Gasoline Install Date: Not reported 04/30/1992 Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Not reported Piping Type: Not reported Construction Material: Not reported

Impressed Device: No

WDS:

Site Id: MI0000692129 WMD Id: 391333

Site Specific Name: CITY OF GRAND RAPIDS LEONARD ST RIGHT OF WAY

Mailing Address: 300 MONROE AVE NW

Mailing City/State/Zip: 49503 Mailing County: KENT

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

P59 **JACK'S SERVICE CENTER INVENTORY** U003328781 NNW 850 LEONARD ST NW LUST N/A

1/4-1/2 **GRAND RAPIDS, MI 49504** 0.484 mi.

2558 ft. Site 1 of 2 in cluster P

INVENTORY: Relative:

Higher Bea Number: Not reported Township: Not reported

Actual: District: **Grand Rapids** 616 ft. Data Source: Part 213 Latitude: 42.98506

Longitude:

LUST:

Facility ID: 00016860

Source: STATE OF MICHIGAN Owner Name: Jack's Serv Ctr 850 Leonard St NW Owner Address:

-85.69017

Owner City, St, Zip: Grand Rapids, MI 49504-4155

Owner Contact: Not reported Owner Phone: (615) 459-0975

Country: USA

District: **Grand Rapids District Office** Site Name: Jack's Service Center

42.98459 Latitude: Longitude: -85.69056 Date of Collection: 02/19/2002

Method of Collection: GPS Code Meas. Standard Positioning Service SA Off

Accuracy:

Accuracy Value Unit: **METERS** Horizontal Data: NAD83 Point Line Area: **POINT**

Desc Category: Plant Entrance (Freight)

Leak Number: C-0193-02 04/17/2002 Release Date: Substance Released: Unknown Release Status: Open Release Closed Date: Not reported

Leak Number: C-0461-03

11/06/2003 Release Date: Substance Released: Used Oil Release Status: Closed Release Closed Date: 02/10/2004

UST:

Facility ID: 00016860 Facility Type: **ACTIVE**

Owner Name: JACK'S SERV CTR Owner Address: 850 LEONARD ST NW

Owner City, St, Zip: GRAND RAPIDS, MI 49504-4155

Owner Country: Owner Contact: Not reported Owner Phone: (615) 459-0975 Contact: Jack C Wielhouwer Contact Phone: (616) 459-0925 Date of Collection: 02/19/2002

UST

WDS

Direction Distance

Elevation Site Database(s) EPA ID Number

JACK'S SERVICE CENTER (Continued)

U003328781

EDR ID Number

Accuracy: 10
Accuracy Value Unit: METERS
Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: GPS Code Meas. Standard Positioning Service SA Off

Latitude: 42.98459 Longitude: -85.69056

Tank ID:

Tank Status: Currently In Use

Capacity: 8000
Product: Gasoline
Install Date: 04/22/1984
Remove Date: Not reported

Tank Release Detection: Automatic Tank Gauging

Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Suction: Valve at Tank

Construction Material: Cathodically Protected Steel, Epoxy Coated Steel

Impressed Device: Yes

Tank ID: 2

Tank Status: Currently In Use

Capacity: 4000
Product: Gasoline
Install Date: 04/22/1984
Remove Date: Not reported

Tank Release Detection: Automatic Tank Gauging

Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Suction: Valve at Tank

Construction Material: Cathodically Protected Steel, Epoxy Coated Steel

Impressed Device: Yes

Tank ID:

Tank Status: Removed from Ground

 Capacity:
 8000

 Product:
 Gasoline

 Install Date:
 04/22/1969

 Remove Date:
 11/05/2003

Tank Release Detection: Automatic Tank Gauging

Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Suction: Valve at Tank
Construction Material: Asphalt Coated or Bare Steel

Impressed Device: Yes

Tank ID: 4

Tank Status: Removed from Ground

Capacity: 500
Product: Used Oil
Install Date: 04/22/1978

Direction
Distance

Elevation Site Database(s) EPA ID Number

JACK'S SERVICE CENTER (Continued)

U003328781

EDR ID Number

Remove Date: 11/06/2003

Tank Release Detection: Inventory Control, Manual Tank Gauging

Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Gravity Fed?

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: Yes

Tank ID:

Tank Status: Currently In Use

Capacity: 45
Product: OIL
Install Date: 04/22/1978
Remove Date: Not reported
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID:

Tank Status: Currently In Use

Capacity: 45
Product: OIL
Install Date: 04/22/1978
Remove Date: Not reported
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 7

Tank Status: Currently In Use

Capacity: 35
Product: OIL
Install Date: 04/22/1974
Remove Date: Not reported
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID:

Tank Status: Currently In Use

Capacity: 35
Product: OIL
Install Date: 04/22/1974
Remove Date: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

JACK'S SERVICE CENTER (Continued)

U003328781

EDR ID Number

Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Construction Material: Asphalt Coated or Bare Steel

Impressed Device: No

WDS:

 Site Id:
 MIG000007258

 WMD Id:
 458048

 Site Specific Name:
 AMOCO OIL CO

 Mailing Address:
 850 LEONARD ST NW

Mailing City/State/Zip: 49504 Mailing County: KENT

60 1ST STREET N.W., 601 INVENTORY S114026282 SSE 601 1ST STREET NW N/A

SSE 601 1ST STREET NW N/A 1/4-1/2 GRAND RAPIDS, MI 49504

0.485 mi. 2560 ft.

Relative: INVENTORY:

Higher Bea Number: Not reported Township: Grand Rapids
Actual: District: Grand Rapids
617 ft. Data Source: Part 201

Latitude: 42.97214 Longitude: -85.68274

Q61 667 LEONARD STREET NW INVENTORY S114029521

NNE 667 LEONARD STREET NW 1/4-1/2 KENT (County), MI 49504

0.485 mi.

2562 ft. Site 1 of 3 in cluster Q

Relative: INVENTORY:

Lower Bea Number: 201002732GR Township: Grand Rapids Actual: District: Grand Rapids

613 ft. Data Source: BEA

Latitude: Not reported Longitude: Not reported

Q62 667 LEONARD STREET NW BEA S110482869
NNE 667 LEONARD STREET NW N/A

1/4-1/2 GRAND RAPIDS, MI 49504

0.485 mi.

2562 ft. Site 2 of 3 in cluster Q

Relative: BEA:

Lower Secondary Address: Not reported

BEA Number: 2732

Actual: District: Grand Rapids 613 ft. Date Received: 05/27/2010

N/A

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

667 LEONARD STREET NW (Continued)

S110482869

Submitter Name: 3R Foods Inc Petition Determination: No Request

Petition Disclosure: 0

No Hazardous Substance(s) Category:

Determination 20107A: No Request Reviewer: austina

Division Assigned: Storage Tank Division

N63 **CERC-NFRAP SPUR GAS STATION** 1003871685 MID981094824

420 STOCKING ST SSE 1/4-1/2 **GRAND RAPIDS, MI 49505**

0.486 mi.

2566 ft. Site 2 of 3 in cluster N

Relative:

CERC-NFRAP:

Site ID: Higher

Federal Facility: Not a Federal Facility Actual: NPL Status: Not on the NPL

615 ft. Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

0503382

Program Priority:

Description: **Great Lakes**

CERCLIS-NFRAP Assessment History:

PRELIMINARY ASSESSMENT Action:

Date Started: Date Completed: 07/29/86

NFRAP-Site does not qualify for the NPL based on existing information Priority Level:

Action: **ARCHIVE SITE**

Date Started:

Date Completed: 07/29/86 Priority Level: Not reported

Action: **DISCOVERY**

Date Started: 06/30/85 Date Completed: Priority Level: Not reported

US BROWNFIELDS 1016356765 Q64 **RALPH'S MARKET** NNE 655-667 LEONARD STREET NW **FINDS** N/A

1/4-1/2 **GRAND RAPIDS, MI 49504**

0.489 mi.

Actual:

Site 3 of 3 in cluster Q 2582 ft. **US BROWNFIELDS:**

Relative: Recipient name: Grand Rapids, City of Lower

Grant type: Assessment RALPH'S MARKET Property name:

613 ft. Property #: Not reported

Parcel size:

Property Description: Not reported Latitude: 42.985388

Longitude: -85.685265000000002

HCM label: Address Matching-House Number

Direction Distance Elevation

evation Site Database(s) EPA ID Number

RALPH'S MARKET (Continued)

1016356765

EDR ID Number

Map scale: Not reported

Point of reference: Entrance Point of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 107701
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported
Assessment funding: 3800

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 178000
Redev. funding source: Local Funding
Redev. funding entity name: Grand Rapids
Redevelopment start date: Not reported
Assessment funding entity: Not reported
Cleanup funding entity: Not reported

Grant type: P

Accomplishment type: Phase I Environmental Assessment

Accomplishment count: 1

Cooperative agreement #: 00E60801
Ownership entity: Private
Current owner: Not reported

Did owner change:

Cleanup required:

Video available:

Photo available:

Institutional controls required:

N

N

N

IC Category proprietary controls:
IC cat. info. devices:
IC cat. gov. controls:
IC cat. enforcement permit tools:
IC in place date:

Not reported
Not reported
Not reported
Not reported

IC in place:

State/tribal program date:

State/tribal program ID:

State/tribal NFA date:

Air contaminated:

Air cleaned:

No

No

Not reported

Not reported

Not reported

Not reported

Not reported

Asbestos found: Y

Not reported Asbestos cleaned: Not reported Controled substance found: Controled substance cleaned: Not reported Not reported Drinking water affected: Not reported Drinking water cleaned: Groundwater affected: Not reported Groundwater cleaned: Not reported Lead contaminant found: Not reported Lead cleaned up: Not reported Not reported No media affected: Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found: Y

Other metals cleaned: Not reported Other contaminants found: Not reported Other contams found description: Not reported

PAHs found: Y

Distance Elevation

Site Database(s) **EPA ID Number**

RALPH'S MARKET (Continued)

1016356765

EDR ID Number

PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported

Petro products found:

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs:

Past use greenspace acreage: Not reported Past use residential acreage: Not reported Not reported Past use commercial acreage: Past use industrial acreage: Not reported Future use greenspace acreage: Not reported Future use residential acreage: Not reported

Future use commercial acreage:

Future use industrial acreage: Not reported Not reported Greenspace acreage and type: Superfund Fed. landowner flag:

Arsenic cleaned up: Not reported Not reported Cadmium cleaned up: Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported mercury cleaned up: Not reported Not reported nickel cleaned up: No clean up: Not reported Pesticides cleaned up: Not reported Selenium cleaned up: Not reported Not reported SVOCs cleaned up: Not reported Unknown clean up: Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Chromium contaminant found: Not reported Not reported Copper contaminant found: Not reported Iron contaminant found: Mercury contaminant found: Not reported Nickel contaminant found: Not reported Not reported No contaminant found: Not reported

Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Not reported Unknown media cleaned up: Past Use: Multistory Not reported

Pesticides contaminant found: Selenium contaminant found:

SVOCs contaminant found:

Future Use: Multistory

Unknown contaminant found:

Media affected Bluiding Material:

Recipient name: Grand Rapids, City of

Not reported

Not reported

Not reported

Not reported Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

RALPH'S MARKET (Continued)

1016356765

EDR ID Number

Grant type: Assessment
Property name: RALPH'S MARKET
Property #: Not reported

Parcel size:

Property Description: Not reported Latitude: 42.985388

Longitude: -85.68526500000002

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Entrance Point of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 107701
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported

Assessment funding: 3800

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 2600000

Redev. funding source:
Redev. funding entity name:
Redevelopment start date:
Assessment funding entity:
Cleanup funding entity:

Private/Other Funding
Ralph's Market
Not reported
Not reported
Not reported

Grant type:

Accomplishment type: Phase I Environmental Assessment

Accomplishment count: 1

Cooperative agreement #: 00E60801
Ownership entity: Private
Current owner: Not reported

Did owner change:

Cleanup required:

Video available:

Photo available:

Institutional controls required:

N

N

N

No

IC Category proprietary controls:

IC cat. info. devices:

IC cat. gov. controls:

IC cat. enforcement permit tools:

IC in place date:

Not reported

Not reported

Not reported

Not reported

Not reported

IC in place: No

State/tribal program date:
State/tribal program ID:
Not reported
State/tribal NFA date:
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported

Asbestos found:

Asbestos cleaned: Not reported Not reported Controled substance found: Not reported Controled substance cleaned: Drinking water affected: Not reported Not reported Drinking water cleaned: Groundwater affected: Not reported Groundwater cleaned: Not reported Not reported Lead contaminant found: Lead cleaned up: Not reported

Distance Elevation

Site Database(s) EPA ID Number

RALPH'S MARKET (Continued)

1016356765

EDR ID Number

No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found:

Other metals cleaned: Not reported Other contaminants found: Not reported Other contams found description: Not reported

PAHs found: Y

PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported

Petro products found:

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected: Y

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs: 15

Past use greenspace acreage:
Past use residential acreage:
Past use commercial acreage:
Past use industrial acreage:
Past use industrial acreage:
Past use greenspace acreage:
Not reported
Not reported
Not reported
Not reported
Not reported

Future use commercial acreage:

Future use industrial acreage: Not reported Greenspace acreage and type: Not reported

Superfund Fed. landowner flag: N

Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Not reported Copper cleaned up: Iron cleaned up: Not reported mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Not reported Unknown clean up: Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Not reported Chromium contaminant found: Copper contaminant found: Not reported Iron contaminant found: Not reported Not reported Mercury contaminant found: Nickel contaminant found: Not reported No contaminant found: Not reported Pesticides contaminant found: Not reported Not reported Selenium contaminant found: SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Future Use: Multistory Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

RALPH'S MARKET (Continued)

1016356765

Media affected Bluiding Material: Not reported Not reported Media affected indoor air: Building material media cleaned up: Not reported Not reported Indoor air media cleaned up: Unknown media cleaned up: Not reported Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of Grant type: Assessment Property name: RALPH'S MARKET

Property #: Not reported

Parcel size:

Not reported Property Description: Latitude: 42.985388

Longitude: -85.68526500000002

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Entrance Point of a Facility or Station Datum: North American Datum of 1983

ACRES property ID: 107701 Start date: Not reported Completed date: Not reported Acres cleaned up: Not reported Cleanup funding: Not reported Cleanup funding source: Not reported Assessment funding: 4000

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 178000 Redev. funding source: Local Funding **Grand Rapids** Redev. funding entity name: Redevelopment start date: Not reported Assessment funding entity: Not reported Cleanup funding entity: Not reported

Grant type:

Accomplishment type: Cleanup Planning

Accomplishment count:

Cooperative agreement #: 00E60801 Ownership entity: Private Current owner: Not reported

Did owner change: Ν Cleanup required: Yes Video available: No Photo available: Yes Institutional controls required: Ν

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported IC in place date: Not reported

IC in place: No

State/tribal program date: Not reported State/tribal program ID: Not reported Not reported State/tribal NFA date: Air contaminated: Not reported Air cleaned: Not reported

Asbestos found:

Asbestos cleaned: Not reported

Distance Elevation

Site Database(s) EPA ID Number

RALPH'S MARKET (Continued)

1016356765

EDR ID Number

Controled substance found: Not reported Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported Groundwater affected: Not reported Groundwater cleaned: Not reported Lead contaminant found: Not reported Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found: Y

Other metals cleaned: Not reported
Other contaminants found: Not reported
Other contams found description: Not reported

PAHs found: Y

PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported

Petro products found: Y

Petro products cleaned:
Sediments found:
Sediments cleaned:
Sediments cleaned:
Soil affected:
Not reported
Y

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs: 15

Past use greenspace acreage:
Past use residential acreage:
Past use commercial acreage:
Past use industrial acreage:
Past use industrial acreage:
Past use industrial acreage:
Past use greenspace acreage:
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported

Future use commercial acreage: 1

Future use industrial acreage: Not reported Greenspace acreage and type: Not reported

Superfund Fed. landowner flag: N

Not reported Arsenic cleaned up: Not reported Cadmium cleaned up: Chromium cleaned up: Not reported Not reported Copper cleaned up: Not reported Iron cleaned up: mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported Not reported Selenium cleaned up: SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported Not reported Cadmium contaminant found: Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Not reported

Distance Elevation Site

Site Database(s) EPA ID Number

RALPH'S MARKET (Continued)

1016356765

EDR ID Number

Mercury contaminant found: Not reported Not reported Nickel contaminant found: Not reported No contaminant found: Pesticides contaminant found: Not reported Selenium contaminant found: Not reported Not reported SVOCs contaminant found: Not reported Unknown contaminant found: Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment
Property name: RALPH'S MARKET
Property #: Not reported
Parcel size: 1

Property Description: Not reported Latitude: 42.985388

Longitude: -85.68526500000002

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Entrance Point of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 107701
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported
Assessment funding: 4000

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 2600000

Redev. funding source:

Redev. funding entity name:

Redevelopment start date:

Assessment funding entity:

Cleanup funding entity:

Not reported

Not reported

Not reported

Grant type: P

Accomplishment type: Cleanup Planning

Accomplishment count: 0

Cooperative agreement #: 00E60801
Ownership entity: Private
Current owner: Not reported

Did owner change:

Cleanup required:

Video available:

Photo available:

Institutional controls required:

N

N

N

N

N

N

N

IC Category proprietary controls:
IC cat. info. devices:
IC cat. gov. controls:
IC cat. enforcement permit tools:
IC in place date:

Not reported
Not reported
Not reported
Not reported

Direction Distance Elevation

Site Database(s) EPA ID Number

RALPH'S MARKET (Continued)

1016356765

EDR ID Number

IC in place: No

State/tribal program date:
State/tribal program ID:
Not reported
State/tribal NFA date:
Not reported
Air contaminated:
Not reported
Not reported
Not reported
Not reported
Not reported

Asbestos found: Y

Asbestos cleaned: Not reported Controled substance found: Not reported Controled substance cleaned: Not reported Not reported Drinking water affected: Not reported Drinking water cleaned: Groundwater affected: Not reported Groundwater cleaned: Not reported Lead contaminant found: Not reported Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found: Y

Other metals cleaned: Not reported
Other contaminants found: Not reported
Other contams found description: Not reported
PAHs found: Y

PAHs cleaned up: Not reported
PCBs found: Not reported
PCBs cleaned up: Not reported
Petro products found: Y

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected: Y

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs: 15

Past use greenspace acreage:
Past use residential acreage:
Past use commercial acreage:
Past use industrial acreage:
Past use industrial acreage:
Puture use greenspace acreage:
Puture use residential acreage:
Not reported
Not reported
Not reported
Not reported

Future use commercial acreage:

Future use industrial acreage: Not reported Greenspace acreage and type: Not reported

Superfund Fed. landowner flag:

Arsenic cleaned up: Not reported Not reported Cadmium cleaned up: Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported

Distance Elevation Site

Site Database(s) EPA ID Number

RALPH'S MARKET (Continued)

1016356765

EDR ID Number

Selenium cleaned up: Not reported Not reported SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Cadmium contaminant found: Not reported Not reported Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Not reported Mercury contaminant found: Nickel contaminant found: Not reported Not reported No contaminant found: Not reported Pesticides contaminant found: Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of Grant type: Assessment
Property name: RALPH'S MARKET
Property #: Not reported

Parcel size:

Property Description: Not reported Latitude: 42.985388

Longitude: -85.68526500000002

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Entrance Point of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 107701
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported

Assessment funding: 4000

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 325000

Redev. funding source: State/Tribal Funding (non-section 128(a))

Redev. funding entity name:
Redevelopment start date:
Assessment funding entity:
Cleanup funding entity:

MEDC
Not reported
Not reported
Not reported

Grant type: F

Accomplishment type: Cleanup Planning

Accomplishment count:

Cooperative agreement #: 00E60801
Ownership entity: Private
Current owner: Not reported

Did owner change: N
Cleanup required: Yes

Direction Distance Elevation

Site Database(s) EPA ID Number

RALPH'S MARKET (Continued)

1016356765

EDR ID Number

Video available: No Photo available: Yes Institutional controls required: N

IC Category proprietary controls:
IC cat. info. devices:
IC cat. gov. controls:
IC cat. enforcement permit tools:
IC in place date:

Not reported
Not reported
Not reported
Not reported

IC in place: No

State/tribal program date:
State/tribal program ID:
Not reported
State/tribal NFA date:
Not reported
Air contaminated:
Not reported
Not reported
Not reported
Not reported

Asbestos found: Y

Asbestos cleaned: Not reported Not reported Controled substance found: Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported Not reported Groundwater affected: Groundwater cleaned: Not reported Lead contaminant found: Not reported Lead cleaned up: Not reported Not reported No media affected: Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found:

Other metals cleaned: Not reported
Other contaminants found: Not reported
Other contams found description: Not reported
PAHs found: Y

PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported

Petro products found: Y

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected: Y

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs: 15

Past use greenspace acreage:
Past use residential acreage:
Past use commercial acreage:
Past use industrial acreage:
Past use industrial acreage:
Past use greenspace acreage:
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported

Future use commercial acreage:

Future use industrial acreage: Not reported Greenspace acreage and type: Not reported

Superfund Fed. landowner flag: N

Arsenic cleaned up: Not reported

Direction Distance Elevation

on Site Database(s) EPA ID Number

RALPH'S MARKET (Continued)

1016356765

EDR ID Number

Cadmium cleaned up: Not reported Not reported Chromium cleaned up: Copper cleaned up: Not reported Not reported Iron cleaned up: mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported Not reported Pesticides cleaned up: Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Not reported Unknown clean up: Not reported Arsenic contaminant found: Cadmium contaminant found: Not reported Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Not reported Not reported Mercury contaminant found: Nickel contaminant found: Not reported No contaminant found: Not reported Pesticides contaminant found: Not reported Not reported Selenium contaminant found: SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment
Property name: RALPH'S MARKET
Property #: Not reported

Parcel size:

Property Description: Not reported Latitude: 42.985388

Longitude: -85.68526500000002

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Entrance Point of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 107701
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported
Assessment funding: 12514

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 178000
Redev. funding source: Local Funding
Redev. funding entity name: Grand Rapids
Redevelopment start date: Not reported
Assessment funding entity: Not reported
Cleanup funding entity: Not reported

Distance
Elevation Site

RALPH'S MARKET (Continued)

Grant type: F

Accomplishment type: Phase II Environmental Assessment

Accomplishment count: 0

Cooperative agreement #: 00E60801
Ownership entity: Private
Current owner: Not reported

IC Category proprietary controls:
IC cat. info. devices:
IC cat. gov. controls:
IC cat. enforcement permit tools:
IC in place date:

Not reported
Not reported
Not reported
Not reported

IC in place: No

State/tribal program date:
State/tribal program ID:
Not reported
State/tribal NFA date:
Not reported
Air contaminated:
Not reported
Not reported
Not reported
Not reported
Not reported

Asbestos found:

Asbestos cleaned: Not reported Controled substance found: Not reported Not reported Controled substance cleaned: Drinking water affected: Not reported Drinking water cleaned: Not reported Groundwater affected: Not reported Not reported Groundwater cleaned: Lead contaminant found: Not reported Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Not reported Other cleaned up:

Other metals found:

Other metals cleaned: Not reported Other contaminants found: Not reported Other contams found description: Not reported

PAHs found: Y

PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported

Petro products found: Y

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs: 15

Past use greenspace acreage:
Past use residential acreage:
Not reported
Not reported
Not reported
Not reported

1016356765

EDR ID Number

EPA ID Number

Database(s)

Direction Distance Elevation

Site Database(s) EPA ID Number

RALPH'S MARKET (Continued)

1016356765

EDR ID Number

Past use industrial acreage: Not reported Not reported Not reported Not reported Not reported Not reported Not reported

Future use commercial acreage:

Future use industrial acreage: Not reported Greenspace acreage and type: Not reported

Superfund Fed. landowner flag: N

Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Not reported Copper cleaned up: Not reported Iron cleaned up: mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported Not reported Selenium cleaned up: SVOCs cleaned up: Not reported Unknown clean up: Not reported Arsenic contaminant found: Not reported Not reported Cadmium contaminant found: Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Not reported Mercury contaminant found: Not reported Not reported Nickel contaminant found: No contaminant found: Not reported Pesticides contaminant found: Not reported Selenium contaminant found: Not reported Not reported SVOCs contaminant found: Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Past Use: Multistory Not reported

Recipient name: Grand Rapids, City of

Grant type: Assessment
Property name: RALPH'S MARKET
Property #: Not reported

Parcel size: 1

Property Description: Not reported 42.985388

Longitude: -85.68526500000002

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Entrance Point of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 107701
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported

Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

RALPH'S MARKET (Continued)

1016356765

Assessment funding: 12514

US EPA - Brownfields Assessment Cooperative Agreement Assessment funding source:

Redevelopment funding: 2600000

Private/Other Funding Redev. funding source: Redev. funding entity name: Ralph's Market Not reported Redevelopment start date: Assessment funding entity: Not reported Cleanup funding entity: Not reported

Grant type:

Accomplishment type: Phase II Environmental Assessment

Accomplishment count:

Cooperative agreement #: 00E60801 Ownership entity: Private Current owner: Not reported

Did owner change: Cleanup required: Yes Video available: Nο Photo available: Yes Institutional controls required:

Not reported IC Category proprietary controls: IC cat. info. devices: Not reported IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported IC in place date: Not reported

IC in place: No

State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Air cleaned: Not reported

Asbestos found:

Asbestos cleaned: Not reported Controled substance found: Not reported Controled substance cleaned: Not reported Not reported Drinking water affected: Not reported Drinking water cleaned: Groundwater affected: Not reported Groundwater cleaned: Not reported Lead contaminant found: Not reported Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found:

Other metals cleaned: Not reported Other contaminants found: Not reported Other contams found description: Not reported

PAHs found:

PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported

Petro products found:

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected:

Soil cleaned up: Not reported

Distance EDR ID Number
Elevation Site EDR ID Number
Database(s) EPA ID Number

RALPH'S MARKET (Continued)

1016356765

Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs: 15

Past use greenspace acreage:
Past use residential acreage:
Past use commercial acreage:
Past use industrial acreage:
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported

Future use commercial acreage:

Future use industrial acreage: Not reported Greenspace acreage and type: Not reported

Superfund Fed. landowner flag: N

Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported Not reported mercury cleaned up: nickel cleaned up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported Selenium cleaned up: Not reported Not reported SVOCs cleaned up: Unknown clean up: Not reported Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Not reported Mercury contaminant found: Not reported Nickel contaminant found: Not reported Not reported No contaminant found: Pesticides contaminant found: Not reported Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up:

Recipient name: Grand Rapids, City of Grant type: Assessment
Property name: RALPH'S MARKET
Property #: Not reported

Parcel size:

Past Use: Multistory

Property Description: Not reported Latitude: 42.985388

Longitude: -85.68526500000002

HCM label: Address Matching-House Number

Not reported

Map scale: Not reported

Distance

Elevation Site Database(s) EPA ID Number

RALPH'S MARKET (Continued)

1016356765

EDR ID Number

Point of reference: Entrance Point of a Facility or Station
Datum: North American Datum of 1983

ACRES property ID: 107701
Start date: Not reported
Completed date: Not reported
Acres cleaned up: Not reported
Cleanup funding: Not reported
Cleanup funding source: Not reported
Assessment funding: 12514

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding: 325000

Redev. funding source: State/Tribal Funding (non-section 128(a))

Redev. funding entity name:
Redevelopment start date:
Assessment funding entity:
Cleanup funding entity:

MEDC
Not reported
Not reported
Not reported

Grant type: P

Accomplishment type: Phase II Environmental Assessment

Accomplishment count: 0

Cooperative agreement #: 00E60801
Ownership entity: Private
Current owner: Not reported

Did owner change:

Cleanup required:

Video available:

Photo available:

Institutional controls required:

N

N

N

IC Category proprietary controls:
IC cat. info. devices:
IC cat. gov. controls:
IC cat. enforcement permit tools:
IC in place date:

Not reported
Not reported
Not reported
Not reported

IC in place: No

State/tribal program date:

State/tribal program ID:

Not reported
State/tribal NFA date:

Not reported
Not reported
Not reported
Air contaminated:

Not reported
Not reported
Not reported

Asbestos found: Y

Asbestos cleaned: Not reported Not reported Controled substance found: Not reported Controled substance cleaned: Drinking water affected: Not reported Not reported Drinking water cleaned: Not reported Groundwater affected: Groundwater cleaned: Not reported Lead contaminant found: Not reported Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found: Y

Other metals cleaned: Not reported
Other contaminants found: Not reported
Other contams found description: Not reported

PAHs found: Y

PAHs cleaned up: Not reported

Direction Distance Elevation

Site Database(s) EPA ID Number

RALPH'S MARKET (Continued)

1016356765

EDR ID Number

PCBs found: Not reported PCBs cleaned up: Not reported

Petro products found: Y

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected: Y

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs: 15

Past use greenspace acreage:
Past use residential acreage:
Past use commercial acreage:
Past use industrial acreage:
Past use industrial acreage:
Past use greenspace acreage:
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported

Future use commercial acreage: 1

Future use industrial acreage: Not reported Greenspace acreage and type: Not reported

Superfund Fed. landowner flag: N

Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Not reported Chromium cleaned up: Copper cleaned up: Not reported Iron cleaned up: Not reported mercury cleaned up: Not reported nickel cleaned up: Not reported Not reported No clean up: Pesticides cleaned up: Not reported Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Not reported Unknown clean up: Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Chromium contaminant found: Not reported Copper contaminant found: Not reported Iron contaminant found: Not reported Not reported Mercury contaminant found: Not reported Nickel contaminant found: No contaminant found: Not reported Not reported Pesticides contaminant found: Not reported Selenium contaminant found: SVOCs contaminant found: Not reported Not reported Unknown contaminant found: Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Not reported Media affected indoor air: Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported

Recipient name: Grand Rapids, City of

Not reported Not reported

Grant type: Assessment

Unknown media cleaned up:

Past Use: Multistory

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

RALPH'S MARKET (Continued)

1016356765

Property name: RALPH'S MARKET

Property #: Not reported

Parcel size:

Property Description: Not reported Latitude: 42.985388

-85.68526500000002 Longitude:

HCM label: Address Matching-House Number

Map scale: Not reported

Point of reference: Entrance Point of a Facility or Station Datum: North American Datum of 1983

ACRES property ID: 107701 Not reported Start date: Completed date: Not reported Acres cleaned up: Not reported Cleanup funding: Not reported Cleanup funding source: Not reported

Assessment funding: 3800

Assessment funding source: US EPA - Brownfields Assessment Cooperative Agreement

Redevelopment funding:

Redev. funding source: State/Tribal Funding (non-section 128(a))

Redev. funding entity name: **MEDC** Redevelopment start date: Not reported Not reported Assessment funding entity: Cleanup funding entity: Not reported

Grant type:

Accomplishment type: Phase I Environmental Assessment

Accomplishment count:

Cooperative agreement #: 00E60801 Ownership entity: Private Current owner: Not reported

Did owner change: N Cleanup required: Yes Video available: No Photo available: Yes Institutional controls required: Ν

IC Category proprietary controls: Not reported IC cat. info. devices: Not reported IC cat. gov. controls: Not reported IC cat. enforcement permit tools: Not reported IC in place date: Not reported

IC in place: No

State/tribal program date: Not reported State/tribal program ID: Not reported Not reported State/tribal NFA date: Air contaminated: Not reported Air cleaned: Not reported

Asbestos found:

Asbestos cleaned: Not reported Controled substance found: Not reported Not reported Controled substance cleaned: Drinking water affected: Not reported Drinking water cleaned: Not reported Not reported Groundwater affected: Groundwater cleaned: Not reported Lead contaminant found: Not reported Lead cleaned up: Not reported No media affected: Not reported

Distance
Elevation Site

Database(s)

EDR ID Number EPA ID Number

RALPH'S MARKET (Continued)

1016356765

Unknown media affected: Not reported Other cleaned up: Not reported

Other metals found: Y

Other metals cleaned: Not reported
Other contaminants found: Not reported
Other contams found description: Not reported

PAHs found:

PAHs cleaned up:

PCBs found:

PCBs cleaned up:

Not reported

Not reported

Not reported

Petro products found: Y

Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported

Soil affected: Y

Soil cleaned up: Not reported Surface water cleaned: Not reported

VOCs found:

VOCs cleaned: Not reported Cleanup other description: Not reported

Num. of cleanup and re-dev. jobs: 15

Past use greenspace acreage:
Past use residential acreage:
Past use commercial acreage:
Past use industrial acreage:
Past use industrial acreage:
Puture use greenspace acreage:
Puture use residential acreage:
Puture use residential acreage:
Puture use residential acreage:
Puture use residential acreage:

Not reported
Not reported
Not reported

Future use commercial acreage:

Future use industrial acreage: Not reported Greenspace acreage and type: Not reported

Superfund Fed. landowner flag: N

Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Not reported Copper cleaned up: Iron cleaned up: Not reported mercury cleaned up: Not reported nickel cleaned up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Unknown clean up: Not reported Not reported Arsenic contaminant found: Not reported Cadmium contaminant found: Chromium contaminant found: Not reported Not reported Copper contaminant found: Iron contaminant found: Not reported Mercury contaminant found: Not reported Not reported Nickel contaminant found: No contaminant found: Not reported Pesticides contaminant found: Not reported Selenium contaminant found: Not reported Not reported SVOCs contaminant found: Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

RALPH'S MARKET (Continued)

1016356765

S114026346

N/A

INVENTORY

Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Past Use: Multistory Not reported

FINDS:

Registry ID: 110042300113

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES)

is an federal online database for Brownfields Grantees to

electronically submit data directly to EPA.

P65 900 LEONARD STREET NW NNW 900 LEONARD STREET NW KENT (County), MI 49503 1/4-1/2

0.497 mi.

2626 ft. Site 2 of 2 in cluster P

INVENTORY: Relative:

200601962GR Bea Number: Higher Township: **Grand Rapids** Actual: District: **Grand Rapids**

616 ft. Data Source: BEA

> Latitude: Not reported Longitude: Not reported

Bea Number: 201102883GR Township: **Grand Rapids Grand Rapids** District:

Data Source: **BEA**

Not reported Latitude: Longitude: Not reported

Bea Number: 200702113GR Township: **Grand Rapids** District: Grand Rapids Data Source: **BEA**

Latitude: 42.985 -85.69083 Longitude:

N66 LUST **GSG LLC** U003327813 SSE **438 STOCKING AVE NW** UST N/A

1/4-1/2 **GRAND RAPIDS, MI 49504**

0.500 mi.

Site 3 of 3 in cluster N 2638 ft.

LUST: Relative:

Facility ID: 00004193 Lower

Source: STATE OF MICHIGAN

Actual: Owner Name: GSG LLC 614 ft.

Owner Address: 438 Stocking Ave NW Owner City,St,Zip: Grand Rapids, MI 49504

Direction Distance

Elevation Site Database(s) EPA ID Number

GSG LLC (Continued) U003327813

Owner Contact: Not reported Owner Phone: (616) 458-3359

Country: USA

District: Grand Rapids District Office

Site Name: Spur Station #1557

Latitude: 42.97186 Longitude: -85.68473 Date of Collection: 01/29/2002

Method of Collection: GPS Code Meas. Standard Positioning Service SA Off

Accuracy: 10
Accuracy Value Unit: METERS
Horizontal Data: NAD83
Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Leak Number: C-4004-85
Release Date: 10/01/1987
Substance Released: Not reported
Release Status: Closed
Release Closed Date: 02/16/1993

UST:

Facility ID: 00004193
Facility Type: ACTIVE
Owner Name: GSG LLC

Owner Address: 438 STOCKING AVE NW Owner City,St,Zip: GRAND RAPIDS, MI 49504

Owner Country: USA
Owner Contact: Not reported
Owner Phone: (616) 458-3359
Contact: Not reported
Contact Phone: Not reported
Date of Collection: 01/29/2002
Accuracy: 10
Accuracy Value Unit: METERS

Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: GPS Code Meas. Standard Positioning Service SA Off

Latitude: 42.97186 Longitude: -85.68473

Tank ID:

Tank Status: Currently In Use

Capacity: 10000
Product: Gasoline
Install Date: 05/01/1981
Remove Date: Not reported

Tank Release Detection: Manual Tank Gauging, Tank Tightness Testing Pipe Realease Detection: Automatic Line Leak Detectors, Line Tightness Testing

Piping Material: Fiberglass Reinforced Plastic

Piping Type: Pressure

Construction Material: Cathodically Protected Steel

Impressed Device: No

Tank ID: 2

EDR ID Number

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

GSG LLC (Continued) U003327813

Tank Status: Currently In Use

Capacity: 10000
Product: Gasoline
Install Date: 05/01/1981
Remove Date: Not reported

Tank Release Detection: Manual Tank Gauging, Tank Tightness Testing Pipe Realease Detection: Automatic Line Leak Detectors, Line Tightness Testing

Piping Material: Fiberglass Reinforced Plastic

Piping Type: Pressure

Construction Material: Cathodically Protected Steel

Impressed Device: No

67 NO AM CORP INVENTORY \$108632560 SSE 329 SUMMER AVE NW PART 201 N/A

SSE 329 SUMMER AVE NW PART 201 N/
1/2-1 GRAND RAPIDS, MI 49504 AUL
0.701 mi. WDS

0.701 mi. 3701 ft.

Relative: INVENTORY:

Lower Bea Number: Not reported

Township: Grand Rapids

Actual: District: Grand Rapids

611 ft. Data Source: Part 201

Latitude: 42.96962 Longitude: -85.6805

PART 201:

Facility ID: 41000768

Facility Status: Inactive - no actions taken to address contamination

Source: Not reported

 SAM Score:
 38

 SAM Score Date:
 06/02/2005

 Township:
 07N

 Range:
 12W

 Section:
 25

 Quarter:
 NW

 Quarter/Quarter:
 NE

Pollutants: Not reported

AUL:

Status: Recorded
Site Name: No-Am Corporation
Property: No-Am Corporation

Land Use Restriction Type:
Program Type:
Program Support Assigned User:
Program Support Assigned Date:
Legal Description Of Property:
Based On The Deq Ref #:
MDEQ Reference Number:
RC
Part 201
Nicholas Ekel
10/25/2011
Site Address
11120104026
RC-RRD-201-04-026

Property Or Description Restricted Area: Not reported Lead Division: RRD

File Name Of Hyperlinked Legal Doc: U:\\KERMIT\\11120104026.PDF

Mapped Polygons Area In Acres: 1.0205
Mapped Polygons Area In Square Miles: 0.0015
Date Data Entry Started: 12/14/2011
Date Data Entry Finished: 12/14/2011

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

NO AM CORP (Continued) S108632560

Individual Or Staff Assoc With The Mapping: Nicholas Ekel

Program Used To Map Restricted Features: ArcINFO 9.3 & IcoMAP 4.2

Date Legal Paperwork Stamped/Filed/Register Of Deeds: 05/17/1995

Commercial I Land Use Restriction: Commercial li Land Use Restriction: 0 Commercial lii Land Use Restriction: 0 Commercial Iv Land Use Restriction: 0 Industrial Land Use Restriction: 1 Residential Land Use Restriction: 0 Recreational Land Use Restriction: 0 Multiple Land-Use Restrictions: 0 Site Specific Restrictions: 0 Groundwater Consumption Restrictions: 1 **Groundwater Contact Restrictions:** Special Well Construction Requirements: 0 Special Building Restrictions: **Excavation And Soil Movement Restrictions:**

Excavation And Soil Movement Restrictions:

Soil Movement Requirements:

There Is A Restriction On All Construction:

Monitoring Well Protected, No Tampering Or Removal:

There Is An Exposure Barrier In Place:

There Is A Health And Safety Plan:

There Is A Permanent Marker On The Site:

0

Map Comments: 20111025 - LRUR is NOT mapped in KERMIT - Nick Ekel20111214 - LRUR is

mapped in KERMIT - Nick Ekel

Comment: Not reported

WDS:

 Site Id:
 MID006026132

 WMD Id:
 394116

 Site Specific Name:
 NO AM CORP

Mailing Address: 329 SUMMER AVE NW

Mailing City/State/Zip: 49504 Mailing County: KENT

68 900-1010 MONROE AVENUE NW
East 900-1010 MONROE AVENUE NW

1/2-1 GRAND RAPIDS, MI

0.762 mi. 4026 ft.

Relative: DEL_PART201:

Lower Facility ID: 41000941

Status: Delisted - no longer meets criteria specified in rules

Actual: 611 ft.

BEA:

SEA:

Secondary Address: Not reported

BEA Number: 673

District: Grand Rapids
Date Received: 02/24/2000
Submitter Name: 940 Monroe L.L.C.
Petition Determination: No Request

Petition Disclosure: 0

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: moyerr

Division Assigned: Environmental Response Division

S104911871

N/A

DEL PART 201

BEA

Direction Distance

Elevation Site Database(s) EPA ID Number

900-1010 MONROE AVENUE NW (Continued)

S104911871

EDR ID Number

Secondary Address: Not reported

BEA Number: 674
District: Grand Rapids
Date Received: 02/24/2000
Submitter Name: 900 Monroe L.L.C.
Petition Determination: No Request

Petition Disclosure: 0

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: moyerr

Division Assigned: Environmental Response Division

69 WOLVERINE BRASS WORKS INVENTORY

69 WOLVERINE BRASS WORKS ESE 648 MONROE AVE NW 1/2-1 GRAND RAPIDS, MI 49503 NVENTORY S108896097 PART 201 N/A BEA

WDS

0.814 mi. 4298 ft.

Relative: INVENTORY:

Lower Bea Number:

Township: Grand Rapids

Actual: District: Grand Rapids

612 ft. Data Source: Part 201

Latitude: 42.97461 Longitude: -85.67143

PART 201:

Facility ID: 41001057

Facility Status: Inactive - no actions taken to address contamination

Source: Not reported

Not reported

 SAM Score:
 34

 SAM Score Date:
 06/18/2007

 Township:
 7N

 Range:
 12W

 Section:
 24

 Quarter:
 SE

 Quarter/Quarter:
 SW

Pollutants: Cr+3; Pb; Ag; TCE; VC

BEA:

Secondary Address: Not reported BEA Number: 1081

District: Grand Rapids

Date Received: 08/19/2002

Submitter Name: Tower Automotive Products, Inc.

Petition Determination: No Request

Petition Disclosure: 0

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: stringed

Division Assigned: Environmental Response Division

WDS:

Site Id: MID006025332 WMD Id: 394110

Site Specific Name: WOLVERINE BRASS WORKS

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

WOLVERINE BRASS WORKS (Continued)

Mailing Address: 648 MONROE AVE NW

49503 Mailing City/State/Zip: **KENT** Mailing County:

70 WHITTAKER ELECTRIC **DEL PART 201** S105965947

ΝE **1320 FRONT BEA** N/A

1/2-1 **GRAND RAPIDS, MI 49505**

0.831 mi. 4389 ft.

DEL_PART201: Relative:

Facility ID: 41000385 Lower

Status: Delisted - no longer meets criteria specified in rules

Actual: 606 ft.

BEA:

Secondary Address: Not reported

BEA Number: 3136

Grand Rapids District: Date Received: 03/08/2012 Submitter Name: **TDC Realestate LLC**

Petition Determination: No Request Petition Disclosure: Category: Not reported

Determination 20107A: No Request Reviewer: odonneld

Division Assigned: **Environmental Response Division**

Secondary Address: Not reported BEA Number: 3137

District: **Grand Rapids** Date Received: 03/08/2012

Submitter Name: Technical Design Concepts Inc

Petition Determination: No Request

Petition Disclosure:

Category: Not reported Determination 20107A: No Request Reviewer: odonneld

Division Assigned: **Environmental Response Division**

71 **AUTOBOND (FORMER) INVENTORY** S105144244 **ESE** 706 BOND AVE. NW **PART 201** N/A **GRAND RAPIDS, MI 49503** 1/2-1 **BEA**

0.841 mi. 4442 ft.

INVENTORY: Relative:

Bea Number: Not reported Higher

Township: **Grand Rapids** Actual: District: **Grand Rapids** 615 ft. Data Source: Part 201

Latitude: 42.97579 Longitude: -85.6714

PART 201:

41000791 Facility ID:

WDS

S108896097

Direction Distance

Elevation Site Database(s) EPA ID Number

AUTOBOND (FORMER) (Continued)

S105144244

EDR ID Number

Facility Status: Interim Response conducted

SE

Source: Automotive Stamping

 SAM Score:
 30

 SAM Score Date:
 01/06/2005

 Township:
 07N

 Range:
 12W

 Section:
 24

 Quarter:
 NE

Pollutants: TCE; Metals

BEA:

Secondary Address: Not reported

BEA Number:

Quarter/Quarter:

District: Grand Rapids
Date Received: 09/05/1995
Submitter Name: H-Z Properties, Inc

Petition Determination: Affirmed

Petition Disclosure: 1

Category: Same Hazardous Substance(s)

Determination 20107A: Affirmed Reviewer: moyerr

Division Assigned: Environmental Response Division

Secondary Address: Not reported

BEA Number: 20

District: Grand Rapids
Date Received: 11/15/1995

Submitter Name: Optimum Manufacturing INC

Petition Determination: Affirmed

Petition Disclosure: 1

Category: Same Hazardous Substance(s)

Determination 20107A: Affirmed Reviewer: odonneld

Division Assigned: Environmental Response Division

WDS:

Site Id: MID982610610

WMD ld: 401249

Site Specific Name: GR SPRING & STAMPING INC

Mailing Address: 706 BOND AVE NW

Mailing City/State/Zip: 49503 Mailing County: KENT

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

72 **RELIABLE EQUIPMENT CERCLIS** 1000245371 NNE **633 RICHMOND ST NW** RCRA NonGen / NLR MID006407969

1/2-1 **GRAND RAPIDS, MI 49504** ICIS 0.982 mi. **FINDS** 5185 ft.

RAATS PART 201 Relative: **INVENTORY** Higher **BROWNFIELDS**

AIRS Actual: BEA 620 ft. **WDS PRP**

CERCLIS:

Site ID: 0506594 EPA ID: MID006407969

Facility County: **KENT**

Short Name: RELIABLE EQUIPMENT

Congressional District: 05 IFMS ID: 05LE SMSA Number: 3000 USGC Hydro Unit: 04050006

Not a Federal Facility Federal Facility:

DMNSN Number: 0.00000 Site Orphan Flag: Ν RCRA ID: Not reported

USGS Quadrangle: Not reported Site Init By Prog: Not reported NFRAP Flag: Not reported Parent ID: Not reported RST Code: Not reported

EPA Region: 05 Classification: Not reported Site Settings Code:

Not reported NPL Status: Not on the NPL DMNSN Unit Code: Not reported RBRAC Code: Not reported RResp Fed Agency Code: Not reported

Non NPL Status: Referred to Removal - NFRAP

Non NPL Status Date: 06/14/00 26081 Site Fips Code: CC Concurrence Date: //

CC Concurrence FY: Not reported Alias EPA ID: Not reported Site FUDS Flag: Not reported

Not reported Alias Comments:

Site Description: Not reported **CERCLIS Assessment History:**

Action Code: 001

DISCOVERY Action:

Date Started: // Date Completed: 12/19/91 Priority Level: Not reported Operable Unit: SITEWIDE

Primary Responsibility: **EPA Fund-Financed**

Planning Status: Not reported Urgency Indicator: Not reported

Direction Distance Elevation

tion Site Database(s) EPA ID Number

RELIABLE EQUIPMENT (Continued)

1000245371

EDR ID Number

Action Anomaly: Not reported

Action Code: 001

Action: Notice Letters Issued

Date Started: / /
Date Completed: 01/09/92
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: Federal Enforcement

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code: 005

Action: Notice Letters Issued

Date Started: / /
Date Completed: 01/09/92
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: EPA Fund-Financed Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code: 001

Action: ISSUE REQUEST LETTERS (104E)

Date Started: / /
Date Completed: 01/09/92
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: Federal Enforcement

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code: 002

Action: ISSUE REQUEST LETTERS (104E)

Date Started: / /
Date Completed: 01/30/92
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: Federal Enforcement

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code: 006

Action: Notice Letters Issued

Date Started: / /
Date Completed: 01/30/92
Priority Level: Not reported
Operable Unit: SITEWIDE

Direction Distance Elevation

ance EDR ID Number vation Site Database(s) EPA ID Number

RELIABLE EQUIPMENT (Continued)

1000245371

Primary Responsibility: EPA Fund-Financed Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code: 002

Action: Notice Letters Issued

Date Started: / /
Date Completed: 01/30/92
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: Federal Enforcement

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code: 001

Action: UNILATERAL ADMIN ORDER

Date Started: //

Date Completed: 05/11/92
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: Federal Enforcement

Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 008

Action: Notice Letters Issued

Date Started: / /
Date Completed: 06/11/92
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code: 003

Action: ISSUE REQUEST LETTERS (104E)

Date Started: / /

Date Completed: 06/11/92
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: Federal Enforcement

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code: 003

Action: Notice Letters Issued

Date Started: / /

Distance

Elevation Site Database(s) EPA ID Number

RELIABLE EQUIPMENT (Continued)

1000245371

EDR ID Number

Date Completed: 06/11/92
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: Federal Enforcement

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code: 001
Action: REMOVAL
Date Started: 06/18/92
Date Completed: 08/03/92
Priority Level: Stabilized
Operable Unit: SITEWIDE

Primary Responsibility: EPA Fund-Financed

Planning Status: Primary
Urgency Indicator: Time Critical

Action Anomaly: Original Action Take Over

Action Code: 001

Action: PRELIMINARY ASSESSMENT

Date Started: / /

Date Completed: 11/05/92

Priority Level: Higher priority for further assessment

Operable Unit: SITEWIDE

Primary Responsibility: State, Fund Financed

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code: 001

Action: SITE INSPECTION

Date Started: // Date Completed: 04/07/93

Priority Level: NFRAP-Site does not qualify for the NPL based on existing information

Operable Unit: SITEWIDE

Primary Responsibility: State, Fund Financed

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code: 004

Action: Notice Letters Issued

Date Started: /

Date Completed: 04/23/93
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: Federal Enforcement

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Direction Distance

Elevation Site Database(s) **EPA ID Number**

RELIABLE EQUIPMENT (Continued)

1000245371

EDR ID Number

Action Code: 004

ISSUE REQUEST LETTERS (104E) Action:

Date Started: // Date Completed: 04/23/93 Priority Level: Not reported Operable Unit: SITEWIDE

Primary Responsibility: Federal Enforcement

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code:

Action: Notice Letters Issued

Date Started: Date Completed: 04/23/93 Priority Level: Not reported Operable Unit: SITEWIDE

Primary Responsibility: **EPA Fund-Financed** Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code: 001

POTENTIALLY RESPONSIBLE PARTY REMOVAL Action:

Date Started: 08/03/92 Date Completed: 09/08/94

Partially Cleaned up Priority Level: Operable Unit: SITEWIDE Primary Responsibility: Responsible Party

Planning Status: Primary Urgency Indicator: Time Critical

Action Anomaly: New Action Resulting from Take Over

Action Code: 001

NON-NATIONAL PRIORITIES LIST POTENTIALLY RESPONSIBLE PARTY SEARCH Action:

Date Started: Date Completed: 09/08/94 Not reported Priority Level: Operable Unit: SITEWIDE

Primary Responsibility: Federal Enforcement

Planning Status: Primary Urgency Indicator: Not reported Action Anomaly: Not reported

RCRA NonGen / NLR:

Date form received by agency: 05/19/2008

Facility name: RELIABLE EQUIPMENT CORPORATION

Facility address: 633 RICHMOND ST NW

GRAND RAPIDS, MI 49504

EPA ID: MID006407969 Contact: ANTHONY PRESTON Contact address: 633 RICHMOND ST NW GRAND RAPIDS, MI 49504

Direction Distance

Elevation Site Database(s) EPA ID Number

RELIABLE EQUIPMENT (Continued)

1000245371

EDR ID Number

Contact country: US

Contact telephone: (616) 363-4823 Contact email: Not reported

EPA Region: 05

Land type: Other land type Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NO ACTIVE O/OP AS NOT GENERATING WASTE

Owner/operator address: Not reported Not reported Owner/operator country: Not reported Owner/operator telephone: Not reported

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/13/2008
Owner/Op end date: Not reported

Owner/operator name: NO ACTIVE O/OP AS NOT GENERATING WASTE

Owner/operator address: Not reported

Not reported

Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/13/2008
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Nο Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No No Used oil processor: User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 04/30/2008

Site name: RELIABLE EQUIPMENT CORPORATION

Classification: Not a generator, verified

Date form received by agency: 03/31/1998

Site name: RELIABLE EQUIPMENT CORPORATION

Classification: Not a generator, verified

Direction Distance Elevation

ration Site Database(s) EPA ID Number

RELIABLE EQUIPMENT (Continued)

1000245371

EDR ID Number

Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Facility Has Received Notices of Violations:

Regulation violated: Not reported

Area of violation: TSD - Financial Requirements

Date violation determined: 11/12/1991
Date achieved compliance: 08/05/1993
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL Enforcement action date: 11/14/1991

Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: State Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 11/12/1991
Date achieved compliance: 08/05/1993
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 11/14/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Distance

Elevation Site Database(s) EPA ID Number

RELIABLE EQUIPMENT (Continued)

1000245371

EDR ID Number

Regulation violated:
Area of violation:

Date violation determined:
Date achieved compliance:
Violation lead agency:

Not reported
LDR - General
11/12/1991
08/05/1993
State

Enforcement action: WRITTEN INFORMAL

Enforcement action date:

Enf. disposition status:

Enf. disp. status date:

Enforcement lead agency:

Proposed penalty amount:

Final penalty amount:

Paid penalty amount:

Enforcement lead agency:

State

Not reported

Not reported

Not reported

Not reported

Regulation violated: Not reported

Area of violation: TSD - Closure/Post-Closure

Date violation determined: 11/12/1991
Date achieved compliance: 08/05/1993
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 11/14/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 12/05/1990
Date achieved compliance: 08/05/1993
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 11/14/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General

Date violation determined: 06/25/1986
Date achieved compliance: 02/24/1989
Violation lead agency: State

Enforcement action: INITIAL 3008(A) COMPLIANCE

Enforcement action date: 04/25/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 2000
Final penalty amount: 2000
Paid penalty amount: Not reported

Regulation violated: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

RELIABLE EQUIPMENT (Continued)

Paid penalty amount:

1000245371

Area of violation: Generators - General

06/25/1986 Date violation determined: 02/24/1989 Date achieved compliance: Violation lead agency: State

Enforcement action: FINAL 3008(A) COMPLIANCE ORDER

Not reported

Enforcement action date: 02/16/1989 Enf. disposition status: Not reported Enf. disp. status date: Not reported EPA Enforcement lead agency: Proposed penalty amount: Not reported Final penalty amount: Not reported

Regulation violated: Not reported Area of violation: Generators - General

Date violation determined: 06/25/1986 02/24/1989 Date achieved compliance: Violation lead agency: State

Enforcement action: STATE CONSENT/COMPLIANCE ORDER 3008(A)

Enforcement action date: 02/24/1989 Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: State

Proposed penalty amount: Not reported Final penalty amount: 2000 Paid penalty amount: Not reported

Regulation violated: Not reported Area of violation: Generators - General

Date violation determined: 06/25/1986 Date achieved compliance: 02/24/1989 Violation lead agency: State

Enforcement action: FINAL CIVIL JUDICIAL ACTION FOR IMMINENT AND SUBSTANTIAL ENDANGERMENT

Enforcement action date: 04/23/1993 Enf. disposition status: Not reported Enf. disp. status date: Not reported EPA Enforcement lead agency: Proposed penalty amount: 15000 Final penalty amount: 15000 Paid penalty amount: 15000

Regulation violated: Not reported

Area of violation: Generators - General

Date violation determined: 06/25/1986 Date achieved compliance: 02/24/1989

Violation lead agency: State

WRITTEN INFORMAL Enforcement action:

Enforcement action date: 06/27/1986 Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: State Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: Generators - General

Direction Distance

Elevation Site Database(s) EPA ID Number

RELIABLE EQUIPMENT (Continued)

1000245371

EDR ID Number

Date violation determined: 06/25/1986
Date achieved compliance: 02/24/1989
Violation lead agency: State

Enforcement action: REFERRAL TO DEPARTMENT OF JUSTICE

Enforcement action date: 06/14/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General

Date violation determined: 06/25/1986
Date achieved compliance: 02/24/1989
Violation lead agency: State

Enforcement action: STATE TO EPA ADMINISTRATIVE REFERRAL

Enforcement action date: 01/05/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

Final penalty amount: Not reported Not reported Paid penalty amount: Not reported Not reported

Regulation violated: Not reported
Area of violation: Generators - General

Date violation determined: 06/25/1986
Date achieved compliance: 02/24/1989
Violation lead agency: State

Enforcement action: INITIAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY

Enforcement action date: 03/07/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported

Final penalty amount:

Paid penalty amount:

Not reported

Not reported

Evaluation Action Summary:

Evaluation date: 08/05/1993

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 11/12/1991

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: TSD - General Date achieved compliance: 08/05/1993 Evaluation lead agency: State

Evaluation date: 11/12/1991

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: TSD - Closure/Post-Closure

Date achieved compliance: 08/05/1993

Direction Distance

Elevation Site Database(s) EPA ID Number

RELIABLE EQUIPMENT (Continued)

1000245371

EDR ID Number

Evaluation lead agency: State

Evaluation date: 11/12/1991

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: TSD - Financial Requirements

Date achieved compliance: 08/05/1993 Evaluation lead agency: State

Evaluation date: 11/12/1991

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: LDR - General Date achieved compliance: 08/05/1993 Evaluation lead agency: State

Evaluation date: 12/05/1990

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: LDR - General Date achieved compliance: 08/05/1993 Evaluation lead agency: State

Evaluation date: 06/14/1989

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation: Not reported
Date achieved compliance: Not reported

Evaluation lead agency: EPA

Evaluation date: 08/18/1988

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 06/25/1986

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 02/24/1989 Evaluation lead agency: State

Evaluation date: 01/30/1985

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

ICIS:

 Enforcement Action ID:
 05-1993-0891

 FRS ID:
 110003584256

 Program ID:
 FRS 110003584256

 Action Name:
 RELIABLE EQUIPMENT

Full Address: 633 RICHMOND ST NW GRAND RAPIDS MI 49504

State: Michigan

Facility Name: RELIABLE EQUIPMENT CORPOR

Facility Address: 633 RICHMOND ST NW GRAND RAPIDS, MI 49504

Enforcement Action Type: CERCLA 106 AO For Resp Action/Imm Haz

Facility County: KENT EPA Region #: 5

Direction Distance

Elevation Site Database(s) EPA ID Number

RELIABLE EQUIPMENT (Continued)

1000245371

EDR ID Number

Enforcement Action ID: 05-1993-0891 FRS ID: 110003584256

Program ID: CERCLIS MID006407969
Action Name: RELIABLE EQUIPMENT

Full Address: 633 RICHMOND ST NW GRAND RAPIDS MI 49504

State: Michigan

Facility Name: RELIABLE EQUIPMENT
Facility Address: 633 RICHMOND ST NW
GRAND RAPIDS, MI 49504

Enforcement Action Type: CERCLA 106 AO For Resp Action/Imm Haz

Facility County: KENT EPA Region #: 5

Enforcement Action ID: 05-1993-0891 FRS ID: 110003584256

Program ID: RCRAINFO MID006407969
Action Name: RELIABLE EQUIPMENT

Full Address: 633 RICHMOND ST NW GRAND RAPIDS MI 49504

State: Michigan

Facility Name: RELIABLE EQUIPMENT CORPOR

Facility Address: 633 RICHMOND ST NW GRAND RAPIDS, MI 49504

Enforcement Action Type: CERCLA 106 AO For Resp Action/Imm Haz

Facility County: KENT EPA Region #: 5

Enforcement Action ID: 05-1989-0158
FRS ID: 110003584256
Program ID: FRS 110003584256

Action Name: RELIABLE EQUIPMENT, INC.

Full Address: 633 RICHMOND ST NW GRAND RAPIDS MI 49504

State: Michigan

Facility Name: RELIABLE EQUIPMENT CORPOR

Facility Address: 633 RICHMOND ST NW GRAND RAPIDS, MI 49504

Enforcement Action Type: Civil Judicial Action

Facility County: KENT EPA Region #: 5

Enforcement Action ID: 05-1989-0158 FRS ID: 110003584256

Program ID: CERCLIS MID006407969
Action Name: RELIABLE EQUIPMENT, INC.

Full Address: 633 RICHMOND ST NW GRAND RAPIDS MI 49504

State: Michigan

Facility Name: RELIABLE EQUIPMENT
Facility Address: 633 RICHMOND ST NW
GRAND RAPIDS, MI 49504

Enforcement Action Type: Civil Judicial Action

Facility County: KENT EPA Region #: 5

Enforcement Action ID: 05-1989-0158 FRS ID: 110003584256

Program ID: RCRAINFO MID006407969
Action Name: RELIABLE EQUIPMENT, INC.

Full Address: 633 RICHMOND ST NW GRAND RAPIDS MI 49504

Direction
Distance

Elevation Site Database(s) EPA ID Number

RELIABLE EQUIPMENT (Continued)

1000245371

EDR ID Number

State: Michigan

Facility Name: RELIABLE EQUIPMENT CORPOR

Facility Address: 633 RICHMOND ST NW

GRAND RAPIDS, MI 49504

Enforcement Action Type: Civil Judicial Action

Facility County: KENT EPA Region #: 5

Program ID: CERCLIS MID006407969

Facility Name: RELIABLE EQUIPMENT CORPOR

Address: 633 RICHMOND ST NW

Tribal Indicator: N Fed Facility: No

NAIC Code: Not reported SIC Code: 3599

Program ID: FRS 110003584256

Facility Name: RELIABLE EQUIPMENT CORPOR

Address: 633 RICHMOND ST NW

Tribal Indicator: N Fed Facility: No

NAIC Code: Not reported SIC Code: 3599

Program ID: RCRAINFO MID006407969
Facility Name: RELIABLE EQUIPMENT CORPOR

Address: 633 RICHMOND ST NW

Tribal Indicator: N Fed Facility: No

NAIC Code: Not reported SIC Code: 3599

Program ID: CERCLIS MID006407969

Facility Name: RELIABLE EQUIPMENT CORPOR

Address: 633 RICHMOND ST NW

Tribal Indicator: N Fed Facility: No

NAIC Code: Not reported SIC Code: 3599

Program ID: FRS 110003584256

Facility Name: RELIABLE EQUIPMENT CORPOR

Address: 633 RICHMOND ST NW

Tribal Indicator: N Fed Facility: No

NAIC Code: Not reported SIC Code: 3599

Program ID: RCRAINFO MID006407969
Facility Name: RELIABLE EQUIPMENT CORPOR

Address: 633 RICHMOND ST NW

Tribal Indicator: N Fed Facility: No

NAIC Code: Not reported SIC Code: 3599

Direction Distance Elevation

Site Database(s) EPA ID Number

RELIABLE EQUIPMENT (Continued)

1000245371

EDR ID Number

FINDS:

Registry ID: 110003584256

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CERCLIS (Comprehensive Environmental Response, Compensation, and Liability Information System) is the Superfund database that is used to support management in all phases of the Superfund program. The system contains information on all aspects of hazardous waste sites, including an inventory of sites, planned and actual site activities, and financial information.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

PART 201:

Facility ID: 41000053

Facility Status: Evaluation in progress
Source: Chemicals and Allied Products

SAM Score: 38

 SAM Score Date:
 09/29/2004

 Township:
 07N

 Range:
 12W

 Section:
 13

 Quarter:
 NW

 Quarter/Quarter:
 SW

 Pollutants:
 CN; Pb; Ni

INVENTORY:

Bea Number: Not reported
Township: Grand Rapids
District: Grand Rapids
Data Source: Part 201
Latitude: 42.99294
Longitude: -85.68384

Direction Distance

Elevation Site Database(s) EPA ID Number

RELIABLE EQUIPMENT (Continued)

1000245371

EDR ID Number

BROWNFIELD:

Facility ID: Not reported

Region: 1

Status: Completed

Property Use: Property owned by Philomena Trust and Land, operated by Preston

Industrial (Tool).

Use at Time of Listing: Property owned by Philomena Trust and Land, operated by Preston

Industrial (Tool).

BEA: Yes

Ernie Id Number: 41000053

AIRS:

State Registration Number: N1674 Naics Code: Not reported Contact Name: Not reported Contact Phone: Not reported Contact Address: Not reported Contact City, St, Zip: Not reported Permit Number: 532-87 Date Received: 07/17/1987 State Registration Number: N1674 Country: Not reported

Application Reason: PLATING TANKS W/ SCRUBBER

Record Type: Not reported State County FIPS: Not reported Facility Category: Not reported SIC Primary: Not reported Tribal Code: Not reported Not reported Supplemental Location Text: Dun & Brad Street Number: Not reported **Business Name:** Not reported Principal Product: Not reported Principal Product Description: Not reported

UTM Zone (Geo Coordinates Universal Transverse Mercator System): Not reported

UTM Horizontal Coord: Not reported **UTM Vertical Coord:** Not reported Mailing Name: Not reported Mailing Contact Person: Not reported Mailing Street: Not reported Mailing City: Not reported Mailing State: Not reported Mailing Zip: Not reported Mailing Zip 4 Extension: Not reported Compliance Person: Not reported Compliance Area Code: Not reported Compliance Phone Number: Not reported **Emission Inventory Contact Person:** Not reported El Contact Area Code: Not reported El Contact Phone Number: Not reported Permit Contact Person: Not reported Permit Contact Person Area Code: Not reported Not reported Permit Contact Person Phone Number: Federal Employer Id Number: Not reported # Of Employees: Not reported Reporting Year: Not reported Date Record Was Created: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

RELIABLE EQUIPMENT (Continued)

1000245371

EDR ID Number

BEA:

Secondary Address: Not reported BEA Number: 3473

District: Grand Rapids
Date Received: 06/21/2013

Submitter Name: Richmond Transfer Station LLC

Petition Determination: No Request

Petition Disclosure: 0

Category: Not reported Determination 20107A: No Request Reviewer: pawlosj2

Division Assigned: Environmental Response Division

Secondary Address: Not reported

BEA Number: 306

District: Grand Rapids
Date Received: 12/09/1997

Submitter Name: Philomena Trust & Land, L.L.C.

Petition Determination: Affirmed Petition Disclosure: 1

Category: Same Hazardous Substance(s)

Determination 20107A: No Request Reviewer: odonneld

Division Assigned: Environmental Response Division

Secondary Address: Not reported

BEA Number: 598

District: Grand Rapids
Date Received: 10/04/1999

Submitter Name: Gary Pitsch, Member/Manager

Petition Determination: Affirmed

Petition Disclosure: 1

Category: Same Hazardous Substance(s)

Determination 20107A: No Request Reviewer: pawlosj2

Division Assigned: Environmental Response Division

WDS:

Site Id: MID006407969 WMD Id: 394195

Site Specific Name: RELIABLE EQUIPMENT CORPORATION

Mailing Address: 633 RICHMOND ST NW

Mailing City/State/Zip: 49504 Mailing County: KENT

PRP:

PRP name: ADVANCE PLATING

ANTHONY PRESTON, SR ATTWOOD CORP. ATTWOOD CORP.

BIGELOW-MCFADDEN SEPTIC TANK SYSTEMS

CRAMPTON MANUFACTURING DOEHLER-JARVIS LTD. PARTNERSHIP GENERAL MOTORS CORPORATION GENERAL MOTORS CORPORATION GENERAL MOTORS CORPORATION

MAP FINDINGS Map ID Direction

Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

RELIABLE EQUIPMENT (Continued)

1000245371

GRAND RAPIDS DIE CASTING CORP.

KEELER BRASS COMPANY

LESCOA - THE LESLIE METAL ARTS CO., INC.

LESCOA - THE LESLIE METAL ARTS CO., INC.

LESCOA - THE LESLIE METAL ARTS CO., INC.

NAT'L. LEAD INDUS./DOEHLER-JARVIS DIV.

NAT'L. LEAD INDUS./DOEHLER-JARVIS DIV.

PLASTIC PLATE

PRESTON, ANTHONY SR.

PRESTON, ANTHONY SR.

RELIABLE EQUIPMENT CORP.

RELIABLE EQUIPMENT CORP.

RELIABLE EQUIPMENT CORP.

STA-RITE INDUSTRIES, INC./AMERICAN SANITARY DIV.

TUBULAR SALES

TUBULAR SALES

Count: 4 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	
GRAND RAPIDS	S103085176	68TH. ST. & DIVISION AREA	68TH. STREET AND DIVISION AREA		PART 201, DEL PART 201	
KENT COUNTY	S114022589	1271-1727 ALPINE AVENUE	1721-1727 ALPINE AVENUE		INVENTORY	
KENT COUNTY	S114025688	3718 ALPINE AVENUE NW	3718 ALPINE AVENUE NW		INVENTORY	
KENT COUNTY	S114023282	1750 ALPINE AVENUE N. W. (A TO Z M	1750 ALPINE AVENUE N. W.		INVENTORY	

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 09/29/2014 Source: EPA Date Data Arrived at EDR: 10/08/2014 Telephone: N/A

Last EDR Contact: 10/08/2014 Date Made Active in Reports: 11/17/2014

Number of Days to Update: 40 Next Scheduled EDR Contact: 01/19/2015 Data Release Frequency: Quarterly

NPL Site Boundaries

EPA's Environmental Photographic Interpretation Center (EPIC)

Telephone: 202-564-7333

EPA Region 1 EPA Region 6

Telephone 617-918-1143 Telephone: 214-655-6659

EPA Region 3 EPA Region 7

Telephone 215-814-5418 Telephone: 913-551-7247

EPA Region 4 **EPA Region 8**

Telephone 404-562-8033 Telephone: 303-312-6774

EPA Region 5 EPA Region 9

Telephone 312-886-6686 Telephone: 415-947-4246

EPA Region 10

Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 09/29/2014 Source: EPA Date Data Arrived at EDR: 10/08/2014 Telephone: N/A Date Made Active in Reports: 11/17/2014

Last EDR Contact: 10/08/2014

Number of Days to Update: 40 Next Scheduled EDR Contact: 01/19/2015 Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Source: EPA

Date of Government Version: 10/15/1991 Date Data Arrived at EDR: 02/02/1994 Date Made Active in Reports: 03/30/1994

Number of Days to Update: 56

Telephone: 202-564-4267 Last EDR Contact: 08/15/2011

Next Scheduled EDR Contact: 11/28/2011 Data Release Frequency: No Update Planned

Federal Delisted NPL site list

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 09/29/2014 Date Data Arrived at EDR: 10/08/2014 Date Made Active in Reports: 11/17/2014

Number of Days to Update: 40

Source: EPA Telephone: N/A

Last EDR Contact: 10/08/2014

Next Scheduled EDR Contact: 01/19/2015 Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 10/25/2013 Date Data Arrived at EDR: 11/11/2013 Date Made Active in Reports: 02/13/2014

Number of Days to Update: 94

Source: EPA

Telephone: 703-412-9810 Last EDR Contact: 11/24/2014

Next Scheduled EDR Contact: 03/09/2015 Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 07/21/2014 Date Data Arrived at EDR: 10/07/2014 Date Made Active in Reports: 10/20/2014

Number of Days to Update: 13

Source: Environmental Protection Agency

Telephone: 703-603-8704 Last EDR Contact: 10/07/2014

Next Scheduled EDR Contact: 01/19/2015 Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 10/25/2013 Date Data Arrived at EDR: 11/11/2013 Date Made Active in Reports: 02/13/2014

Number of Days to Update: 94

Source: EPA

Telephone: 703-412-9810 Last EDR Contact: 11/24/2014

Next Scheduled EDR Contact: 03/09/2015 Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/10/2014 Date Data Arrived at EDR: 07/02/2014 Date Made Active in Reports: 09/18/2014

Number of Days to Update: 78

Source: EPA

Telephone: 800-424-9346 Last EDR Contact: 12/29/2014

Next Scheduled EDR Contact: 04/13/2015 Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/10/2014
Date Data Arrived at EDR: 07/02/2014
Date Made Active in Reports: 09/18/2014

Number of Days to Update: 78

Source: Environmental Protection Agency

Telephone: 312-886-6186 Last EDR Contact: 12/29/2014

Next Scheduled EDR Contact: 04/13/2015 Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/10/2014 Date Data Arrived at EDR: 07/02/2014 Date Made Active in Reports: 09/18/2014

Number of Days to Update: 78

Source: Environmental Protection Agency

Telephone: 312-886-6186 Last EDR Contact: 12/29/2014

Next Scheduled EDR Contact: 04/13/2015 Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/10/2014 Date Data Arrived at EDR: 07/02/2014 Date Made Active in Reports: 09/18/2014

Number of Days to Update: 78

Source: Environmental Protection Agency

Telephone: 312-886-6186 Last EDR Contact: 12/29/2014

Next Scheduled EDR Contact: 04/13/2015 Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/10/2014 Date Data Arrived at EDR: 07/02/2014 Date Made Active in Reports: 09/18/2014

Number of Days to Update: 78

Source: Environmental Protection Agency

Telephone: 312-886-6186 Last EDR Contact: 12/29/2014

Next Scheduled EDR Contact: 04/13/2015 Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 09/18/2014 Date Data Arrived at EDR: 09/19/2014 Date Made Active in Reports: 10/20/2014

Number of Days to Update: 31

Source: Environmental Protection Agency

Telephone: 703-603-0695 Last EDR Contact: 12/03/2014

Next Scheduled EDR Contact: 03/16/2015 Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 09/18/2014 Date Data Arrived at EDR: 09/19/2014 Date Made Active in Reports: 10/20/2014

Number of Days to Update: 31

Source: Environmental Protection Agency

Telephone: 703-603-0695 Last EDR Contact: 12/03/2014

Next Scheduled EDR Contact: 03/16/2015 Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 08/29/2014 Date Data Arrived at EDR: 10/09/2014 Date Made Active in Reports: 10/20/2014

Number of Days to Update: 11

Source: Department of the Navy Telephone: 843-820-7326 Last EDR Contact: 11/17/2014

Next Scheduled EDR Contact: 03/02/2015 Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 09/29/2014 Date Data Arrived at EDR: 09/30/2014 Date Made Active in Reports: 11/06/2014

Number of Days to Update: 37

Source: National Response Center, United States Coast Guard

Telephone: 202-267-2180 Last EDR Contact: 12/29/2014

Next Scheduled EDR Contact: 04/13/2015 Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: This state does not maintain a SHWS list. See the Federal CERCLIS list and Federal NPL list. This state does not maintain a SHWS list. See the Federal CERCLIS list and Federal NPL list.

Date of Government Version: N/A
Date Data Arrived at EDR: 10/31/2013
Date Made Active in Reports: 11/20/2013

Number of Days to Update: 20

Source: Dept of Environmental Quality

Telephone: 517-284-5103 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: No Update Planned

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Solid Waste Facilities Database

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 09/30/2014 Date Data Arrived at EDR: 10/01/2014 Date Made Active in Reports: 10/17/2014

Number of Days to Update: 16

Source: Dept of Environmental Quality

Telephone: 517-335-4035 Last EDR Contact: 10/01/2014

Next Scheduled EDR Contact: 01/12/2015 Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

LUST: Leaking Underground Storage Tank Sites

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 08/01/2014 Date Data Arrived at EDR: 08/19/2014 Date Made Active in Reports: 09/03/2014

Number of Days to Update: 15

Source: Dept of Environmental Quality

Telephone: 517-373-9837 Last EDR Contact: 11/17/2014

Next Scheduled EDR Contact: 03/02/2015 Data Release Frequency: Annually

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 03/01/2013 Date Data Arrived at EDR: 03/01/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 42

Source: Environmental Protection Agency

Telephone: 415-972-3372 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Quarterly

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 05/22/2014 Date Data Arrived at EDR: 08/22/2014 Date Made Active in Reports: 09/18/2014

Number of Days to Update: 27

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 10/06/2014 Date Data Arrived at EDR: 10/29/2014 Date Made Active in Reports: 11/17/2014

Number of Days to Update: 19

Source: EPA Region 6 Telephone: 214-665-6597 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 11/03/2014 Date Data Arrived at EDR: 11/05/2014 Date Made Active in Reports: 11/17/2014

Number of Days to Update: 12

Source: EPA, Region 5 Telephone: 312-886-7439 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015

Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 05/20/2014 Date Data Arrived at EDR: 06/10/2014 Date Made Active in Reports: 08/22/2014

Number of Days to Update: 73

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Quarterly

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 11/04/2014 Date Data Arrived at EDR: 11/07/2014 Date Made Active in Reports: 11/17/2014

Number of Days to Update: 10

Source: EPA Region 8 Telephone: 303-312-6271 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Quarterly

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 02/01/2013
Date Data Arrived at EDR: 05/01/2013
Date Made Active in Reports: 11/01/2013

Number of Days to Update: 184

Source: EPA Region 1 Telephone: 617-918-1313 Last EDR Contact: 10/31/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 07/30/2014 Date Data Arrived at EDR: 08/12/2014 Date Made Active in Reports: 08/22/2014

Number of Days to Update: 10

Source: EPA Region 4 Telephone: 404-562-8677 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Semi-Annually

State and tribal registered storage tank lists

UST 2: Underground Storage Tank Listing

A listing of underground storage tank site locations that have unknown owner information.

Date of Government Version: 10/28/2014 Date Data Arrived at EDR: 10/29/2014 Date Made Active in Reports: 12/01/2014

Number of Days to Update: 33

Source: Dept of Environmental Quality

Telephone: 517-335-7211 Last EDR Contact: 10/20/2014

Next Scheduled EDR Contact: 02/02/2015 Data Release Frequency: Annually

UST: Underground Storage Tank Facility List

Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 08/01/2014 Date Data Arrived at EDR: 08/19/2014 Date Made Active in Reports: 09/03/2014

Number of Days to Update: 15

Source: Dept of Environmental Quality Telephone: 517-335-4035 Last EDR Contact: 11/17/2014

Next Scheduled EDR Contact: 03/02/2015 Data Release Frequency: Annually

AST: Aboveground Tanks

Registered Aboveground Storage Tanks.

Date of Government Version: 10/31/2014 Date Data Arrived at EDR: 10/31/2014 Date Made Active in Reports: 12/01/2014

Number of Days to Update: 31

Source: Dept of Environmental Quality Telephone: 517-373-8168 Last EDR Contact: 11/17/2014

Next Scheduled EDR Contact: 03/02/2015

Data Release Frequency: No Update Planned

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 02/01/2013 Date Data Arrived at EDR: 05/01/2013 Date Made Active in Reports: 01/27/2014

Number of Days to Update: 271

Source: EPA, Region 1 Telephone: 617-918-1313 Last EDR Contact: 10/31/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 07/30/2014 Date Data Arrived at EDR: 08/12/2014 Date Made Active in Reports: 08/22/2014

Number of Days to Update: 10

Source: EPA Region 4 Telephone: 404-562-9424 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 11/03/2014 Date Data Arrived at EDR: 11/05/2014 Date Made Active in Reports: 11/17/2014

Number of Days to Update: 12

Source: EPA Region 5 Telephone: 312-886-6136 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 10/06/2014 Date Data Arrived at EDR: 10/29/2014 Date Made Active in Reports: 11/06/2014

Number of Days to Update: 8

Source: EPA Region 6 Telephone: 214-665-7591 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Semi-Annually

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 08/20/2014 Date Data Arrived at EDR: 08/22/2014 Date Made Active in Reports: 09/18/2014

Number of Days to Update: 27

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 11/04/2014 Date Data Arrived at EDR: 11/07/2014 Date Made Active in Reports: 11/17/2014

Number of Days to Update: 10

Source: EPA Region 8 Telephone: 303-312-6137 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Quarterly

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 08/14/2014 Date Data Arrived at EDR: 08/15/2014 Date Made Active in Reports: 08/22/2014

Number of Days to Update: 7

Source: EPA Region 9 Telephone: 415-972-3368 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 05/20/2014 Date Data Arrived at EDR: 06/10/2014 Date Made Active in Reports: 08/15/2014

Number of Days to Update: 66

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Quarterly

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010 Date Data Arrived at EDR: 02/16/2010 Date Made Active in Reports: 04/12/2010

Number of Days to Update: 55

Source: FEMA

Telephone: 202-646-5797 Last EDR Contact: 10/10/2014

Next Scheduled EDR Contact: 01/26/2015 Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

AUL: Engineering and Institutional Controls

A listing of sites with institutional and/or engineering controls in place.

Date of Government Version: 09/03/2014 Date Data Arrived at EDR: 09/03/2014 Date Made Active in Reports: 10/17/2014

Number of Days to Update: 44

Source: Dept of Environmental Quality

Telephone: 517-373-4828 Last EDR Contact: 12/01/2014

Next Scheduled EDR Contact: 03/16/2015 Data Release Frequency: Varies

State and tribal voluntary cleanup sites

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008 Date Data Arrived at EDR: 04/22/2008 Date Made Active in Reports: 05/19/2008

Number of Days to Update: 27

Source: EPA, Region 7 Telephone: 913-551-7365 Last EDR Contact: 04/20/2009

Next Scheduled EDR Contact: 07/20/2009 Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 09/29/2014 Date Data Arrived at EDR: 10/01/2014 Date Made Active in Reports: 11/06/2014

Number of Days to Update: 36

Source: EPA, Region 1 Telephone: 617-918-1102 Last EDR Contact: 10/01/2014

Next Scheduled EDR Contact: 01/12/2015 Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Brownfields and USTfield Site Database

All state funded Part 201 and 213 sites, as well as LUST sites that have been redeveloped by private entities using the BEA process. Be aware that this is not a list of all of the potential brownfield sites in Michigan.

Date of Government Version: 07/27/2012 Date Data Arrived at EDR: 07/31/2012 Date Made Active in Reports: 09/20/2012

Number of Days to Update: 51

Source: Dept of Environmental Quality Telephone: 517-373-4805

Last EDR Contact: 10/24/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Varies

BROWNFIELDS 2: Brownfields Building and Land Site Locations

A listing of brownfield building and land site locations. The listing is a collaborative effort of Michigan Economic Development Corporation, Michigan Economic Developers Association, Detrot Edison, Detroit Area Commercial Board of Realtors

Date of Government Version: 04/09/2007 Date Data Arrived at EDR: 04/10/2007 Date Made Active in Reports: 05/01/2007

Number of Days to Update: 21

Source: Economic Development Corporation

Telephone: 888-522-0103 Last EDR Contact: 11/25/2014

Next Scheduled EDR Contact: 03/16/2015

Data Release Frequency: Varies

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 09/22/2014 Date Data Arrived at EDR: 09/23/2014 Date Made Active in Reports: 10/20/2014

Number of Days to Update: 27

Source: Environmental Protection Agency

Telephone: 202-566-2777 Last EDR Contact: 12/22/2014

Next Scheduled EDR Contact: 04/06/2015 Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009 Date Data Arrived at EDR: 05/07/2009 Date Made Active in Reports: 09/21/2009

Number of Days to Update: 137

Source: EPA, Region 9 Telephone: 415-947-4219 Last EDR Contact: 10/24/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258

Subtitle D Criteria.

Date of Government Version: 06/30/1985 Date Data Arrived at EDR: 08/09/2004 Date Made Active in Reports: 09/17/2004

Number of Days to Update: 39

Source: Environmental Protection Agency

Telephone: 800-424-9346 Last EDR Contact: 06/09/2004 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

SWRCY: Recycling Facilities

A listing of recycling center locations.

Date of Government Version: 07/11/2014 Date Data Arrived at EDR: 07/11/2014 Date Made Active in Reports: 08/11/2014

Number of Days to Update: 31

Source: Dept of Environmental Quality

Telephone: 517-241-5719 Last EDR Contact: 12/29/2014

Next Scheduled EDR Contact: 04/13/2015 Data Release Frequency: Varies

HIST LF: Inactive Solid Waste Facilities

The database contains historical information and is no longer updated.

Date of Government Version: 03/01/1997 Date Data Arrived at EDR: 02/28/2003 Date Made Active in Reports: 03/06/2003

Number of Days to Update: 6

Source: Dept of Environmental Quality

Telephone: 517-335-4034 Last EDR Contact: 02/28/2003 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998 Date Data Arrived at EDR: 12/03/2007 Date Made Active in Reports: 01/24/2008

Number of Days to Update: 52

Source: Environmental Protection Agency

Telephone: 703-308-8245 Last EDR Contact: 10/29/2014

Next Scheduled EDR Contact: 02/16/2015 Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 07/25/2014 Date Data Arrived at EDR: 09/09/2014 Date Made Active in Reports: 10/20/2014

Number of Days to Update: 41

Source: Drug Enforcement Administration

Telephone: 202-307-1000 Last EDR Contact: 11/25/2014

Next Scheduled EDR Contact: 03/16/2015 Data Release Frequency: Quarterly

PART 201: Part 201 Site List

A Part 201 Listed site is a location that has been evaluated and scored by the DEQ using the Part 201 scoring model. The location is or includes a "facility" as defined by Part 201, where there has been a release of a hazardous substance(s) in excess of the Part 201 residential criteria, and/or where corrective actions have not been completed under Part 201 to meet the applicable cleanup criteria for unrestricted residential use. The Part 201 List does not include all of the sites of contamination that are subject to regulation under Part 201 because owners are not required to inform the DEQ about the sites and can pursue cleanup independently. Sites of environmental contamination that are not known to DEQ are not on the list, nor are sites with releases that resulted in low environmental impact.

Date of Government Version: 10/01/2013 Date Data Arrived at EDR: 10/03/2014 Date Made Active in Reports: 10/03/2014

Number of Days to Update: 0

Source: Department of Environmental Quality

Telephone: 517-284-5103 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015
Data Release Frequency: No Update Planned

INVENTORY: Inventory of Facilities

The Inventory of Facilities has three data sources: Facilities under Part 201, Environmental Remediation, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (NREPA) identified through state funded or private party response activities (Projects); Facilities under Part 213, Leaking Underground Storage Tanks of the NREPA; and Facilities identified through submittals of Baseline Environmental Assessments (BEA) submitted pursuant to Part 201 or Part 213 of the NREPA. The Part 201 Projects Inventory does not include all of the facilities that are subject to regulation under Part 201 because owners are not required to inform the Department of Environmental Quality (DEQ) about the facilities and can pursue cleanup independently. Facilities that are not known to DEQ are not on the Inventory, nor are locations with releases that resulted in low environmental impact. Part 213 facilities listed here may have more than one release; a list of releases for which corrective actions have been completed and list of releases for which corrective action has not been completed is located on the Leaking Underground Storage Tanks Site Search webpage. The DEQ may or may not have reviewed and concurred with the conclusion that the corrective actions described in a closure report meets criteria. A BEA is a document that new or prospective property owners/operations disclose to the DEQ identifying the property as a facility pursuant to Part 201 and Part 213. The Inventory of BEA Facilities overlaps in part with the Part 201 Projects facilities and Part 213 facilities. There may be more than one BEA for each facility.

Date of Government Version: 10/27/2014 Date Data Arrived at EDR: 10/28/2014 Date Made Active in Reports: 12/01/2014

Number of Days to Update: 34

Source: Department of Environmental Quality

Telephone: 517-284-5136 Last EDR Contact: 10/28/2014

Next Scheduled EDR Contact: 02/09/2015
Data Release Frequency: Quarterly

DEL PART 201: Delisted List of Contaminated Sites

A deleted site has been removed from the Part 201 List because information known to the DEQ at the time of the evaluation does not support inclusion on the Part 201 List. This designation is often applied to sites where changes in cleanup criteria resulted in a determination that the site no longer exceeds any applicable cleanup criterion.

A delisted site has been removed from the Part 201 List because response actions have reduced the levels of contaminants to concentrations which meet or are below the criteria for unrestricted residential use.

Date of Government Version: 08/01/2013 Date Data Arrived at EDR: 08/01/2013 Date Made Active in Reports: 09/11/2013

Number of Days to Update: 41

Source: Dept of Environmental Quality

Telephone: 517-373-9541 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Varies

CDL: Clandestine Drug Lab Listing
A listing of clandestine drug lab locations.

Date of Government Version: 10/20/2008 Date Data Arrived at EDR: 11/18/2008 Date Made Active in Reports: 11/21/2008

Number of Days to Update: 3

Source: Department of Community Health

Telephone: 517-373-3740 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Varies

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 07/25/2014 Date Data Arrived at EDR: 09/09/2014 Date Made Active in Reports: 10/20/2014

Number of Days to Update: 41

Source: Drug Enforcement Administration

Telephone: 202-307-1000 Last EDR Contact: 11/25/2014

Next Scheduled EDR Contact: 03/16/2015 Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/18/2014 Date Data Arrived at EDR: 03/18/2014 Date Made Active in Reports: 04/24/2014

Number of Days to Update: 37

Source: Environmental Protection Agency

Telephone: 202-564-6023 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Varies

LIENS: Lien List

An Environmental Lien is a charge, security, or encumbrance upon title to a property to secure the payment of a cost, damage, debt, obligation, or duty arising out of response actions, cleanup, or other remediation of hazardous substances or petroleum products upon a property, including (but not limited to) liens imposed pursuant to CERCLA 42 USC * 9607(1) and similar state or local laws. In other words: a lien placed upon a property's title due to an environmental condition

Date of Government Version: 09/17/2014 Date Data Arrived at EDR: 10/22/2014 Date Made Active in Reports: 11/26/2014

Number of Days to Update: 35

Source: Dept of Environmental Quality Telephone: 517-241-7603 Last EDR Contact: 10/17/2014

Next Scheduled EDR Contact: 02/02/2015
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 09/30/2014 Date Data Arrived at EDR: 10/01/2014 Date Made Active in Reports: 11/06/2014

Number of Days to Update: 36

Source: U.S. Department of Transportation

Telephone: 202-366-4555 Last EDR Contact: 10/01/2014

Next Scheduled EDR Contact: 01/12/2015 Data Release Frequency: Annually

PEAS: Pollution Emergency Alerting System

Environmental pollution emergencies reported to the Department of Environmental Quality such as tanker accidents, pipeline breaks, and release of reportable quantities of hazardous substances.

Date of Government Version: 09/16/2014 Date Data Arrived at EDR: 09/18/2014 Date Made Active in Reports: 10/17/2014

Number of Days to Update: 29

Source: Dept of Environmental Quality

Telephone: 517-373-8427 Last EDR Contact: 12/05/2014

Next Scheduled EDR Contact: 03/23/2015 Data Release Frequency: Quarterly

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/10/2014 Date Data Arrived at EDR: 07/02/2014 Date Made Active in Reports: 09/18/2014

Number of Days to Update: 78

Source: Environmental Protection Agency

Telephone: 312-886-6186 Last EDR Contact: 12/29/2014

Next Scheduled EDR Contact: 04/13/2015 Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012 Date Data Arrived at EDR: 08/07/2012 Date Made Active in Reports: 09/18/2012

Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety

Telephone: 202-366-4595 Last EDR Contact: 11/04/2014

Next Scheduled EDR Contact: 02/16/2015 Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 11/10/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 62

Source: USGS

Telephone: 888-275-8747 Last EDR Contact: 11/07/2014

Next Scheduled EDR Contact: 01/26/2015 Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 06/06/2014 Date Data Arrived at EDR: 09/10/2014 Date Made Active in Reports: 09/18/2014

Number of Days to Update: 8

Source: U.S. Army Corps of Engineers

Telephone: 202-528-4285 Last EDR Contact: 12/12/2014

Next Scheduled EDR Contact: 03/23/2015 Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2013 Date Data Arrived at EDR: 01/24/2014 Date Made Active in Reports: 02/24/2014

Number of Days to Update: 31

Source: Department of Justice, Consent Decree Library

Telephone: Varies

Last EDR Contact: 12/24/2014

Next Scheduled EDR Contact: 04/13/2015 Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 11/25/2013 Date Data Arrived at EDR: 12/12/2013 Date Made Active in Reports: 02/24/2014

Number of Days to Update: 74

Source: EPA

Telephone: 703-416-0223 Last EDR Contact: 12/12/2014

Next Scheduled EDR Contact: 03/23/2015 Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010 Date Data Arrived at EDR: 10/07/2011 Date Made Active in Reports: 03/01/2012

Number of Days to Update: 146

Source: Department of Energy Telephone: 505-845-0011 Last EDR Contact: 11/26/2014

Next Scheduled EDR Contact: 03/09/2015 Data Release Frequency: Varies

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/05/2014 Date Data Arrived at EDR: 09/04/2014 Date Made Active in Reports: 11/17/2014

Number of Days to Update: 74

Source: Department of Labor, Mine Safety and Health Administration

Telephone: 303-231-5959 Last EDR Contact: 12/03/2014

Next Scheduled EDR Contact: 03/16/2015 Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 07/31/2013 Date Made Active in Reports: 09/13/2013

Number of Days to Update: 44

Source: EPA

Telephone: 202-566-0250 Last EDR Contact: 11/26/2014

Next Scheduled EDR Contact: 03/09/2015 Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2006 Date Data Arrived at EDR: 09/29/2010 Date Made Active in Reports: 12/02/2010

Number of Days to Update: 64

Source: EPA

Telephone: 202-260-5521 Last EDR Contact: 12/22/2014

Next Scheduled EDR Contact: 04/06/2015 Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act) FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009 Date Data Arrived at EDR: 04/16/2009 Date Made Active in Reports: 05/11/2009

Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances

Telephone: 202-566-1667 Last EDR Contact: 11/19/2014

Next Scheduled EDR Contact: 03/09/2015 Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act) A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009 Date Data Arrived at EDR: 04/16/2009 Date Made Active in Reports: 05/11/2009

Number of Days to Update: 25

Source: EPA

Telephone: 202-566-1667 Last EDR Contact: 11/19/2014

Next Scheduled EDR Contact: 03/09/2015 Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006 Date Data Arrived at EDR: 03/01/2007 Date Made Active in Reports: 04/10/2007

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 12/17/2007

Next Scheduled EDR Contact: 03/17/2008 Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 12/17/2008

Next Scheduled EDR Contact: 03/17/2008 Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009 Date Data Arrived at EDR: 12/10/2010 Date Made Active in Reports: 02/25/2011

Number of Days to Update: 77

Source: EPA

Telephone: 202-564-4203 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 07/31/2014 Date Data Arrived at EDR: 10/29/2014 Date Made Active in Reports: 11/06/2014

Number of Days to Update: 8

Source: Environmental Protection Agency

Telephone: 202-564-5088 Last EDR Contact: 10/10/2014

Next Scheduled EDR Contact: 01/26/2015 Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2014 Date Data Arrived at EDR: 10/15/2014 Date Made Active in Reports: 11/17/2014

Number of Days to Update: 33

Source: EPA

Telephone: 202-566-0500 Last EDR Contact: 10/15/2014

Next Scheduled EDR Contact: 01/26/2015 Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 07/22/2013 Date Data Arrived at EDR: 08/02/2013 Date Made Active in Reports: 11/01/2013

Number of Days to Update: 91

Source: Nuclear Regulatory Commission

Telephone: 301-415-7169 Last EDR Contact: 12/04/2014

Next Scheduled EDR Contact: 03/23/2015 Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 10/07/2014 Date Data Arrived at EDR: 10/08/2014 Date Made Active in Reports: 10/20/2014

Number of Days to Update: 12

Source: Environmental Protection Agency

Telephone: 202-343-9775 Last EDR Contact: 10/08/2014

Next Scheduled EDR Contact: 01/19/2015 Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 08/16/2014 Date Data Arrived at EDR: 09/10/2014 Date Made Active in Reports: 10/20/2014

Number of Days to Update: 40

Source: EPA

Telephone: (312) 353-2000 Last EDR Contact: 12/09/2014

Next Scheduled EDR Contact: 03/23/2015 Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995 Date Data Arrived at EDR: 07/03/1995 Date Made Active in Reports: 08/07/1995

Number of Days to Update: 35

Source: EPA

Telephone: 202-564-4104 Last EDR Contact: 06/02/2008

Next Scheduled EDR Contact: 09/01/2008 Data Release Frequency: No Update Planned

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 08/01/2014 Date Data Arrived at EDR: 08/12/2014 Date Made Active in Reports: 11/06/2014

Number of Days to Update: 86

Source: Environmental Protection Agency

Telephone: 202-564-8600 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 02/26/2013 Date Made Active in Reports: 04/19/2013

Number of Days to Update: 52

Source: EPA/NTIS Telephone: 800-424-9346 Last EDR Contact: 11/26/2014

Next Scheduled EDR Contact: 03/09/2015 Data Release Frequency: Biennially

UIC: Underground Injection Wells Database

A listing of underground injection well locations. The UIC Program is responsible for regulating the construction, operation, permitting, and closure of injection wells that place fluids underground for storage or disposal.

Date of Government Version: 10/29/2014 Date Data Arrived at EDR: 10/30/2014 Date Made Active in Reports: 12/01/2014

Number of Days to Update: 32

Source: Dept of Environmental Quality

Telephone: 517-241-1515 Last EDR Contact: 10/27/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Varies

DRYCLEANERS: Drycleaning Establishments A listing of drycleaning facilities in Michigan.

Date of Government Version: 07/24/2014 Date Data Arrived at EDR: 07/25/2014 Date Made Active in Reports: 08/11/2014

Number of Days to Update: 17

Source: Dept of Environmental Quality

Telephone: 517-335-4586 Last EDR Contact: 10/20/2014

Next Scheduled EDR Contact: 02/02/2015 Data Release Frequency: Annually

NPDES: List of Active NPDES Permits

General information regarding NPDES (National Pollutant Discharge Elimination System) permits and NPDES Storm Water permits.

Date of Government Version: 10/07/2014 Date Data Arrived at EDR: 10/08/2014 Date Made Active in Reports: 10/17/2014

Number of Days to Update: 9

Source: Dept of Environmental Quality

Telephone: 517-241-1300 Last EDR Contact: 10/08/2014

Next Scheduled EDR Contact: 01/19/2015 Data Release Frequency: Varies

AIRS: Permit and Emissions Inventory Data Permit and emissions inventory data.

Date of Government Version: 09/26/2014 Date Data Arrived at EDR: 09/26/2014 Date Made Active in Reports: 11/19/2014

Number of Days to Update: 54

Source: Dept of Environmental Quality

Telephone: 517-373-7074 Last EDR Contact: 12/18/2014

Next Scheduled EDR Contact: 04/06/2015 Data Release Frequency: Varies

BEA: Baseline Environmental Assessment Database

A BEA is a document that new or prospective property owners/operations disclose to the DEQ identifying the property as a facility pursuant to Part 201 and Part 213. The Inventory of BEA Facilities overlaps in part with the Part 201 Projects facilities and Part 213 facilities. There may be more than one BEA for each facility.

Date of Government Version: 08/21/2013 Date Data Arrived at EDR: 08/23/2013 Date Made Active in Reports: 09/12/2013

Number of Days to Update: 20

Source: Dept of Environmental Quality

Telephone: 517-373-9541 Last EDR Contact: 11/17/2014

Next Scheduled EDR Contact: 03/02/2015 Data Release Frequency: No Update Planned

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 12/08/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 34

Source: USGS

Telephone: 202-208-3710 Last EDR Contact: 11/07/2014

Next Scheduled EDR Contact: 01/26/2015 Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011 Date Data Arrived at EDR: 03/09/2011 Date Made Active in Reports: 05/02/2011

Number of Days to Update: 54

Source: Environmental Protection Agency

Telephone: 615-532-8599 Last EDR Contact: 11/18/2014

Next Scheduled EDR Contact: 02/02/2015 Data Release Frequency: Varies

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 01/05/2011 Date Data Arrived at EDR: 01/07/2011 Date Made Active in Reports: 02/14/2011

Number of Days to Update: 38

Source: Dept of Environmental Quality Telephone: 517-335-4034

Last EDR Contact: 12/29/2014

Next Scheduled EDR Contact: 04/13/2015 Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 09/04/2014 Date Data Arrived at EDR: 09/04/2014 Date Made Active in Reports: 10/20/2014

Number of Days to Update: 46

Source: Environmental Protection Agency

Telephone: 202-566-1917 Last EDR Contact: 11/11/2014

Next Scheduled EDR Contact: 03/02/2015 Data Release Frequency: Quarterly

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014 Date Data Arrived at EDR: 09/10/2014 Date Made Active in Reports: 10/20/2014

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: N/A

Last EDR Contact: 12/12/2014

Next Scheduled EDR Contact: 03/23/2015 Data Release Frequency: Varies

COAL ASH DOE: Sleam-Electric Plan Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 08/07/2009 Date Made Active in Reports: 10/22/2009

Number of Days to Update: 76

Source: Department of Energy Telephone: 202-586-8719 Last EDR Contact: 10/17/2014

Next Scheduled EDR Contact: 01/26/2015

Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 10/14/2014 Date Data Arrived at EDR: 10/22/2014 Date Made Active in Reports: 11/26/2014

Number of Days to Update: 35

Source: Dept of Environmental Quality Telephone: 517-335-6610

Last EDR Contact: 10/06/2014

Next Scheduled EDR Contact: 01/19/2015 Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011 Date Data Arrived at EDR: 10/19/2011 Date Made Active in Reports: 01/10/2012

Number of Days to Update: 83

Source: Environmental Protection Agency

Telephone: 202-566-0517 Last EDR Contact: 10/31/2014

Next Scheduled EDR Contact: 02/09/2015 Data Release Frequency: Varies

WDS: Waste Data System

The Waste Data System (WDS) tracks activities at facilities regulated by the Solid Waste, Scrap Tire, Hazardous

Waste, and Liquid Industrial Waste programs.

Date of Government Version: 09/10/2014 Date Data Arrived at EDR: 09/11/2014 Date Made Active in Reports: 10/17/2014

Number of Days to Update: 36

Source: Dept of Environmental Quality

Telephone: 517-284-6562 Last EDR Contact: 11/20/2014

Next Scheduled EDR Contact: 03/09/2015 Data Release Frequency: Quarterly

COAL ASH: Coal Ash Disposal Sites

Coal fired power plants in Southeast Michigan that have coal ash handling on site.

Date of Government Version: 10/15/2014 Date Data Arrived at EDR: 10/16/2014 Date Made Active in Reports: 11/26/2014

Number of Days to Update: 41

Source: Dept of Environmental Quality

Telephone: 586-753-3754 Last EDR Contact: 10/06/2014

Next Scheduled EDR Contact: 01/19/2015 Data Release Frequency: Varies

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013 Date Data Arrived at EDR: 03/21/2014 Date Made Active in Reports: 06/17/2014

Number of Days to Update: 88

Source: Environmental Protection Agency

Telephone: 617-520-3000 Last EDR Contact: 11/14/2014

Next Scheduled EDR Contact: 02/23/2015 Data Release Frequency: Quarterly

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/25/2013 Date Data Arrived at EDR: 10/17/2014 Date Made Active in Reports: 10/20/2014

Number of Days to Update: 3

Source: EPA

Telephone: 202-564-6023 Last EDR Contact: 12/29/2015

Next Scheduled EDR Contact: 04/13/2015 Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 11/11/2011 Date Data Arrived at EDR: 05/18/2012 Date Made Active in Reports: 05/25/2012

Number of Days to Update: 7

Source: Environmental Protection Agency

Telephone: 703-308-4044 Last EDR Contact: 11/14/2014

Next Scheduled EDR Contact: 02/23/2015 Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 06/04/2014 Date Data Arrived at EDR: 06/12/2014 Date Made Active in Reports: 07/28/2014

Number of Days to Update: 46

Source: Environmental Protection Agency

Telephone: 703-603-8787 Last EDR Contact: 10/06/2014

Next Scheduled EDR Contact: 01/19/2015 Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites

may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001 Date Data Arrived at EDR: 10/27/2010 Date Made Active in Reports: 12/02/2010

Number of Days to Update: 36

Source: American Journal of Public Health

Telephone: 703-305-6451 Last EDR Contact: 12/02/2009 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management,

Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 02/06/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 339

Source: U.S. Geological Survey Telephone: 888-275-8747 Last EDR Contact: 11/07/2014

Next Scheduled EDR Contact: 01/26/2015

Data Release Frequency: N/A

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/16/2014 Date Data Arrived at EDR: 10/31/2014 Date Made Active in Reports: 11/17/2014

Number of Days to Update: 17

Source: EPA

Telephone: 202-564-2496 Last EDR Contact: 12/23/2014

Next Scheduled EDR Contact: 04/13/2015 Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data A listing of minor source facilities.

Date of Government Version: 10/16/2014 Date Data Arrived at EDR: 10/31/2014 Date Made Active in Reports: 11/17/2014

Number of Days to Update: 17

Source: EPA

Telephone: 202-564-2496 Last EDR Contact: 12/23/2014

Next Scheduled EDR Contact: 04/13/2015 Data Release Frequency: Annually

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A Source: EDR, Inc.

Date Data Arrived at EDR: N/A Telephone: N/A

Date Made Active in Reports: N/A Last EDR Contact: N/A

Number of Days to Update: N/A Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

EDR US Hist Auto Stat: EDR Exclusive Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A Source: EDR, Inc.
Date Data Arrived at EDR: N/A Telephone: N/A
Date Made Active in Reports: N/A Last EDR Contact: N/A

Number of Days to Update: N/A Next Scheduled EDR Contact: N/A

Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A Source: EDR, Inc.
Date Data Arrived at EDR: N/A Telephone: N/A
Date Made Active in Reports: N/A Last EDR Contact: N/A

Number of Days to Update: N/A Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Michigan.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/24/2013

Number of Days to Update: 176

Source: Department of Environmental Quality

Telephone: N/A

Last EDR Contact: 06/01/2012 Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Michigan.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/13/2014

Number of Days to Update: 196

Source: Department of Environmental Quality

Telephone: N/A

Last EDR Contact: 06/01/2012 Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

RGA PART 201: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Michigan.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/24/2013

Number of Days to Update: 176

Source: Department of Environmental Quality

Telephone: N/A

Last EDR Contact: 06/01/2012 Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2013 Date Data Arrived at EDR: 08/19/2013 Date Made Active in Reports: 10/03/2013

Number of Days to Update: 45

Source: Department of Energy & Environmental Protection

Telephone: 860-424-3375 Last EDR Contact: 11/17/2014

Next Scheduled EDR Contact: 03/02/2015 Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 07/19/2012 Date Made Active in Reports: 08/28/2012

Number of Days to Update: 40

Source: Department of Environmental Protection

Telephone: N/A

Last EDR Contact: 10/10/2014

Next Scheduled EDR Contact: 01/26/2015 Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 11/01/2014 Date Data Arrived at EDR: 11/05/2014 Date Made Active in Reports: 11/24/2014

Number of Days to Update: 19

Source: Department of Environmental Conservation

Telephone: 518-402-8651 Last EDR Contact: 11/05/2014

Next Scheduled EDR Contact: 02/16/2015 Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2013 Date Data Arrived at EDR: 07/21/2014 Date Made Active in Reports: 08/25/2014

Number of Days to Update: 35

Source: Department of Environmental Protection

Telephone: 717-783-8990 Last EDR Contact: 10/20/2014

Next Scheduled EDR Contact: 02/02/2015 Data Release Frequency: Annually

RI MANIFEST: Manifest information Hazardous waste manifest information

Date of Government Version: 12/31/2013

Date Data Arrived at EDR: 07/15/2014
Date Made Active in Reports: 08/13/2014

Number of Days to Update: 29

Source: Department of Environmental Management

Telephone: 401-222-2797 Last EDR Contact: 11/26/2014

Next Scheduled EDR Contact: 03/09/2015 Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2013 Date Data Arrived at EDR: 06/20/2014 Date Made Active in Reports: 08/07/2014

Number of Days to Update: 48

Source: Department of Natural Resources

Telephone: N/A

Last EDR Contact: 12/12/2014

Next Scheduled EDR Contact: 03/30/2015 Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc.

Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services

Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services,

a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary

and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are

comparable across all states.

Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Centers, Group & Family Homes

Source: Bureau of REgulatory Services

Telephone: 517-373-8300

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetlands Inventory Source: Department of Natural Resources

Telephone: 517-241-2254

Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK®-PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

802 ALPINE AVENUE NW 802 ALPINE AVENUE NW GRAND RAPIDS, MI 49504

TARGET PROPERTY COORDINATES

Latitude (North): 42.9782 - 42° 58' 41.52" Longitude (West): 85.6877 - 85° 41' 15.72"

Universal Tranverse Mercator: Zone 16 UTM X (Meters): 607004.9 UTM Y (Meters): 4759014.5

Elevation: 615 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map: 42085-H6 GRAND RAPIDS WEST, MI

Most Recent Revision: 1996

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

- 1. Groundwater flow direction, and
- 2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General East

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

FEMA Flood

Target Property County KENT, MI Electronic Data
YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property:

2601060005C - FEMA Q3 Flood data

Additional Panels in search area:

2601060010C - FEMA Q3 Flood data 2601060015C - FEMA Q3 Flood data 2601060020C - FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Electronic

NWI Quad at Target Property
GRAND RAPIDS WEST

Data Coverage
YES - refer to the

YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius: 1.25 miles Location Relative to TP: 1 - 2 Miles NNE

Site Name: Peninsular Plating Company

Site EPA ID Number: MID981195696

Surficial Aguifer Flow Dir.: NE TOWARD INDIAN MILL CREEK.

Measured Depth to Water: 5 feet to 8 feet.

Hydraulic Connection: The surficial aquifer is located within a shallow sand formation and

is underlain by 17 feet of hard glacial till.

Sole Source Aquifer: No information about a sole source aquifer is available
Data Quality: Information based on site-specific subsurface investigations is

documented in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

 LOCATION
 GENERAL DIRECTION

 MAP ID
 FROM TP
 GROUNDWATER FLOW

GEOCHECK[®] - PHYSICAL SETTING SOURCE SUMMARY

	LOCATION	GENERAL DIRECTION
MAP ID	FROM TP	GROUNDWATER FLOW
1	1/4 - 1/2 Mile NE	Not Reported
2	1/4 - 1/2 Mile SSE	SW
3	1/4 - 1/2 Mile ENE	S
4	1/2 - 1 Mile South	ENE
5	1/2 - 1 Mile NNE	NW
6	1/2 - 1 Mile SSW	Not Reported
7	1/2 - 1 Mile ENE	W
8	1/2 - 1 Mile WNW	N
9	1/2 - 1 Mile NE	Not Reported
A10	1/2 - 1 Mile NE	NW
A11	1/2 - 1 Mile NE	S
B12	1/2 - 1 Mile SSE	E
B13	1/2 - 1 Mile SSE	Not Reported
14	1/2 - 1 Mile ENE	NW
15	1/2 - 1 Mile ESE	E

For additional site information, refer to Physical Setting Source Map Findings.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

GEOLOGIC AGE IDENTIFICATION

Era: Paleozoic Category: Stratified Sequence

System: Mississippian
Series: Meramecian Series

Code: M2 (decoded above as Era, System & Series)

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: CAPAC
Soil Surface Texture: loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward

movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Somewhat poorly. Soils commonly have a layer with low hydraulic

conductivity, wet state high in profile, etc. Depth to water table is

1 to 3 feet.

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: HIGH

Depth to Bedrock Min: > 60 inches

Depth to Bedrock Max: > 60 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

	Soil Layer Information						
Boundary				Classi	Classification		
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	8 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 2.00 Min: 0.60	Max: 7.30 Min: 5.60
2	8 inches	35 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0.60 Min: 0.20	Max: 7.30 Min: 5.60
3	35 inches	60 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0.60 Min: 0.20	Max: 8.40 Min: 7.40

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: loamy fine sand

muck sandy loam fine sandy loam

sand loamy sand

Surficial Soil Types: loamy fine sand

muck sandy loam fine sandy loam

sand loamy sand

Shallow Soil Types: loamy sand

loamy very fine sand

sand

Deeper Soil Types: fine sand

clay loam stratified sandy loam loamy fine sand

muck sand

gravelly - sand

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE SEARCH DISTANCE (miles)

Federal USGS 1.000

Federal FRDS PWS Nearest PWS within 1 mile

State Database 1.000

FEDERAL USGS WELL INFORMATION

LOCATION

MAP ID WELL ID FROM TP

No Wells Found

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

LOCATION MAP ID WELL ID FROM TP

No PWS System Found


Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

LOCATION MAP ID WELL ID FROM TP

No Wells Found

PHYSICAL SETTING SOURCE MAP - 04170139.2r



SITE NAME: 802 Alpine Avenue NW
ADDRESS: 802 Alpine Avenue NW
Grand Rapids MI 49504

CLIENT: PM Environmental, Inc. CONTACT: Lindsey Sorensen INQUIRY#: 04170139.2r

LAT/LONG: 42.9782 / 85.6877

INQUIRY #: 04170139.2r DATE: December 30, 2014 8:42 am

Map ID Direction Distance				
Elevation			Database	EDR ID Number
1 NE 1/4 - 1/2 Mile Lower	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	0-002126 Not Reported Not Reported Not Reported 15 10/31/1990	AQUIFLOW	28602
2 SSE 1/4 - 1/2 Mile Higher	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	410107 SW Not Reported Not Reported 8 03/01/1996	AQUIFLOW	27792
3 ENE 1/4 - 1/2 Mile Lower	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	410148 S Not Reported Not Reported 7 to 11 04/28/1995	AQUIFLOW	27979
4 South 1/2 - 1 Mile Lower	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	410556 ENE Not Reported Not Reported 15 07/21/1986	AQUIFLOW	28548
5 NNE 1/2 - 1 Mile Lower	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	69264-S NW Not Reported Not Reported Not Reported 02/26/1993	AQUIFLOW	28517
6 SSW 1/2 - 1 Mile Higher	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	0-006157 Not Reported Not Reported 12 Not Reported 02/11/1987	AQUIFLOW	27832
7 ENE 1/2 - 1 Mile Lower	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	0-007217 W Not Reported Not Reported 7 01/15/1997	AQUIFLOW	28583

Map ID Direction Distance				
Elevation			Database	EDR ID Number
8 WNW 1/2 - 1 Mile Higher	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	0-016994 N Not Reported Not Reported 10-12 07/22/1998	AQUIFLOW	28465
9 NE 1/2 - 1 Mile Lower	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	0-002326 Not Reported Not Reported Not Reported 8 11/23/1994	AQUIFLOW	28447
A10 NE 1/2 - 1 Mile Lower	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	410249 NW 4 8 Not Reported 02/11/1991	AQUIFLOW	28513
A11 NE 1/2 - 1 Mile Lower	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	15285 S 7.5 Not Reported Not Reported 06/24/1998	AQUIFLOW	27702
B12 SSE 1/2 - 1 Mile Lower	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	410563 E Not Reported Not Reported 7 01/08/1997	AQUIFLOW	28575
B13 SSE 1/2 - 1 Mile Lower	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	0-017835 Not Reported 3 5 Not Reported 06/1990	AQUIFLOW	28090
14 ENE 1/2 - 1 Mile Higher	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	410636 NW Not Reported 5.4 Not Reported 09/17/1993	AQUIFLOW	28045

Map ID Direction Distance Elevation

Elevation Database EDR ID Number

15 ESE 1/2 - 1 Mile Higher

 Site ID:
 0-020983

 Groundwater Flow:
 E

 AQUIFLOW
 28068

Shallowest Water Table Depth: Not Reported Deepest Water Table Depth: Not Reported Average Water Table Depth: Not Reported Date: Not Reported 08/18/1997

AREA RADON INFORMATION

State Database: MI Radon

Radon Test Results

Zipcode	Test Date	LT Sign	Resul
49504	11/23/1998		1.6
49504	2/17/2009		1.6
49504	1/21/2009		1.6
49504	11/5/1998		1.5
49504	10/29/1998		1.5
49504	12/2/1998		1.5
49504	10/31/1998		1.5
49504	2/17/1994		1.5
49504	11/1/1997		1.5
49504	12/14/1998		1.5
49504	11/28/1998		1.5
49504	5/8/2002		1.5
49504	2/28/2008		1.6
49504	2/19/2007		1.6
49504	5/9/2008		1.6
49504	4/4/2007		1.6
49504	9/8/2000		1.6
49504	5/18/2001		1.6
49504	3/30/2009		1.6
49504	2/7/2009		1.6
49504	2/9/2007		1.5
49504	2/6/2007		1.5
49504	2/27/2006		1.5
49504	6/21/2007		1.5
49504	4/24/2007		1.5
49504	5/8/2008		1.5
49504	4/20/1999		1.5
49504	1/22/2002		1.5
49504	2/5/2007		1.5
49504	3/1/2004		1.4
49504	10/13/2009		1.5
49504	1/29/2010		1.5
49504	11/3/1997		1.4
49504	11/1/1997		1.4
49504	11/2/1998		1.4
49504	12/18/1998		1.4
49504	11/23/1998		1.4
49504	10/31/1998		1.4
49504	11/17/1998		1.4
49504	12/3/1998		1.4
49504	12/2/1998		1.4
49504	10/12/1998		1.4
49504	2/20/2001		1.4
49504	10/31/2009		1.4
49504	1/26/2009		1.4
49504	11/20/1998		1.3
49504	11/20/1000		1.0
1000-			

	11/24/1998	1.3
40504	3/13/2008	1.4
49504		
49504	1/4/2008	1.4
49504	2/9/2007	1.3
49504	3/20/2007	1.3
49504	2/17/1994	1.3
49504	11/21/1998	1.3
49504	10/30/1998	1.3
49504	12/18/1997	1.3
49504	11/23/1998	1.3
49504	11/2/1998	1.3
49504	1/30/2001	1.3
49504	1/31/2009	1.3
49504	1/19/2010	1.3
49504	9/21/2009	1.3
49504	11/10/1998	1.2
49504	11/5/1998	1.2
49504	11/16/1998	1.2
49504	11/28/1998	1.2
49504	12/14/1998	1.2
49504	12/26/1998	1.2
49504	11/2/1998	1.2
49504	12/16/1998	1.2
49504	12/14/1998	1.2
49504	12/14/1996	1.2
49504	1/9/1998	
49504	4/25/1998	1.2
49504	3/5/2002	1.2 1.2
49504	2/2/2000	1.3
49504	5/18/2001	1.3
49504	3/19/2009	1.3
49504	3/5/2009	1.3
49504	4/21/1994	1.2
49504	11/5/1999	1.2
49504	12/24/1999	1.2
49504	2/1/2002	1.2
49504	7/1/2005	1.2
49504	2/9/2007	1.2
49504	4/24/2006	1.2
49504	1/13/2006	1.2
49504	11/27/1998	1.1
49504	2/22/1999	1.1
49504	12/14/1998	1.1
49504	12/14/1998	1.1
49504	12/22/1998	1.1
49504	10/29/1998	1.1
49504	12/31/1993	1.1
49504	12/18/1998	1.1
49504	4/9/2002	1.1
49504	10/29/1998	1.1
49504	2/16/2000	1.2
49504	10/15/2009	1.2
49504	2/21/2009	1.2
49504	11/21/1997	1.1
49504	3/9/1996	1.1
49504	11/19/1998	1.1
49504		

	40/00/4000	
	12/22/1998	1.1
49504	9/26/2007	1.1
49504	4/22/1999	1.1
49504	4/15/1999	1.1
49504	1/20/2009	1.1
49504	2/22/2005	1.1
49504	3/28/2005	1.1
49504	8/26/2006	1.1
49504	5/17/2007	1.1
49504	1/25/2008	1.1
49504	1/18/2008	1.1
49504	3/12/2007	1.1
49504	1/27/1999	1.0
49504	1/11/1999	1.0
49504	12/14/1998	1.0
49504	11/10/1997	1.0
49504	1/11/1999	1.0
49504	3/5/1994	1.0
49504	2/2/2009	1.1
49504	4/30/1998	1.0
49504	1/29/1996	1.0
49504	11/13/1998	1.0
49504	3/31/1999	1.0
49504	3/5/1999	1.0
49504	11/24/1995	1.0
49504	2/26/2000	1.0
49504	2/24/1995	1.0
49504	3/24/2001	1.0
49504	1/24/2009	1.0
49504	2/13/2009	1.0
49504	1/12/2009	1.0
49504	11/14/2009	1.0
49504	12/5/2005	1.0
49504	2/10/2007	1.0
49504	3/2/2007	1.0
49504	10/1/2007	1.0
49504	1/21/2008	1.0
49504	3/16/2007	1.0
49504	4/24/2008	1.0
49504	5/7/2007	1.0
49504	12/7/1998	1.9
49504	11/23/1998	1.9
49504	12/23/1996	1.9
49504	12/11/1998	1.9
49504	11/5/1998	1.9
49504	12/5/1998	1.9
49504	12/18/1998	1.9
49504	10/30/1998	1.9
49504	12/31/1998	1.9
49504	3/13/1999	1.9
49504	10/29/1998	1.9
49504	10/27/2005	1.9
49504	12/22/1998	1.8
49504	12/16/1998	1.8
49504	12/26/1998	1.8
49504	11/30/1993	1.8
49504		

	11/19/1998	1.8
49504	11/20/1998	1.8
49504	11/13/1998	1.8
49504	1/2/1999	1.8
49504	11/10/1998	1.8
49504	11/12/1998	1.8
49504	11/19/2001	1.8
49504	1/26/2004	1.8
49504	5/10/2007	1.9
49504	2/26/2007	1.9
49504	10/29/1994	1.9
49504	11/5/1999	1.9
49504	9/13/1999	1.9
49504	10/10/2009	1.9
49504	6/29/2009	1.9
49504	12/16/2008	1.9
49504	11/3/1997	1.8
49504	1/18/2008	1.8
49504	2/20/2007	1.8
49504	2/28/2008	1.8
49504	1/25/2008	1.8
49504	2/20/2001	1.8
49504	11/8/1999	1.8
49504	2/21/2009	1.8
49504	11/6/2009	1.8
49504	4/3/2009	1.8
49504	4/10/2009	1.8
49504	1/21/2009	1.8
49504	1/29/2009	1.8
49504	5/6/2005	1.8
49504	2/27/2004	1.8
49504	2/3/2007	1.8
49504	10/17/2008	1.8
49504	10/27/2008	1.7
49504	1/21/2008	1.7
49504	5/26/2009	1.7
49504	12/29/2007	1.7
49504	3/30/2001	1.7
49504	10/29/1998	1.7
49504	11/2/1998	1.7
49504	10/30/1998	1.7
49504	2/9/1999	1.7
49504	10/30/1998	1.7
49504	11/5/1998	1.7
49504	1/10/2005	1.7
49504	11/19/1998	1.6
49504	11/20/1998	1.6
49504	2/10/1996	1.6
49504	12/7/1998	1.6
49504	10/31/1998	1.6
49504	9/15/2009	1.7
49504	2/13/2009	1.7
49504	2/27/2009	1.7
49504	11/16/2009	1.7
49504	2/2/2009	1.7
49504	3/3/2009	1.7
49504	0,0,200	1.7
73JU4		

	11/13/1998		1.6
49504	10/29/1998		1.6
49504	2/19/2007	<	0.3
49504	12/14/1998	<	0.3
49504	12/14/1998	<	0.3
49504	11/17/1997	<	0.3
49504	12/18/1998	<	0.3
49504	12/22/1998	<	0.3
49504	1/26/2004	<	0.3
49504	2/12/2002	•	0.5
49504	3/1/1999	<	0.3
49504	7/9/2005	<	0.3
49504	2/10/2004	<	0.3
49504	7/9/2005	<	0.3
49504	4/24/1998	<	0.3
49504	4/14/1998	<	0.3
49504	11/5/1998	<	0.3
49504	11/19/1998	<	0.3
49504	4/30/1998	<	0.3
49504	12/1/1998	<	0.3
49504	11/2/1998	<	0.3
49504	8/26/2005	<	0.3
49504	1/9/2006		0.5
49504	3/17/2008		0.5
49504	9/7/2001	<	0.3
49504	2/26/2007		0.5
49504	2/28/2006	<	0.3
49504	10/5/2009		0.5
49504	3/28/2003	<	0.3
49504	2/2/2009		0.5
49504	1/15/2010		0.5
49504	5/25/2004	<	0.3
49504	2/23/2007	<	0.3
49504	10/24/2001		0.4
49504	2/21/1995		0.4
49504	11/15/2003	<	0.3
49504	5/31/2008	<	0.3
49504	5/8/2008	<	0.3
49504	4/20/2007	<	0.3
49504	5/7/1998	<	0.3
49504	11/7/1998 12/24/2001	<	0.3
49504 49504	4/7/2007	<	0.3 0.3
49504	3/10/2007	<	0.3
49504	3/10/2007	<	0.3
49504	11/7/1998	<	0.3
49504	11/28/1998	<	0.3
49504	11/7/1998	<	0.3
49504	5/18/1998	<	0.3
49504	11/2/1998	<	0.3
49504	3/25/1999	<	0.3
49504	2/1/2002	<	0.3
49504	2/1/2006	<	0.3
49504	4/17/2006	<	0.3
49504	2/8/2007	<	0.3
49504	8/10/2007	<	0.3
49504			

	12/14/1998		0.3
49504	2/24/1999	<	0.3
49504	2/19/1999	<	0.3
49504	5/6/2002	<	0.3
49504	2/23/2007	<	0.3
49504	2/24/1999	<	0.3
49504	2/15/1999	<	0.3
49504	4/11/2008	<	0.3
49504	2/8/1999	<	0.3
49504	11/1/1997	<	0.3
49504	1/11/1999	<	0.3
49504	1/18/1999	<	0.3
49504	12/22/1998	<	0.3
49504	1/18/1999	<	0.3
49504	3/8/1999		0.8
49504	11/5/1998		0.8
49504	11/30/1998		0.8
49504	12/22/1998		0.8
49504	1/14/2010		1.0
49504	11/9/1998		0.9
49504	11/30/1998		0.9
49504	11/28/1998		0.9
49504	11/1/1997		0.9
49504	10/29/1998		0.8
49504	12/18/1998		0.8
49504	11/14/1998		0.8
49504	12/19/1998		0.8
49504	12/18/1998		0.8
49504	5/9/1998		0.8
49504	12/16/1998		0.8
49504	12/19/1998		0.8
49504	11/3/2003		0.7
49504	3/15/2004		0.7
49504	10/29/1998		0.9
49504	10/29/1998		0.9
49504	11/5/1998		0.9
49504	11/13/1998		0.9
49504	12/23/1997		0.9
49504	3/6/1999		0.9
49504	12/16/1998		0.9
49504	2/8/1999		0.9
49504	12/11/1998		0.9
49504	3/27/2006		0.6
49504	8/26/2006		0.7
49504	10/27/2006		0.7
49504	11/3/2003		0.9
49504	12/15/2003		0.9
49504	5/3/2006		0.6
49504	2/5/2007		0.6
49504	1/28/2008		0.7
49504	2/23/2008		0.7
49504	3/3/2007		0.7
49504	9/5/2006		0.6
49504	1/22/2008		0.6
49504	11/8/2008		0.7
49504	6/6/2007		0.6
49504			

	7/9/2007	0.6
49504	2/4/2008	0.6
49504	4/9/2008	0.8
49504	4/7/2008	0.8
49504	6/4/2001	0.7
49504	2/15/2007	0.9
49504	4/25/2006	0.9
49504	3/17/2008	0.6
49504	4/24/2008	0.6
49504	11/16/1999	0.6
49504	4/25/2001	0.6
49504	2/16/1995	0.6
49504	2/15/2000	0.8
49504	8/10/1999	0.7
49504	12/15/2008	0.7
49504	3/2/2007	0.9
49504	1/18/2000	0.6
49504	4/11/2009	0.6
49504	1/29/2000	0.8
49504	6/29/2009	0.7
49504	1/8/2010	0.7
49504	2/9/2009	0.7
49504	1/15/2010	0.7
49504	3/5/2008	0.7
49504	1/21/2008	0.9
	5/10/2008	
49504 49504		0.9
	1/17/2008 2/4/2008	0.9
49504		0.9
49504	3/30/2009	0.6
49504	1/30/2009	0.6
49504	1/15/2010	0.6
49504	4/18/2009	0.6
49504	3/3/2009	0.6
49504	11/13/1998	0.5
49504	11/6/1997	0.5
49504	12/23/1998	0.5
49504	12/14/1998	0.6
49504	11/9/1998	0.6
49504	10/30/1997	0.6
49504	10/23/1995	0.6
49504	12/14/1998	0.6
49504	12/16/1998	0.6
49504	3/19/2001	0.9
49504	2/19/2000	0.9
49504	11/25/1998	0.5
49504	11/21/1997	0.5
49504	11/2/1998	0.5
49504	11/16/1998	0.5
49504	2/12/1999	0.5
49504	12/3/1998	0.5
49504	11/7/1998	0.5
49504	11/2/1998	0.5
49504	4/21/2009	0.8
49504	2/3/2009	8.0
49504	12/26/1998	0.7
49504	1/27/1999	0.6
49504		

	12/12/1998	0.6
10501	7/23/2009	
49504		0.9
49504	2/2/1996	0.5
49504	1/26/1996	0.5
49504	8/24/1998	0.5
49504	12/14/1998	0.5
49504	11/9/1998	0.5
49504	10/30/1997	0.7
49504	11/9/1998	0.7
49504	11/25/1998	0.7
49504	11/19/1998	0.7
49504	11/12/1998	0.7
49504	11/23/1998	0.7
49504	11/5/1998	0.6
49504	11/12/1997	0.6
49504	8/21/2009	0.9
49504	1/20/2009	0.9
49504	3/2/2009	0.9
49504	8/31/1998	0.5
49504	1/17/2002	0.5
49504	5/23/1998	0.7
49504	11/19/1998	0.7
49504	11/16/1998	0.7
49504	7/3/2009	0.9
49504	1/15/2009	0.9
49504	2/6/2009	0.9
49504	3/25/1999	8.0
49504	11/10/1997	8.0
49504	10/30/1998	8.0
49504	12/14/1998	8.0
49504	3/15/1999	8.0
49504	3/8/1999	8.0
49504	11/6/1997	2.6
49504	11/2/1998	2.6
49504	2/5/2009	2.6
49504	2/3/2009	2.6
49504	2/11/2009	2.6
49504	4/24/2009	2.8
49504	11/23/1998	2.7
49504	4/15/1998	2.5
49504	11/7/1998	2.5
49504	12/22/1998	2.5
49504	10/29/1998	2.5
49504	10/28/1998	2.5
	1/9/1999	2.5
49504		
49504	11/2/2001 3/21/2007	2.5
49504		2.5
49504	10/30/1999	2.5
49504	2/6/2001	2.5
49504	11/3/2009	2.5
49504	2/2/2009	2.5
49504	11/3/1998	2.4
49504	10/30/1998	2.4
49504	11/2/1998	2.4
49504	8/11/2006	2.4
49504	2/5/2007	2.4
49504		

	4/25/2007	2.4
49504	2/2/2007	2.2
49504	1/26/2009	2.4
49504	10/29/1998	2.3
49504	12/1/1998	2.3
49504	11/25/1997	2.3
49504	6/4/1998	2.3
49504	10/29/1998	2.3
49504	12/13/1995	2.3
49504	11/13/1998	2.3
49504	2/24/1999	2.3
49504	11/10/1998	2.2
49504	5/9/1998	2.2
49504	8/19/1999	2.2
49504	2/17/2004	2.3
49504	11/8/1997	2.2
49504	8/24/2009	2.2
49504	2/23/2007	2.3
49504	12/18/1998	2.1
49504	10/30/1998	2.1
49504	1/19/1999	2.1
49504	12/11/1998	2.1
49504	4/16/1998	2.1
49504	4/11/1998	2.1
49504	10/29/1998	2.1
49504	11/23/1998	2.1
49504	2/23/2009	2.9
49504	1/14/2010	2.9
49504	11/2/1998	2.6
49504	10/30/1998	2.6
49504	11/7/2003	2.6
49504	11/13/1998	2.8
49504	10/23/1998	2.8
49504	11/7/1998	2.8
49504	10/31/1998	2.8
49504	2/24/1999	2.8
49504	4/20/1998	2.8
49504	2/17/2003	2.7
49504	1/24/2001	3.0
49504	11/16/2009	3.0
49504	12/29/2005	2.6
49504	1/24/2009	3.0
49504	1/31/2009	3.0
49504	4/11/1998	2.9
49504	10/29/1998	2.9
49504	4/11/1998	2.9
49504	1/25/1999	2.9
49504	10/4/1995	2.9
49504	5/19/2005	2.8
49504	2/16/2002	2.9
49504	2/5/2007	2.8
49504	2/9/2007	2.8
49504	11/20/1999	2.7
49504	4/19/1999	2.6
49504	3/31/2009	2.7
49504	1/29/2009	2.7
49504		

	3/16/2009		0.3
49504	3/16/2009	<	0.3
49504	2/21/2009	<	0.3
49504	1/21/2008	<	0.3
49504	1/21/2008	<	0.3
49504	2/12/2008	<	0.3
49504	2/9/2008	<	0.3
49504	2/1/2008	<	0.3
49504	2/3/2009	<	0.3
49504	2/5/2009	<	0.3
49504	3/2/2009	<	0.3
49504	2/27/2009	<	0.3
49504	12/1/2000		3.8
49504	12/7/1999		3.8
49504	7/11/2009		3.8
49504	5/10/2007		3.6
49504	3/21/2007	<	0.3
49504	2/8/2008	<	0.3
49504	5/26/2009		3.6
49504	12/5/1998		3.5
49504	11/16/1998		3.5
49504	11/16/1998		3.5
49504	11/3/1997		3.5
49504	12/26/1998		3.5
49504	5/21/1994	<	0.3
49504	1/12/2006		3.5
49504	3/8/2007		3.5
49504	6/9/2000	<	0.3
49504	6/22/2000	<	0.3
49504	12/26/1998		3.4
49504	10/31/1998		3.4
49504	12/14/1998		3.4
49504	10/30/1998		3.4
49504	4/25/2000		3.4
49504	2/8/2007		3.1
49504	12/11/1999	<	0.3
49504	3/6/2008		3.1
49504	12/18/1998		3.3
49504	5/7/2001	<	0.3
49504	10/20/2007		3.2
49504	12/9/2000	<	0.3
49504	7/11/2009		3.1
49504	3/21/2009		3.1
49504	11/2/1998		3.0
49504	12/15/2008	<	0.3
49504	12/15/2008	<	0.3
49504	12/15/2008	<	0.3
49504	2/5/2009	<	0.3
49504	4/18/2009		3.2
49504	11/3/1997		3.1
49504	2/25/2008		3.3
49504	2/25/1999		3.9
49504	12/14/1998		3.7
49504	1/11/1999		3.7
49504	12/18/1998		3.1
49504	12/22/1998		3.1
49504			

	3/19/2009	<	0.3
49504	3/19/2009	<	0.3
49504	3/23/2009	<	0.3
49504	4/24/2009	<	0.3
49504	1/15/2010	<	0.3
49504			0.3
49504 49504	11/23/2009	<	
	11/20/2009	<	0.3
49504	2/23/2009		3.9
49504	3/17/2008		3.7
49504	1/24/2000		3.7
49504	5/7/2009	<	0.3
49504	11/2/1998		3.8
49504	1/20/1999		3.8
49504	3/6/1999		3.8
49504	12/26/1998		3.8
49504	11/12/1998		3.8
49504	3/3/2007		3.4
49504	1/21/2009	<	0.3
49504	1/24/2009	<	0.3
49504	1/19/2010		3.3
49504	1/29/2010		3.3
49504	11/5/1997		3.2
49504	11/10/1998		3.2
49504	3/2/2009	<	0.3
49504	10/31/1998		7.6
49504	10/31/1998		7.6
49504	12/4/1998		7.2
49504	3/18/1997		7.2
49504	10/31/2008		6.6
49504	6/18/2004		7.1
49504	12/16/1998		6.3
49504	12/30/1998		6.2
49504	2/12/2007		6.2
49504	11/20/2008		6.2
49504	8/15/2009		6.1
49504	11/17/2009		5.6
49504	11/3/2009		5.6
	11/16/2009		
49504	11/8/2009		5.6
49504 49504			6.0
	11/21/1998		5.1
49504	5/11/1998		5.1
49504	12/8/1999		4.9
49504	11/1/1997		5.9
49504	8/14/2006		5.1
49504	1/15/2000		4.8
49504	1/29/2009		4.8
49504	3/30/2009		5.5
49504	11/9/1998		5.4
49504	11/5/1998		5.4
49504	11/2/2005		4.7
49504	2/2/2009		5.8
49504	7/13/2009		4.7
49504	4/11/2002		5.3
49504	4/30/2001		5.0
49504	3/15/2000		5.0
49504	4/29/1994		4.7
49504			

	11/5/1999	5.7
49504	1/29/2009	5.7
49504	11/17/1998	4.9
49504	11/2/1998	5.2
49504	1/29/2010	7.5
49504	1/11/1999	7.4
49504	11/7/1998	6.7
49504	3/15/1997	6.7
		6.7
49504	10/18/2003	
49504	12/4/1998	6.6
49504	11/21/2002	6.6
49504	1/29/2009	7.8
49504	11/13/2008	7.3
49504	11/17/2008	6.9
49504	2/2/1999	2.0
49504	1/28/1999	2.0
49504	12/14/1998	2.0
49504	12/18/1998	2.0
49504	10/29/1998	2.0
49504	3/31/2008	13.3
49504	10/31/1998	11.5
49504	4/11/2008	10.2
49504	11/8/2005	2.1
49504	4/5/2006	2.0
49504	5/29/2006	2.1
49504	7/20/2007	2.1
49504	10/8/2007	2.0
49504	2/18/2008	2.0
49504	2/18/2008	9.1
49504	3/6/1999	8.5
49504	4/21/2008	2.1
49504	11/1/1999	2.1
49504	10/30/1999	2.1
49504	12/6/1999	2.0
49504	1/18/1995	2.0
49504	6/23/2001	2.0
49504	2/21/2009	2.1
49504	2/5/2009	2.0
49504	11/19/2009	2.0
49504	5/14/1998	2.0
49504	11/6/1997	2.0
49504	5/23/1996	2.0
49504	2/2/2009	4.5
49504	10/31/1998	4.4
49504	12/16/1998	4.4
49504	10/30/1998	4.0
49504	12/16/1998	4.0
49504	11/21/1998	4.1
49504	11/21/1998	4.1
49504	12/6/2007	4.4
49504	11/6/1997	4.2
49504	11/16/1998	4.2
49504	1/27/1999	4.2
49504	3/29/1999	4.2
49504	2/17/2009	4.6
49504	12/14/2007	4.1
49504		

AREA RADON INFORMATION

11/13/1998 4.3 49504 4/11/1998 4.3 49504 4/9/2001 4.5

Federal EPA Radon Zone for KENT County: 2

Note: Zone 1 indoor average level > 4 pCi/L.

: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.

: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 49504

Number of sites tested: 12

Area Average Activity % <4 pCi/L % 4-20 pCi/L % >20 pCi/L Living Area - 1st Floor Not Reported Not Reported Not Reported Not Reported Not Reported Not Reported Living Area - 2nd Floor Not Reported Not Reported Basement 1.533 pCi/L 100% 0% 0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)

Source: United States Geologic Survey

EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetlands Inventory Source: Department of Natural Resources

Telephone: 517-241-2254

HYDROGEOLOGIC INFORMATION

AQUIFLOW^R Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services

The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)

Telephone: 800-672-5559

SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)

This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Water Well Data

Source: Department of Environmental Quality

Telephone: 517-335-9218

The data in this file was obtained from Wellogic, the Michigan Department of Environmental Quality Statewide Groundwater Database (SGWD). Wellogic contains approximately 425,000 water well records found within the State of Michigan, and although it represents the best available data, it cannot be considered a complete database of all the wells or well records in existence.

OTHER STATE DATABASE INFORMATION

Michigan Oil and Gas Wells

Source: Department of Environmental Quality

Telephone: 517-241-1528

Locations of oil and gas wells are compiled from permit records on file at the Geological Survey Division (GSD), Michigan Department of Natural Resources.

RADON

State Database: MI Radon

Source: Department of Environmental Quality

Telephone: 517-335-9551 Radon Test Results

Michigan Radon Test Results

Source: Department of Environmental Quality

Telephone: 517-335-8037

These results are from test kits distributed by the local health departments and used by

Michigan residents. There is no way of knowing whether the devices were used properly, whether there are duplicates (or repeat verification) test (i.e., more than one sample per home), etc.

Area Radon Information

Source: USGS

Telephone: 703-356-4020

The National Radon Database has been developed by the U.S. Environmental Protection Agency

(USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at

private sources such as universities and research institutions.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

EPA Radon Zones Source: EPA

Telephone: 703-356-4020

Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor

radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities

Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater

Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared

in 1975 by the United State Geological Survey

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

WRITTEN REQUESTS FOR FILE REVIEWS AND WRITTEN RESPONSES



ISO 9001 REGISTERED

Lansing

3340 Ranger Road Lansing, MI 48906

f: 877-884-6775 t: 517-321-3331 4080 W. 11 Mile Rd Berkley, MI 48072

f: 877-884-6775 t: 248-336-9988

Detroit

Grand Rapids 560 5th Street NW, Suite 301

Grand Rapids, MI 49504 f: 877.884.6775 t: 616.285.8857

VIA EMAIL: DEQFOIA@michigan.gov

Requested & Reviewed By: Sorensen@pmenv.com

December 29, 2014

Susan Vorce, FOIA Coordinator Office of Environmental Assistance Department of Environmental Quality

FOIA Coordinator:

Please accept this Freedom of Information Act request for file information for the following sites located in **Kent County**:

RRD records maintained in the Grand Rapids District Office Only:

- North End Transmission Service; 802 Alpine Avenue NW, Grand Rapids (FID: 00013761)
- Walmiller All-Service; 856 7th Street NW, Grand Rapids (FID: 00011368)
- 555 7th Street NW, Grand Rapids (BEA 3480)

OWMRP records maintained in the Grand Rapids District Office Only:

North End Transmissions Inc.; 802 Alpine Avenue NW, Grand Rapids (EPA ID: MID017095530)

We would like to review the files at the Grand Rapids District office before copies are made. Please contact me at 616-222-1777 or by email at Sorensen@pmenv.com to set up an appointment, or if you have any questions or concerns. Thank you.

Sincerely,

PM Environmental, Inc.,


Lindsey Sorensen
Staff Researcher
560.5th Street NW, Suite 1

560 5th Street NW, Suite 301 Grand Rapids, MI 49504

PME Project Number: 03-3849-0 BH (6/2/14)

Appendix E









1.800.313.2966 www.pmenv.com hengst@pmenv.com

Education

 Grand Valley State University B.S. Natural Resource Management

Certifications

 OSHA 29 CFR 1910.120 (c)(3) 40– hour HAZWOPER Course

BRYANT HENGST

STAFF CONSULTANT

Areas of expertise

- Staff Researcher for Phase I Environmental Site Assessments.
- Data collection, site investigation, and preparation of Phase I Environmental Site Assessments.
- Project investigator and engineer for Phase I and Phase II Environmental Site Assessments.
- Collection and evaluation of data for Transaction Screens, Phase I ESAs, and preparation of reports.
- Experience in implementation and completion of various site assessment standards and professional protocol and commercial lending requirements. (ASTM E-1527)
- Data collection and evaluation for Phase II Environmental Site Assessment Reports.
- Data management and report preparation for quarterly groundwater monitoring.
- Field Technician for the drilling of soil borings, installation of monitoring wells, collection of soil and water samples, excavation oversight, and surveying.
- Two years experience completing Phase I ESA site visits, which includes documentation of building materials and a discussion of suspect ACBM with licensed asbestos inspectors.





1.800.313.2966 www.pmenv.com shadley@pmenv.com

Education

Central Michigan University B.S. Geography and Environmental Science

Certifications

- Certified Asbestos Building Inspector State of Michigan Accreditation #A29309
- Certified Asbestos Management Planner State of Michigan Accreditation #A29309
- Certified Asbestos Project Designer State of Michigan Accreditation #A29309
- Certified Asbestos Hazard Evaluation Specialist State of Ohio #ES349636
- Certified Storm Water Management Operator State of Michigan CC-10849
- Section 106 of the Historic Preservation Act
- Radon Measurement Specialist, The National Radon Safety Board #13SS049
- Licensed Secondary Radon Tester Indiana State Department of Health RTS00679
- Meets the definition of Environmental Professional as defined in § 312.10 of 40 CFR 312

Professional Activities

Commercial Alliance of Realtors (CAR) West Michigan Educational Committee

SHAWN SHADLEY

REGIONAL MANAGER/SENIOR CONSULTANT

Mr. Shadley is a Regional Manager and Senior Consultant at PM Environmental, Inc. and has served clients in the Midwest and Southeast United States since 2001. He specializes in U.S. Department of Housing and Urban Development (HUD) Chapter 9 projects and Michigan State Housing Development Authority (MSHDA) Environmental review requirements. His recent focus includes providing developers, attorneys, and lenders with environmental due diligence services such as Phase I & II ESAs, BEAs Due Care Plans, NEPA compliance assessments, asbestos-containing material and lead based paint surveys.

Areas of expertise

- Data collection, site investigation, and preparation of Phase I Environmental Site Assessment (ESA) projects.
- Data collection, site investigation, and preparation of Transaction Screen projects.
- Experience in implementation and completion of various site assessment standards and professional protocol and commercial lending requirements (ASTM E-1527, ASTM E-1528).
- Project Investigator and preparer for Phase II ESAs.
- Project Investigator and preparer for Baseline Environmental Assessments and Due Care Plans in accordance with the Natural Resources and Environmental Protection Act, P.A. 451 of 1994, Parts 201 and 213.
- Bulk asbestos containing materials samples.
- Asbestos Operations and Maintenance Plans.
- Demolition inspections for commercial and residential properties.
- Completion of NEPA Assessments in accordance with Federal Regulations 24 CFR Part 50 and 24 CFR Part 58.





1.800.313.2966 www.pmenv.com sexton@pmenv.com

Education

- Michigan State University B.A. International Relations
- Specialization: Environmental Economics International Department
- University of Michigan Masters of Science Resource Policy and Behavior
- MDEQ Cleanup Criteria Training
- ASTM Phase I and Phase II Processes
 Training

Certifications

- Certified Asbestos Building Inspector Accreditation #A30924
- Meets the definition of Environmental Professional as defined in § 312.10 of 40 CFR 312

Professional Activities

- Environmental Bankers Association
- CREW Network Board Liaison for CREW Detroit Outreach

BETH SEXTON

NATIONAL MANAGER - DUE DILIGENCE GROUP

Mrs. Sexton (formerly Bailey) is the National Due Diligence Manager for PM Environmental, Inc. Mrs. Sexton has over 10 years of experience performing environmental due diligence on a variety of properties for financial institutions and borrowers, retail chains, industrial conglomerates, and real estate developers. She specializes in Phase I Environmental Site Assessments and Risk Management.

As the National Due Diligence Manager, Mrs. Sexton manages all aspects of the over 7,000 annual transactional due diligence projects from throughout the United States. Mrs. Sexton is a Michigan native with a Bachelor Degree from Michigan State University and a Master of Science from The University of Michigan.

Areas of expertise

- Data collection, site investigation, and preparation of Phase I Environmental Site Assessment (ESA) projects.
- Data collection, site investigation, and preparation of Transaction Screen projects.
- Experience in implementation and completion of various site assessment standards and professional protocol and commercial lending requirements (ASTM E-1527, ASTM E-1528)./
- Project Investigator and preparer for Phase II ESAs.
- Project Investigator and preparer for Baseline Environmental Assessments in accordance with the Natural Resources and Environmental Protection Act, P.A. 451 of 1994, Parts 201 and 213.
- Limited bulk asbestos containing materials samples.
- Demolition inspections for commercial and industrial properties.
- Completion of Brownfield Plans and associated regulatory paperwork.
- Coordination and management for PM Environmental, Inc. Phase I ESA Department.

Appendix F



COMMON ACRONYMS AND TERMINOLOGY USED IN THE COURSE OF THIS PHASE I ESA

The following is a list of common acronyms:

All Appropriate Inquiry	AAI
Asbestos Containing Materials	ACM
Aboveground Storage Tank	AST
American Society for Testing Materials	ASTM
Approximate Minimum Search Distance	ASMD
Comprehensive Environmental Response, Compensation and Liability Act	CERCLA
Environmental Data Resources	EDR
Environmental Site Assessment	ESA
Federal Emergency Response Notification System	ERNS
Large Quantity Generator	LQG
Leaking Underground Storage Tank	LUST
National Priority List	NPL
No Further Remedial Action Planned	NFRAP
PM Environmental, Inc.	PME
Polychlorinated Biphenyls	PCBs
Resource Conservation and Recovery Act	RCRA
Small Quantity Generator	SQG
Treatment Storage and Disposal Facility	TSD
Underground Storage Tank	UST
United States Environmental Protection Agency	USEPA

TERMINOLOGY

The following provides definitions and descriptions of certain terms that may be used in this report. Several terms are defined by ASTM Standard Practice E 1527. The Standard Practice should be referenced for further detail (such as the precise wording), related definitions, or additional explanation regarding the meaning of terms.

Asbestos containing material (ACM): Any material found to contain greater than 1% asbestos using an analytical method that is approved by the USEPA for asbestos analysis.

De minimis conditions: Conditions that generally do not present a material risk or harm to public health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.

Friable material: Defined in the National Emission Standards for Hazardous Air Pollutants (NESHAP) as a material that can be pulverized or reduced to dust using hand pressure only.

General risk of enforcement action: The likelihood that an environmental condition would be subject to enforcement action if brought to the attention of appropriate

governmental agencies. If the circumstances suggest an enforcement action would be more likely than not, then the condition is considered a general risk of enforcement action.

Historical recognized environmental condition (HREC): Environmental condition which in the past would have been considered a recognized environmental condition, but which may or may not be considered a recognized environmental condition currently. The final decision rests with the environmental professional and will be influenced by the current impact of the historical recognized environmental condition on the subject property. If a past release of any hazardous substances or petroleum products has occurred in connection with the subject property, with such remediation accepted by the responsible regulatory agency (for example, as evidenced by the issuance of a no further action letter or equivalent), this condition shall be considered a historical recognized environmental condition.

Non-friable material: Defined by National Emission Standards for Hazardous Air Pollutants (NESHAP) as a material that cannot be pulverized or reduced to dust using hand pressure only. According to NESHAP, non-friable building materials include those in Category I (packings, gaskets, resilient floor coverings/adhesives, and asphalt roofing materials) and those in Category II (all other materials).

Recognized environmental condition (REC): The presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the subject property or into the ground, ground water, or surface water of the subject property. The term includes hazardous substances or petroleum products even under conditions in compliance with laws. The term is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.

Subject property: The area that is the focus of a Phase I Environmental Site Assessment. The boundaries are not necessarily consistent with recorded legal descriptions of real estate, and are defined by the User.

Suspect ACM of concern: Defined as "(I) all friable suspect ACMs (II) any non-friable suspect ACMs expected to be disturbed by renovation or demolition activities planned for the subject property."

General Scope of Services for Phase I ESA

The purpose of the Phase I ESA is to gather sufficient information to develop an independent professional opinion about the environmental condition of the subject property. The ESA will be conducted in an attempt to satisfy the ASTM Standard (E-1527-13) and the U.S. EPA Standards and Practices for All Appropriate Inquiry as defined in the Small Business Liability Relief and Brownfields Revitalization Act. The Phase I ESA will encompass the following scope of work:

Records Review

- Federal and State database search for sites within the ASTM approximate minimum search distances.
- Review of one or more additional state environmental record sources (e.g., fire department, health department, published local or state site contamination lists, etc.). PM is typically exhaustive in inquiry with these resources.
- Utilization of as many of the ASTM standard historical sources as necessary and as reasonably ascertainable and likely to be useful to document all obvious uses of the subject property from the present, back to the subject property's first developed usage (agricultural or the placement of fill) or 1940, whichever is earlier (e.g., aerial photographs, fire insurance maps, topographic maps, street directories, building record and other sources including knowledgeable interviewees). PM is typically exhaustive in usage of these resources to document subject property historical usages. Chain of title is not typically consulted by PM unless all other standard and historical sources cannot adequately document subject property usages or if required by a lender. A separate fee to the lump sum quoted will be assessed for obtainment of chain of title.
- A records review in accordance with the requirements for a Vapor Intrusion Assessment per ASTM E-2600-08 is not included in this scope of work.

Site Reconnaissance

- The objective of the site reconnaissance is to obtain information regarding the likelihood of recognized environmental conditions in connection with the subject property.
- The exterior of the subject property and any structures, as well as, pathways, roads, etc., will be visually and physically observed.
- The interior of the structures on the subject property will be visually and physically observed. This includes all common areas, maintenance and repair rooms, boiler rooms and representative number of occupant spaces. Observations under floors, above ceilings or behind walls are not required unless specified by requirements other than the ASTM standard.
- PM will evaluate non-ASTM scope issues with a visual inspection, and comment on asbestos containing building materials, lead based paint, and water intrusion associated with mold. Sampling is not included within this scope of work, but can be completed under a separate proposal.
- Current and past uses of the subject property and adjoining properties, and general uses of surrounding properties, to the extent visually and physically observed will be recorded. Emphasis is placed on subject property or adjoining property usages involving use, treatment, storage, disposal or generation of hazardous substances or petroleum products. These observations may include process details on raw material and waste management practices.
- General description of structures and improvements on the subject property (number and age of buildings, ancillary structures, utilities, storage tanks, hazardous substance and petroleum product usage, general chemical or raw material usage, heating and cooling, stains, solid waste, waste water, etc.).

Interviews with Owners and Occupants

• Interviews with owners, occupants, key site manager and user (person on behalf Phase I ESA conducted), typically with regard to information about current and historical uses, general site setting information, site specific documents, litigation, administrative orders, notices of violations with regard to environmental issues, etc.

Interviews with Local Government Officials

A reasonable attempt will be made to interview at least one staff member of any of the following: the
local fire department, the local agency or state agency having jurisdiction over environmental matters in
the area in which the subject property is located, and/or the local health department. PM is typically
exhaustive in its inquiry of these sources, unless professional experience has indicated the resource is
not beneficial.

Evaluation and Report Preparation

• The report of the Phase I ESA findings will generally follow the ASTM format unless otherwise requested by the client or as outlined in any applicable lender requirements. The report will include documentation of sources, methodology, limitations, and credentials. Liability/risk evaluations, recommendations for Phase II ESA testing and remediation techniques are not provided within the scope of an ASTM performed assessment. Phase I ESA reports are kept in the strictest client confidence and are issued directly to the client. Issuance or reliance on the Phase I ESA report for purposes of making loan decisions by a private lender may be included in the Phase I ESA report if specified by the client.

USER'S CONTINUING OBLIGATIONS UNDER CERCLA

Conducting a Phase I ESA alone does not provide a landowner with protection against CERCLA liability. Landowners who want to maintain a bona Fide Prospective Purchaser, an Innocent Landowner, or a Contiguous Property Owner Defense must also comply with other pre-acquisition and post-acquisition requirements in the CERCLA regulations and AAI standards. The responsibilities for each defense are summarized below.

Bona Fide Prospective Purchaser Responsibilities

The Bona Fide Prospective Purchaser defense is intended for individuals or entities purchasing a property known to be contaminated. To obtain and maintain the defense, the individual or entity seeking the defense must also satisfy the following requirements (AAI, Section II D.1.):

- Have acquired a property after all disposal activities involving hazardous substances ceased at the property;
- Provide all legally required notices with respect to the discovery or release of any hazardous substances at the property;
- Exercise appropriate care by taking reasonable steps to stop continuing releases, prevent any threatened future releases, and prevent or limit human, environmental, or natural resources exposure to any previously released hazardous substance;
- Provide full cooperation, assistance, and access to persons authorized to conduct response actions or natural resource restorations;
- Comply with land use restrictions established or relied on in connection with a response action;
- Not impede the effectiveness or integrity of any institutional controls;
- Comply with any CERCLA request for information or administrative subpoena; and
- Not be potentially liable, or affiliated with any other person who is potentially liable for response costs for addressing releases at the property.

Innocent Landowner Responsibilities

The Innocent Landowner Defense protects individuals or entities (ultimately the "property owner") purchasing a property that is not known to be contaminated. The property owner must also satisfy the following requirements to obtain and maintain the defense (AAI, Section II D.3 and CERCLA Section 107(b)(3)):

- Have no reason to know that any hazardous substance which is the subject of a release of threatened release was disposed of on, in, or at the facility;
- Provide full cooperation, assistance and access to persons authorized to conduct response actions at the property;
- Comply with any land use restrictions and not impeding the effectiveness or integrity of any institutional controls;

- Take reasonable steps to stop continuing releases, prevent any threatened release, and prevent to limit human, environmental, or natural resource exposure to any hazardous substances released on or from the landowner's property;
- Demonstrate that the act or omission that caused the release or threat of release of hazardous substances and the resulting damages were caused by the third party with whom the person does not have employment, agency, or contractual relationship;
- Exercise due care with respect to the hazardous substance concerned, taking into consideration the characteristics of such hazardous substance, in light of all relevant facts and circumstances;
- Take precautions against foreseeable acts or omissions of a third party and the consequences that could result from such acts or omissions.

Contiguous Property Owner Defense

The Contiguous Property Owner Defense protects individuals or entities purchasing a property that is not known to be contaminated, but could be contaminated by migration from a contiguous property owned by someone else. To qualify as a contiguous property owner, a landowner must have no knowledge of contamination prior to acquisition, or reason to know of contamination at the time of acquisition, have conducted AAI, and meet all of the criteria set forth in AAI Section II.D.2 and CERCLA Section 107(q)(1)(A), which include:

- Not cause, contribute, or consent to the release or threatened release;
- Not be potentially liable nor affiliated with nay other person potentially liable for response costs at the property;
- Take reasonable steps to stop continuing releases, prevent any threatened release, and prevent or limit human, environmental, or natural resource exposure to any hazardous substances released on or from the landowner's property;
- Provide full cooperation, assistance, and access to persons authorized to conduct response actions or natural resource restorations;
- Comply with land use restrictions established or relied on in connection with a response action;
- Not impede the effectiveness or integrity of any institutional controls;
- Comply with any CERCLA request for information or administrative subpoena;
- Provide all legally required notices with respect to discovery or release of any hazardous substances at the property.

Persons who know, or have reason to know, that the property is or could be contaminated at the time of acquisition of a property cannot qualify for the liability protection as a contiguous property owner, but may be entitles to Bona Fide Prospective Purchaser status.